PHILCO Factory-Supervised



SERVICE

Shop Practices and Service Techniques

RADIO

DECEMBER, 1951

SUPPLEMENTS TO SERVICE MANUALS

During the last year there have been prepared and distributed to you, the Service Members, manuals covering the repair and adjustment of all the present Philco Radio models. We are taking this opportunity to bring these service manuals up-to-date with the latest "run" change information, part number corrections, and addition of part numbers covering new cabinet colors. We trust that this information will be added to your present manuals or kept intact with your service notes. If the latter course is taken, a good idea would be to add an appropriate note in each manual affected to refer you to the proper supplement. Additional information of this type will be sent as other changes are made.

SUPPLEMENT TO PR-1899, SERVICE MANUAL FOR MODEL 51-632

Addition to parts list

The part number of the plastic tip of the off-on switch lever is 54-8165.

SUPPLEMENT TO PR-1911 SERVICE MANUAL FOR MODEL 51-1330

Corrections to parts list

C-10 Condenser, tone compensation	ı
.0068mf	45-3505-57*
W-1 Line Cord	L-2183*
Pointer	56-5630-31
Tuning shaft	56-8370

Correction to schematic

The value of C-10 should be .0068mf.

The drawing of the 2nd IF transformer circuit under Run #2 on page 4 should be changed as follows: Lug designation 3 and 4 should be transposed.

Production change information

The wiring of C-9 was reversed. C-9A, .007mf DC blocking condenser, was wired so that C-9B, 220 mmf grid by-pass, will connect from the 7C6 plate to B— and act as a plate by-pass condenser. This change occured without a run number.

Run #3

To reduce AVC distortion:— The secondary of Z-1 is disconnected from the AVC line and is now connected to B—. A 180 ohm resistor, Part No. 66-1188340, is now wired from pin 7 to B— and is used for cathode bias of the 7B7, IF amplifier. A .05mf condenser, Part No. 61-0122*, is wired in parallel with the above resistor as cathode by-pass.

SUPPLEMENT TO PR-1898, SERVICE MANUAL FOR MODEL 51-1730

Corrections to parts list

C-15	Condenser, tone compensation,	
	.0068mf,	45-3505-57
T-3	Transformer, filament	32-8461
	Dial scale	54-5100-1
	Pointer5	6-5630-3FCP
	Pilot-lamp bracket-and-clip assen	ibly delete
	Spring, hairpin (2)	57-1468FA3
	Speed nut, changer mounting (3)	W-2554

Correction to schematic

The value of C-15, tone compensating condenser, should be .0068mf.

Production change information

C-18, the line by-pass condenser, was changed in value to .047mf., Part No. 45-3505-62, soon after the start of production.

Run #3

To reduce AVC distortion:— The grid return lead (lug 1 of Z2) is removed from AVC and connected to B-. A 330 ohm resistor, Part No. 66-1338340, is added in the cathode circuit of the 7B7 IF amplifier. The cathode bias resistor is by-passed by a .05mf condenser, Part No. 61-0122*.

Copyright, 1951, PHILCO CORPORATION

SUPPLEMENT TO PR-1902, SERVICE MANUAL FOR MODELS 51-1731 AND 51-1732

Corrections to parts list

C-10 Condenser, neutralization,
3.3mmf 30-1224-49
C-21 Condenser, DC blocking, phono coupling
Model 51-1731 .001mf 45-3505-52*

J-3 Socket, phono input 27-6252

Model 51-1732 .0033mf 45-3505-55*

Corrections to schematic

C-21 The value of this condenser is .001mf for Model 51-1731 and .0033mf for Model 51-1732.

The condenser between R-22 and R-23, the screen by-pass of the 2nd IF amplifier is C-33 with a value of .01mf.

The resistor from the Volume Control tap to the tone control is R-29 with a value of 27,000 ohms for Model 51-1731 and 18,000 ohms for Model 51-1732.

SUPPLEMENT TO PR-1903, SERVICE MANUAL FOR MODELS 51-1733 AND 51-1734

Corrections to parts list

J-5	Socket, phono input	27-6252
L-A1	Loop aerial, Model 51-1734	
	Aerial assembly not carried.	
	Plug only.	27-4785-11
L-S1	Speaker, Model 51-1734	36-1611-7
	Bin light cable assembly	41-3944-3
	Speaker Bolts (4)	W700-2

Corrections to schematic

The voltage at the junction of R-47, R-46, and C-59C should read 145V.

The two switch sections in the IF circuit that appear under Z4 should be designated as follows: Top section is WS-4 (F) and bottom section is WS-4 (R) The switch contact of WS-1(F) connected to the 7F8 mixer grid should be lug 9 instead of lug 1. Also, the switch arm of this section should have an arrow head touching lug 7.

The 7F8 mixer grid is pin 1.

The condenser in parallel with R-19 in the AM oscillator is C-21.

Production change information

Run #2

To improve FM sensitivity:— R-23 was changed in value to 1000 ohms, Part No. 66-2108340.

Page Two

Run #3

To improve AM sensitivity of the 7F8:— R-19 was changed to 1500 ohms, Part No. 66-2158340.

Run #4

To reduce low level audio distortion with sensitive 6AV6's at high signal level a 15mmf ceramic condenser, Part No. 62-015400021, was added from 1st audio grid, pin 1 of 6AV6 to ground.

Run #5

The AM oscillator coil, L5, was changed to Part No. 32-4153-11. However, the original part, No. 32-4153-6 will be used as replacement.

Run #6

To stabilize the FM i-f:— C-36 was changed in value to .003mf, Part No. 61-0109*.

MODEL 51-1736 — SUPPLEMENT TO PR-1902, SERVICE MANUAL FOR MODELS 51-1731 AND 51-1732

Model 51-1736 is identical to Model 51-1732 with the following exceptions.

LS-1 Speaker	36-1610-9
Cabinet	10824-4
Doors, matched set of 2	45-6685
Door knob (2)	56-8747-1
Door pull (2)	56-7138-2
Frame, changer mounting	76-6600

SUPPLEMENT TO PR-1478, SERVICE MANUAL FOR MODEL M-8 RECORD CHANGER

Change in parts list

The push-off cover assembly, Part No. 76-2984, is no longer carried, but the available components are as follows:

Bumper, holddown	54-4460
Record shelf	56-4626-1

SUPPLEMENT TO PR-1731, SERVICE MANUAL FOR MODEL M-20 RECORD CHANGER

Corrections to parts list and Fig. 16

Idler wheel	45-6559
Pulley assembly	45-6558
Turntable	35-2705

SUPPLEMENT TO PR-1923, SERVICE MANUAL FOR MODEL M-22 RECORD CHANGER

Corrections to parts list

Knob, speed control (Fig. 10)	54-4787
Drive belt (used on Motor 35-1451)	
(Fig. 11)	54-7959

SUPPLEMENT TO PR-1949, SERVICE MANUAL FOR MODELS 52-540, 52-541 AND 52-542

Code 122

This code of the above three models incorporates the "tube saver" resistor. The changes are as follows: The resistor, Part No. 33-1343-3 is wired across a three lug terminal panel at the oscillator end of the chassis. Electrically this resistor is in the series filament string between the output tube, which is now a 35L6, and the 12BA6 IF amplifier, as shown in the accompanying schematic. (Figure 1)

Additions to parts list

52-540-E Cabinet, ebony	10750-6
Knobs, (2)	54-4527-3
52-541-G Cabinet, gray	10747-1
Knobs (2)	54-4674-1
52-542-M Cabinet, mahogany	10769-7
Dial scale	54-5132-3
Knobs (2)	54-4718-34
52-542-E Cabinet, ebony	10769-11
Dial Scale	54-5132-3
Knobs (2)	54-4718-35

Corrections to parts list

, , , , , , , , , , , , , , , , , , ,	
Baffle, speaker, 52-540	Delete
Baffle, speaker, 52-541	Delete
Back, 52-542	54-7911
Baffle, speaker, 52-542	Delete
Dial Scale, 52-542	54-5132
Dial Backplate assembly (part of	76-7048) Delete

SUPPLEMENT TO PR-1950, SERVICE MANUAL FOR MODEL 52-544

Additions to parts list

52-544-E Cabinet, ebony	10745-5
Baffle and cloth	
Jewel	54-4304-1
Knobs, volume	. 27-4815-8
Auto-off-on and delayed of	f 54-4736-5
Auto set	
Time set	54-4736-8
Clock and cable assembly	76-7418
Dial scale	. 54-5055-2

Corrections to parts list

Baffle and cloth, 52-544W	Delete
Auto-off-on Knob, 52-544M	54-4736
Auto-off-on Knob, 52-544I	54-4736-1
Volume Knob, 52-544W	27-4815-7
Auto-off-on Knob, 52-544W	54-4736-5
Socket, clock	27-6273

SUPPLEMENT TO PR-1951, SERVICE MANUAL FOR MODELS 52-640 AND 52-641

Corrections to parts list

C-10	Condenser, ceramic, 4 section	30-1237
R-3	Resistor, bias, 820 ohms 60	6-1828340
	Handle, 52-640 (part of handle and bracket, 76-6967)	
	Handle and bracket assembly, 52-64 (order handle, Part No. 56-7940	1
	Pointer, 52-641	56-7973-1




FIGURE 1

SUPPLEMENT TO PR-1952, SERVICE MANUAL FOR MODEL 52-643

Corrections to parts list

Handle Assembly	76-6970-4
Dial backplate assembly (order backplate	
56-9190)	Delete
Pointer	.56-8774-1
Clip (coil mtg.)	56-4109

SUPPLEMENT TO PR-1953, SERVICE MANUAL FOR MODELS 52-940, 52-941 AND 52-942

Corrections to parts list

Back, 52-940	318-3288
Baffle, 52-940	54-7938-2
Clip scale mtg., 52-941	56-7886FE7
Cabinet, 52-941	
Back, 52-941	318-3289
Back, 52-942	318-3290
Baffle, cardboard, 52-942	Delete
Bezel, 52-942	56-7436-1
Plug, aerial, 4 pin	27-6214-1
m 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Delete

SUPPLEMENT TO PR-1955, SERVICE MANUAL FOR MODEL 52-944

Corrections to parts list

C-7	Condenser, screen by-pass,
	220mmf
C-16	Condenser, plate de-coupling, .01mf 61-0120*
	Back, flange, and socket assembly Delete
	Washer, speaker mtg. Delete

Additions to parts list

SUPPLEMENT TO PR-1956, SERVICE MANUAL FOR MODEL 52-1340

Corrections to parts list

LA-1 Loop antenna,		code 122		76-2127-13		
	Cabinet,	code	121			10840-5
	Cabinet.	code	122			10840-5