

**BLACK & WHITE TV** 

For Service Technicians

# The Tele-vue Trouble-Shooter

# Instructions for Using

Simply select the Tele-Vue Trouble-Shooter Chart by observing the symptom on the TV Receiver and referring to one of the following groups of troubles:

- 1. VIDEO
- 2. SOUND
- 3. SYNC
- 4. LOW VOLTAGE
- 5. HI VOLTAGE
- 6. VERTICAL SWEEP
- 7. HORIZONTAL SWEEP

After determining the group in which the trouble is occurring, check the group below for the exact symptom, and the chart number.

	GROUP	
	Symptom	Chart No
1.	Snowy Pix	
۷.	No Pix, No Sound	
3. 4.	Weak Pix	3 and .
	No Pix	5 and 6
6.	Fading Pix	8 and 21
/. 0	Smeared Pix	
9	Too Much Contrast	
10.	Black Bar Across C.R.T.	
11.	Dark Raster with White Flashes	14
-	GROUP 2	
	Symptom	Chart No
1.	No Sound	47
2.	Distorted Sound	48
	Buzz in Sound	, ,

	Symptom	Chart	No.
1.			18
3.	Loss of Sync		21
4.	. Pix Pull as Scene Change		22
5. 6.	. No vertical sync		- 23
7.			30 31
8.	Vertical Blanking Bar at Bottom of Pix		9
	GROUP	_	
	Symptom	Chart	No.
1.			42
2.	120 cps Pull in Pix		43
3. 4.	=		44 45
5.	Poor Focus		16
6.	No Sound Raster or Pix		46
	GROUP 5		
	Symptom	Chart	No.
1.	No Roster	15 and	36
2. 3.	Zo Th. T. Treak Ruster	39 and	
	Blooming	• • • • • • • • • • • • • • • • • • • •	40 41
	GROUP		
	Symptom	Chart	No.
1.	No Vertical Sweep		24
2. 3.	Foldover at Bottom of Pix		25
3. 4.	Off Frequency Not Enough Height	• • • • • • • • • • • • • • • • • • • •	26
5.	Too Much Height		27 28
6.	Poor Linearity		29
	GROUP 7		
	Symptom	Chart I	No.
1.	Off Frequency		32
2. 3.	Not Enough Width		33
3. 4.	White Lines on Left of Raster Christmas Tree Raster		34 35
5.	Vertical White Line	**********	37

# THE PRACTICAL APPROACH TO BLACK & WHITE TV THEORY

### INTRODUCTION

In troubleshooting a television receiver, we are fortunate that the set can be broken down to seven (7) main sections. This makes possible the isolation of the source of trouble, which is, after all, what we try to do in ony form of troubleshooting. The seven sections of the television receiver are presented in the Tele-Vue Troubleshooter so that the procedure of isolating the trouble begins with the selection of the chart. Once the chart has been selected. and this is done by observing the symptom on the receiver, a step by step check can be made starting with the most likliest cause, down to the last possible cause. These step by step checks were made on all makes and models, and results are amazing. Most cures occured during the first few checks because of the order of checking. On each chart the troubleshooting digest explains some of the theory behind the trouble, this is valuable information that should be read before going into the check steps. Through this, knowledge can be gained that will prove helpful on future repairs.

### REVIEW OF TELEVISION

The signal picked up by the television antenna is more complex than that found in radio. The reason for this is that the television signal must contain not only sound, but also picture information and synchronizing pulses so that the picture on the screen is stable. The sound section of the receiver is very similar to that found in radio with the one exception that the television sound is F.M. and the radio, on the broadcast band, is A.M. However, this does not mean that the entire sound receiving circuits are different, instead it means that a different type of detector is used, and that the bandwidth of the I.Fs is larger. As for the mixer, local oscillator, I.Fs, and audio circuits, they are almost identical to those found in A.M. radio.

The picture information is A.M., but covers a higher frequency than radio. This means that the circuits that handle the information must have a wider bandpass than is found in radio circuits. For example, the average A.M. radio handles frequencies up to 5 kc, while in the television receiver the frequencies go up to 4 megacycles. In order to handle these frequencies, peaking coils are used. The path of the picture information through the television receiver is similar to that of the signal passing through a radio, see Fig. 1. That is, from the antenna the TV signal passes through an RF amplifier, then on to




FIG. 1


the mixer where it is mixed with the local oscillator signal. From here it is passed to the I.Fs, these are called the VIDEO I.Fs, and the typical I.F. frequency is either 25.75 mc, or 45.75 mc. In TV, usually three I.F. amplifiers are used. From the I.Fs the signal goes to the detector, where the carrier is removed, and only the picture information is allowed to pass to the video amplifiers. Finally, after sufficient amplification, the picture information is fed to the picture tube. The varying electron stream inside the tube strikes the phosphor screen with varying strength to produce the illumination that gives us the picture. So you see, the television picture circuits are almost identical to the radio circuits, the main difference being in the frequencies that are used.

In order that the picture be produced in the same sequence as that in the studio, the electron beam inside of the picture tube must be controlled in its sideward and up and down motion. This is the job of the synchronizing circuits. Special pulses are sent out along with the sound and picture information, to control the sweep of the circuits that cause the beam to move inside of the CRT. A magnetic field is produced around the neck of the CRT by the deflection yoke, this field determines the action of the electron stream. In the TV receiver, it is the job of the horizontal and vertical sweep circuits to produce the correct magnetic field for the yoke. It is the sweep circuits that must be controlled by the synchronizing pulses, Fig. 2.

At some point between the video detector and the picture

tube, part of the signal is passed to a circuit called the SYNC SEPARATOR. Here the signal is removed, and only the synchronizing pulses are permitted to pass to the SYNC AMPLIFIER. This circuit amplifies the synchronizing pulses so that they are large enough to control the operating frequency of the horizontal and vertical sweep systems, Fig. 3.

In order that the screen of the CRT attract the electrons emitted from its cathode, a very high voltage is required. This will vary depending upon the screen size, but seldom falls below 7 kv, nor goes above 22 kv, for television receivers. In order to have this amount of voltage, a special circuit is set up in the horizontal sweep system that provides this high voltage due to collapsing magnetic fields. This is often referred to as the "flyback high voltage system".



### TROUBLESHOOTING PROCEDURE

In troubleshooting the television receiver, we have one of the greatest aids right at our fingertips. I am referring to the CRT. It is possible, by observing the CRT, to quickly isolate the cause of the trouble, to one of the seven sections mentioned at the beginning of this discussion. In some cases, it is possible to even isolate the cause of the trouble to just a few components out of the hundreds that are used in a television receiver. Let us look at the seven sections, and see how this is possible.


- 1. Video
- 2. Sound
- 3. Sync
- 4. Horizontal sweep
- 5. Vertical sweep
- 6. Low voltage
- 7. High voltage

### **VIDEO**

If the screen has no picture information, or the picture information is distorted in some way, weak, or smeared, etc, then our troubleshooting should be confined to the video circuits. Once this has been determined, then we can begin to isolate the trouble in the video section by quickly determining if the signal at the video detector is good or bad. This is done by means of the oscilloscope, one of the most valuable instruments in television servicing. If an oscilloscope is not available, then the VTVM or VOM can be used with fairly good results. If the signal at the detector is good, then our troubleshooting will lead us toward the CRT, and once again the oscilloscope or the meter will be our guide. If, however, the signal at the video detector is poor, then we must proceed back into the I.F. and R.F. circuits. To do this we will need the aid of a signal generator, or a meter. However, the signal generator is capable of feeding in a signal to the I.F. and R.F. circuits, that can be observed on the CRT, and will give us faster results. So you see, the picture tube has been a great aid in telling us the path of troubleshooting that we must follow.

### SOUND

This section almost goes without saying. If the picture is clear, and synchronized correctly, but the sound is distorted, or not clear in any way, then we must go straight to the sound circuit. The same checks that were discussed in the radio section, can be applied to the sound system of a television receiver. The fact that the sound is F.M. in no way changes this. All of the charts listed for troubles in the sound system of a television receiver



can be applied to an FM receiver and an AM receiver. However, because of the different frequencies involved, and the fact that the sound is only a port of the overall receiver, it was found necessary to use separate charts for this section.

### SYNC

The sync section of a television receiver, locks in the frequency of the vertical and horizontal sweep systems. Therefore, if the picture on the CRT is in any way out of sync, we concentrate our troubleshooting on the sync circuits. For example, suppose the sound is clear, and the picture information on the CRT is good, but the picture is rolling in the vertical direction, our attention must turn to the vertical synchronizing section of the receiver. Now this happens to consist of just a small circuit that is known as the integrator network, and we would immediately go to that network to find the answer to our trouble. This is one of those cases mentioned were it is possible, by observing the CRT, to isolate the cause of of the trouble to just a few parts in the receiver.

### HORIZONTAL SWEEP

The horizontal section of the television receiver controls the sideward movement of the electron beam inside the CRT. If this movement is in any way distorted, let us say it has some white lines on the left side of the picture, then we would know that the trouble is in the horizontal sweep circuit, and with the aid of the oscilloscope and meter, we can quickly isolate the cause of the trouble. If the horizontal sweep circuit quits completely, then we will lose all of the high voltage, because the collapsing field of the horizontal sweep system provides the receiver with its high voltage. This might at first tend to confuse this trouble, in the horizontal sweep, with a trouble in the high voltage itself. However, a few simple checks can be made at this time to determine if the trouble is in the high voltage or sweep circuit.

### VERTICAL SWEEP

The vertical sweep section of the receiver controls the beam inside the CRT in its up and down movement. Such things as height, body proportions, and squeezed sections of the picture, are controlled by this circuit. If the picture did not fill the screen at top and bottom, then our attention goes to the vertical system. This consists of an oscillator and an output tube, along with their individual components, but, it has been isolated by observing the picture on the screen.


### LOW VOLTAGE

The low voltage power supply controls ALL sections of the television receiver, therefore all sections will be affected by a trouble in this section. If the vertical and horizontal sections were affected, and the sound had trouble as well, then we would check the low voltage power supply because it is common to all of these. One of the common troubles in this section is low B plus. This will cause shrinkage on all sides of the screen, and weak sound at the same time.

### HIGH VOLTAGE

The high voltage is responsible for the brightness of the raster. Any troubles pertaining to the raster itself will therefore be localized to the high voltage. The only trouble that you might run into here, is the one already mentioned where the high voltage might be defective because of a trouble in the horizontal sweep. Once again, let me assure you that this can be isolated to either the horizontal sweep or the high voltage, with a few simple quick checks.

In summing up the troubleshooting of the television receiver, we find that the first step is to identify the defective section of the receiver. This will break up the set into the seven sections just mentioned. Once the trouble has been identified to one of these sections, then the process of isolating down to the defective component begins. Here we will follow the same procedures as were outlined in the radio troubleshooting procedure. Namely, visual inspection, tube substitution, signal injection (this will include use of the oscilloscope), voltage and resistance measurements, and finally component substitution. One thing must be kept in mind when replacing components, that is the physical size and placement. This is much more critical in a television receiver than in a radio. If possible try to replace a component with the same size as the defective one, and place the new part in the same location, and at the same angle, as the old one. This will avoid any difficulty with stray capacitance that may upset the alignment of the receiver. As you can see, great importance must be placed on the analysis of the trouble, and that depends on YOU. It is suggested that you read carefully the troubleshooting digest on the particular chart that you select for each trouble. Here you will find information that will help you determine that you have the correct trouble, and at the same time increase your ability to analyze the symptom.



The cooperation of Admiral makes this material available.

Replace R.F.
Amplifier Tube.

3

Check voltage on plate-screen and Grid of R.F.Amp-lifier.

4

If no voltage on plate or screen check B + line.

5

If voltage on plate and screen check tuner R.F. contacts.

6

Clean tuner and look for cold solder joints.

7

Take resistance checks on cathode and grid of R.F. Amplifier.

### DIGEST (A)

A SNOWY PIX MUST BE CAUSED BY EITHER THE R.F. AMPLIFIER STAGE OR THE AN-TENNA CIRCUIT, IN SOME RARE CASES THE A.G.C. MAY BE TOO GREAT TO THE GRID OF THE R.F. AM-PLIFIER IN WHICH CASE TROUBLE-SHOOTING THE A.G.C. WOULD BE NECES-SARY. THIS VOLTAGE WOULD HAVE TO EX-CEED - 6 VOLTS.



SNOWY PIX

SYMPTOM

DIGEST (B)

IN A VERY WEAK SIG-NAL AREA A SNOWY PIX IS NORMAL, IF SET WAS WORKING NOR-MALLY, THEN SOME TROUBLE MUST BE SUSPECTED. WHEN THE R.F. AMP. DOES NOT AMPLIFY, DUE TO SOME DEFECT, OR THE INPUT IS VERY WEAK (POOR AN-TENNA) NOISE WILL BE STRONG AS THE SIGNAL, AND WILL APPEAR AS A SNOWY EFFECT OVER THE PICTURE.

8

In additive tuner check contacts on switch by pushing them.

9

Watch Pix as you make check. It may clear as pressure is applied.

10

If tuner has hi-lo band check contacts on this switch.

11

SECTION

SCHEMATIC,

교

Take resistance check of antenna input coil circuit.


12

If none of the above help, align R.F. stage.

13

14

TROUBLE



NTRL WHITTIER, CALIF.U.S A

CIRCUIT

DIAGRAM -

I'Fs Video detec-

Check for loss of

voltage on above

3

Make special check of A.G.C.

Voltage should be O volts.

tor.

tubes.

DIGEST (B)

Connect generator Mod.I.F. to grid of tube before

sound takeoff.

SECTION

SCHEMATIC,

TELE

Should see black bars on C.R.T. If you do then move generator back.

10

If no black bars. Check that stage for resistance in grid-cathode.

11

Keep moving gen-erator back to grid of tubes until mixer.

12

If bars at mixer feed in 55,25 mc. on ch 2 position at mixer grid.


13

If no black bars, L.osc. is not working check E and R on L.osc.

14

If black bars at 55.25 mc. then trouble in RF amp. or tuner contacts.

NO PIX AND NO SOUND WOULD NORMALLY IN-DICATE A TROUBLE EXISTING IN THE TUNER, SINCE THIS IS COMMON TO BOTH PIX & SOUND. IN AN IN-TER-CARRIER SET THIS TROUBLE WOULD ALSO BE FOUND IN THE VIDEO I.F. AMP-LIFIERS. USE OF MARKER GENERATOR IS A GREAT HELP IN FINDING THE SOURCE OF TROUBLE.



If more than - 3 volts check volts A.G.C. load resistor.


5

If keyed A.G.C. check bias voltage on A.G.C.

6

Too much voltage on grid of keyed A.G.C. tube will cause trouble.

If A,G,C, is at 0 volts then use a marker generator as follows.



IF THE A.G.C. VOL-TAGE WERE TOO LARGE THE FRONT END AND SOME VIDEO I.F. TUBES WOULD BE CUT OFF. THIS WOULD PREVENTANY SIGNAL FROM PASSING, AND LOSS OF PIX AND SOUND WOULD RE-SULT. THE FIRST FEW CHECKS ASSUME THAT THE SET IS AN INTERCARRIER. IF IT ISN'T THEN NO NEED TO CHECK SOME OF THE I.F.'s OR VIDEO

NO PIX - NO SOUND DETECTOR. SYMPTOM

NTRL WHITTIER, CALIF.U.S A

### Change front end Video I.F. Det and video Amp.

2

tubes.

Check-Voltage on Plate-Screen and of above Grid tubes.

3

If beyond 20% on any of the above tubes check reason.

Pay close attention to grid voltages. A.G.C. may be too great.

5

If all voltage appear normal use a marker Generator as follows.

6


Connect generator To grid of last I. F. at I.F. modulated.

7

Look for black bars on Pix tube turn down gener-ator till bars are grey.

### DIGEST (A)

A WEAK PIX IS CAUSED BY A DEFECT IN THE VIDEO STAGES. THIS MAY BE IN THE TUNER-VIDEO I.F.'s. OR. THE VIDEO AMP-LIFIER CIRCUIT. THE R.F. AMP. COULD NOT BE THE CAUSE SINCE A SNOWYPIX IS NOTICED WITH POOR OPERATION OF THE R.F. ONE OF THE FIRST THINGS TO FIND OUT WITH THIS TROUBLE IS IF THE OUTPUT OF THE VI-DEO DET. IS LARGE ENOUGH IN PEAK TO AMP. THIS PEAK SHOULD BE FROM I TO 2 VOLTS.



WEAK PIX

SYMPTOM

THE PEAK TO PEAK AMPLITUDE AT THE VIDEO DET. WILL DE-TERMINE IN WHICH THE DIRECTION TROUBLE WILL BE. MORE THAN 1-2 V.IT WILL MEAN THAT THE SIGNAL REACH-ING THE DET. IS SUF-FICIENT. IN THIS CASE THE TROUBLE MUST BE IN THE VIDEO AMP. IF HOW-EVER. THE SIGNALAT VIDEO DETECTOR IS LESS THAN 1 V.P.P. THE TROUBLE IS IN THE VIDEO I.F.'s OR TUNER. WE WILL AS-SUME THAT THE OUT-PUT AT THE DET. IS LESS THAN 1 V.P.P.

DIGEST (B)

Move generator back one stage. Bars should now be black.

8

9

If black bars seen turn down gen. till bars are grey. Move back one stage.

10

0

SECTION

SCHEMATIC,

TELE-FAX

Continue moving gen. back. If bars grey at any grid check as follows.

11

Vary frequency of gen. to see if black bars appear at any point on

12


If they do, it means poor align-ment. Check alignment.

13

If bars remain weak check resistance of that stage or open capacitor.

14

If trouble is in tuner, check for poor contact on tuner switch or cold solder.



NTRL WHITTIER, CALIF.U.S A

Replace tubes in front end video I.F., Video Det. and Video amp.

Check peak to peak at video det. load. Should be at least lv.P.P.

3

If less than lv. P.P. refer to Chart #3.

Check signal at grid of first video amp. Should be same as at det. load.

5

If less,then check peaking coils and coupling cap. for o pen.

6


If normal at grid of 1st video amp. move scope to plate.

7

If one video amp. is used signal at plate should be 30 times larger

### DIGEST (A)

IN THIS PARTICULAR CONDITION OF A WEAK PICTURE WE ARE GO-ING TO ASSUME THAT THE TROUBLE IS IN THE VIDEO AMP, CIR-CUIT. THIS TROUBLE COULD BE CAUSED BY A DEFECT IN THE FRONTENDOF VIDEO I.F. AMPLIFIERS ALSO, ONE OF THE MOST IMPORTANT STEPS AT THIS TIME IS TO FIND OUT IF THE SIGNAL REACH-ING THE VIDEO DET-ECTOR IS LARGE ENOUGH. WE SHOULD HAVE AT LEAST 1V P.P. THIS CAN BE CHECKED WITH A SCOPE AT THE DET-ECTOR LOAD, IF SIG-NAL IS LESS, THEN REFER TO CHART #3.



WEAK PIX

SYMPTOM

### DIGEST (B)

THE USE OF THE SCOPE IN TRACKING DOWN THIS TROUBLE IS A BIG HELP SINCE WE CAN SEE IF THE SIGNAL IS WEAK AT ANY POINT. TUBES ARE THE BIGGEST CAUSE OF A WEAK PIX, BUT MANY TIMES A BAD FEAKING COIL OR COUPLING CAP-ACITOR MAY BE THE TROUBLE. IT MUST ALSO BE KEPT IN MIND THAT A WEAK C.R.T. MAY CAUSE YOU TO SET THE BRIGHTNESS CON-TROL TOO HIGH AND GIVE THE EFFECTOF A WEAK PIX. A 50V P.P. AT C.R.T. GRID WILL BE A GOOD CHECK FOR LARGE ENOUGH SIGNAL TO THE C.R.T.

8 It two video amp, are used, signal should be about

9

6 times larger.

If signal at plate is small check plate-screen cathode voltages.

10

Watch Cathode voltage closely if high. Cathode resistor may be open.

11

If signal normal at plate. Check grid of 2nd video amp.

12

If small, check peaking coils and coupling cap. for open.


13

Move scope to plate. Should be 6 times larger. If not, check volt-

14

If good signal at plate trouble is between this point and grid of C.R.T.





NTRL WHITTIER, CALIF.U.S A

SECTION SCHEMATIC,

FA

ELE

DIGEST (B)

8

Replace local oscillator tube.

2

In some cases replacing local oscillator will detune front end.

3

A number of L.O. tubes should be tried.

4

Dirty tuner contacts or poor soldering should be checked for next.

5

In tuners with wafer switch, clean only metal contacts.

6

Poor grounding on Local osc. circuit may be causing the trouble.

7

Any capacitor in the L.O. Circuit that changes value as the set warms up.

THE CONDITION KNOWN AS DRIFTING CAN BE RECOGNIZED BY THE FADING THAT TAKES PLACE IN THE SOUND AFTER THE TV SET IS SWITCHED ON FOR A FEW MINUTES. THE OUTSTANDING FEATURE OF THIS TROUBLE IS THE FACT THAT A RE-ADJUSTMENT OF THE FINE TUNING CON-TROL WILL BRING BACK THE SOUND. FADING MAY CON-TINUE IN THE ABOVE FASHION FOR 10 MIN-UTES IN SOME CASES FINE TUNING WILL BRING SOUND BACK EVERY TIME.



DRIFTING

THE CAUSE OF DRIFT-ING IS THE LOCAL OSCILLATOR CIR-CUIT. AS THE TV SET WARMS UP SOME COM-PONENT CHANGES VALUE. THIS IN TURN CAUSES THE LOCAL OSCILLATOR TO CHANGE FREQUENCY SLIGHTLY. SINCE THE SOUND IS MOST CRI-TICALIN TVA SLIGHT CHANGE IN LOCAL OSCILLATOR FRE-OUENCY WILL AF-FECT THE SOUND WITHOUT ANY NO-TICEABLE EFFECT ON THE PICTURE. THIS CONDITION IS FOUND MAINLY IN SPLIT CARRIER RECEIVERS. In the tuner schamatic shown this would be 6-115 and c-116 Replace both.

9

In other tuners replace capacitors in tank circuitand feed back circuit.

10

Somephilco tuners have A.F.C. for L.O. in this case check A.F.C. circuit.

11

SECTION

**SCHEMATIC,** 


**ELE-1** 

12

13

14

14



NTRL WHITTIER, CALIF. U.S. A.

tubes.

With selector on a channel look for composite signal at video det.

3

If no signal at det. proceed. If signal is present go to Chart #6.

4

Place gen.at grid last I.F. Feed in mod. I.F. Should see black bars on C.R.T.

5

If no black bars check voltage and resistance of this stage.

6


If bars are seen. Move gen. back to next I.F. grid same input signal.

7

If no bars at this point then check voltage and resistance of this stage

### DIGEST (A)

WHENNO PIX IS ON C. R.T. BUT GOOD SOUND IS NOTICED IT IS MOST LIKELY THAT THE TROUBLE EXISTS AFTER THE SOUND TAKE OFF POINT, IT MAY BE POSSIBLE FOR THE TROUBLE TO BE FOUND BE-FORE THE SOUND TAKE OFF, BUT IS MOST UNLIKELY.THIS POSSIBILITY WILL BE COVERED IN THE TROUBLE - SHOOTING PROCEDURE.



NO PIX SOUND NORMAL

SYMPTOM

TROUBLE

### DIGEST (B)

THIS TROUBLE COULD OCCURING BE-FORE OR AFTER THE VIDEO DET. SINCE THE SIGNAL CAN BE SEEN ON THE SCOPE AFTER DETECTION. IT IS MOST CONVEN-**IENT** START TO TROUBLE - SHOOTING BY LOOKING AT THE OUTPUTOF THE DET. ON THE SCOPE. WE WILL ASSUME THAT NO OUTPUT IS NO-TICEDAT THIS POINT. TROUBLE IN THE VIDEO AMPS. WILL BE COVERED ON CHART NO. 6 ON VIDEO AMP. TROUBLES.

8

If bars are seen move gen. back to next 1.F. stage same input signal.



SECTION

SCHEMATIC,

TELE-FAX

9

This will probably be 1st 1.F. grid If bars seen then trouble in tuner.

10

If no bars then check voltage and resistance around this tube.

11

If tuner feed gen. to mixer grid same signal fed in as before.


12

If no bars then mixer is bad. Check voltage and resistance.

13

If black bars are seen then refer to #12 in chart #2.

14



NTRL WHITTIER, CALIF, U.S.A.

CIRCUIT

DIAGRAM .

Admiral

Check for a signal at the output of the video det. If none present refer to Chart #5.

3

If signal at video det. check signal at Grid of 1st video amplifier.

If none check coupling cap. If direct coupled continue with check #5.

If signal at grid of 1st amp. check signal at plate. If none check #6.


6

Checkplate screen cathode voltage. If cathode i (V. or more cathoce Ris open.

If signal is at plate move scope to grid of 2nd video amp.

### DIGEST (A)

IN WAS MENTIONED IN CHART #5 THAT NO PIX COULD BE CAUSE-ED BY TROUBLES BE-FORE OR AFTER THE VIDEO DET. IN THAT CHART WE ASSUMED THE TROUBLE TO BE BEFORE THE VIDEO DET. IN THIS CASE WE WILL TROUBLE-SHOOT FOR TROUBLE AFTER THE VIDEO DET. IN ALL CASES OF NO PIX IT IS AL-WAYS BEST TO RE-PLACE TUBES FIRST SINCE THEY ARE MOST LIKELY TO CAUSE THE TROUBLE. THE SCOPE IS THEN USED AT THE VIDEO DETECTOR.



NO PIX SOUND NORMAL

SYMPTOM

### DIGEST (B)

IN TROUBLE - SHOOT-ING THE VIDEO AMP. THE USE OF THE OS-CILLOSCOPE IS MOST IMPORTANT.SINCE WE CAN SEE WHERE THE SIGNAL IS OR IS NOT. ONCE THE LOSS OF SIGNAL IS NOTED ON THE SCOPE, IT NOW BECOMES JUST A QUESTION OF VOLT-A GE AND RESISTANCE MEASUREMENTS OF THE STAGE THAT IS NOT PASSING THE SIGNAL A GOOD KNOW-LEDGE OF VOLTAGE R EADINGS EXPECTED AT VARIOUS POINTS IN THE VIDEO AMP, LIFIERSTRIP WILL BE HELPFUL IN FINDING THE TROUBLE.

If no signal at grid then coupfing cap, is open or grid shorted to ground.

### 9

If signal at grid of 2nd video amp. move scope to plate. If no signal check as in #6.

### 10

If signal at plate then trouble must be from this point to C.R.T.

### 11

Do not be concerned about a poor looking signal, this trouble is a complete loss.

### 12

Plate voltages should be within 20%.


### 13

If a peaking coil is open, signal from one side to other will change.

### 14

The above check in #13 should be done closely. Amplitude should remain same.

## TROUBLE



NTRL WHITTIER, CALIF.U.S.A.

CIRCUIT

DIAGRAM •

SECTION

SCHEMATIC,

**TELE-FAX** 

Replace all tubes in the video path.

2

Place scope at output of video detector.

3

When Pix fades and signal on scope fades trouble is before Det.

4

If signal on scope remains, trouble is in Video amp.

5

With trouble before det, use a signal gen.

6


When Pix fades, feed in Modulated I.F. signal.

7

Start at last I.F. grid and work back to tuner.

### DIGEST (A)

A FADING PICTURE CAN BE A VERY HARD THING TOLOCATE UN-LESS YOU USE SOME DEFINITE PROCEDURE. THE CONDITION IT-SELF WILL GIVE A PERFECT PICTURE ON THE SCREEN WHEN THE SET IS SWITCHED ON, AND AFTER A WHILE THE PICTURE WILL FADE OUT SLOW-LY.THE PICTURE MAY REMAIN OUT FOR **OUITE SOME TIME AND** THEN IT MAY BEGIN TO APPEAR AGAIN. THE PICTURE MAY LAST FOR SOME TIME OR MAY BEGIN TO FADE ONCE MORE AFTER A FEW MINUTES THIS WOULD BE THE INDICATION OF A FADING PICTURE.



FADING PIX

SYMPTOM

### DIGEST (B)

THE MOST LIKELY THING TO CAUSE THIS TROUBLE IS A HEATER CIRCUIT IN ONE OF THE TUBES BECOMING OPEN. AFTER WARM-ING UP WHEN IT OPENS THE TUBE WILL COOL AND THE HEAT-**ERSMAY TOUCH AGAIN** THUS MAKING THE TUBE OPERATE ON AND OFF. OTHER CAU-SES OF THIS FADING MAY BE OPEN RESIS-TORS THAT MAY BE MAKING AND BREAK-ING CONTACT OR A DEFECTIVE COIL IN THE VIDEO I.F. A SIG-NAL GENERATOR AND SCOPE WILL HELP IN LOCATING THE TROU-BLE TO ONE STAGE AND THEN THE VIVM CAN BE USED TO PIN DOWN THE COMPO-NENT.

8

Black bars should be seen on CRT.

8

SECTION

SCHEMATIC,

LE-F

9

If black bars missing at grid of a tube trouble there.

10

Take voltage and resistance reading of bad stage.

11

If signal remains on scope when Pix fades.

12

Use scope to follow signal to CRT.


13

If signal on scope missing at any tube, trouble is there.

14

Take resistance and voltage readings of bad stage.





Emerson

CIRCUIT

**DIAGRAM** 

NTRL WHITTIER, CALIF.U.S A

DIGEST (B)

8

Replace front end video I.F. and video amp.tubes.

2

Check for signal at video detector with scope.

3

If signal is present refer to Chart #6.

4

If no signal at det. feed marker gen. modulated I.F. to 1st I.F. Grid.

5

If black bars appear on CRT move gen. back one stage.


6

Continue this signal inection until black bars do not appear.

7

Check stage not passing signal, if grid has zero volts refer to Chart #5.

IN SOME CASES WHERE WE FIND NO PIX BUT NORMAL SOUND THE TROUBLE COULD BE IN THE FRONT END, VIDEO I.F. OR VIDEO AMPLIFIER CIRCUITS. HOWEVER IT IS POS-SIBLE THAT THE AGC IS DEVELOPING A LARGE AMOUNT OF BIAS ON THE I.F. AND R.F. AMPLIFIERS AND ALMOST CUTTING THEM OFF, SO THAT ONLY SOUND WILL PASS. IN TROUBLE-SHOOTING THIS, WE WILL USE NORMAL PROCEDURE TO LO-CATE THE TROUBLE.



NO PIX GOOD SOUND

SYMPTOM

IN SOME CONDITIONS OCCUR THAT WILL CAUSE THE AGC CIR-CUIT TO DEVELOP A LARGE AGC VOLTAGE, LOSS OF PIX WILL RE-SULT. THIS CONDITION IS FOUND VERY OF TEN IN KEYED AGC CIR-CUITS WHERE THE GRID VOLTAGE OF THE AGC TUBE IS DE-TERMINED BY THE PLATE CIRCUIT OF THE VIDEO AMP-LIFIER TUBE. IF ANY TROUBLE OCCURS IN THE VIDEO AMPLIFIER THEN THE AGC CIR-CUIT WILL BE AF-FECTED.

If grid at -4 volts or more check AGC load resistor.

9

If load resistor normal check bias on AGC tube if used.

10

If bias is way off check AGC tube circuit.

11

SECTION

SCHEMATIC,

**TELE-FAX** 

If keyed AGC is used check video amp circuit.

12


With no picture AGC voltage should be zero.

13

If some voltage is on the AGC line then the AGC is defective.

14

TROUBLE



Emerson

NTRL WHITTIER, CALIF.U.S.A.

CIRCUIT

Vary fine tuning control. Note if smear changes.

3

If smear changes greatly check local oscillator adjustments.

4

It local osc. adjustments do not help, check video I.F. response curve.

5

If fine tuning has little effect on smear, check signal at video det.

6

If signal is poor at video det. check peaking coil and det. load.

7

If signal is normal at video detmove scope to grid of 1st video amp.

### DIGEST (A)

A SMEARED PIX CAN BE CAUSED BY MANY SECTIONS IN A TV RECEIVER, ONE OF THE COMMON DEFECTS IS POOR ALIGNMENT. THIS COULD BE IN THE FRONT END OR THE FRONT END OR THE FRONT END OR THE FINE TUNING CONTROL. IF THE SMEAR IN THE PIX CLEARS UP A LITTLE, OR GETS WORSE IT WILL, INDICATE THAT THE ALIGNMENT IS OFF, SINCE UNDER NORMAL CONDITIONS THE FINE TUNING SHOULD HAVE HARDLY ANY EFFECT ON THE PIX, IF ALIGNMENT IS INDICATED FOLLOW MANUFACTURERS INSTRUCTIONS. IF THE FINE TUNING HAS NO EFFECT ON THE PIX, THEN TROUBLE MUST BE IN THE VIDEO AMP.



SMEARED PIX

SYMPTOM

### DIGEST (B)

TROUBLE-SHOOT-ING THE VIDEO AMP. FOR A SMEARED PIX. AGAIN THE ONCE SCOPE IS NECESSARY. MOST COMMON TROU-BLES THAT CAUSE THIS ARE FOUND IN PEAKING COILS AND OPEN BY-PASS CAP-ACITORS. HOWEVER. BY USING THE SCOPE IT CAN BE DETER-MINED EXACTLY WHERE THIS TROUBLE IS OCCURING. VERY SELDOM IS THIS TROU-BLE CAUSED BY TUBES HOWEVER THEY MUST BE CHECKED IN CASE THEY ARE CAUS-ING THIS CONDITION.

If normal move scope to plate of lst video amp, if poor check #9.

# (10

SECTIO

SCHEMATIC,

×

4

rece-F

9

Check bias and plate voltage. If low, peaking coil at plate may be open.

10

Plate load resistor may have increased or open bypass capacitor

11

To check for open cap. bridge with good one or check at cap, with scope.

12

No signal should be noticed if capacitor is good.


13

If second video amp. is used then follow above checks 7-12 on 2nd amp.

14

Signal on both sides of a peaking coil should be same if coil is good.

TROUBLE



NTRL WHITTIER, CALIF U.S.A.

CIRCUIT

SECTION

SCHEMATIC,

AX

TELE-F.

Check setting of contrast and A.G. C. Controls.

2

Replace all tubes in front end, vi-deo I.F. and video amp.

3

Check A.G.C. voltage. Should be at least 6 volts on all tubes it feeds.

If A.G.C. is low refer to chart #19 on A.G.C.

5

If A.G.C. voltage is normal check output of video det. for 2v P.P. sienal

If signal is very large at det. recheck A.G.C. voltage.

With normal signal at det. Trouble is in video amp.

A PIX THAT IS TOO DARKCAN BE JUST AS BAD AS A PIX THAT IS VERY WEAK. UNDER THIS CONDITION THE PIX BECOMES TOO CONTRASTY AND THE DIFFERENT SHADES DONOT STAND OUT AS WELL AS THEY SHOULD INMOST GOOD OPERA-TING SETS. WHEN THE CONTRAST IS AT A MAXIMUM THE PIX SHOULD BE TOO DARK TO WATCH. IN SOME CASES THE A.G.C. CONTROL MAY BE SET INCORRECTLY, THIS SHOULD BE CHECKED FIRST, NOT ALL SETS HAVE AN A.G.C. CON-

TROL.



**VERY DARK PIX** 

SYMPTOM

TOO DARK A PIX CAN BE CAUSED BY INCOR-**RECT CONTRAST SET-**TING, OR A.G.C. CON-TROL SETTING. THIS SHOULD BE CHECKED FIRST SINCE THIS IS THE EASIEST THING TO CHECK. TUBES MAY ALSO BE INTERNALLY SHORTED CAUSING MAXIMUM GAIN AS THE PASSES SIGNAL THROUGH IT. THESE MUST BE CHECKED BY REPLACEMENT. AL-IGNMENT COULD ALSO CAUSE THIS TROUBLE BUT THIS SHOULD ONLY BE SUSPECTED IF THE SET HAS BEEN TAMPERED WITH.

Check video amp. for shorted cathode cap, or de-crease in cathode resistor.

9

Check for open peaking coil at plate of video amp.

10

If a plate bypass capacitor is used check it for an open.

11

Look for increase in plate load resistor.


12

Check contrast control circuit for a decrease in resistance.

13

If all appear normal, then check alignment of set.

14



7

NTRL WHITTIER, CALIF. U.S. A.

control has little or no effect check No. 3.

3

Measure voltages at base of C.R.T. with base re-moved.

Grid zero, screen 300v and cathode varies from 100v to zero.

5

Cathode voltage depends on setting of brightness control.

6

If cathode voltage does not change check brightness circuit and control.

7

Control may have open center tap or B plus feeding control may be low.

### DIGEST (A)

THIS IS AN IMMEDIATE INDICATION THAT THE PIX TUBE IS BAD. AL-THOUGH IN SOME CASES A BAD BRIGHT-NESS CONTROL COULD CAUSE THIS CONDI-TION. IT WILL BE NO-TICED THAT IF THE BRIGHTNESS CONTROL DOES AFFECT THE PIX.THAT IT WILLNOT CAUSE THE RASTER TO DISAPPEAR AS FOUND UNDER NOR-MAL OPERATING CONDITIONS.



PIX BRIGHT -**NO CONTROL** 

SYMPTOM

### DIGEST (B)

AN INTERNAL SHORT BETWEEN ELEMENTS IN THE PIX TUBE WILL PLACE A POSI-TIVE VOLTAGE ON THE GRID OF THE PIX TUBE. NORMALLY THE GRIDHAS ZERO VOLTS AND THE CATHODE VOLTAGE, CONNECTED TO THE BRIGHTNESS CONTROL, CONTROLS THE CONDUCTION OF THE C.R.T. HOWEVER. WITH THE GRID POSI-TIVE, THE C.R.T. WILL CONDUCT REGARD-LESS OF CATHODE VOLTAGE.

some cases brightness control feeds grid and cathode is constant.

9

Closely check schematic for above condition.

10

If this is being used then grid should vary from Ov to - 100v.

11

If grid is positive check coupling cap to grid for short.

12

If all checks are normal then C.R. T. is bad.

13

Tap neck of C.R.T. slightly. This may restore normal operation.

14

19XP4 180K < ₹ R436 270 K T.047 MF R437 1KV 2.7 MFG

R324 TO 8+ 270V ( JCT. OF 1502 120 K & C50481 BRIGHTNESS C319 # 45V 6.8.5% JIME CONTRAST CONNECT TO A, B OR C WHICHEVER PROVIDES BEST FOCUS . **~~~** 8.2 K C321 (C505C) C421 5 MF 1KV C = 5 MF = 200 V

FOCUS

CIRCUIT

270V

DIAGRAM

R319

NTRL WHITTIER, CALIF.U.S A

SECTION

SCHEMATIC,

-FAX

These first checks assume only one black bar on C.R.T.

With bar on Pix remove R.F. if bar remains R.F. amp. OK.

3

Replace R.F. tube pull L.O. if bar remains, L.O. is OK.

Replace L.O. remove mixer if bar remains mixer OK.

5

Continue the above methods pulling one tube at a time.

6

Try 1st I.F., 2nd I.F., etc. Det. tube and video amplifiers.

If at any time bar disappears then the tube pulled is bad.

### DIGEST (A)

WITH A BLACK BAR ON C.R.T. THE TROUBLE IS LIMITED TO THE VIDEO CIRCUITS. THIS COULD BE THE FRONT END - VIDEO I.F. - -OR VIDEO AMP. INCLU-DING THE C.R.T. THIS HOLDS TRUE IF ONE BLACK BAR IS NOTI-CED. IF TWO BLACK BARS ARE NOTICED THEN TROUBLE IS IN THE POWER SUPPLY. THIS SHOULD BE DE-TERMINED **BEFORE BEGINNING TROUBLE-**SHOOTING.



BLACK BAR ON C.R.T.

SYMPTOM

DIGEST (B)

IN THE CONDITION OF ONE BLACK BAR THE TROUBLE IS A SHORT BETWEEN HEATER & CATHODE OF ANY VIDEO TUBE WITH TWO BLACK BARS THE TROUBLE IS AN OPEN FILTER IN THE POWER SUPPLY SINCE TWO BARS INDICATE 120 CPS AND THIS IS FOUND ONLY IN THE POWER SUPPLY.

If last video amp. does not remove bar C.R.T. must have short.

9

Check from cathode to heaters with ohmmster on C.R.T.

10

O

SECTION

SCHEMATIC,

4

Should have infinite resistance if a reading is found, replace C.R.T.

11

If two black bars are noticed bridge all filter cap.


12

When open filter cap, is bridged, black bars will disappear.

13

14

TROUB



CIRCUIT

NTRL WHITTIER, CALIF.U.S A

Vary the brightness control to see effect.

2

It raster remains dim check voltage on grid and ca-thode.

Grid should be zero and cathode varies from Ov to 100v.

If both are normal then tap all around neck of C.R.T.

5

Do this tapping gently. If flashes appear as you tap then C.R.T.is bad.


6

As another check measure H.V.Now check back of C. R.T. for voltage.

On C.R.T.grid OV cathode Ov to 100v and screen 300v.

### DIGEST (A)

IN THIS TROUBLE THERE IS A DARK OR RASTER AND DIM EVERYNOWAND THEN SOME WHITE STREAKS ARE NOTICED ON THE C.R.T. AT THIS TIME THE BRIGHTNESS CON-TROL WILL TELL THE REST OF THE STORY. IF WHEN THE CON-TROL IS VARIED NO EFFECT IS NOTICED THEN THIS POINTS TO C.R.T. TROUBLE.



DARK RASTER WHITE FLASHES

SYMPTOM

DIGEST (B)

AN OPEN CATHODE IN-SIDE THE C.R.T. WILL. CAUSE A VERY DIM RASTER TO BE SEEN BUT THE CONTROLS WILLHAVE NO EFFECT ON THIS. THE FLASHES THAT MAY APPEAR FROM TIME TO TIME ARE CAUSED BY VIB-RATION THAT MOMEN-TARILY CAUSE THE CATHODE WIRES IN-SIDE THE C.R.T. TO TOUCH.

8

If H.V. and base pin voltages normal then C.R.T. bad.

9

In case of lack of voltage on any of the checks find out why.

10

SECTION


**SCHEMATIC,** 

**TELE-FAX** 

11

13

14



NTR L WHITTIER, CALIF. U.S. A.

12

tubes.

2

Touch finger on center tap of volume control.

3

If a buzz is heard trouble is in IF.

Use a sig. gen. at a little less than IF frequency.

5

Feed it to grid of IF amp.Modulated signal.


6

If no Tone in speaker take voltage and resistance check of IF and DET.

Trouble must be between IF grid and volume control.

WITH NO SOUND IN A TV SET THE TROUBLE IS LIMITED TO THE SOUND CIRCUIT ONLY. TUBES SHOULD BE CHECKED FIRST AS THEY ARE THE MOST TROUBLE. COMMON THE CHECKS THAT ARE USED ON A RADIO CAN BE APPLIED AT THIS TIME, SUCH AS TOUCHING THE CEN-TER TAP OF THE VOL-UME CONTROL AND LISTENING FOR A BUZZ FROM THE SPEAKER, REMOVING THE OUTPUT TUBE AND LISTENING FOR A CLICK, ETC. IF THE TROUBLE IS BEFORE THE DETECTOR THEN A GENERATOR MUST

BE USED TO LOCAL-IZE THE TROUBLE.



NO SOUND

SYMPTOM

DIGUST (8)

THE SOUND CIRCUIT IN A TV RECEIVER IS TAKEN OFF EITHER BEFORE OR AFTER THE VIDEO DETEC-TOR, IN MODERN SETS IT USUALLY IS AFTER THE DETECTOR, FROM THIS TAKE OFFPOINT IT IS FED TO AN I.F. AMP, AND THEN FED TO A SOUND DETEC-TOR, THIS MAY BE A RATIO DET. OR A DIS-CRIMINATOR. AFTER DETECTION THE SOUND IS APPLIED TO THE AUDIO AMP CIR-CUITS, WHERE IT IS AMP AND PASSED TO THE LOUD SPEAKER. WITH NO SOUND THE TROUBLE CAN BE AT ANY POINT FROM THE SOUND TAKE OFF ON.

If Tone, move gen to sound take off if no tone check Circuit.

SECTION

SCHEMATIC,

9

If no buzz at tap of volume control Audio amps are bad.

10

Take voltage of amp circuit and resistance check.

Output transformer or speaker may be open.

12

13 14

3DT6 T301 CONN L302 CONN AUDIO DET

Motorola

CIRCUIT

1/2 6AU8

AUDIO IF

DIAGRAM •

NTRL WHITTIER, CALIF.U.S A

11

Replace all sound Tubes.

2

Measure all plate and screen voltages on sound tubes.

3

Measure bias on audio amp tubes.

4

Audio output should have 8-12 volts bias.

5

First audio amp. should have almost zero bias.

6


If bias is way off, check coupling cap for leakage.

7

Also check cathode resistor for change in value.

### DIGEST (A)

DISTORTION IN THE SOUND CIRCUITS OF A TV RECEIVER ARE THE SAME TROUBLES THAT CAUSE DISTOR-TION IN RADIO, THE ONLY DIFFERENCE IN THIS CASE IS THAT MANY TIMES THE DIS-TORTION IS DUE TO POOR ALIGNMENT. LEAKY COUPLING CAPACITORS AND BAD TUBES ARE BY FAR THE MOST COMMON TROUBLES HOWEVER AND SHOULD BE CHECKED.LOCAL OS -CILLATOR ADJUST-MENTS MIGHT BE TRIED FIRST IF THEY ARE KNOWN BECAUSE THE TUNER MAY BE JUST A LITTLE OUT OF ADJUSTMENT. THE FINE TUNING MAY TELL YOU THIS IF VARIED.



DISTORTION

SYMPTOM

### DIGEST (B)

DISTORTION WILL OC-CUR IN THE SOUND CIRCUIT OF TV WHEN-EVER THE SOUND SIG-NAL PASSES THROUGH A TUBE THAT HAS THE WRONG BIAS ON IT THIS WILL HAPPEN MOST OFTEN IN THE AUDIO AMP CIRCUIT SINCE THE BIAS ON THESE TUBES IS FAIR-LY CRITICAL, IF THE IF CIRCUITS ARE OUT OF ALIGNMENT IT IS POSSIBLE THAT DIS-TORTION WILLOCCUR, HOWEVER IN MOST CASES POOR ALIGN-MENT WILL CAUSE A BUZZ TO APPEAR IN SOUND. TUBES ARE THE MOST COMMON CAUSES OF THIS TROUBLE.

Keep in mind that the speaker may

be bad.

SECTION

SCHEMATIC,

9

If voltage of audio amp is o.k. check into I.F. circuits.

10

If the I.Fs check plate resistors and cathode circuit.

11

If all the above checks are normal then align sound LF.


12

trouble still align present video I.F.

13

14

TROUBLE



CIRCUIT

NTRL WHITTIER CALIF U.S.A.

Replace all sound, video I.F. and front end tubes.

2

If 6BN6 is sound det. adjust buzz control on rear panel.

3

If buzz varies as vert.hold is moved, check shielding of sound wiring.

4

Contrast may be set too high causing buzz.

5

Make sure buzz is on all channels, if not, transmitter may cause buzz.

6

Adjust L.O. to see if buzz fades out.

7

Measure a. g. c. voltage at video I.F. grids.

### DIGEST (A)

MANY TIMES IN A TV SET A BUZZ WILL BE HEARD IN THE SOUND. THERE ARE MANY CAUSES OF THIS CON-DITION RANGING FROM ALIGNMENT TO TROU-BLES AT THE STA-TION: CERTAIN STEPS MUST BE TAKEN TO LOCALIZE THIS TROU-BLE TO ONE PARTI-CULAR STAGE OR CIR-CUIT. IN THIS CASE THE FRONT PANEL CONTROLS ARE A GREAT HELP, FOR EX-AMPLE IF THE VER-TICAL HOLD CONTROL IS VARIED AND THE BUZZ INCREASES OR DECREASES IN PITCH, THEN THE TROUBLE IS RADIATION FROM THE VERTICAL CIR-CUIT.



BUZZ

SYMPTOM

DIGEST (B)

BUZZ IN THE SOUND HAS TWO COMMON CAUSES, ONE IS THE VIDEC IF TUBES BEING DRIVEN TO CUTOFF BY THE SIGNAL WHICH WOULD INDICATE A.G.C. TROUBLE.THE OTHER BEING POOR ALIGNMENT WHICH WILL INTRODUCE A BUZZ IN THE SOUND SIGNAL. SOME CASES OF RADIATION FROM THE VERTICAL OUT-PUT XFMR FEEDING INTO THE AUDIC AMP-LIFIERS HAVE BEEN ENCOUNTERED BUT THIS IS NOT A COM-MON TROUBLE, SOME OF THE TV SETS HAVE A BUZZ CON-TROL ON THE BACK PANEL THESE SETS USE A 6BN6 AS A SOUND DETECTOR.

8

Should have 3-6 volts a.g.c.

9

If a.g.c. is low say zero or 1 volt refer to Chart \*19.

10

With normal a.g.c. replace electrolytic at ratio det.

11

If ratio det is not used or electrolytic is good, align sound.


12

If sound will not align replace Detector transformer.

13

If sound alignment does not help align Video IF.

14



FAX SCHEMATIC, SECTION 2

NTRL WHITTIER, CALIF.U.S A

CIRCUIT

Adjust fine tuning and local osc.

2

Microphonic tube in front end may cause this. Replace tuner tubes.

3

If sound traps are used adjust them slightly.

4

It sound bars change, then continue to adjust traps.

5

If no change noticed traps are okay.

6


Bridge all filter capacitors in the audio strip.

7

Filter below audio output transformer most likely open.

### DIGEST (A)

SOUND IN THE PIC-TURE CAN BE RECO-GNIZED BY THE BARS THAT APPEAR IN THE PIX AS THE SOUND IS BEING HEARD IN THE SPEAKER. IN A NUM-BER OF CASES THE SOUND BARS WILL AP-PEARAS THE VOLUME CONTROL IS INCREAS-ED. OTHER CASES WILL SHOW SOUND BARS WITH JUST A VERY LOW SETTING THE OF VOL UME. BO TH CASES HOW-EVER INDICATE THAT THE SOUND IS BEING PICKED UP IN THE VIDEO AMPS AND BEING PASSED TO THE C.R.T. THE TROUBLE ITSELF SHOULD NOT BE CONFUSED WITH 4.5 MC INTERFERENCE WHICH SHOWS UP AS A FINE GRAIN PATTERN ON THE SCREEN.



SOUND BARS IN THE PIX

SYMPTOM

### DIGEST (B)

SOUND BARS IN THE PIX ARE CAUSED BY THE SOUND BEING PICKED UP IN THE VIDEO STRIP. MOST LIKELY CAUSE OF THIS IS AN OPEN FIL-TER CAPACITOR IN THE B+ LINE THAT FEEDS THE AUDIO POOR STRIP. THE FILTERING THAT RESULTS WILL CAUSE THE SOUND TO FEED THROUGH INTO THE PIX. ANOTHER CAUSE OF THIS TROUBLE IS POOR ALIGNMENT IN THE SOUND CIRCUIT OR IN THE SOUND TRAPS THAT ARE LO-CATED IN THE VIDEO STRIP. MISALIGNMENT OF THE LOCAL OS-CILLATOR WILL ALSO GIVE SOUND BARS IN THE PIX.

8

Bridge all filters if not sure which are in audio strip.

50

SECTION

SCHEMATIC,


9

If filters check okay align sound circuit.

10

11

TROUBLE



Motorola

12

13

14

NTRL WHITTIER, CALIF. U.S. A

CIRCUIT

Replace R.F. I, F. and A.G.C. tubes.

2

Check voltage on I.F. grids. With this trouble it should be almost zero.

3

Switch set off and check Res. to ground from I.F. grid.

4

Res. should be high, around 1 meg. Check schematic if available.

5

If very low resistance check for shorted Capacitor in A.G.C.

6

If resistance is high on A.G.C. line check for open resistor.

7

If resistance to ground in A.G.C. is normal check A.G.C. tube circuit.

### DIGEST (A)

THIS TROUBLE IS COM-MON IN CIRCUITS WHERE SEPARATE A.G.C. TUBES ARE USED AS IN KEYED A.G.C. CIRCUITS. TROUBLE CAN BE RE-COGNIZED BY NEG-ATIVE PICTURE. THIS SHOWS EVERYTHING THAT SHOULD BE WHITE AS BLACK AND EVERYTHING BLACK SHOWS WHITE. THIS WILL ALWAYS BE AC-COMPANIED BY ROL-LINGAND TEARING AS IN LOSS OF SYNC. NOTE THAT BLANKING BARIS WHITE INSTEAD OF BLACK.



ROLLING-TEARING NEGATIVE PIX

SYMPTOM

DIGEST (B)

WITH COMPLETE LOSS OF A.G.C. VOLTAGE THE R.F. AMP. AND VIDEO I.F. TUBES ARE AMPLIFYING WITH MAXIMUM GAIN. THIS WILL CAUSE THEI.F. STAGES TO DETECT THE SIGNAL BEFORE THE DETECTOR AND THE RESULTIS A SIG-NAL OF OPPOSITE POLARITY AT THE DETECTOR OUTPUT. THIS WILL ALSO CAUSE NO SYNC. DUE TO WRONG POLARITY OF SYNC PULSE, THUS ROLLING, TEARING & A NEGATIVE PIX.

8

In keyed A.G.C. Check bias on A.G.C. tube.

9

Also check for keying pulse on plate of tube.

10

If keying pulse missing check back to flyback for open lead.

11

Keying pulse should be 500v peak to peak.

12

With above checks normal, trouble is in I.F. circuit.

13

Suspect leaky capacitor to I.F. grids.

14

CIRCUIT

DIAGRAM

CTION SCHEMATIC, LE-FA

NTRL WHITTIER, CALIF.U.S A

If any AGC controls are used adjust them first.

2

Replace any AGC R.F. or I.F. tubes.

3

Check negative voltage across AGC load resistor.

4

Now check negative voltage on I.F. grids fed by the AGC.

5


AGC voltage should be the same at the I.F. grids as across the AGC load.

6

If the voltage is different check for leaky cap in AGC line.

Coupling capacitor may be leaky to an I.F. grid.

THIS CONDITION IN-DICATES PARTIAL LOSSOFAGC VOLTAGE. THE LOSS OF SYNC WILL OCCUR ONLY ON STRONG CHANNELS SUCH AS TWO OR FOUR. THE SETTING OF ANY AGC ADJUSTMENT SHOULD BE CHECKED FIRST IN CASE IT HAS BEEN MISADIUSTED. IF A CONTROL IS USED IT SHOULD BESET WHILE WATCHING A STRONG CHANNEL FOR THE BEST PIX.



POOR SYNC ON STRONG CHANNEL

SYMPTOM

TROUBLE

DIGEST (B)

WITH PARTIAL LOSS OF AGC THE INCOMING SIGNAL ON A STRONG CHANNEL WILL OVER-DRIVE THE VIDEO I.F. AMPLIFIERS AND CAUSE THE SYNC PULSES TO BE CLIP-PED OFF IN THE I.F. STAGES. THIS IN TURN WILL CAUSE POOR SYNC ON THESE CHANNELS AND PIC-TURE PULL MAY ALSO BENOTICED. IN AREAS WHERE THE SIGNAL STRENGTH IS WEAK COMPLETE LOSS OF AGC WILL ALSO CAUSE THE SAME CONDITION.

AGC voltage should be about -4 to -6 volts.



O

SECTION

SCHEMATIC,

ELE-FAX

9

If AGC voltage low check AGC load resistor for a change.

10

In keyed AGC signal at plate of AGC tube should be 500v p to p.

11

Check correct bias on keyed AGC tube.

12

With all above checks normal refer to chart #18.

13

14

PART OF PATTERN APPROX. 1MMF 2ND VIDEO V-GA GASB

NTRL WHITTIER, CALIF.U.S A

**CIRCUIT** 

DIAGRAM OFFERE

Replace all sync tubes.

2

With scope check signal at input to first sync tube.

3

It no signal precheck for sent, line from open sync take off point.

If signal at input, move to plate of first sync tube.

5


If no signal at plate check plate, screen and cathode voltages.

6

Do not troubleshoot if a poor signal is at plate.

If no signal at plate then trouble must be in that circuit.

WITH LOSS OF SYNC. AS THIS TROUBLE IN-DICATES PICTURE WILL BE ROLLING SIDEWAYS AND DOWN-WARD AT THE SAME TIME. IN ORDER TO MAKE SURE THAT THIS IS OCCURING, ADJUST BOTH THE VERTICAL AND HORIZONTAL HOLD CONTROLS AT THE SAME TIME. TO SEE IF THE PICTURE WILL HOLD MOMEN-TARILY, IF IT DOES, THEN WE HAVE LOSS OF SYNC. MAKE SURE THAT THE PICTURE IS NOT NEGATIVE AT THE SAME TIME SINCE THAT WOULD INDI-CATE A.G.C. TROU-BLE.



COMPLETE LOSS OF SYNC

SYMPTOM

SYNC TUBES SHOULD BE CHANGED FIRST SINCE THEY ARE THE MOSTLIKELY CAUSE OF THIS CON-DITION. IF THEY DO CLEAR THE TROUBLE THE SCOPE SHOULD BE USED SINCE IT CAN SHOW YOU WHERE THE LOSS OF SIGNAL IS OCCURING. THE TROU-BLE CAN BE ANY-WHERE FROM THE SYNC TAKE OFF POINT TO THE OUT-PUT OF THE SYNC CIRCUITS.

Check for signal at grid of second sync tube.

9

If no signal, check coupling cap for open or grid circuit for short.

10

If signal at grid check for signal at plate.

SECTION

SCHEMATIC,

TELE-FAX

11

If none present at plate check voltage and resistance of this circuit.


12

Trouble is caused by complete loss of sync.

13

Signal must be lost in sync circuit use scope to check this.

14



NTRL WHITTIER, CALIF. U.S. A.

DIAGRAM •

CIRCUIT

Replace all sync

2

tubes.

If tubes OK check input to the first sync tube.

3

This signal must be good. If signal is poor check ago or video amp.

4

If good signal go to output of first sync tube.

5

If sync pulses are suppressed at this point check voltage at tube.

6

If first tube is sync sep. bias should be - 20 volts with signal applied.

7

If grid voltage on sync sep. is low or zero, check coupling cap for leak.

THIS CONDITION OC-CURS WHEN THE SCENE CHANGES OR WHEN A COMMERCIAL IS SHOWN AND THE CAMERA SWITCHES BACK TO THE PROGRAM, ITMAY ALSO BE NOTICED THAT IF VERY LITTLE VIDEO IS ON THE SCREEN, OR THERE IS LITTLE MOVEMENT IN THE SCENE, THE PIX MAY APPEAR VERY GOOD, WITH NO PUL-LING AT ALL. IF GREAT ACTIVITY IS TAKING PLACE THEN PIX PULL WILL BE

NOTICED.



PICTURE PULL

SYMPTOM

DIGEST (B)

TROUBLE THIS CAUSED BY VIDEO IN-FORMATION IN THE TRYING SYNC TRIGGER THE HORI-ZONTAL OSCILLATOR. THIS WILL NOT AF-FECT THE VERTICAL OSCILLA TOR SINCE THE INTEGRATING NETWORK WILL BY-PASS ALL VIDEO IN-FORMATION. USUALLY LEAKY COUPLING CAPACITORS IN THE SYNC CIRCUIT WILL THE CAUSE. IN SOME CASES MISAD-JUSTMENT OF THE A.G.C. CIRCUIT WILL GIVE THE SAME

If signal at plate is normal check at grid of second sync tube.

9

Watch for loss of amplitude of sync pulse only.

10

Output of sync separator should be sync pulses only.

11

SECTION

SCHEMATIC,

×

ELE-FA

With pix pull video will be present at the sync separator output.

12


Check coupling capacitor and grid resistor of sync sep.

13

Also check for high plate voltage on sync tubes.

14

TROUBLE



NTRL WHITTIER, CALIF. U.S. A

THE

WITH THIS TROUBLE

THE PICTURE WILL

HOLD MOMENTARILY

HOLD CONTROL IS AD-

JUSTED BUT WILL NOT

LOCK INTO SYNC. AS

PICTURE

MADE TO ROLL DOWN-

WARDS IT SHOULD

SNAP DOWN AS THE

BLANKING BAR NEARS

THE BOTTOM, THIS

WOULD INDICATE

NORMAL OPERATION OF THE VERTICAL

SYNC. WITH LOSS OF

VERTICAL SYNC THE

PICTURE WILL ROLL

SLOWLY DOWN ALL

THE WAY TO THE

BOTTOM.

THE VERTICAL

In some cases a tube is used to amplify only the vertical sync.

2

If the above tube is used replace it.

3

Turn down brightness control and remove vertical OSC tube.

4

Place scope at oscillator grid to check for loss of signal.

5

If a signal is at OSC grid, it is probably very small.

6

Check for a shorted integrator capacitor.

7

If a printed integrator circuit is used replace it.



LOSS OF VERTICAL SYNC

SYMPTOM

DIGEST (B)

THE TROUBLE IN THIS SYMPTOM IS LIMITED TO A VERY SMALL SECTION OF THE TV RECEIVER. SOME -WHERE BETWEEN THE OUTPUT OF THE SYNC CIRCUITS, AND THE INPUT TO THE VER-TICAL OSCILLATOR. POOR SYNC MAY GIVE ALMOST THE SAME CONDITION AS LOSS OF VERTICAL SYNC EXCEPT THAT THE HORIZONTAL WILL BE VERY TOUCHY AND HARD TO LOCK IN.

8

Check for an open resistor leading from sync output to vertical OSC.

9

If horizontal is holding good trouble must be in above checks.

10

If horizontal is poor too, then check Chart on poor sync.

11

12

13

14

TUNER AGC O

-22

-13 bits

-22

-13 bits

-23

-33 v

-34 v

-34

CIRCUIT

DIAGRAM •

SCHEMATIC, SECTION

*TELE-FAX* 

NTRL WHITTIER, CALIF. U.S. A.

try and sync pix.

If one pix will momentarily appear continue, if not check Chart No. 32.

3

Replace AFC tube oscillator and tube.

After replacing above tubes readjust controls.


5

Check for sync pulses to the a.f.c. tube with scope.

6

If no sync pulses at a.f.c. check back to sync circuit.

If sync pulses normal, check for references waveshape to a.f.c.



AND THE AFC IS NOT

ITS

CONTROLLING

FREQUENCY



NO HORIZON TAL SYNC

SYMPTOM

### DIGEST (B)

THERE ARE THREE BASIC AFC CIRCUITS, SYNCROLOCK, MULTIVIBRATOR, AND SYNCROGUIDE. THESE AFC SYSTEMS STOP WORKING, THEN THE HORIZONTAL OSCIL LA TOR WILL OPERATE ABOVE OR BELOW 15750. THIS WILL CAUSE THE PIC-TURE TO BE OUT OF HORIZONTAL SYNC SINCE IT WILL HAVE NO CONTROLLING ACTION.ADJUSTMENTS SHOULD CAUSE THE PICTURE TO HOLD BRIEFLY, IF NOT, THEN REFER CHART NO. 32.

If no reference waveshape, check back for loss of pulse.

9

If wave shapes normal, check resistance from a.f.c. to OSC.

10

multivibrator system, check re-sistors of equal value in a.f.c.

SECTION

SCHEMATIC,

ELE-FAX

11

In syncroguide check cathode resistors of a.f.c. tube.


12

Trouble must be in a.f.c. or in feed from a.f.c. to osc.

13

14

TROUBLE



NTRL WHITTIER, CALIF.U.S.A.

CIRCUIT

SECTION

SCHEMATIC,

×

TELE-FA

Try all horizontal OSC adjustments as listed in digest

Switch set off and on to check for improvements as adjustments are made.

3

Replace horizontal oscillator and any a.f.c. tubes.

Check for good sync pulses to the a.f.c. circuit.


Check comparison waveshape also feeding a.f.c. cir-cuit from hor.

6

If sync pulses or comparison waveshape are poor check why.

comparison wave poor, may have bad cap feeding a.f.c. circuit.

POOR AFC ACTION NOTICED CAN BE WHEN THE SET IS FIRST SWITCHED ON. OR AS THE SET IS SWITCHED FROM ONE CHANNEL TO AN-OTHER. IN BOTH CASES THE PICTURE WILL GO OUT OF HORIZONTAL SYNC. AND THE HORIZONTAL HOLD MUST BE AD-**JUSTED TO BRING THE** PICTURE BACK INTO SYNC. THE HORI-ZONTAL CONTROLS SHOULD ALL BE AD-JUSTED FIRST IN OR-DER TO SEE IF THE CONDITION CAN BE CURED. MANY TIMES A SLIGHT ADJUSTMENT IS ALL THAT IS NEC-ESSARY.



POOR A.F.C.

SYMPTOM

SOME OF THE CON-TROLS THAT MAY BE OUT OF ADJUSTMENT ARE THE FOLLOWING. HORIZONTAL HOLD. HORIZONTAL FRE-QUENCY. A.F.C. HORI-ZONTAL LOCK, HORI -ZONTAL PHASE. AF-TER THESE ADJUST-MENTS HAVE BEEN MADE THE TUBES SHOULD BE REPLAC-ED. IF THIS DOES NOT HELP, THEN THE SCOPE CAN BE USED TO CHECK FOR CO-RRECT WAVESHAPES IN THE AFC CIRCUIT. THE WAVESHAPES FOUND IN THE VAR-IOUS AFC CIRCUITS SHOULD BE KNOWN.

If sync pulses are poor, check sync circuit.

9

With normal wave shapes check resistors in a.f.c. circuit.

10

Replace all capacitors around a.f.c. circuit.

11


Be sure to check a.f.c. filter network at grid of hor. osc.

12

In Syncroguide circuit, hor. lockingrange cap may be bad.

13

14



CIRCUIT

DIAGRAM .

Emerson

NTRL WHITTIER, CALIF U.S.A.

Do not replace any tubes since they do not cause this trouble.

2

Check signal at video det. and notice size of vertical sync. pulse.

3

Move scope to grid of 1st video amp. look for decrease or vertical sync.

4

If vertical sync. is smaller, check coupling capacitor 4.5 mc coil.

5

If normal at grid of 1st video amp. move to grid of 2nd video amp.

6

Note if sync. is reduced. If so check for bad coupling cap or 4.5 mc coil.

7

If sync is normal at grid of 2nd video amp. check signal at plate. THIS TROUBLE IS A VERY MISLEADINGONE BECAUSE THE TROU-BLE APPEARS TO BE THE VERTICAL CIRCUIT. HOWEVER, WE FIND THIS TROU-BLE TO BE IN VIDEO AMP. OR IN THE SYNC CIRCUIT. IN MOST CASES A DECREASE IN COUPLING CAPA-CITOR IS THE TROU-BLE, OR SOMETIMES AN OPEN 4.5 MC TRAP COIL. THE SCOPE IS A MUST IN QUICKLY FINDING THIS CON-DITION SINCE WE CAN SEE EXACTLY WHERE THE TROUBLE IS OC-CURING.



VERTICAL PHASING

SYMPTOM

DIGEST (B)

VERTICAL PHASING OCCURS WHEN THE VERTICAL SYNC PULSE IS OUT OF PHASE WITH THE ORI-GINAL VERTICAL SYNC PULSE SENT FROM TRANSMITTER. THIS WILL HAPPEN IF THE 60 CPS SYNC IS PASSED THROUGH A SMALL CAP. BEFORE THE SYNC TAKE OFF POINT OR WHILE PASS-ING TO THE SYNC OUT-PUT CIRCUIT, THIS TROUBLE WILL NOT BE CAUSED BEFORE THE VIDEO DETECTOR. PICTURE IS LOCKED IN AT THIS POINT ON SCREEN AND USUALLY RETRACE LINES ARE NOTICED.

8

In some rare cases a decrease in cathode cap, will cause this condition.

9

If signal good at grid but vertical is low at plate check cathode cap.

10

If signal is normal at the sync take off then follow thru sync circuit.

SECTION

SCHEMATIC,

11

Look for a decrease in vertical sync pulse only.

12


If trouble is in synccircuitit will be caused by a bad coupling cap.

13

14

\_\_\_\_\_

TROUBLE



NTRL WHITTIER, CALIF U.S.A.

CIRCUIT

Replace low voltage rect and damper tubes.

2

If the low voltage rectis a selenium Refer to Chart #45

3

Measure the output of the low voltage rectifier.

If low, check for open input filter capacitor before replacing it.

5

Check for a large increase in the resistance of the filter choke.


6

Check for correct AC voltage at plates of recufier.

7

If low then power transformeris bad.

THIS IS A COMMON TROUBLE IN TV SETS TODAY THAT ARE WORKING UNDER TOO MUCH STRESS, OR CLOSE TOLERANCES. THE TROUBLE HERE IS IN MOST CASES THE POWER SUPPLY, AND THE LOW VOLTAGE RECTIFIER TUBE IT-SELF IS THE MOST LIKELY CULPRIT. SOME CONDITIONS HAVE BEEN FOUND WHERE THE DAMPER CIRCUITOF THE YOKE HAVE BEEN FOUND DEFECTIVE. BUT THESE ARE RARE WITH A POSTAGE STAMP RASTER.



POSTAGE STAMP RASTER

SYMPTOM

DIGEST (B)

IF THE LOW VOLTAGE CIRCUIT HAS A LOW OUTPUT THEN THE HEIGHT AND WIDTH WILL BE AFFECTED THE MOST SINCE TH ESE RUN WITH CLOSE TOLERANCE ON THE VOLTAGE AP-PLIED. IT MAY BE **FOUND** THAT THE HEIGHT CAN BE AD-IUSTED TO COVER THE SCREEN BUT THE WIDTHWILLNEVER BE ABLE TO DO IT WITH LOW B+. IN A NUMBER OF SETS THE HORIZON-TAL AND VERTICAL OUTPUT TUBES ARE OPERATED BY THE VOLTAGE THAT IS SUPPLIED FROM THE DAMPER TUBE. IN THESE SETS THE DAM-PER CIRCUIT WILL AL-SOCAUSE THE TROUBLE.

If the correct voltage is at the low voltage output, check below.

9


Find out if damper feeds the vertical outout and horizontal.

If it does then check damper cathode circuit for a leaky capacitor.

Also replace all-Horizontal sweep

Replace yoke or flyback as a final possibility.

14



CIRCUIT

**DIAGRAM** 

Motorola

NTRL WHITTIER, CALIF.U.S A

SECTION

SCHEMATIC,

-FAX

10

11

tubes.

12

13

Make sure there is a 120 cps pulland not a 60 cps pull.

2

Count the number of variations from top to bottom of

3

Photograph shows a 120 cycle pull.

If a 60 cps pull is noticed refer to Chart #45.

5

If the pull changes as the scene changes then refer to Chart #22.

6

Bridge all electrolvtic capacitors with known good ones.

7

This should be done one at a time.

WITH A 120 CYCLE PULLIN THE PICTURE THE TROUBLE MUST BE IN THE POWER SUPPLY SINCE THIS IS THE ONLY PLACE IN A A TV SET THAT HAS 120 CYCLES IN IT. IT SHOULD BE SIMFLE TO TELL IF THERE IS THIS CONDITION OC-CURING BECAUSE A CLOSE CHECK ON THE SIDE OF THE PICTURE WILL SHOW IF THERE ARE TWO VARIATIONS IN THE PULL FROM THE TOP OF THE PIC-TURE TO THE BOT-TOM. IF ONLY ONE VARIATION IS NOTI-CED THEN THE TROU-BLE MUST BE CAUSED BY A 60 CYCLE HEAT-ER TO CATHODE SHORT.



120 C. P. S. PULL

SYMPTOM

DIGEST (B)

IN A FULL WAVE REC-TIFIER CIRCUIT THE INPUT FREQUENCY IS DOUBLED BY THE RE-CTIFYING ACTION IN THE POWER SUPPLY. WITH A 60 CYCLE IN-PUT TO THE POWER SUPPLY OF A TV SET WE WILL END UP WITH 120 CYCLE OUTPUT. IF POOR FILTERING IS TAKING PLACE, THEN A PULL WILL BE NO-TICED IN THE PIC-TURE. THIS TROUBLE THEREFORE MUST BE CAUSED BY AN OPEN FILTER IN THE B+ CIRCUIT.

8

When open filter is bridged pull will clear.

9

Be sure to use same values as ones in set.

10

It was found that in some cases wrong values were used.

11

SECTION

SCHEMATIC,

**TELE-FAX** 


Check manufacturers schematic tor correct values.

12

Be sure B + is wired correctly.

13

TROUBLE



NTRL WHITTIER, CALIF. U.S. A.

CIRCUIT

DIAGRAM •

Motorola

14

If smoking, arcing, oroverheating switch set off.

Measure the amount of resistance from rectifier cathode to B-

3

Should be more than 20,000 ohms, with short will be less.

With ohm meter at cathode remove rectifier tube.

5

If low reading now increases rectifier tube is bad.

6

If no effect is noticed move meter to far side of filter choke.

Resistance will probably go down. If it increases check input filter.

ONE OF THE MOST COMMON TR CUBLES IN THE B + CIRCUIT IS A SHORT. THIS OCCURS SO MANY TIMES BE-CAUSE OF THE MANY SECTIONS THAT THE MUST FEED. IN CASES THE MANY SHORT WILL CAUSE A FIRE TO BREAK OUT UNDER THE CHASSIS AND THE REPAIR BILL IS QUITE HIGH. WHEN A SHORT IS IN THE B + LINE THE LOW VOL-TAGE RECTIFIER WILL ARC INTERNALLY OR SOME RESISTORS IN THE CIRCUIT WILL **OVERHEATAND START** TO SMOKE, AS SOON AS THESE **CONDITIONS** ARE NOTICED THE SET SHOULD BE SWITCHED OFF UNTIL THE TROU-BLE IS FOUND.



SHORT IN B +

SYMPTOM

DIGEST (B)

THE MOST IMPORTANT THING TO KEEP IN MIND WITH A SHORT IN THE B + LINE IS THE NORMAL RESISTANCE THAT IS MEASURED FROM THE CATHODE THE RECTIFIER TUBE TO COMMON NEGATIVE. IN MOST CASES THIS IS A 20,000 OHMS OR MORE. IF THE SHORT IS PRE-SENTTHENA READING OF FROM ZERO TO A THOUSAND OHMS MAY BE FOUND. WITH SUCH A LCW RESIS-TANCE IN THE CIR-CUITA LARGE AMOUNT OF CURRENT WILL BE FLOWING RESULTING IN OVERHEATING OF RESISTORS OR AN ARC IN THE RECTIFIER TUBE. THE POWER XFMR ITSELF MAY START TO SMOKE.

Follow all leads from the filter choke with ohmmeter.

Look for decrease in resistance until lowest reading.


Lowest reading may be zero, or just a few ohms.

Remove all parts connected to this point and check for short.

Short in focus control, yoke, or filter capacitor are common.

Follow path of least resistance part.

14



SECTION SCHEMATIC,

NTRL WHITTIER, CALIF.U.S A

9

10

11

12

13

locate bad

Voltage output from a set with

2

seleniums is

about 265v.

If the output voltage is normal trouble is elsewhere.

3

Make sure that the pix does not have a 60 cycle pull.

4

Seleniums are half wave rectifiers thus 60 cycle pull.

5

If pull is noticed with lack of width, check filter cap for open.

6

With low output voltage, and no pix pull, replace seleniums.

7

There is no good check for seleniiums except replacement.

A LARGE NUMBER OF TV SETS TODAY ARE USING SELENIUM RE-CTIFIERS AS A MEANS OF OBTAINING THE LOW VOLTAGE. THIS IS A CHEAPER METHOD THAN THE USUAL 5U4G TUBE, AND WITH NORMAL CARE THE SELENIUM RECTIFIER SHOULD LAST THE LIFETIME OF THE SET. IN MOST CASES HOW-EVER THE SELENIUM IS MISUSED IN THAT IT IS OFTEN PLACED UNDER THE CHASSIS WHERE THE MOST HEAT IS PRESENT, AND THE MILIAMP RATING IS AT A MINI-MUM. MOST COMMON TROUBLE IS LOW OUTPUT VOLTAGE CAUSING NOT EN-

OUGH WIDTH.



SELENIUM RECTIFIERS

SYMPTOM

DIGEST (B)

SELENIUM RECTIFIERS ARE MADE BY COATING A PLATE OF IRON WITH A LAYER OF SELENIUM AND PLACING A NUMBER OF THESE PLATES IN SERIES. IF THE CURRENT PASSING THROUGH THE PLATES SMALL ENOUGH FOR THE PLATES TO REMAIN COOL THEN THE RECTIFIER SHOULD LAST FOR MANY YEARS. IT IS A L-WAYS ADVISABLE TO REPLACEA SELENIUM RECTIFIER WITH A CURRENT LARGER RATING THAN WAS USED IN THE SET, IF THE SPACE IS AVAIL-ABLE, THAT IS, FOR EXAMPLE, A 250 MA CAN BE REPLACED WITH A 300 MA.

Side of selenium marked + is the cathode.

9

Replace both seleniums to be safe.

10


Try to replace with larger milliamp rating.

11

If there is no B + and seleniums are normal.

Replace electrolytic cap. series with AC line.

14



Motorola

CIRCUIT

NTRL WHITTIER, CALIF. U.S.A.

DIAGRAM •

SECTION

SCHEMATIC,

ELE-FA

12

13

SECTION

SCHEMATIC,

**TELE-FAX** 

Check value of resistor in focus circuit.

2

Focus pot may be open, check carefully.

3

Disconnect focus coil and check its resistance.


Check resistor in parallel with focus pot.

5

Check B + for 20% tolerance.

Check for schematic changes made by manufacturer.

MANY OF THE LATER MODEL RECEIVERS HAVE NO FOCUS AD-HUSTMENTS AT ALL AND DEPEND UPON VOLTAGE APPLIED TO THE FOCUS ANODE OF THE CRT FOR COR-FOCUSING. RECT THESE ARE ELEC-TROSTATIC FOCUS CRT ANDMAY CAUSE POOR FOCUS DUE TO IN-TERNAL ARCING IN CRT. IN OTHER CASES WE FIND FOCUS AD-JUSTMENTS ON THE NECK OF THE CRT AND IN STILL OTHER CASES WE HAVE A FOCUS CONTROL ON THE BACK OF THE CHASSIS.



POOR FOCUS

SYMPTOM

WITH POOR FOCUS NO-TICED ALL ADJUST-MENTS SHOULD BE FIRST. THE TRIED FOCUS COIL ON THE NECK OF THE CRT BE MOVED TO CAN AND FRO TO SEE IF BETTER FOCUS CAN OBTAINED. IF THESE ADJUSTMENTS DO NOT HELP THEN RESISTANCE CHECKS SHOULD BE MADE IN THE FOCUS CIRCUIT. SOME RECEIVERS THE FOCUS HAVE CONTROL IN THE AUDIO OUTPUT CIR-CUIT AND TROUBLES IN THE AUDIO WILL CAUSE POOR FOCUS RESISTORS IN THE **FOCUS CIRCUITOFTEN** CHANGE VALUE.

If focus pot in audio circuit check audio tube. 9

Measure bias on audio output tube.

10

Coupling capacitor to audio output grid may be leaky.

11

Cathode resistor of audio output may have changed value.

12


If all checks are normal, replace focus coil.

13

In CRT with electrostatic focus check voltage on focus pin.

14

CRT with electrostatic focus may be bad.



6

If B + is low refer to chart #42.

NTRL WHITTIER, CALIF.U.S A

DIGEST (B)

IF THERE IS AN OPEN

IN THE AC INPUT CIR-

CUIT TO THE TV SET

THERE WILL BE NO

RASTER OR SOUND.

ALSO IF THE B + LINE

IS OPEN IN ONE WAY

OR OTHER THEN THE

SAME CONDITION WILL.

RESULT. THE REC-

TIFIER TUBE ITSELF

IS THE MOST COMMON

DEFECT UNDER THESE

CONDITIONS. WITH

THE NEW SERIES FILA-

MENT SETS ON THE

MARKET IF ONE OF

THEM OPENS THEN WE

WILL HAVE ALL THE

TUBES OUT BECAUSE

THE FILAMENT CIR-

CUIT WILL NOW BE

OPEN.

Emerson

COURSE

OF

THEN

Chart No. 44.

May be short in

SECTION

SCHEMATIC,

AX

TELE

B + line. Check

Measure B +, if normalor high, suspect open in B +.

Follow B +, along line until no B +.

11

Open filter choke or speaker field.

If no B +and tube is good, check transformer.

14

9

10

12

13

With set on check to see if tubes are lit.

2

If tubes are not lit then trouble is in the AC input.

3

Plug may be broken, line may have open (fuse).

Switch contacts may be bad so jump switch.

5

Transformer may be bad, check resistance of windings.


6

In series filament setcheck all tube filaments.

7

If all tubes light. check fuse, replace rectifier.


WHEN A TV SET HAS NO RASTER PIX OR SOUND THEN TROU-BLE IS IN THE AC IN-PUT CIRCUIT OR THE CIRCUIT. MOST COMMON IS THE B + LINE SINCE IT FEEDS ALL OF THE CIRCUIT AND SO MUCH STRESS IS PLACED ON IT. IF THE TROUBLE IS IN THE AC LINE THEN A BAD PLUG OR BREAK IN THE LINE CORD IS USUALLY THE FAULT. SOME TIMES WE FIND THAT ON-OFF SWITCH MAY BE DEFECTIVE. A OUICKWAY TO TELL IF THE TROUBLE IS IN THE AC LINE IS TO SEE IF THE TUBES LIGHT, IF THEY DO THEN THE TROUBLE ISNOT IN THE AC CIR-CUIT.



NO PIX, RASTER, SOUND

SYMPTOM

T-9



See if HV is present by arcing anode cap to chassis.

If HV is present measure it. If enough refer to Chart No. 15.

3

If no arc check for arc at cap. of HV rectifier.

If arc at this point refer to Chart #38. With no arc replace horizontal tubes.

5

Place scope to grid of Hor. output tube.

6

With NO signal at this point place scope at output of Hor. osc.

7

If no output at osc check voltage, resistance or possible open capacitor.

# DIGEST (A)

THE LOSS OF SWEEP IN THE HORIZONTAL CIR-CUIT WILL CAUSE THE LOSS OF HIGH VOL-TAGE IN MOST CASES. THIS OCCURS BECAUSE THE HORIZONTAL SWEEP CIRCUIT CRE-ATES THE HIGH VOL-TAGE BY MEANS OF FLYBACK ACTION IN THE HORIZONTAL OUTPUT TRANSFORM-ER. THIS NOW MEANS THAT THE TROUBLE CAUSING NO SWEEP WILL ALSO CAUSE NO RASTER TO BE SEEN. LOSS OF RASTER MAY BE TROUBLE IN THE HIGH VOLTAGE CIR-CUIT ITSELF OR THE HORIZONTAL SWEEF, OR EVEN THE C.R.T. FIRST CHECK WILL IN-DICATE WHICH SEC-TION IS AT FAULT.



NO RASTER

SYMPTOM

# DIGEST (B)

IN ORDER TO DETER-MINE IF THE C.R.T. IS THE CAUSE OF NO RASTER A QUICK THE CAUSE OF NO RASTER A QUICK CHECK CAN BE MADE FOR HIGH VOLTAGE, IF NONE IS PRESENT THEN THE CHANCES ARE THAT THE C.R.T. IS O.K. FURTHER CHECKS MUST NOW BE TO DETERMINE MADE TO DETERMINE IF THE HIGH VOLTAGE IS AT FAULT OR THE HORIZONTAL SWEEP, ONE OF THE SIMPLE WAYS IS TO SEE IF AN ARC CAN BE OBTAIN-ED AT THE CAP OF THE HV RECTIFIER. IF NONE AT THAT POINT IT IS MOST LIKELY THAT THE TROUBLE LIES IN THE HORI-ZONTAL SWEEP CIR-CUIT. USE OF THE SCOPE WILL NOW DE-TERMINE THE DE-FECTIVE STAGE.

With signal at grid of output tube should be 70-120 pp.

If very low check all components in hor. osc.

10

If normal check hor, output circuit voltage and resistance.


Remove all capa-citors from flyback, try for HV

Remove leads from flyback to vertical or a.f.c.

If HV with leads removed check disconnected leads for short.

14

Remove yoke, if HV now, replace yoke. If, no HV replace flyback.



NIRI WHITTIER CALLE II S A

9

SECTION

SCHEMATIC,

**TELE-FA** 

11

12

Try for HV.

13

Switch on set and with brightness control at max adjust ion trap.

2

lt ion trap does not bring in raster remove anode cap and arc to chassis.

3

If no arc is noticed then trouble - shoot H.V. circuit in Chart #39.

If arc is present and indicates enough H.V.recheck ion trap.

5

Measure bass pin voltages on C.R.T.

6

Grid O volts cathode 0-100V and screen about 300V.

7

trap.

# DIGEST (A)

THERE ARE MANY CAU-SES OF NO RASTER RAN-GING FROM HORIZON TAL OSCILLATOR TROU-BLE TO A BAD C.R.T. THE CAUSE MUST BE FOUND AS SOON AS POSSIBLE. IN THIS SHEET WE WILL DE-TERMINE IF THE TROUBLE ISINTHE H. VOLTAGE CIRCUITS OR IF THE C.R.T. IS DEFECTIVE AND AS-SUME THAT THE TROUBLE IS THE C.R.T. FOR TROUBLES IN THE HIGH VOLTAGE REFER TO CHART #39.



NO RASTER

SYMPTOM

# DIGEST (B)

IN CASE OF A BAD C.R.T. CAUSING NO RASTER THE TROUBLE MAY BE OPEN FILA-MENT OR LOSS OF EMISSION OF C.R.T. IT SHOULD ALSO BE RE-MEMBERED THAT AN INCORRECT SETTING ON THE ION TRAP WILL ALSO CAUSE THIS CONDITION AND INCORRECT VOLTAGES AT THE BASE OF THE C.R.T.

If ion trap does not help th en C.R.T. is bad.

SCHEMATIC,

9

Some C.R. T.boosters are available but in this case may not help.

10

11

12

13

14

R203 33K RED 5 (IN SOCKET) L202 \* 54V 7 L201 C20117.1 V17 23GP4 CRT BRITE 250K 125K FOCUS LEAD CONNECT TO ONE OF THREE TAPS GIVING BEST OVERALL FOCUS.

CIRCUIT

Motorola

DIAGRAM •

If these voltages are normal once again check ion

DIGEST (B)

8

Remove HV lead and arc to chassis, if arc present refer to Chart \*15.

2

If no arc at anode lead, check for arc with pencil at HV Rect. plate.

3

With an arc at this point replace HV rectifier.

4

If no HV now check HV filter capacitor and resistor at base of tube.

5

Also check for poor solder and dirt at HV rect base.

6

Resistor in series with anode lead may be bad.

7

Make sure anode lead is not broken. WITH NO HIGH VOLTAGE APPLIED TO THE CRT THERE WILL BE NO RASTER ON THE SCREEN BUT THE SOUND WILL BE NORMAL, UNDER THESE CONDITIONS THE TROUBLE MAY BE IN THE HOR IZ ONT ALSWEEP CIRCUIT, OR IN THE HIGH VOLTAGE CIRCUIT, IN ORDER TO DETERMINE WHICH OF THESE TWO STAGES ARE AT FAULT A FEW SIMPLE CHECKS CAN BE MADE, THESE CONSISTMAINLY OF CHECKING FOR AN ARC FROM THE HV LEAD TO CHASSIS, AND FROM THE CAP OF THE HV RECTIFIER, IF NO ARC IS NOTICED AT THE CAP OF THE HV RECTIFIER, THEN THE TROUBLE WILL BE IN THE HOR IZ ONT ALSWEEP CIRCUIT WHICH IS COVERED IN CHART NO. 36.



NO H.V. SOUND OK

SYMPTOM

LOSS OF HIGH VOLTAGE IS A COMMON TROUBLE THAT IS MOST OFTEN CAUSED BY TUBES. IF IT IS CAUSED BY A DEFECT IN THE HV CIRCUIT ONLY, THEN THE ONLY TUBE THAT CAN CAUSE THIS IS THE HV RECTIFIER. WITH NO ARC AT THE PLATE OF THE HV RECTIFIER THE TROUBLE IS IN THE HORIZONTAL SWEEP CIRCUIT SINCE THE HV IS DEPENDANT ON THE SWEEP SECTION WORK-ING. IF AN ARC IS FOUND AT THE PLATE OF THE HV RECTIFIER AND NO HV IS FRESENT AT THE CRT THEN THE TROUBLE IS LIMITED TO THE HV SECTION. COM-MON TROUBLES ARE, BAD RESISTOR IN REC-TIFIER CATHODE, HY FILTER CAPACITOR SHORTED AND OF COURSE THE HV RECTIFIER TUBE. If no arc at HV rect plate remove lead to cap and try for arc on lead.

30

SCHEMATIC

9

If still no arc at loose lead refer to Chart #36.

10

If arc is at loose lead then replace HV rectifier.

11

If still no HV then check filter capacitor and resistors at base.


12

Also check for dirt, poor solder or broken anode lead.

13

14

\_\_\_\_\_



MONTHS AT THE MOST.

IN ALL CASES IT IS

THEN THE

CAN

Turn up brightness control and adjust ion trap.

Measure HV with an HV probe.

3

If low HV refer to Chart #39.


With normal HV Measure CRT base voltages.

5

Grid voltage should be zero.

Cathode voltage should vary from 0 to 100v with brightness.

Screen voltage should be almost B +.



**WEAK RASTER** SYMPTOM

THE CAUSE OF A CRT BECOMING WEAK IS EMMISSION OF ELECTRONS IN THE CRT ITSELF.THIS IS CAUSED BY A COAT-ING THAT FORMS ON THE CATHODE OF THE CRT THAT CUTS DOWN ON THE ELECTRON FLOW IN THE TUBE, A BRIGHTNER GIVES A SLIGHTLY HIGHER HEATER VOL-TAGE TO THE TUBE WHICH OF COURSE WILL INCREASE THE ELECTRON FLOW IN THE TUBE, IF THE CAUSE OF A WEAK RASTER IS LOW HV & A BRIGHTNER OR BOO-STER AS IT IS CALLED IS USED THEN THE RASTER WILL GET BRIGHTER WITHOUT In some cases the gridmay vary with the brightness control.

9

In that case grid should vary from 0 to - 10 0v.

10

If base voltages are normal replace ion trap.

11


If new ion trap does not help replace CRT.

12

A booster may be used to see its effect on CRT.

13

14



NTRL WHITTIER, CALIF. U.S. A.

SECTION CHEMATIC,

ELE-FA

DIGEST (B)

IF A LOW AMOUNT OF

HV IS APPLIED TO

THE SECOND ANODE

OF THE CRT THE RA-

STER WILL BE WEAK

BECAUSE THE FORCE

OF THE ELECTRON

tage rect, and all

horizontal tubes.

If low HV, replace HV rect, low volt-

CHEMATIC,

ELE

9

Take voltage and resistance, check on horizontal output tube.

10

Output circuit may have increased screen resistor.

11

Check resistors at base of HV rectifier for increase.

12

Replace HV filter cap as the old one may be open,

13

Replace flyback as the old one may be weak.

14

Readiust the ion trap to make sure its set correctly.

2

Remove the HV anode lead and with a HV probe measure the HV.

3

The HV should be measured with the HV lead disconnected.

For a 10" CRT the HV should be from 7-9 kv.

5

For a 16" CRT the HV should be from 12-14 kv.

6

For a 21" CRT the HV should be from 14-16 kv.

7

If the HV for the CRT appears to be normal then refer to Chart #17.

LOW H.V. WILL USUAL-LY CAUSE A WEAK RASTER TO BE ON THE CRT. AND IN MANY CASES WILL BE CAUSING BLOOMING. CONDITION THIS MAKES THE RASTER SEEM TO SWELL OUT AS THE BRIGHTNESS CONTROL IS INCREAS-ED. THIS CONDITION MAY BECOME SO BAD THAT THE RASTER WILL COMPLETELY FADE OUT, SOME SIM-PLE CHECKS WILL SOON TELL IF THE HV IS AT FAULT, AND IF SO, TUBE SUBSTI-TUTION AND VOLTAGE CHECKS WILL IN MOST CASES LOCATE THE TROUBLE, A DEFECT-IVE CRT WILL GIVE THE SAME CONDITION AS LOW HV.

LOW H. V. SYMPTOM

BEAM STRIKING THE **PHOSPHOR** SCREEN WILL NOT BE STRONG ENOUGH TO ILLUMI-NATE THE SCREEN TO THE CORRECT BRIGHT-NESS THE CAUSE OF BLOOMING ALONG WITH A WEAK RASTER WILL OCCUR BECAUSE THE SMALL AMOUNT OF CURRENT FLOWING THROUGH THE HV CIR-CUIT WILL DROP THE HVEVEN MORE AND IN SEVERE CONDITIONS THE HV WILL DROP TO A POINT WHERE IT WILL NOT BE ENOUGH TO LIGHT THE CRIT AT

AGC PULSE TOOY HORIZ. 6DQ6A HORIZ. OUTPUT V404 4 160 V 1G3GT HORIZ. H.V. RECTIFIER V406 RED / WHT T402B HORIZ. RANGE C460 .047MF 100.4 KV ~~~ YEL \$15 K 3.50 3 GRAY 680V 680Y 470V 6AX4GTA/B C459 or 6DE4 TO 47 MF DIAGRAM .

NTRL WHITTIER, CALIF. U.S. A

CIRCUIT

If arcing is no-

ticed remove set

from cabinet.

2

Check for poor insulation on HV lead to CRT.

Clean HV lead and place as far from chassis as pos sible.

Remove HV cage and clean dirt from base of HV rectifier.

flyback Clean and check for pointed solder connections.

If pointed solder joints are found round them or resolder.

If arcing continues replace HV filter capacitor.

VERY OFTEN HV ARC-ING OCCURS IN TVRE-CEIVERS. THIS ARCING WILL OCCUR MORE OFTEN IN THE SUM-MER TIME DUE TO HUMIDITY IN MANY AREAS. THE ARCING MAY BE NOTICED AS THE SET IS FIRST SWITCHED ONOR DUR-ING THE TIME THE SET IS PLAYING. ARC-ING MAY REMAIN DUR-ING THE ENTIRE TIME THE SET IS ON AND WILL CAUSE A NUMB-ER OF FLASHES TO CONTINUALLY BE SEEN ON THE SCREEN, THIS IS VERY ANNOY-ING TO THE CUSTOM-ER AND THE SET SHOULD BE CHECKED CAREFULLY FOR THIS TROUBLE **BEFORE** SENDING BACK AS A FINISHED JOB.



H.V. ARCING

SYMPTOM

HV ARCING USUALLY OCCURS AT THE BASE OF THE HV RECT. DR IN THE FLYBACK IT-SELF AND IN ORDER TO SEE THE ARCING IT MAY BE NECES-SARY TO TAKE THE SET INTO A COMPLE-TELY DARK ROOM AND WATCH THE HV SEC-TION. THERE ARE MANY HV SPRAYS ON THE MARKET THAT MAY BE USED TO CLEAR UP THIS TROU-BLE BUT IN MOST CASES IT HAS BEEN FOUND THAT TO RE-PLACE THE DEFEC-TIVE PART IS BY FAR BEST SOLUTION.DUST, DIRT, AND POOR IN-SULATION ARE THE MOST COMMON CAUSES OF THIS TROUBLE.

DIGEST (B)

Arcing may be caused by a cracked resistor in HV rectifier base.

SECTIO

ATĬ

EM/

H

S

딟

If arcing is in flyback a HV insúlating spray may be tried.

10

If spray does not help a new flyback should be used.

11

In a number of cases an arc may beheard as set is switched on.

12


This may be the cause of a poor contact grounding the CRT.

13

This is done by a spring touching the CRT outer coating.

14

Make sure this spring is making good contact.



Readjust ion trap for max. brightness.

2

Replace HV Rectifier and low voltage rectifier.

3

Replace all horizontal sweep tubes.

4

Remove HV anode lead from CRT and measure HV.

5

For a 10" CRT the HV should be from 7-9 kv.


6

For a 16" CRT the HV should be from 12-14kv.

7

For a 21" CRT from 14-16kcv.

BLOOMING IS A COND-ITION THAT CAUSES THE RASTER TO EN-LARGE AND GETWEAK AT THE SAME TIME. WITH A VERY BAD CASE THE RASTER WILL COMPLETELY DISAPPEAR WITH MAX-IMUMSETTINGS OF THE BRIGHTNESS CON-TROL. THIS SHOULD BE TAKEN INTO CON-**SIDERATION** WHEN TRYING TO GET A RASTER BY DOING THE FOLLOWING, AD-JUST ION TRAP WITH THE BRIGHTNESS SET AT MAXIMUM, THEN IF NO RASTER IS NOTIC-ED DECREASE THE BRIGH TN ESS CONTROL SLIGHTLY AND RE-ADJUSTION TRAP.



BLOOMING

SYMPTOM

IF WE HAVE INSUF-FICIENT HV AND THE BRIGHTNESS CONTROL, IS ADVANCED, THE CURRENT PASSING THROUGH THE CRT IS INCREASED AND THE CURRENT IN THE HV CIRCUIT WILL IN-CREASE ALSO, SINCE THE BEAM CURRENT OF THE CRT MUST PASS THROUGH THE HV CIRCUIT IN ORDER TO RETURN TO THE CATHODE OF THE CRT. THIS WILL NOR-MALLY LOWER THE HV ABOUT IKV, IF THE HV IS LOW TO BEGIN WITH THEN A GREAT EFFECT WILL BE NOTICED ON THE WIDTH AND BRIGHT-NESS.

If the HV for the size crt is nomal then CRT is bad.

9

If HV is low refer to Chart #39.

10


11

12

13

**FELE-FA** 

14



CIRCUIT

the HV should be NTRL WHITTIER, CALIF.U.S A

Motorola

SECTION

SCHEMATIC,

TELE-FAX

# Replace the vertical Oscillator and output tubes.

With scope check for a signal at the grid of the ver-tical output tube.

## 3

If none present move to the other side of coupling capacitor.

If none at this point oscillator circuit is not working.

## 5

Check for plate voltage on OSC tube. If none check plate circuit.

### 6

Check grid resistor of OSC tube for open.

Replace capacitor at grid of vertical oscillator.

# DIGEST (A)

THIS IS ONE OF THE EASIEST SYMPTOMS TO RECOGNIZE SINCE ALL THAT WILL BE ON THE SCREEN IS A STRAIGHT, HORIZON-TAL LINE IN THE CENTER OF THE C.R.T.

THIS LIMITS THE TROUBLE TO THE VERTICAL SWEEP CIRCUIT, SINCE IT SWEEPS THE BEAM FROM TOP TO BOTTOM.



NO VERTICAL SWEEP

SYMPTOM

# DIGEST (B)

WITH THIS SYMPTOM THE VERTICAL SWEEP TUBES SHOULD BE RE-PLACED FIRST. IF THIS DOES NOT HELP THEN THE SCOPE CAN BE USED TO GREAT ADVANTAGE SINCE IT WILL SPOT THE DE-EFFECTIVE STAGE RIGHT AWAY. ONCE LOCALIZED TO ONE STAGE, VOLTAGE AND RESISTANCE MEASURE-MENTS WILL LOCATE THE DEFECTIVE COM-PONENT.

If still no sweep, replace OSC trans former.

### 9

If a signal is at grid of output tube, check signal at plate.

## 10

If none at plate check voltages around output tube.

### 11

If voltage mis-sing at any point check for open in circuit.


## 12

If cathode circuit open, a high vol-tage will be at cathode.

## 13

If signal at output plate check transformer or yoke for open.

14



★ C.54, A.0033 MFO CONDENSER, HAS BEEN RELOCATED (TO PREVENT POSSIBILITY OF VERTICAL ORIFT DURING WARM-UP) AND IS HORIZONTALLY MOUNTED ON ETCHED CIRCUIT BOARD, (SEE FIG. #4, PG, 4)

Emerson

NTRL WHITTIER, CALIF. U.S A

CIRCUIT

cal oscillator and

output tube.

IS NOTICED THE VER-

TICAL HEIGHT AND

VERTICAL LINEARITY

CONTROLS SHOULD

BE ADJUSTED TO SEE

IF THE WHITE LINE.

AT THE BOTTOM OF

THE PICTURE CAN BE

ELIMINATED. ONE

THING IS IMPORTANT

AT THIS TIME THAT IS

IF THE HEIGHT CON-

TROL IS INCREASED

WAY BEYOND NORMAL,

THEN THE FOLDOVER

WILL BE WAY BELOW

THE SCREEN, BUT

THE TROUBLE WILL

NOT BE ELIMINATED

ONLY COMPENSATED

FOR, AND THE TROU-

BLE WILL RE-APPEAR AS TIME GOES BY.

EST (B)

put tube trouble

is after this point.

With a normal signal at grid of out-

SECTION

**SCHEMATIC,** 

**ELE-FAX** 

2

With scope, check signal at grid of output tube.

3

If a flat top is noticed on signal, trouble is before this point.

Replace coupling capacitor to output tube grid.

5

Replace charging capacitor C-56

6

If above checks do not help, make sure height control works.

7

If height does not have much control, check plate circuit of OSC.



FOLDOVER AT **BOTTOM OF PICTURE** 

SYMPTOM

THE USE OF THE OS-CILLOSCOPE IN FIND-ING THIS TROUBLE IS VERY HELPFULSINCE THE SAWTOOTH WILL HAVE A FLAT TOP TO BY OBSERVING THE SIGNAL AT THE GRID OF THE VER-TICAL OUTPUT TUBE. WE CAN SEE IF THE TROUBLE IS BEFORE. OR AFTER THIS POINT. IF IT IS BEFORE THIS POINT THEN THESAW-TOOTH WILL HAVE A FLAT TOP TO IT AT THE GRID, AND THE VERTICAL OSCILLA-TOR CIRCUIT MUST BE DEFECTIVE AND CAUSING FOLDOVER.

Check cathode circuitofoutput tube for bad resistor or cap.

10

Check plate. screen voltages and resistors of output tube for change.

11

If filter cap is used below output transformer check it for open.

12

If none of above help, replace output transformer.

13

14

30 CPS C-56

1 3C CPS VERT OSCILLATOR V-14(A) 6DE7 VERT. OUTPUT V-14(B) 6DE7 VERTICAL LINEARITY R-70 VERTICAL SIZE

# C 54, A .0033 MFD CONDENSER, HAS BEEN RELOCATED (TO PREVENT POSSIBILITY OF VERTICAL DRIFT DURING WARM-UP) AND IS HORIZONTALLY MOUNTED ON ETCHED CHROUT BOARD, (35E F1), 4, 4, 19, 4,1

Emerson

NTRL WHITTIER, CALIF.U.S A

CIRCUIT

Adjust vertical hold control.

2

Replace vertical oscillator tube.

3

If a blocking OSC is used, check grid resistors and hold control.

4

It resistors are normal, replace coupling capacitor to OSC grid

5

If still off frequency replace oscillator transformer.

6

If a multivibrator is used, first check grid resistors.

7

Now check plate resistors for a change in value.

# DIGEST (A)

THIS SYMPTOM IS EASY TO FIND SINCE THE VERTICAL HOLD CON-TROL WILL BE UN-ABLE TO BRING ONE PICTURE ON THE SCREEN. IF ONE PIC-TURE DOES MOMEN-TARILY APPEAR THEN THE TROUBLE IS LOSS OF VERTICAL SYNC, AND YOU SHOULD REFER TO CHART #23. IN THIS OFF FREQUENCY CON-DITION YOU MAY FIND MANY PICTURES ON SCREEN. OR LESS THAN ONE PICTURE WHERE PART OF THE PICTURE SEEMS TO LAP OVER THE OTHER PART.



VERTICAL SWEEP OFF FREQUENCY

SYMPTOM

6 EST (B)

THIS TROUBLE IS A SIMPLE ONE TO FIND IF A BLOCKING OS-CILLATOR IS USED AS THE VERTICAL OSCIL-LATOR, UNDER THESE CONDITIONS THE DE-FECT IS IN THE GRID CIRCUIT OF THE OS-CILLATOR TUBE, IF A MULTIVIBRATOR USED AS THE VERTI-CAL OSCILLATOR THEN THE TROUBLE CAN BE ALMOST ANY COMPONENT AROUND THE OSCILLATOR CIR-CUIT. THE BLOCKING OSCILLATOR WILL **HAVE A TRANSFORMER** IN THE GRID PLATE CIRCUIT.

Replace all coupling capacitors to grids of multi-

9

vibrator.

Replace all capacitors at the plates of multivibrator.

10

11

12


CHEMATIC,

13

14

-

TROURIE



\_\_\_\_

NTRL WHITTIER, CALIF.U.S.A.

CIRCUIT

DIGEST (B)

Replace vertical sweep tubes.

2

Check for peak to peak at grid of vertical output tube, should be 90V.

3

If very low check for increase in plate load resistor of vertical OSC.

If resistors are normal, replace charging capacitor.

5

If none of the above help, check the B + line to OSC plate.

6

If peak to peak at grid of vertical output tube is normal check wave at plate.

At plate, wave should be very large, about 1000v peak to peak.

IN MOST TELEVISION RECEIVERS THE VER-TICAL HEIGHT CON-TROL SHOULD BE CAPABLE OF MAKING THE PICTURE GO WAY BEYOND THE TOP AND BOTTOM OF THE SCREEN. WHEN AD-IUSTED CORRECTLY. THE TOP AND BOTTOM OF A TEST PATTERN OUTER CIRCLE SHOULD JUST GO BE-YOND THE EDGES OF THE SCREEN. WITH NOT ENOUGH HEIGHT. THE PICTURE WILL NOT TOUCH THE SCREEN TOP OR BOT-TOM EVEN WHEN THE CONTROLS ARE SET AT MAXIMUM.



NOT ENOUGH HEIGHT

SYMPTOM

ROU

AMONG THE MOST COMMON TROUBLES OF THIS CONDITION ARE TUBES. THE VER-TICAL OUTPUT TRANS-FORMER OR YOKE WILL ALSO CAUSE THIS TROUBLE ALONG WITH MANY SMALLER PARTS. THE SCOPE IS A GREAT HELP IN FINDING THIS TROU-BLE SINCE WE CAN SEE THE SIZE OF THE SIGNALAT ANY GIVEN POINT. ONCE THE TROUBLE IS LOCALI-ZED TO ONE STAGE. THE VTVM CAN BE USED TO FIND THE BAD PART, A CHECK SHOULD BE MADE TO SEE IF THERE IS EN-OUGH WIDTH, SINCE LACK OF HEIGHT AND WIDTH INDICATE B+ TROUBLE.

If low at place, check cathode resistors for increases or open cap.

9

Also plate resistors may increase. or open capacitor in plate circuit.

10

If none of these help, replace vertical output transformer.

11

If wave at plate is normal, output transformer may still be bad.


12

Replace transformer, if still low in height replace voke.

13

Be sure to get exactreplacement of transformer or voke.

14



<u>CT 10</u> 교

NTRL WHITTIER, CALIF.U.S A

CIRCUIT

IN A NUMBER OF TV

DIGEST (B)

Replace the vertical output tube.

2

Adjust the height and vertical linearity control.

3

If one of them has no effect check as follows.

4

Height control may have open center tap.

5

Linearity control may be shorted out be capacitor across it.

6

If both controls work check resistor in series with height.


7

Resistor in series with linearity may have decreased.

SETS IT WILL BE FOUND THAT THE HEIGHT OF THE PIC-TURE CANNOT BE AD-JUSTED SO THAT IT IS SMALL ENOUGH TO JUST REACH THE TOP AND BOTTOM OF THE SCREEN.IN THIS CASE TOO MUCH HEIGHT IS PRESENT AND WE MUST TROUBLESHOOT THE VERTICAL SWEEP CIRCUIT. NOT TOO MANY COMPONENTS WILL CAUSE SUCH A TROUBLE AND THOSE THAT DO ARE SOON FOUND! ADJUSTMENT OF THE VERTICAL CONTROLS MANY TIMES WILL HELP IN

ISOLATING THE TROU-

BLE.



TOO MUCH HEIGHT

SYMPTOM

THE HEIGHT OF THE PICTURE IS OBTAINED BY THE TIME IT TAKES FOR A CAPACITOR TO CHARGE. IF THE RESI-STANCE IN THE CIR-CUIT IS REDUCED THEN THE CAPACITOR WILL CHARGE OUICK-LY AND THE HEIGHT OF THE PICTURE IS INCREASED. IN THE PLATE CIRCUIT OF THE VERTICAL OS-CILLATOR WE FIND THE RESISTORS AND CAPACITOR A CHANGE IN VALUE OF THESE PARTS WILL CAUSE TOO MUCH HEIGHT. INTERNAL SHORT IN THE VERTICAL OUT-PUT TUBE MAY ALSO CAUSE THIS TROUBLE.

Replace charging capacitor.

9

If all parts check normal then output Xfmr is bad.

10

Be sure to obtain correct replacement of Xfmr.

11


12

**SCHEMATIC,** 

**ELE-FAX** 

13

14



CIRCUIT

**DIAGRAM** 

2

Replace vertical OSC and output tubes. Check B + for normal.

3

Use scope to check wave shape at grid of vertical output tube.

4

If top of wave squashed, check coupling capacitor for leaky.

5

Also check value of grid resistor at output tube.

6

Replace charging capacitor C410

7

If signal normal at grid of output, check wave at plate.

# DIGEST (A)

THIS CONDITION IS NO-TICED OUICKLY IF A TEST PATTERN PRESENT. THE CIRCLE IN THE TEST PATTERN WILLAPPEAR SOUASH-ED AT THE TOP OR BOTTOM. IF A TEST PATTERN IS NOT PRE-SENTPOOR LINEARITY MAY BE NOTICED WHEN A BALL OR ANY ROUND OBJECT IS ON THE SCREEN. NOTICE SHOULD BE TAKEN OF THE RATIO BE-TWEEN THE FACES AND BODIES OF THE PEOPLE. IF IT AP-PEARS POOR, THEN POOR LINEARITY MAY BE THE CAUSE.

POOR VERTICAL
LINEARITY

SYMPTOM

SEST (B)

THE VERTICAL LINEA-RITY AND HEIGHT CONTROLS SHOULD BE ADJUSTED FIRST IF POOR LINEARITY IS NOTICED. THESE CON-TROLS HAVE AN EF-FECTONEACHOTHER, AND WILL BOTH HAVE TO BE ADJUSTED AT THE SAME TIME. THE HEIGHT CONTROL HAS MOST EFFECT ON THE BOTTOM OF THE PIC-AND TURE. THE LINEARITY CONTROL AFFECTS THE TOP OF THE PICTURE MOST. IF THESE CONTROLS DO NOT HELP THE SITUATION, TUBES SHOULD BE SUBSTI-TUTED, A CURVE IN THE SAW TOOTH WAVE-SHAPE IS CAUSING THIS TROUBLE.

8

If poor wave at plate, check cathode resistor.

9

Cathode filter capacitor of output may be leaky.

10

Measure ohms of output transformer primary and resistor in series with it.

11

SECTION

SCHEMATIC,

ELE-FAX

Output tube plate filter capacitor may be open, if one is used.


12

Replace vertical output transformer.


13

Replace yoke.

14



POURIF



NTRL WHITTIER, CALIF.U.S A

CIRCUIT

Replace horizontal oscillator and any A.F.C. tubes.

2

Try all adjustments in the horizontal osc circuit to bring the pix into sync.

3

These adjustments are horizontal frequency, hor. hold, hor. lock, a.f.c.or hor.phase.

4

Remove or disable A.F.C. circuit. Try adjustments again.

5

If pix now holds momentarily A.F. C. circuit should be checked.


6

If pix still will not sync, then hor. osc. circuit is off frequency.

7

Check all resistors in the plate grid, and cathode of the hor. osc.

THIS CONDITION IS SIMILAR TO NO A.F.C. CONTROL AS FOUND IN CHART #30. THE BIG **EXCEPTION IS THAT** NO ADJUSTMENT OF ANY OF THE HORI-ZONTAL CONTROLS WILL MAKE ONE PIC. TURE APPEAR ON THE SCREEN. OF COURSE THE ADJUSTMENTS SHOULD BE TRIED FIRST TO SEE IF THEY WILL CAUSE ONE PIC-TURE TO APPEAR MO-MENTARILY. IF THIS DOES OCCUR REFER TO CHART \*30. WITH THE OFF FREQUENCY TROUBLE MULTIPLE PICTURESMAY BE NO-TICED ON THE SCREEN.



OFF HORIZONTAL FREQUENCY

SYMPTOM

DIGEST (B)

THE SCOPE DOES NOT HELPIN THIS TYPE OF TROUBLE SINCE THE OSCILLATOR IS WORK-ING JUST TOO FAST OR TOO SLOW. TUBES CAUSE THIS TROUBLE MANY TIMES AND SHOULD ALWAYS BE REPLACED ONCE THE ADJUSTMENTS HAVE NO NOTICEABLE EF-FECT. IT MAY BE THAT THE ADJUST-MENTS MAY ALMOST BRING THE PICTURE INTO SYNC WHEN AD-JUSTED ALL THE WAY IN ONE DIRECTION. A NUMBER OF SPECIFIC COMPONENTS CAUSE THIS TROUBLE, AND ARE ALL IN THE HORIZONTAL OSCIL-LATOR CIRCUIT.

8

Replaceany capacitors around hor. osc. especially grid capacitor.

**32** 

SECTION

SCHEMATIC,

**FELE-FA** 

9

If lack of width is also noticed, check for low voltage to hor.osc.

10

An open filter in the B + line to hor.osc.may cause this trouble.

11

If all resistors and capacitors have been checked replace hor. osc. coil.

12

Make sure that you have checked 4 and 5 of this sheet.

13

14

TROUBLE

7875 CPS

7875 C

CIRCUIT

DIAGRAM •

drive control.

Try adjustment of

width control and

Replacehor. OSC. output, damper, and low voltage rectifier tubes.

3

If seleniums are used as rectifiers check B + voltage. Should be 265v.

With scope check P to P at grid of hor. output should be from 70-120v.

If low, check hor. osc. circuit for change in resistors or charging cap.

6

If normal P to P check resistors in hor. output tube.

7

Check damper voltage, if low replace capacitors at cathode.

WITH NOT ENOUGH WIDTH THE SIDES OF THE SCREEN WILL BE BLACK. THIS MAY BARELY BE NOTI-CEABLE, OR IT MAY BE IN AS MUCH AS TWO INCHES ON EACH SIDE.ADJUSTMENT OF THE WIDTH CONTROL SHOULD BE TRIED FIRST BUT USUALLY THIS CONTROL WILL ONLY MOVE THE WIDTH ABOUT HALF AN INCH ON EITHER SIDE. TUBES IN THE HORIZONTAL CIR-CUIT WILL VERY OF-CAUSE TEN THIS

CONDITION.



NOT ENOUGH WIDTH

SYMPTOM

DIGEST (B)

WITH A WEAK SIGNAL APPLIED TO THE DE-FLECTION YOKE THE HORIZONTAL SWEEP WILL NOT COVER THE ENTIRE SCREEN, THE CAUSE OF THIS CAN BE TUBES. THE FLY-BACK CIRCUIT, OR EVEN THE DEFLEC-TION YOKE ITSELF-MOST COMMON TROUBLE IN THE HORIZONTAL OUTPUT TUBE AND ITS AS-SOCIA TED COMPO-NENTS- INSUFFICIENT B + WILL ALSO CAUSE LACK OF WIDTH.

Bridge all capacitors in hor. output tube.

9

Increase width by placing .05 mfd 600v cap across width coil.

10

In some cases complete removal of width coil will help slightly.

11

If none of the above checks help replace flyback or

12


SCHEMATIC,

**TELE-FAX** 

The flyback is the more likely of the two, try it first.

13

14



**CIRCUIT** 

NTRL WHITTIER, CALIF. U.S. A.

DIAGRAMA ....

Adjust drive control to try and remove white lines.

2

Replace hor. output tube and damper. Readiust drive control.

3

Check grid resistor of the horizontal output for a decrease in value.

Replace bootstrap capacitor located at the cathode of damper tube.

5

Replace bootstrap capacitor located at end of linearity coil.

6

Recheck tubes after capacitors have been replaced.

7

Replace capacitor across half of horizontal deflection coils.

IN SOME CASES THESE WHITE LINES ON THE LEFT SIDE OF THE RASTERMAY BE VERY BRIGHT OR HARDLY NOTICEABLE THE HORIZONTAL DRIVE CONTROL SHOULD ALWAYS BE CHECKED FIRST FOR CORRECT SETTING SINCE IT WILL CAUSE THESE LINES TO APPEAR THE CORRECT SET-TING OF THE DRIVE CONTROL IS WHEN IT IS AT A POINT JUST BEFORE WHITE LINES ARE NOTICED ON THE SCREEN.



WHITE LINES

SYMPTOM

## DIGEST (B)

MANY TIMES THE DAM-PER CIRCUIT IS AT FAULT SINCE IT CON-TROLS THE SWEEP ON THE FIRST THIRD OF THE SCREEN IF POOR DAMPINGIS OCCURING THE UNWANTED OS-CILLATIONS OCCUR IN THE HORIZONTAL SWEEP CIRCUITS AND THE RESULT IS WHITE LINES ON THE LEFT SIDE OF THE SCREEN. TOO MUCH SIGNAL TO THE HORIZONTAL OUTPUT TUBE WILL ALSO CAUSE WHITE LINES ABOUT ONE THIRD WAY IN FRONT LEFTSIDE OF SCREEN.

See if yoke or horizontal output trans, have been replaced.

9

If so make sure correct parts have been used.

10

A mismatch in these parts will cause white lines on screen.

11

Replace yoke.

12


Replace Flyback

13

14



ON RASTER



NTRL WHITTIER, CALIF.U.S A

SECTION SCHEMATIC, ELE-FAX

SECTION

CHEMATIC,

Ň

TELE-F

Replace hor. Osc. and a.f.c. tube.

2

Try adjustment of all hor. controls to lock Pix in.

3

Switch set on and off to check if adjustments correct the trouble.

4

Measure all resistors at the hor. osc circuit for change in value.

5

Determine if hor. osc coil has a cracked slug in the core.


6

Replace capacitor across osc coil it may be intermittent.

7

If a syncroguide circuit is used replace capacitor at osc grid.

WITH THIS CONDITION IT MAY BE NOTICED THAT THE TROUBLE WILL OC-CUR ONLY WHEN THE SET IS FIRST SWITCHED ON, OR THAT THE TROU-BLE MAY APPEAR WHEN THE STATIONS ARE CHANGED, AT OTHER TIMES YOU MAY FIND THAT THE TROUBLE IS CONTINUOUS AND THAT NOADJUSTMENT OF THE HORIZONTAL HOLD OR FREQUENCY WILL HELP. MOST TIMES IT WILL BE FOUND THAT WHEN THE TROUBLE IS NOTICED FREQUENCY OR HOLD CONTROL WILL STOP THIS CONDITION AND THE PICTURE MAY REMAIN NORMAL FOR THE ENTIRE TIME THAT THE SET IS SWITCHED ON.



XMAS TREE EFFECT

SYMPTOM

A HIGH PITCHED WHI-STLE WILL USUALLY BE NOTICED ALONG WITH TROUBLE AND THIS WHAT IS HAPPENING IS THAT THE HORIZONTAL OSCILIATOR IS OPERA-TING ERRATICALLY. STARTING AND THIS STOPPING CAUSES THE HORIZONTAL SWEEP TO COLLAPSE TO A THIN LINE BUT BECAUSE IT STARTS TO SWEEP AGAIN ALMOST IMMEDIA-TELY IT GIVES THE AP-PEARANCE CALLED XMAS TREE EFFECT WHICH IS REALLY WHITE IAGGED LINES IN THE CENTER OF THE RASTER. THIS TROUBLE THEREFORE MUST BE IN THE HORIZONTAL OSCI-LIATOR CIRCUIT

If a multivbrator is used replace cap from plate to grid of osc.

In other type circuits replace capacitors in osc grid and plate.

10

Resolder all pin contacts in the hor. osc. tube.

11

Arcing in the damper tube may give the appearance of X mas tree.

12

Arcing in the Yoke may also appear as Xmas tree.


13

Check both yoke and damper for arcing.

14

Replace the Hor. osc. coil if Xmas tree persists.

TROUBLE



Admiral

NTRL WHITTIER, CALIF.U.S A

CIRCUIT

If yoke has plug check for open contact.

2

Unsolder yoke and measure resis-tance of horizontal windings.

3

Should have low resistance about 15 ohms.

If normal check connections yoke to circuit.

5

Take close check of flyback secondary for open.

6

If voke has to be replaced be sure to get correct part.

7

With trouble in 7" sets trouble is in sweep circuit.

IF THE RASTER ON THE SCREEN SHOWS A THIN WHITE LINE IN THE CENTER, THE CAUSE MUST BE LIMI-TED TO TROUBLE IN THE YOKE OR OUTPUT CIRCUIT OF THE FLY-BACK TRANSFORMER. THERE ARE A NUMBER OF SETS ON THE MAR-KET THATWILL CAUSE THIS SAME CONDITION TO OCCUR BECAUSE OF TROUBLE IN THE HORIZONTAL SWEEP CIRCUIT, BUT THESE SETS ARE THE 7" SCREEN TYPE AND HAVE ELECTROSTAT-IC CRT.



WHITE LINE IN CENTER OF SCREEN

SYMPTOM

WHEN THE DEFLEC-TION YOKE IS OPEN. THE SIGNAL THAT COMES FROM THE HORIZONTAL SWEEP CIRCUIT WILL NOT CAUSE THE BEAM TO SWEEP THE CRT SIDE-WAYS **AL THOUGH** THERE STILL WILL BE HIGH VOLTAGE DEVE-LOPED. THIS WILL MEAN THAT A SINGLE WHITE LINE WILL BE NOTICED ON THE SCREEN.IN THE SMALL 7" TV SETS THE HV SYSTEM HAD NOTHING TO DO WITH THE HOR-IZONTAL SWEEP CIR-CUIT AND ANY TROU-BLE IN THE SWEEP SECTIONWOULD IN NO WAY AFFECT THE HV. IN THIS CASE LOSS OF SWEEP WOULD GIVE

A WHITE LINE.

Replace tubes in horizontal sweep circuit of 7" sets.

9

Refer to chart No. 36 if above check does not help.

10

11

12

AGC PULSE  6DQ6A  HORIZ, OUTPUT V404	TROUB	NOTE - R437(390Q, 1M) USED WHEN R431 AND R433 ARE 220Q EACH
RAGE  RANGE  RANGE  RANGE  A 134V  HORIZ.  RANGE  A 134V  A 13	7403 5100 51 000 1 R466 2 1 000 1 R466 2 1 100 16 RED 1 10 10 16 RED 1 10 16 RED	1G3GT H.V. RECTIFIER 7 V406 15.58V  RED/WHT V405 DAMPER 6AX4GTA/B OR 6DE 4

NTRL WHITTIER, CALIF. U.S. A.

13

14

SCHEMATIC,

**FELE-FAX**