

Cyclopedia *of* Applied Electricity

A General Reference Work on

DIRECT-CURRENT GENERATORS AND MOTORS, STORAGE BATTERIES,
ELECTRIC WIRING, ELECTRICAL MEASUREMENTS, ELECTRIC
LIGHTING, ELECTRIC RAILWAYS, POWER STATIONS,
POWER TRANSMISSION, ALTERNATING-CURRENT
MACHINERY, TELEPHONY, TELEGRAPHY, ETC.

Prepared by a Corps of

ELECTRICAL EXPERTS, ENGINEERS, AND DESIGNERS OF THE HIGHEST
PROFESSIONAL STANDING

Illustrated with over Two Thousand Engravings

SEVEN VOLUMES

CHICAGO
AMERICAN TECHNICAL SOCIETY
1912

COPYRIGHT, 1905, 1906, 1908, 1909, 1911

BY

AMERICAN SCHOOL OF CORRESPONDENCE

COPYRIGHT, 1905, 1906, 1908, 1909, 1911

BY

AMERICAN TECHNICAL SOCIETY

Entered at Stationers' Hall, London

All Rights Reserved



WILLIAM ESTY

Head of Department of Electrical Engineering, Lehigh University.



Authors and Collaborators

FRANCIS B. CROCKER, E. M., Ph. D.

Professor of Electrical Engineering, Columbia University, New York
Past-President, American Institute of Electrical Engineers

WILLIAM ESTY, S. B., M. A.

Head, Department of Electrical Engineering, Lehigh University
Joint Author of "The Elements of Electrical Engineering"

HENRY H. NORRIS, M. E.

Professor in Charge, Department of Electrical Engineering, Cornell University

JAMES R. CRAVATH

Consulting Electrical Engineer
Formerly Associate Editor, *Electrical World*

GEORGE C. SHAAD, E. E.

Professor of Electrical Engineering, University of Kansas

ROBERT ANDREWS MILLIKAN, Ph. D.

Professor of Physics, University of Chicago

KEMPSTER B. MILLER, M. E.

Consulting Engineer and Telephone Expert
Of the firm of McMeen & Miller, Electrical Engineers and Patent Experts, Chicago

LOUIS DERR, S. B., A. M.

Professor of Physics, Massachusetts Institute of Technology

DAVID P. MORETON, B. S., E. E.

Associate Professor of Electrical Engineering, Armour Institute of Technology
American Institute of Electrical Engineers

MORTON ARENDT, E. E.

Assistant Professor of Electrical Engineering, Columbia University, New York
American Institute of Electrical Engineers

Authors and Collaborators—Continued

GEORGE W. PATTERSON, S. B., Ph. D.

Head, Department of Electrical Engineering, University of Michigan



WILLIAM H. FREEDMAN, C. E., E. E., M. S.

Head, Department of Applied Electricity, Pratt Institute, Brooklyn, N. Y.

Formerly Head, Department of Electrical Engineering, University of Vermont



CHARLES THOM

Chief of Quadruplex Department, Western Union Main Office, New York City



CHARLES G. ASHLEY

Electrical Engineer, and Expert in Wireless Telephony and Telegraphy



A. FREDERICK COLLINS

Editor, *Collins Wireless Bulletin*

Author of "Wireless Telegraphy, Its History, Theory, and Practice"



CHARLES E. KNOX, E. E.

Consulting Electrical Engineer

American Institute of Electrical Engineers



JOHN LORD BACON

Engineer and Superintendent of Construction with R. P. Shields & Son, General Contractors and Builders

American Society of Mechanical Engineers



JESSIE M. SHEPHERD, A. B.

Associate Editor, Textbook Department, American School of Correspondence



GEORGE R. METCALFE, M. E.

Editor, American Institute of Electrical Engineers

Formerly Head, Technical Publication Department, Westinghouse Electric & Manufacturing Co.



R. F. SCHUCHARDT, B. S.

Testing Engineer, Commonwealth Edison Co. Chicago



LEIGH S. KEITH, B. S.

Managing Engineer with McMeen & Miller, Electrical Engineers and Patent Experts, Chicago

American Institute of Electrical Engineers

Authors and Collaborators—Continued

SAMUEL G. McMEEN

Consulting Engineer and Telephone Expert
Of the Firm of McMeen & Miller, Electrical Engineers and Patent Experts, Chicago
American Institute of Electrical Engineers



LAWRENCE K. SAGER, S. B., M. P. L.

Patent Attorney and Electrical Expert, New York City



ERNEST L. WALLACE, B. S.

Assistant Examiner, United States Patent Office, Washington, D. C.
Formerly Instructor in Electrical Engineering, American School of Correspondence



PERCY H. THOMAS, S. B.

Of Thomas & Neall, Electrical Engineers, New York City
Formerly Chief Electrician, Cooper Hewitt Electric Co.



JAMES DIXON, E. E.

American Institute of Electrical Engineers



GLENN M. HOBBS, Ph. D.

Secretary, American School of Correspondence
Formerly Instructor in Physics, University of Chicago
American Physical Society



H. C. CUSHING, Jr.

Consulting Electrical Engineer
Author of "Standard Wiring for Electric Lighting Power"



J. P. SCHROETER

Graduate, Munich Technical School
Instructor in Electrical Engineering, American School of Correspondence



ALTON D. ADAMS

Consulting Engineer, and Expert on Hydro-Electric Power Development



CHARLES DAY

With Dodge & Day, Engineers, Philadelphia
American Institute of Electrical Engineers



HARRIS C. TROW, S. B., *Managing Editor*

Editor-in-Chief, Textbook Department, American School of Correspondence

Authorities Consulted

THE editors have freely consulted the standard technical literature of America and Europe in the preparation of these volumes. They desire to express their indebtedness, particularly to the following eminent authorities, whose well-known works should be in the library of every electrician and engineer.

Grateful acknowledgment is here made also for the invaluable co-operation of the foremost engineering firms and manufacturers in making these volumes thoroughly representative of the very best and latest practice in the design, construction, and operation of electrical machinery and instruments; also for the valuable drawings, data, suggestions, criticisms, and other courtesies.

FRANCIS B. CROCKER, M. E., Ph. D.

Head of Department of Electrical Engineering, Columbia University; Past-President, American Institute of Electrical Engineers
Author of "Electric Lighting"; Joint Author of "Management of Electrical Machinery," "Electric Motors"

~

SCHUYLER S. WHEELER, D. Sc.

President, Crocker-Wheeler Co.; Past-President, American Institute of Electrical Engineers
Joint Author of "Management of Electrical Machinery"

~

ALFRED E. WIENER, E. E., M. E.

Member, American Institute of Electrical Engineers
Author of "Practical Calculation of Dynamo-Electric Machines"

~

WILLIAM S. FRANKLIN, M. S., D. Sc.

Professor of Physics, Lehigh University
Joint Author of "The Elements of Electrical Engineering," "The Elements of Alternating Currents"

~

WILLIAM ESTY, S. B., M. A.

Head of Department of Electrical Engineering, Lehigh University
Joint Author of "The Elements of Electrical Engineering"

~

R. B. WILLIAMSON

Joint Author of "The Elements of Alternating Currents"

~

HORATIO A. FOSTER

Consulting Engineer; Member of American Institute of Electrical Engineers; Member of American Society of Mechanical Engineers
Author of "Electrical Engineer's Pocket-Book"

Authorities Consulted—Continued

DUGALD C. JACKSON, C. E.

Head of Department of Electrical Engineering, Massachusetts Institute of Technology;
Member, American Society of Mechanical Engineers, American Institute of Electrical Engineers, etc.

Author of "A Textbook on Electromagnetism and the Construction of Dynamos"; Joint
Author of "Alternating Currents and Alternating-Current Machinery"

J. FISHER-HINNEN

Late Chief of the Drawing Department at the Oerlikon Works
Author of "Continuous-Current Dynamos"

WILLIAM L. HOOPER, Ph. D.

Head of Department of Electrical Engineering, Tufts College
Joint Author of "Electrical Problems for Engineering Students"

ROBERT ANDREWS MILLIKAN, Ph. D.

Professor of Physics, University of Chicago
Joint Author of "A First Course in Physics," "Electricity, Sound and Light," etc.

JOHN PRICE JACKSON, M. E.

Professor of Electrical Engineering, Pennsylvania State College; Member, American
Institute of Electrical Engineers, etc.
Joint Author of "Alternating Currents and Alternating-Current Machinery"

MICHAEL IDVORSKY PUPIN, A. B., Sc. D., Ph. D.

Professor of Electro-Mechanics, Columbia University, New York
Author of "Propagation of Long Electric Waves," and "Wave-Transmission over Non-
Uniform Cables and Long-Distance Air Lines"

LAMAR LYNDON, B. E., M. E.

Consulting Electrical Engineer; Associate Member of American Institute of Electrical
Engineers; Member, American Electro-Chemical Society
Author of "Storage Battery Engineering"

EDWIN J. HOUSTON, Ph. D.

Professor of Physics, Franklin Institute, Pennsylvania; Joint Inventor of Thomson-
Houston System of Arc Lighting; Electrical Expert and Consulting Engineer
Joint Author of "Alternating Currents," "Arc Lighting," "Electric Heating,"
"Electric Motors," "Electric Railways," "Incandescent Lighting," etc.

ARTHUR E. KENNELLY, D. Sc.

Professor of Electrical Engineering, Harvard University
Joint Author of "Alternating Currents," "Arc Lighting," "Electric Heating,"
"Electric Motors," "Electric Railways," "Incandescent Lighting," etc.

Authorities Consulted—Continued

SILVANUS P. THOMPSON, D. Sc., B. A., F. R. S., F. R. A. S.
Principal and Professor of Physics in the City and Guilds of London Technical College;
Past-President, Institution of Electrical Engineers
Author of "Electricity and Magnetism," "Dynamo-Electric Machinery," "Polyphase
Electric Currents and Alternate-Current Motors," "The Electromagnet," etc.

KEMPSTER B. MILLER, M. E.
Consulting Engineer and Telephone Expert; of the Firm of McMeen and Miller,
Electrical Engineers and Patent Experts, Chicago
Author of "American Telephone Practice"

MAURICE A. OUDIN, M. S.
Member, American Institute of Electrical Engineers
Author of "Standard Polyphase Apparatus and Systems"

FREDERICK BEDELL, Ph. D.
Professor of Applied Electricity, Cornell University
Author of "The Principles of the Transformer"; Joint Author of "Alternating
Currents"

H. F. PARSHALL
Member of American Institute of Electrical Engineers, Institution of Electrical
Engineers, American Society of Mechanical Engineers, etc.
Joint Author of "Armature Windings of Electric Machines"

J. A. FLEMING, M. A., D. Sc. (Lond.), F. R. S.
Professor of Electrical Engineering in University College, London; Late Fellow and
Scholar of St. John's College, Cambridge; Fellow of University College, London;
Member, Institution of Electrical Engineers; Member of the Physical Society of
London; Member of the Royal Institution of Great Britain, etc., etc.
Author of "The Alternate-Current Transformer," etc.

LOUIS BELL, Ph. D.
Consulting Electrical Engineer; Lecturer on Power Transmission, Massachusetts
Institute of Technology
Author of "Electric Power Transmission," "Power Distribution for Electric Railways,"
"The Art of Illumination," "Wireless Telephony," etc.

CHARLES PROTEUS STEINMETZ
Consulting Engineer, with the General Electric Co.; Professor of Electrical Engineering,
Union College
Author of "The Theory and Calculation of Alternating-Current Phenomena," "Theo-
retical Elements of Electrical Engineering," etc.

MORTON ARENDT, E. E.
Assistant Professor of Electrical Engineering, Columbia University, New York
Joint Author of "Electric Motors"

Authorities Consulted—Continued

J. J. THOMSON, D. Sc., LL. D., Ph. D., F. R. S.

Fellow of Trinity College, Cambridge University; Cavendish Professor of Experimental Physics, Cambridge University
Author of "The Conduction of Electricity through Gases," "Electricity and Matter," etc.

HENRY SMITH CARHART, A. M., LL. D.

Professor of Physics and Director of the Physical Laboratory, University of Michigan
Author of "Primary Batteries," "Elements of Physics," "University Physics," "Electrical Measurements," "High School Physics," etc.

F. A. C. PERRINE, A. M., D. Sc.

Consulting Engineer; Formerly President, Stanley Electric Manufacturing Company;
Formerly Manager, Insulated Wire Department, John A. Roebling's Sons Company
Author of "Conductors for Electrical Distribution"

WILLIAM MAVER, Jr.

Ex-Electrician, Baltimore and Ohio Telegraph Company
Author of "Wireless Telegraphy," "American Telegraphy and Encyclopedia of the Telegraph"

E. B. RAYMOND

Testing Department, General Electric Co.
Author of "Alternating-Current Engineering"

AUGUSTUS TREADWELL, Jr., E. E.

Associate Member, American Institute of Electrical Engineers
Author of "The Storage Battery: A Practical Treatise on the Construction, Theory, and Use of Secondary Batteries"

SAMUEL SHELDON, A. M., Ph. D.

Professor of Physics and Electrical Engineering, Polytechnic Institute of Brooklyn
Joint Author of "Dynamo-Electric Machinery," "Alternating-Current Machines"

HOBART MASON, B. S., E. E.


Assistant in Electrical Engineering, Polytechnic Institute of Brooklyn; Associate Member, American Institute of Electrical Engineers
Joint Author of "Dynamo-Electric Machinery," "Alternating-Current Machines"

H. M. HOBART, B. Sc.

Member, Institution of Civil Engineers, American Institute of Electrical Engineers
Joint Author of "Armature Construction"

ALBERT CUSHING CREHORE, A. B., Ph. D.

Electrical Engineer; Assistant Professor of Physics, Dartmouth College
Author of "Synchronous and Other Multiple Telegraphs"; Joint Author of "Alternating Currents"



TWO 1,500-K. W. ALLIS-CHALMERS STEAM TURBINES AND GENERATORS IN PLANT OF THE KERR MILLS
OF THE AMERICAN THREAD CO., FALL RIVER, MASS.
Allis-Chalmers Co., Milwaukee, Wis.

Foreword

ONE of the simplest acts in modern life is switching on the electric current that gives light or power, or that makes possible communication between distant points. A child can perform that act as effectively as a man, so thoroughly has electricity been broken to the harness of the world's work; but behind that simple act stand a hundred years of struggle and achievement, and the untiring labors of thousands of the century's greatest scientists. To compact the results of these labors into the compass of a practical reference work is the achievement that has been attempted—and it is believed accomplished—in this latest edition of the *Cyclopedia of Applied Electricity*.

Books on electrical topics are almost as many as the subjects of which they treat and many of them are worthy of a place in the first rank. But many, also, worthy in themselves, are too scientific in their treatment to be available for the mass of electrical workers; and all of them, if gathered into a great common library, would contain so many duplicate pages that their use would entail an appalling waste of time upon the man who is trying to keep up with electrical progress. To overcome these difficulties the publishers of this *Cyclopedia* went direct to the original sources, and secured as writers of the various sections, men of wide practical experience and thorough technical training, each an acknowledged authority in his work; and these contributions have been correlated by our Board of Editors so as to make the work a unified whole, logical in arrangement and at the same time devoid of duplication.

¶ The Cyclopedia is, therefore, a complete and practical working treatise on the generation and application of electric power. It covers the known principles and laws of Electricity, its generation by dynamos operated by steam, gas, and water power; its transmission and storage; and its commercial application for purposes of power, light, transportation, and communication. It includes the construction as well as the operation of all plants and instruments involved in its use; and it is exhaustive in its treatment of operating "troubles" and their remedies.

¶ It accomplishes these things both by the simplicity of its text and the graphicness of its supplementary diagrams and illustrations. The Cyclopedia is as thoroughly scientific as any work could be; but its treatment is as free as possible from abstruse mathematics and unnecessary technical phrasing, while it gives particular attention to the careful explanation of involved but necessary formulas. Diagrams, curves, and practical examples are used without stint, where they can help to explain the subject under discussion; and they are kept simple, practical, and easy to understand.

¶ The Cyclopedia is a compilation of many of the most valuable Instruction Books of the American School of Correspondence, and the method adopted in its preparation is that which this School has developed and employed so successfully for many years. This method is not an experiment, but has stood the severest of all tests—that of practical use—which has demonstrated it to be the best devised for the education of the busy, practical man.

¶ In conclusion, grateful acknowledgment is due to the staff of authors and collaborators, without whose hearty co-operation this work would have been impossible.



Table of Contents

VOLUME IV

ALTERNATING-CURRENT MACHINERY PART I . *By Wm. Esty* † Page *11

E. M. F.s and Currents—Simple Alternator—Advantages of Alternating Currents—D. C. vs. A. C. Problems—Average and Effective Values of E. M. F.—Instantaneous and Average Power—Harmonic E. M. F.s and Currents—Synchronism—Phase Difference—Maximum and Effective Values—Inductance—Capacity—Resonance—E. M. F. Losses in Transmission Lines—Indicating Instruments: Ammeters, Voltmeters, Electrodynamometers—Induction Instruments: Wattmeters—Integrating Instruments: Watt-Hour Meters

ALTERNATING-CURRENT MACHINERY PART II . *By Wm. Esty* Page 109

Alternators—Fundamental Equation—Armature Reaction and Inductance—Regulation—Field Excitation—Polyphase Alternators and Systems—Y and Δ -Connected Armatures—E. M. F. and Current Relations—Power—Balanced and Unbalanced Systems—Armature Windings—Commercial Types—Revolving Armature Alternators—Revolving Field Alternators—Construction—Water-Wheel-Driven and Steam Turbine-Driven Alternators

ALTERNATING-CURRENT MACHINERY PART III . *By Wm. Esty* Page 191

Economy Factors—Speed—Voltage—Regulation—Frequency—Power Losses—Efficiency—Output—Rating and Overload Capacities—American Institute Rules—Temperature Rise—Alternator Tests—Synchronous Motors—Synchronous vs. D. C. Motors—Starting—Hunting—Torque and Power Output—Field Excitation and Power Factor—Synchronous Motor as Condenser—Synchronous Motor Tests

ALTERNATING-CURRENT MACHINERY PART IV . *By Wm. Esty* Page 247

Transformer—Action—Maximum Core Flux—Coil Resistance and Magnetic Leakage—Regulation—Connections—Constant-Voltage Transformers—Autotransformers—Transformers in Polyphase Systems—Phase Transformation—Transformer Losses, Efficiency, Regulation, and Rating—Commercial Types—Core Type—Shell Type—Cooling—Constant-Current Transformers—Mounting of Transformers—Transformer Tests

ALTERNATING-CURRENT MACHINERY PART V . *By Wm. Esty* Page 333

Conversion of A. C. to D. C.—Rectifying Commutator—Aluminum Valve Rectifier—Mercury-Vapor Arc Rectifier—Rotary Converter—Three-Ring, Four-Ring, and Six-Ring Converters—E. M. F. and Current Relations—Uses of Rotary Converters—Starting—Characteristic Types—Hunting—Inverted Rotaries—Control of D. C. Voltage—Field Excitation—Six-Phase Converter—Transformer Connections—Testing—Motor-Generators—Uses and Types

ALTERNATING-CURRENT MACHINERY PART VI . *By Wm. Esty* Page 389


Induction Motor—Stator Windings—Starting Resistance—Efficiency—Torque—Speed—Rotor Resistance—Structural Details—Types of Rotors—Starting and Operation—Installation—Single-Phase Induction Motor—Starting—Induction Generator—Frequency Changer—Induction vs. Synchronous Motor—Induction Motor Tests—Switchboards—Feeder Panels—Lincoln Synchronizer—Air-Break Switches—Circuit Breakers—Oil-Break Switches—Voltage Regulators—Voltmeter Compensators—Lightning Arresters—Appendix

REVIEW QUESTIONS Page 487

INDEX Page 499

* For page numbers, see foot of pages.

† For professional standing of authors, see list of Authors and Collaborators at front of volume.



ENGINE-DRIVEN GENERATING UNIT AND TRANSFORMERS FOR ALTERNATING CURRENT
Allis-Chalmers Co., Milwaukee, Wis.

ALTERNATING=CURRENT MACHINERY

PART I

ALTERNATING ELECTROMOTIVE FORCES AND CURRENTS

Simple Alternator. The alternator is an arrangement by means of which mechanical energy is used to cause the magnetic flux from a magnet to pass through the opening of a coil of wire first in one and then in the opposite direction. This varying magnetic flux induces in the coil, first in one direction and then in the other, what is called an *alternating electromotive force*, which in turn produces an *alternating current* in the coil, and in the circuit which is connected to the terminals of the coil.

In the common type of alternator, the above-mentioned magnet and coil move relatively to each other. Fig. 1 shows the essential features of such an alternator. The poles *N, S, N, S*, etc., of a multipolar magnet called the *field magnet*, project radially inwards toward the passing teeth *a a a* of a rotating mass *A* of laminated iron; and upon these teeth are wound coils of wire *c c*, in which the alternating electromotive force is induced. The rotating mass of iron with its windings of wire is called the *armature*. At one end of the armature (not shown in the figure) are mounted two insulated metal rings *r r*, called *collecting rings*. These metal rings are connected to the ends of the armature winding, and metal brushes *b b* rub on these rings, thus keeping the ends of the armature winding in continuous contact with the terminals of the external circuit to which the alternator supplies alternating current. No external circuit is shown in the figure.

The electromotive forces induced in adjacent armature coils are in opposite directions at each instant, and the coils are so connected together that these electromotive forces do not oppose each

Copyright, 1911, by American School of Correspondence.

other. This is done by reversing the connections of every alternate coil, as indicated by the dotted lines connecting the coils in Fig. 1. The electromagnetic action of this type of alternator depends only upon the *relative* motion of field magnet and armature, and large machines are usually built with stationary armature and revolving field magnet. In the type of machine illustrated in Fig. 1, the armature revolves while the field magnet is stationary. This type, called the *revolving-armature* type, is generally adopted in small alternators.

The field magnet of an alternator is usually an electromagnet which is excited by a continuous electric current supplied by an independent generator, generally by an auxiliary continuous-current dynamo, called the *exciter*. The exciting current flows through coils




Fig. 1. Diagram of Armature and Field of Simple Alternator

of wire wound on the projecting poles *N, S, N, S* of the field magnet. These coils are not shown in Fig. 1.

The type of *armature core* shown in Fig. 1 is called the *toothed* armature core; and the *armature winding* is said to be *concentrated*, that is, the armature conductors are grouped in a few heavy bunches. Armature cores are also made with many small slots, in which the armature conductors are grouped in small bunches. This type of core is called a *multi-toothed* core, and the winding is said to be *distributed*.

In some of the earlier types of alternators the armature core consisted of a smooth, cylindrical mass of laminated iron, upon

the face of which the conductors were arranged in bands side by side, one layer or more in depth. This type of armature is called the *smooth-core* armature; it has been superseded by the toothed core type.

Variations of Electromotive Force. *Cycle.* The electromotive force of an alternator passes through a set of *positive* values while a given coil of the armature is passing from a south to a north pole of the field magnet, and through a similar set of *negative* values while the coil is passing from a north to a south pole. The complete set of values, including positive and negative is called a *cycle*.

Frequency. Frequency is equal to the number of cycles per second; it is sometimes expressed by stating the number of alternations or reversals per minute. For example, an alternator having a frequency of 133 cycles per second has 266 reversals or alternations per second, or 15,960 alternations per minute. Frequencies are sometimes specified in alternations per minute, but specification in cycles per second is the more usual practice and is preferable.

$$\text{cycles per sec.} = \frac{\text{alternations per min.}}{2 \times 60}$$

Period. The fractional part of a second occupied by one cycle is called the periodic time, or period, of the alternating electromotive force or current.

Let f be the frequency in cycles per second, and T the period expressed as a fraction of a second. Then

$$f = \frac{1}{T} \quad (1)$$

Therefore, if an alternating current has a frequency of 60 cycles per second, the period T of one cycle is one-sixtieth of a second.

Relations Between Speed and Frequency. Let p be the number of poles of the field magnet of an alternating-current machine; let n be the speed of its armature in revolutions per minute; and let f be the frequency of its electromotive force in cycles per second. Then

$$f = \frac{p}{2} \times \frac{n}{60} \quad (2)$$

Examples. 1. A certain alternator has 10 poles, and runs at 1,500 revolutions per minute. What is its frequency?

SOLUTION. Substituting 10 for p , and 1,500 for n , in equation (2), we have

$$f = \frac{10}{2} \times \frac{1500}{60} = 125 \text{ cycles per second}$$

2. An alternator is to run at 600 revolutions per minute and is to give a frequency of 60 cycles per second. What number of poles is required?

SOLUTION. Solving equation (2) for p , we have

$$p = \frac{2 \times 60 \times f}{n}$$

from which, substituting $f=60$, and $n=600$, we have

$$p = \frac{2 \times 60 \times 60}{600} = 12 \text{ poles}$$

Advantages and Disadvantages of Alternating Currents. The electric transmission of a given amount of power may be accomplished by a large current at low electromotive force, or by a small current at high electromotive force. In the first case very large and expensive transmission wires must be used, or the loss of power in the transmission line will be excessive. In the second case comparatively small and inexpensive transmission wires may be used. Thus it is a practical necessity to employ high electromotive forces in long-distance transmission of power.

Example. It is desired to transmit 1,000 kilowatts of power over a distance of 10 miles, supposing that a loss in the line of 10 per cent of the power delivered is considered permissible. This corresponds to a loss of 100 kilowatts.

SOLUTION.—Case 1. Suppose that the electromotive force at the receiving end of the line is to be 100 volts. Then the current would be 1,000,000 watts divided by 100 volts, or 10,000 amperes. The resistance of the line must be such that the watts lost in the line—namely 100,000 watts—would be equal to I^2R , so that the resistance R of the line must be $\frac{W}{I^2}$, or 0.001 ohm.

This would require two transmission wires each 10 miles long and 33 inches in diameter, or a total weight of 175,000 tons of copper, which would cost about \$52,500,000.

Case 2. Suppose that the electromotive force at the receiving end of the line is to be 1,000 volts. Then the current would be 1,000,000 watts divided by 1,000 volts, or 1,000 amperes. The resistance of the line must be such that the watts lost in the line—namely, 100,000 watts—would be equal to I^2R , so that the resistance R of the line must be 0.1 ohm. This would require two transmission wires, each 10 miles long and 3.3 inches in diameter, or a total weight of 1,750 tons of copper, which would cost about \$525,000.

TABLE I
Size and Cost of Copper Wire—Two-Wire System

To transmit 1,000 kilowatts a distance of 10 miles (one way) with a line loss equal to 10 per cent of the power delivered, for three different values of electromotive force

Volts at Receiving End of Line E	Amperes in Line I	Ohms in Line R	Diameter of Wire, in Inches	Weight of Wire, in Tons	Cost of Line Copper, in Dollars
100	10,000	0.001	33	175,000	52,500,000
1,000	1,000	0.1	3.3	1,750	525,000
10,000	100	10.0	0.33	17.5	5,250

Case 3. Suppose that the electromotive force at the receiving end of the line is to be 10,000 volts. Then the current would be 1,000,000 watts divided by 10,000 volts, or 100 amperes. The resistance of the line must be such that the watts lost in the line—namely 100,000 watts—would be equal to I^2R , so that the resistance R of the line must be 10 ohms. This would require two transmission wires, each 10 miles long and 0.33 inch in diameter, or a total weight of 17.5 tons of copper, which would cost about \$5,250.

These results are summarized in Table I.

Transformation of High E. M. F.'s. High electromotive forces are dangerous under the conditions that ordinarily obtain among users of electric light and power; and many types of apparatus, such as incandescent lamps, operate satisfactorily only with medium or low electromotive forces. Therefore, means must be provided, at a receiving station, for transforming the power delivered, from high electromotive force and small current to low electromotive force and large current, if long-distance transmission is to be successful. This is called *step-down transformation*. The advantage of the alternating current over the direct current lies almost wholly in the cheapness of construction and of operation, and in the high efficiency of the alternating-current apparatus as compared with the direct-current apparatus that is required for transformation.

In step-down transformation of direct current, a motor takes a small current from the high-electromotive-force transmission mains, and drives a dynamo which delivers large current to service mains at low electromotive force. This apparatus, or its equivalent, the *dynamotor*, is expensive to construct; it requires attention in operation; and its efficiency is never, perhaps, above 90 per cent.

The step-down transformation of alternating currents is accomplished by means of the *alternating-current transformer*, which is described later on. The alternating-current transformer is very much cheaper than a dynamo and motor of the same output; it requires no attention in operation; and its efficiency under full load is usually greater than 97 per cent, especially in large sizes.

Simple Construction of A. C. Machines. The alternating current has some minor advantages over the direct current on account of the fact that alternating-current machines are frequently simpler in construction than direct-current machines. In particular, the commutator is not an essential part of an alternating-current generator. Again, in the case of the inductor alternator and the induction motor, the rotating part may not have any sliding electrical contacts whatever.

Miscellaneous A. C. Machines. The simple *single-phase* alternating current is not well adapted to general power service. The single-phase alternating-current induction motor does not start satisfactorily under load, in the case of large machines, although self-starting single-phase motors up to perhaps 20 horse-power are in commercial use, where neither direct-current nor polyphase alternating-current machines are available.

The single-phase series commutator motor within a few years has been developed especially for electric railway service both for trolley cars and for electric locomotives. Its operating characteristics, resembling closely those of the direct-current series motor, however, are not suitable for general power requirements. This type of motor is used on the electric locomotives of the New York, New Haven and Hartford Railroad.

For uninterrupted service the *synchronous motor* is frequently used, the starting being effected by an auxiliary engine or other independent mover. The synchronous motor is not satisfactory when frequent starting is necessary, for such service the *induction motor* being used. The simple induction motor, to start satisfactorily, must be supplied with two or more distinct alternating currents transmitted to the motor over separate lines. This is called the *polyphase* system of transmission, and is reserved for full treatment in later pages.

For some purposes, especially for the electrolytic processes

used on a large scale in electro-chemical works, only direct current can be used. When power transmitted by alternating current is to be delivered in the form of direct current, the conversion is effected by means of the *rotary converter*, *motor generator*, or *mercury rectifier*.

Comparison of Direct- and Alternating-Current Problems.

Direct Current. In direct-current work the electrical engineer is concerned with the relations between electromotive force, resistance, current, and power. These relations are determined by the applications of the following laws:

POWER LAW for direct-current circuits

$$P = EI \quad (3)$$

in which P is the total power in watts delivered to a circuit by a generator of which the terminal electromotive force is E volts, when it produces a current of I amperes.

OHM'S LAW for direct-current circuits

$$I = \frac{E}{R} \quad (4)$$

in which I amperes is the steady current produced by E volts acting on a circuit of R ohms resistance.

JOULE'S LAW for direct-current circuits

$$P = I^2 R \quad (5)$$

in which P is the power in watts expended in heating a circuit of R ohms resistance, when a current of I amperes is forced through the circuit.

KIRCHHOFF'S LAWS for direct-current circuits.

1. When a circuit branches, the current in the main circuit is equal to the sum of the currents in the separate branches.

2. (a) When two or more sources of electromotive force are connected in series, the total electromotive force is the sum of the individual electromotive forces.

3. (b) When an electromotive force acts on a number of elements or things in series, it is subdivided into parts, each of which acts upon one of the elements, and the sum of these parts is equal to the total electromotive force. For example, an arc-light dynamo of which the terminal electromotive force is 3,000 volts,

acts on 60 similar arc lamps connected in series. Neglecting the resistance of the connecting wires, each lamp is acted upon by one-sixtieth of the total electromotive force, or by 50 volts.

Alternating Current. In alternating-current work the electrical engineer is likewise concerned with the relations between electromotive force, resistance, current, and power. These relations are determined by the application of the same fundamental laws as in the case of direct currents, but in more or less modified forms.* A summary of the fundamental laws of alternating currents is here given simply for purposes of comparison.

POWER LAW for alternating-current circuits

$$P = EI \cos \theta \quad (6)$$

in which P is the power in watts delivered to a circuit by an alternator of which the "effective" terminal electromotive force is E volts, when it produces an "effective" current of I amperes in a circuit, and $\cos \theta$ is what is called the "power factor" of the circuit.

OHM'S LAW for alternating-current circuits

$$I = \frac{E}{\sqrt{R^2 + X^2}} \quad (7)$$

in which I is the "effective" current in amperes produced by an "effective" electromotive force of E volts acting on a circuit of which the resistance is R ohms, and the "reactance" is X ohms. The expression $\sqrt{R^2 + X^2}$ in equation (7) is called the *impedance*, and it is expressed in ohms.

JOULE'S LAW for alternating-current circuits

$$P = I^2 R \quad (5)$$

in which P is the power in watts expended in heating a circuit of R ohms resistance when an "effective" alternating current of I amperes is forced through the circuit.

KIRCHOFF'S LAWS for alternating-current circuits

1. When an alternating-current circuit branches, the "effective" current in the main circuit is the "geometric"† (or "vector") sum of the "effective" currents in the separate branches.

*The student is not expected to understand fully the reasons for the statements here given, until he has completed Parts I and II.

†Alternating electromotive forces and alternating currents are added in the same way that forces are added, that is, by means of the principle known as the "parallelogram of forces."

Example. An alternator A , Fig. 2, supplies an effective current of I amperes in the main circuit, which divides into two branches. The effective currents in the two branches are I_1 and I_2 amperes, respectively. The relation between I , I_1 , and I_2 is shown in Fig. 3. The angles θ_1 and θ_2 depend




Fig. 2. Diagram of a Branched Alternating Circuit




Fig. 3. Vector Diagram of Branched Circuit

upon the relative values of the resistance and reactance of the respective branches, as is explained later. It is to be particularly noticed that the arithmetical sum of I_1 and I_2 is in general greater than I .

2. (a) When two or more alternators (or transformer secondaries) are connected in series, the total effective electromotive force is the “geometric” (or “vector”) sum of the effective electromotive forces of the individual alternators.




Fig. 4. Two Alternators in Series




Fig. 5. Vector Diagram of E. M. F.s for Two Alternators in Series

Example. Two alternators A_1 and A_2 , Fig. 4, of which the effective electromotive forces are E_1 and E_2 , respectively, are connected in series to supply mains. Then the effective electromotive force E , between mains, is the geometric sum of E_1 and E_2 , as shown in Fig. 5. The angle θ depends upon the positions, relatively to the field magnets, of the armature coils on the respective machines.

(b) When an alternating electromotive force E acts upon a number of elements or things in series, it is subdivided into parts, each of which acts upon one of the elements, and the "geometric" (or "vector") sum of these parts is equal to E .

Example. Two coils b and c , Fig. 6, are connected in series between mains supplied from an alternator, of which the effective electromotive force is E . Then the total effective electromotive force E is subdivided into two parts E_1 and E_2 , which act upon the respective coils, as indicated in Fig. 6; and the "geometric," or "vector" sum of E_1 and E_2 is equal to E , as shown in Fig. 7. The angles θ_1 and θ_2 depend upon the relative resistance and reactance of the respective coils. It is to be particularly noticed that the arithmetical sum of E_1 and E_2 is in general greater than E .

Physical Basis for the Differences between D. C. and A. C. Calculations. The above mentioned differences between direct-current and alternating-current calculations are due to the fact that an alternating current changes rapidly in value from instant to instant, while a direct current is steady and does not change its




Fig. 6. Alternating Current Through Two Coils in Series




Fig. 7. Vector Diagram of E. M. F. for Conditions Shown in Fig. 6.

direction of flow. A clear idea of the efforts of the rapid changes of an alternating current may be obtained as follows:

Fig. 8 represents an alternator producing alternating current in a circuit of wire; and Fig. 9 represents a valveless pump, of which the piston oscillates rapidly up and down, producing an alternating current of water in a circuit of pipe. The electromotive force of the alternator A not only has to overcome the resistance of the wire in order to cause an alternating current to surge back and forth through the circuit, but it also has to overcome the electrical inertia of the circuit—*first*, in getting a pulse of current started; and *second*, in stopping this pulse of current and starting another in the reverse direction. The pressure developed by the pump P not only has to

overcome the frictional resistance of the pipe in order to cause an alternating current of water to surge back and forth through the pipe, but it also has to overcome the inertia of the water in the pipe




Fig. 8. Simple Alternating Circuit




Fig. 9. Water Analogy for an Alternating Circuit

—*first*, in getting a pulse of water current started; and *second*, in stopping this pulse of water current and starting another in the reverse direction.

Fig. 10 represents an alternator producing alternating current in a circuit of wire which contains a condenser *C*; and Fig. 11 represents a valveless pump producing an alternating current of water in a circuit of pipe, which leads to a chamber *HH*, across which is stretched an elastic diaphragm *DD*. In this case the pressure developed by the pump has to overcome the frictional resistance of the pipe, the inertia of the water, and the elastic reaction of the diaphragm *DD*. Similarly the alternating electromotive force of




Fig. 10. Alternating Circuit Containing Condenser




Fig. 11. Water Analogy for Alternating Circuit with Condenser

the alternator *A*, Fig. 10, has to overcome the electrical resistance of the wire, the electrical inertia of the wire circuit, and the electro-elastic reaction of the insulating material, or dielectric, between the plates of the condenser.

The electrical inertia of a circuit is called its *inductance* and the electro-elasticity of a condenser is called its *capacity*, and it is to inductance and capacity that the peculiar features of alternating-current calculations are due.

The effect of capacity is strikingly shown by the fact that an alternating current may be made to flow through a circuit which for direct currents would be an open circuit like that shown in Fig. 10. Thus an alternator connected to long transmission lines, which are disconnected at the distant end and perfectly insulated from the ground, will send a considerable alternating current into the lines, which current can be measured by an alternating-current ammeter. In such a case the current is called the *charging current* of the line;




Fig. 12. Development of Three Field Magnet Poles and E. M. F. Curve for One Cycle

and it may amount to several amperes, according to the length of the line, the distance apart and size of wires, and the electromotive force of the alternator.

Graphical Representation of Alternating Electromotive Forces and Currents. When an armature conductor of an alternator approaches a *north* pole of the field magnet, the electromotive force of the machine rises in value as the conductor enters the strong field under the pole; and the electromotive force falls in value as the conductor passes from under the pole. As the conductor passes the point midway between two adjacent poles, the electromotive force of the machine falls to zero, since no lines of the force are cut

at this point. As the armature continues to revolve and the conductor approaches the next (the *south*) pole of the field magnet, the electromotive force of the machine again increases in value, but in a direction opposite to that of the previous electromotive force; and it falls again to zero as the conductor passes from under the south pole and reaches the point midway between the next pair of poles.

In Fig. 12 are represented the development of three successive poles *S*, *N*, *S* of the field magnet of an alternator, from which the lines of magnetic flux are emanating, and spreading out more or less as they enter the armature core. The armature core, also a developed view, is shown as having only one slot *A*, which contains a number of armature conductors. The ordinates of the curve *E E E E E* represent the successive instantaneous values of the electromotive force induced in the armature conductors as the slot moves from left to right.

The duration of one cycle is indicated in the figure, and this cycle repeats itself as the conductors pass by successive *pairs* of field poles. Thus, in a ten-pole alternator, there would be five complete cycles, or five complete waves of the electromotive curve for each revolution. When a wave

repeats itself after a definite time interval, it is called a *periodic wave*.

The curve *E E E E E* is called the *electromotive curve* or *electromotive force wave* of the alternator.

A curve of which the ordinates represent the successive instantaneous values of the alternating current and of which the abscissas represent time, is called an *alternating-current curve* or *alternating-current wave*.

Figs. 13, 14, and 15 show typical forms of electromotive force curves given by commercial alternators. Fig. 13 shows what is called a "peaked" wave; Fig. 14 shows a "flat-topped" wave; and Fig. 15 shows a "sine" or "sinusoidal" wave. All three waves are of




Fig. 13. Typical E. M. F. Curve for Alternator—
"Peaked" Wave

course periodic. The exact shape of the electromotive force wave given by an alternator depends upon the relations between pole pitch (distance from center to center of adjacent poles), width, and




Fig. 14. Typical E. M. F. Curve for Alternator—
"Flat Topped" Wave

shape of pole faces, width of armature coils, and distribution of coils on the armature. Alternators which give electromotive force waves approximating a sine wave, are preferred for power transmission.

Average and Effective Values of E. M. F. The average value of an alternating electromotive force or current *during a complete cycle* is zero, inasmuch as similar sets of positive and negative values occur.

The average value of an electromotive force or current *during the positive (or negative) part of a cycle* is usually spoken of briefly as the "average value" or "mean value," and is not zero.

Consider now an alternating current, of which the instantaneous value is i . The rate at which heat is generated in a circuit through which the current flows is i^2R , where R is the resistance of the circuit; and the *average* rate at which heat is generated in the circuit is R multiplied by the *average* value of i^2 .

A continuous current which would produce the same heating effect would be one of which the square is equal to the average value of i^2 , or of which the actual value is equal to $\sqrt{\text{average } i^2}$. This square root of the average square of an alternating current is called the *effective value* of the alternating current. Similarly, the square




Fig. 15. Typical E. M. F. Curve for Alternator —
"Sine" Wave

root of the average square of an alternating electromotive force is called the *effective value* of the alternating electromotive force.

Voltmeters and ammeters used for measuring alternating electromotive force or current always give effective values irrespective of wave form; and in specifying an alternating electromotive force or current, its effective value is always used.

Example. Ten successive instantaneous values of an alternating electromotive force during half a cycle are 0, 30, 60, 80, 90, 95, 90, 80, 60, and 30 volts. The sum of these values is 615 volts, which, divided by the number of values, namely ten, gives 61.5 volts, which is the average value of this electromotive force during half a cycle.

Squaring each of the above values, adding the squares together, and dividing their sum by their number, namely ten, gives the average value of the square of the electromotive force, which is 4,702.5 volts²; and the square root of this average square is 68.57 volts, which is the effective value of the given electromotive force.

Form Factor. The ratio *effective value* ÷ *average value*, depends upon the shape of the electromotive force wave, and is called the "form factor" of the wave.

Example. The form factor in the above case is $\frac{68.57}{61.5}$, or 1.115. The form factor of the electromotive force curve given in Fig. 15, which is a sine wave, is 1.11. The more peaked the wave the greater the value of its form factor. The rectangular electromotive force shown in Fig. 16 has a form factor equal to unity, which is the least possible value of the form factor. This rectangular wave, however, is never realized in commercial alternators.

Instantaneous and Average Power. Let e be the value, at a given instant, of the electromotive force of an alternator and let i be the value of the current at the same instant. Then ei is the power in watts which is delivered by the alternator at the given instant; and the average value of ei during a complete cycle is the average power delivered by the alternator.




Fig. 17. E. M. F., Current, and Power Curves for an Alternator in a Circuit Containing Inductance

In Fig. 17 the full-line curve represents the electromotive force of an alternator and the heavy-dotted curve represents the current delivered by the alternator to a receiving circuit having

inductance, such as an induction motor, for instance. The ordinates of the light-dotted curve represent the successive instantaneous values of the power ei . As shown in the figure, the power has both




Fig. 18. E. M. F., Current, and Power Curves for Alternating Circuit with Large Inductance

positive and negative values; the alternator does work on the circuit when ei is positive, or is above the horizontal axis of time; and the circuit returns power to the alternator when ei is negative, or is below the horizontal axis of time; and this means of course, that while ei is negative, the dynamo is momentarily a motor and will be for the moment returning power to the fly wheel of the driving engine or turbine.

When the inductance of the receiving circuit is very large, the electromotive force and current curves are related as shown in Fig. 18; the instantaneous power ei passes through approximately similar sets of positive and negative values, as shown by the light-dotted curve; and the average power is approximately zero. This case would be very closely exemplified by an alternator connected to a transformer whose secondary was open-circuited, that is, supplying no current.





Fig. 19. Diagram of Harmonic E. M. F.s

considered positive when above O and negative when below O .

Harmonic Electromotive Forces and Currents. A line OP , Fig. 19, revolves, at a uniform rate, f revolutions per second about a point O , in the direction of the arrow gh . Since the length of OP is fixed, the path or locus of the point P will be a circle about O as a center. Consider the projection Ob of this rotating line upon the fixed line AB , this projection being



INTERIOR OF GENERATING STATION, COMMONWEALTH POWER CO.
Courtesy of Allis-Chalmers Company, Milwaukee, Wis.

A harmonic electromotive force (or current) is an electromotive force (or current) which is at each instant proportional to the line Ob .

The line Ob represents at each instant the actual value e of the harmonic electromotive force to a definite scale, and the length of the line OP , which is the maximum length of Ob , represents the maximum value E of the harmonic electromotive force to the same scale. The line Ob passes through a complete cycle of values during one revolution of OP , and so also does the harmonic electromotive force e . Therefore, the revolutions per second f of the line OP is the frequency of the harmonic electromotive force e . The rotating lines E and I , Fig. 20, of which the projections on a fixed line (not shown in the figure) represent the actual instantaneous values e and i of a harmonic electromotive force and a harmonic current, are said to "represent" the harmonic electromotive force and current, respectively. Of course, the rotation of the lines E and I is a thing merely to be imagined. The rotation is understood to be in a counter-clockwise direction, as indicated in Fig. 19.

Clock Diagram Representation. A diagram in which a number of electromotive forces or currents, or both, are represented by lines imagined to be revolving, is called a *clock diagram*. Simple problems involving relations between a number of *harmonic* electromotive forces and currents of the *same frequency*, are most easily treated by means of the clock diagram. The proper representation of alternating electromotive forces and currents in a clock diagram, requires that




Fig. 20. Clock Diagram

- (a) The given electromotive forces and currents be harmonic, and be of the same frequency.
- (b) The lengths of the lines represent their maximum value to a suitable scale although the scales chosen for volts and for amperes may be different.
- (c) The direction of the electromotive forces and currents be indicated by arrow heads.
- (d) The relative position or phase of the electromotive forces and currents be constant and indicated by the angle between the various lines representing the given quantities.

When an electromotive force (or current) wave is not a sine curve, the electromotive force (or current) is not harmonic, and can-

not properly be represented by a line in a clock diagram, because the projection of the rotating line is not at each instant proportional to the electromotive force (or current). The *approximate* represen-




Fig. 21. Method of Plotting Sine E. M. F. Curve

tation, by lines in a clock diagram, of non-harmonic electromotive forces (or currents)—such, for example, as those represented by the curves in Figs. 13, 14, and 16, depends upon the finding of harmonic electromotive forces (or currents) which for the particular purpose in view are approximately equivalent to the actual given electromotive forces (or currents).

Graphical Representation. A harmonic electromotive force or current is represented by a sine wave as shown in Fig. 15. The relation between the rotating line OP in Fig. 19 and the sine-wave curve of electromotive force is shown as follows:




Fig. 22. Simple Dynamo Diagram

Divide the circumference of the circle in Fig. 21 into equal parts, and lay off a horizontal line divided into the same number of equal parts.

Draw horizontal dotted lines through each division on the circumference of the circle, and vertical dotted lines through the corresponding divisions on the horizontal line. The points of the intersection of these pairs of dotted lines are points on a curve which is a curve of sines.

A flat loop of wire with its terminals connected to two collecting rings gives a harmonic electromotive force when it is rotated at constant speed in a uniform magnetic field. This arrangement is shown in Fig. 22.

Algebraic Representation. The line OP , Fig. 19, revolves uniformly f revolutions per second and, therefore, it turns through $2\pi f$ radians* per second, since there are 2π radians in a revolution; that is

$$\omega = 2\pi f \tag{8}$$

in which ω is the angular velocity of the line OP in radians per second. Let time be reckoned from the instant that OP coincides with Oa ; then, after t seconds, OP will have turned through the angle $\beta (= \omega t)$; and from Fig. 19 we have

$$Ob = OP \sin \beta = OP \sin \omega t$$

since Ob is the projection of OP on the line AB . But Ob represents the actual value e of the harmonic electromotive force at the time t , and OP represents its maximum value E ; therefore

$$e = E \sin \omega t \tag{9}$$

is an algebraic expression for the actual value e of a harmonic electromotive force at time t , E being the maximum value of e , and $\frac{\omega}{2\pi}$ being the frequency according to equation (8).

Similarly

$$i = I \sin \omega t \tag{10}$$

is an algebraic expression for the actual value i of a harmonic current at time t , I being the maximum value of i .

If time is reckoned from the instant that OP , Fig. 19, coincides with the line Ob , then equations (9) and (10) become

$$\begin{aligned} e &= E \cos \omega t \\ i &= I \cos \omega t \end{aligned}$$

Synchronism. Two alternating electromotive forces or currents are said to be in synchronism when they have the same frequency. Two alternators are said to run in synchronism when their electromotive forces and frequencies are similar.

Phase Difference. Consider two harmonic electromotive forces represented by the ordinates of the curves E_1 and E_2 , Fig. 23. The electromotive force represented by the curve E_1 reaches its maximum value *before* the electromotive force represented by the curve E_2 . The electromotive force E_1 is said to *lead*, or to be ahead of, the

*The unit of angle chiefly used in mechanics and in all theoretical work is the *radian*. It is the angle of which the arc is numerically equal to the radius (of a circle). There are, therefore, 2π radians in one circumference.

electromotive force E_2 in phase. Conversely, the electromotive force E_2 is said to lag behind or to follow the electromotive force E_1 in phase. The same two




Fig. 23. Curves of Two Related E. M. F.s

electromotive forces E_1 and E_2 are also represented by the lines OE_1 and OE_2 in the clock diagram, Fig. 24. Here the line OE_2 is behind OE_1 , since the imagined rotation about O as a center is counter-clockwise.

The *phase difference* is the time interval θ in Fig. 23, or the angle θ between OE_1 and OE_2 in Fig. 24. If according to equation (9) the actual value of the harmonic electromotive force E_1 is $e_1 = E_1 \sin \omega t$, then the actual value of the electromotive force E_2 , which lags θ degrees behind E_1 , is $e_2 = E_2 \sin (\omega t - \theta)$. Similarly, if E_2 were taken as the reference line in the diagram, its actual value would be $e_2 = E_2 \sin \omega t$, and the value of E_1 would then be $e_1 = E_1 \sin (\omega t + \theta)$.

When the angle θ , Fig. 24, is zero, as shown in Fig. 25, the electromotive forces E_1 and E_2 are said to be *in phase*. In this case the electromotive forces increase together and decrease together;




Fig. 24. Clock Diagram of E. M. F.s for Fig. 23




Fig. 25. Clock Diagram for Curves in Fig. 23 with E. M. F.s in Phase

that is, when E_1 is zero, E_2 is also zero; and when E_1 is at its maximum value, so also is E_2 , etc. Therefore, $e_1 = E_1 \sin \omega t$ and $e_2 = E_2 \sin \omega t$.

When $\theta = 90^\circ$, as shown in Fig. 26, the two electromotive forces are said to be *in quadrature*. In this case one electromotive force is zero when the other is a maximum, etc., or $e_1 = E_1 \sin \omega t$ and $e_2 = E_2 \sin (\omega t - \frac{\pi}{2})$.

When $\theta = 180^\circ$, as shown in Fig. 27, the two electromotive forces are said to be *in opposition*. In this case they are at each instant opposite in sign; and when one is at its positive maximum, the other is at its negative maximum, etc. In this case $e_1 = E_1 \sin \omega t$ and $e_2 = E_2 \sin (\omega t \pm \pi)$. It is to be particularly noted that the principle of phase difference which has been illustrated in Figs. 22-25 for the case of two harmonic electromotive forces E_1 and E_2 , applies equally to the case of two harmonic currents I_1 and I_2 and to the case of an electromotive force E_1 and a current I_1 . Thus if in the clock diagram, Fig. 20, E represented a harmonic electromotive force having a maximum value of 1,000 volts, and I represented a harmonic current having a maximum value of 10 amperes with a phase difference of $\theta = 30^\circ$ between them, the instantaneous values of E and




Fig. 26. Diagram of E. M. F.s of Fig. 23 in Quadrature

I would be

$$e = 1000 \sin \omega t$$

$$i = 10 \sin \left(\omega t - \frac{\pi}{6} \right)$$




Fig. 27. Diagram of E. M. F.s of Fig. 23 When in Opposition

Addition of Harmonic Electromotive Forces and Currents. Consider two harmonic electromotive forces of which the

successive instantaneous values e_1 and e_2 are represented by the projections of the lines E_1 and E_2 , Fig. 28, which are imagined to be revolving about the point O . These electromotive forces being of the same frequency, the lines E_1 and E_2 revolve at the same speed, so that the angle between E_1 and E_2 remains unchanged in value. The ordinary arithmetical sum of e_1 and e_2 , namely $e_1 + e_2$, is a harmonic electromotive force of the same frequency as e_1 and e_2 ; and this electromotive force ($e_1 + e_2$) is represented by the projection of the line E , Fig. 28, which revolves at the same speed as E_1 and E_2 .




Fig. 28. Vector Diagram Showing Two Harmonic E. M. F.s

This is evident when we consider that the projection, on any line, of the diagonal of a parallelogram is equal to the sum of the

projections of two adjacent sides of the parallelogram, as shown in Fig. 29. The projection of E_1 is Oc , which represents e_1 ; and the




Fig. 29. Diagram Showing Addition of Harmonic E. M. F.s

projection of E_2 is equal to cd , which represents e_2 . The projection of the diagonal Ob of the parallelogram is Od , which is the sum of Oc and cd . The two lines marked E_2 in Fig. 29 are equal and parallel and have, therefore, the same projected length on the vertical line.

As a *corollary* to the above, it may be stated that the ordinary arithmetical sum ($e_1 + e_2 + e_3 +$ etc.) of the instantaneous values

of any number of harmonic electromotive forces (or currents) is another harmonic electromotive force (or current) of the same frequency; it is represented in magnitude and phase by a line that is the geometric (or vector) sum of the lines representing the given individual electromotive forces (or currents). This is evident when we consider that $e_1 + e_2$ is a harmonic electromotive force (or current) according to the above discussion; and this, added to e_3 , gives an electromotive force (or current) which is harmonic and of the same

frequency as e_1, e_2 , and e_3 .




Fig. 30. Addition of E. M. F.s by Vector Polygon

The *geometric, or vector, sum* of a number of lines is obtained as follows: Given three lines OE_1, OE_2 , and OE_3 , Fig. 30. Find the diagonal OA of the parallelogram constructed on OE_1 and OE_2 as sides. This gives the vector sum of OE_1 and OE_2 . Next construct a parallelogram on OA and OE_2 as sides; the diagonal OE of this parallelogram is the vector sum of the three given lines. This line OE is the closing

side of the polygon formed by drawing OE_1 , then drawing OE_2 from the extremity of OE_1 (this giving the point A), and then drawing OE_3 from A . This method is called *addition by means of the vector polygon*.

For example, two alternators A and B running in synchronism

are connected *in series* between mains as shown in Fig. 31. If the electromotive forces of *A* and *B* are in phase, the electromotive force between the mains will be simply the numerical sum of the electromotive forces of *A* and *B*. If, on the other hand, the electromotive forces of *A* and *B* differ in phase, the state of affairs will be as represented in Fig. 32, in which the lines *A* and *B* represent the




Fig. 31. Two Alternators Running in Synchronism




Fig. 32. Vector Diagram of Conditions in Fig. 31 if E. M. F.s Differ in Phase

electromotive forces of the alternators *A* and *B*, respectively, θ is the phase difference of *A* and *B*, and the line *E* represents the electromotive force between the mains. The line *E* is the vector sum or resultant of *A* and *B*, and as shown is the diagonal of a parallelogram constructed on *A* and *B* as sides.

Again, alternators *A* and *B* running in synchronism are connected *in parallel* between the mains as shown in Fig. 33. Let the lines *A* and *B*, Fig. 34, represent the currents given by the alternators *A* and *B*, respectively, the phase difference between the currents being θ ; then the current in the main line is represented by *I*.

Consider the case of two circuits *A* and *B*, Fig. 35, connected *in*




Fig. 33. Two Alternators Running in Synchronism Connected in Parallel




Fig. 34. Vector Diagram of Currents for the Condition of Fig. 33

series between the mains of an alternator. The line *E*, Fig. 36, represents the electromotive force between the mains; the line *A*

represents the electromotive force between the terminals of the circuit A ; and the line B represents the electromotive force between the terminals of the circuit B . The circuits A and B are




Fig. 35. Diagram of Two Coils in Series with an Alternator




Fig. 36. Diagram of E. M. F.s for Conditions Shown in Fig. 35

supposed to have inductance. If either of the circuits contains a condenser, then the electromotive forces A and B , Fig. 36, may be nearly opposite to each other in phase, and A and B may each be indefinitely greater than the electromotive force E between the mains.

Again, two circuits A and B , Fig. 37, are connected *in parallel* across the terminals of an alternator as shown. The current I from the alternator is related to the currents A and B as shown in Fig. 38. If either of the circuits A or B contains a condenser, then the currents A and B may be nearly opposite to each other in phase, and the currents A and B may each be indefinitely greater than the current I from the alternator.




Fig. 37. Coils in Parallel with an Alternator

Subtraction of Harmonic Electromotive Forces and Currents. One harmonic electromotive force (or current) is subtracted from another by reversing the direction of the line that represents it in the clock diagram, and then *adding* the reversed line (or vector) to the other. An example of the subtraction of harmonic electromotive forces will be given in connection with the discussion of three-phase electromotive force.

Relation between Maximum and Effective Values. The effective value E or I of a harmonic, electromotive force, or current—that is,

one whose graph is a sine wave—is equal to the maximum value E or I divided by the square root of 2. That is

$$E = \frac{E}{\sqrt{2}} \quad (11)$$

$$I = \frac{I}{\sqrt{2}} \quad (12)$$

This may be shown as follows: Let e ($=E \sin \omega t$) be a harmonic electromotive force. To find the average value of e^2 ($=E^2 \sin^2 \omega t$), it is necessary to find the average value of the square of the sine of the uniformly variable angle ωt . We have the general relation

$$(a) \quad \sin^2 \omega t + \cos^2 \omega t = 1$$

so that

$$(b) \quad \text{Av.} \sin^2 \omega t + \text{Av.} \cos^2 \omega t = 1$$

Now, during a cycle, the cosine of a uniformly variable angle passes similarly through the same set of values as the sine; hence $\text{Av.} \sin^2 \omega t$ and $\text{Av.} \cos^2 \omega t$ are equal, so that from equation (b) above, we have

$$2 \text{Av.} \sin^2 \omega t = 1$$

or

$$\text{Av.} \sin^2 \omega t = \frac{1}{2}$$

The average value of e^2 is

$$\text{Av.} e^2 = E^2 \text{Av.} \sin^2 \omega t$$

or

$$\text{Av.} e^2 = \frac{E^2}{2}$$

and

$$\sqrt{\text{Av.} e^2} = \frac{E}{\sqrt{2}}$$

In Fig. 19 the length of the revolving line OP was understood to represent the *maximum value* of the harmonic electromotive force (or current). When, however, a number of harmonic electromotive forces (or currents) are represented to scale by lines in a clock diagram, the lengths of the lines may be interpreted as giving




Fig. 38. Current Diagram of the Conditions Shown in Fig. 37

not maximum but *effective values*, since there is a constant ratio $\sqrt{2}$ between the effective and the maximum values of each of the electromotive forces (or currents) represented in the diagram.

NOTE. It is desirable to interpret the lines in a clock diagram in terms of effective values rather than maximum values, because effective values are always given by measuring instruments and are nearly always used in numerical calculation. Therefore, unless it is expressly stated to the contrary, the lines in clock diagrams are always understood to represent effective values.

For example, a certain harmonic alternating current gives a reading of 100 amperes on an alternating-current ammeter, and its effective value is, therefore, 100 amperes. This harmonic current actually pulsates between zero and a maximum value of $\pm\sqrt{2} \times 100$ amperes, or ± 141.4 amperes.

Again, a certain harmonic alternating electromotive force gives a reading of 1,000 volts on an alternating-current voltmeter, and its effective value is, therefore, 1,000 volts. This electromotive force actually varies between zero and a maximum value of $\pm\sqrt{2} \times 1,000$ volts, or $\pm 1,414$ volts.

The above simple relation between maximum and effective values is true only for harmonic (that is, sine-wave) electromotive forces and currents. In general, the maximum values of alternating electromotive forces or currents cannot be inferred from effective values as measured by voltmeters or ammeters. Thus, an alternating electromotive force which is known to have a peaked-wave form might have a maximum value very greatly in excess of $\sqrt{2}$ times its effective value.

Expression for Power. (a) When the current is in phase with the electromotive force, that is, when the circuit is non-inductive, then the power (average *ei*, see page 15) is

$$P = EI \quad (13)$$

in which P is the power in watts, E is the effective value of the electromotive force in volts, and I is the effective value of the current in amperes. Equation (13) is identical with the power equation for direct-current circuits.

(b) If the phase difference between current and electromotive force in a given circuit were 90 degrees, which can never actually occur, then the power (average value of *ei*) would be equal to zero, as explained on page 16.

(c) When the phase difference between current and electromotive force is θ° , as shown in Fig. 39, then

$$P = EI \cos \theta \tag{14}$$

in which P is the power (average *ei*) in watts, E is the effective value of the electromotive force in volts, and I is the effective value of the current in amperes.

For example, the given current I shown in Fig. 39 may be thought of as resolved into two components, as shown in Fig. 40. One of these components $I \cos \theta$ is parallel to (that is, in phase with) E ; and the other $I \sin \theta$ is at right angles to E . The power corresponding to the actual current I may be thought of as the sum of the powers corresponding to its two components, respectively. But the component $I \sin \theta$ is at right angles to E , as in (b) above; hence the power corresponding to it is zero. This component is, therefore, frequently called the *wattless component* or better the *reactive component* of the given current.

On the other hand, the component $I \cos \theta$ is parallel to (that is, in phase with) E , as in (a) above; hence the power corresponding to this component is equal to $E \times I \cos \theta$. The component $I \cos \theta$ of the given current I is frequently called the *power component* of I ; and the factor $\cos \theta$ is called the *power factor* of the circuit.




Fig. 39. Diagram Showing Phase Difference Between E, M. F., and Current

Inductance. It has been pointed out, page 11, that an electric circuit has a certain kind of inertia analogous to the inertia of water in a circuit of pipe, and it was there noted that this inertia of an electric circuit is called inductance. If an electric current in a circuit is made to change in value, a portion of the electromotive force acting upon the circuit must be used to *cause* the current to change.

In the same way a force over and above that required to overcome frictional resistance must act upon a moving body to accelerate it, that is, to make its speed increase. The inertia of a body is measured by the force required to accelerate it at the rate of unit change in speed per second; and the inductance of a circuit is measured by the electromotive force required to cause a current in the circuit

to change at the rate of one ampere per second. A circuit is said to have an inductance of one *henry** when one volt (over and above the electromotive force required to overcome the electrical resistance) will cause the current to change at the rate of one ampere per second.

Let x be the rate in amperes per second at which the current in a circuit is increasing in value. Then the electromotive force E (over and above that required to overcome the resistance of the circuit) required to cause the current to increase at this rate is

$$E = Lx \quad (15)$$

in which L is the inductance of the circuit in henrys, E being expressed in volts.




Fig. 40. Resolution of the I of Fig. 39 into Two Components

Example. The coil of a certain large electromagnet has 2.5 henrys of inductance and 5 ohms of resistance. At a given instant this coil is connected to 110-volt direct-current mains. At the instant of connecting the coil, the current is zero, and all of the 110 volts is used to cause the current in the coil to increase, so that, according to equation (15), x is equal to $\frac{E}{L}$, or

110 volts \div 2.5 henrys, or 44 amperes per second. That is, the current in the magnet coil begins to increase at the rate of 44 amperes per second. When the

current in the magnet coil has reached the value of 10 amperes, 50 volts ($= 5 \text{ ohms} \times 10 \text{ amperes}$) of the total 110 volts are used in overcoming the resistance of the coil, so that 60 volts ($= 110 \text{ volts} - 50 \text{ volts}$) are used to make the current increase. Therefore, as the current in the coil passes the value

of 10 amperes, it is increasing at the rate $\frac{E}{L}$, or 60 volts \div 2.5 henrys, or 24 amperes per second.

The inductance of a coil wound on a given spool is proportional to the square of the number of turns N of wire. For example, a given spool wound with No. 16 wire has 500 turns and an inductance of, say, 0.0025 henry; the same spool wound with No. 28 wire would have about eight times as many turns, and its inductance would be about 64 times as great, or 0.16 henry.

*The henry is a very large inductance, and the inductances usually met with in practice are expressed in thousandths of a henry, that is, in milli-henrys.

The inductance of a coil of given shape is proportional to its linear dimensions, the number of turns of wire being unchanged. For example, a given coil has an inductance of 0.022 henry; and a coil three times as large in length, diameter, etc., but having the same number of turns of wire, has an inductance of 0.066 henry.

Formulas for Inductance. The inductance in henrys of a coil of wire wound in a thin layer on a long wooden cylinder of length l centimeters and of radius r centimeters, is

$$L = \frac{4\pi^2 r^2 N^2}{l \times 10^9} \quad (16)$$

in which N is the total number of turns of wire in the coil. This equation is strictly true for very long coils wound in a thin layer; but the equation is also very useful in calculating the approximate inductance of even short, thick coils. Thus, a coil 25 centimeters long and $2\frac{1}{2}$ centimeters mean radius, containing 150 turns of wire, has an approximate inductance of

$$L = \frac{4\pi^2 (2.5)^2 \times 150^2}{25 \times 10^9} = 0.00022 \text{ henry}$$

If a coil of N turns of wire is wound on a long rod of iron, instead of wood or other non-magnetic material, the inductance in henrys is given by the equation

$$L = \frac{4\pi^2 r^2 N^2 \mu}{l \times 10^9} \quad (17)$$

in which L , r , N , and l are the same as in equation (16), and μ is the permeability of the iron core at the particular flux density produced in the iron. This equation applies to any iron rod of length l centimeters and radius r centimeters, wound with N turns of wire, whether in the form of a long, straight rod or bent into a closed ring.

The permeability μ of iron varies from 500 to 1,000 or more; and, therefore, the effect* of placing an iron core in a coil is to increase greatly the inductance of the coil.

The iron core of an inductance coil to be used with alternating currents should be laminated to reduce eddy currents and the con-

*The permeability μ of a given sample of iron is not constant, but decreases in value as the magnetizing force increases. Therefore, the inductance L of a coil having an iron core is not a definite constant quantity as is the inductance of a coil without an iron core.

sequent loss of energy, and to prevent excessive heating of the core.

For example, the inductance of the field coil of a certain shunt-wound dynamo is 7.5 henrys. The inductance of a pair of No. 0, B. & S. copper line wires carried at a distance of 18 inches apart on a pole line is 0.0035 henry per mile. The inductance of the secondary coil of a large induction coil (X-ray coil) having 200,000 turns of wire, is 2,000 henrys.

Series and Parallel. The inductance of two or more coils in series is equal to the sum of the individual inductances.

The equivalent inductance of two or more similar coils in parallel, such as the similar coils on an armature, is equal to $\frac{1}{n}$ of the inductance of one coil, n being the number of coils connected in parallel.

Capacity. It has been pointed out, page 11, that a charged condenser has an elastic-like reaction analogous to the elastic reaction of a distorted diaphragm. The elasticity of a diaphragm might be measured by the pressure required to distort it to the extent of producing one unit of increase of volume in the space on one side of the diaphragm and one unit of decrease of volume in the space on the other side of the diaphragm. Similarly, the capacity of a condenser may be, and in fact is, measured by the electromotive force required to force one unit of charge of electricity into one plate of the condenser, and at the same time to withdraw one unit of charge from the other plate. A condenser is said to have a capacity of 1 *farad** when one volt of electromotive force pushes one coulomb of electric charge into the condenser.

The charge Q pushed into a condenser by a steady electromotive force E is

$$Q = CE \quad (18)$$

in which C is the capacity of the condenser in farads, Q is the charge in coulombs, and E is the electromotive force in volts. The electromotive force required to hold a given charge Q in the condenser is of course equal to $\frac{Q}{C}$.

Condensers, to have a large capacity (as much as a microfarad), are usually made up of alternate sheets of tinfoil and waxed paper,

*The farad is an exceedingly large capacity, and capacities encountered in practice are usually expressed in millionths of a farad, that is, in microfarads.

TABLE II
Inductivities of Dielectrics
Referred to Air as Unity

Glass	3.00 to 10.00	Mica	4.00 to 8.00
Vulcanite	2.50	Shellac	2.93 to 3.3
Paraffin	1.68 to 2.30	Turpentine	2.15 to 2.43
Beeswax	1.86	Petroleum	2.02 to 2.19
Gutta-percha	3.3 to 4.9	Rubber (pure India)	2.12 to 2.24

or mica, as indicated in Fig. 41. Alternate metal sheets are connected together giving two terminals as shown, thus practically forming two metallic plates of large area. A condenser having a capacity of 1 microfarad contains about 3,600 square inches of tinfoil.

Inductivity of Dielectric. The capacity of a condenser of given dimensions depends upon the material used between the plates, called the *dielectric*.

The quotient, capacity of a condenser with given dielectric \div its capacity with air as the dielectric, is called the *inductivity* or the *specific inductive capacity* of the given dielectric. The values of the inductivity for the most commonly used dielectrics are given in Table II.



Fig. 41. Diagram of Condenser

Capacity of Condensers. The capacity of a condenser is given by the equation

$$C = \frac{885 k A}{10^{10} d} \tag{19}$$

in which C is the capacity in microfarads, k is the inductivity of the dielectric used, d is the distance in centimeters between plates, *i. e.*, the thickness of the dielectric, and A is the area in square centimeters of both sides of all the inner plates plus the area of the inner surfaces of the two outside plates.

NOTE. If the total number of plates = n , A will be the area of both sides of $(n-1)$ plates; or, in other words, it is necessary to provide one more plate than is necessary, using both sides, to equal an area of A square centimeters.

Example. It is required to design a plate condenser to have a capacity of 1.5 microfarads using a dielectric of oiled paper 0.0043 inch thick and tinfoil 0.0007 inch thick.

Assuming for the oiled paper an inductivity of 2.67, equation (19) gives for the total active plate area

$$A = \frac{1.5 \times 10^{10} \times 0.0043 \times 2.54}{885 \times 2.67} = 69400 \text{ square centimeters} = 10759 \text{ square inches}$$

If 65 plates be used, the area of one side of each plate will be

$$\frac{10759}{2(65-1)} = 84 \text{ square inches}$$

so that the dimensions of one active plate may be $10\frac{1}{2}'' \times 8''$ and the area of tinfoil needed will be $84 \times 65 = 5460$ square inches.

The capacity of an ordinary 2-quart Leyden jar is about 0.005 microfarad. The capacity of an average submarine telegraph cable is about 0.4 microfarad per nautical mile. The capacity of a pair of transmission lines of No. 0, B. & S. wires placed 18 inches apart between centers on poles, is 0.036 microfarad per mile.

Series and Parallel. The capacity of a number of condensers *in parallel* is equal to the sum of the individual capacities.

The capacity of a number of condensers *in series* is

$$C = \frac{1}{\frac{1}{C_1} + \frac{1}{C_2} + \frac{1}{C_3} + \text{etc.}} \quad (20)$$

in which C_1, C_2, C_3 , etc., are the individual capacities, and C is the joint capacity.

Fundamental Equations of the A. C. Circuit. An alternator A , Fig. 42, delivers an alternating current of I amperes, effective, to





Fig. 42. Alternating Circuit Containing Resistance, Inductance, and Capacity

a circuit consisting of a resistance of R ohms, an inductance of L henrys, and a condenser of which the capacity is C farads, all connected in series. It is to be remembered that any coil having inductance has resistance also; that is, inductance and resistance are practically inseparable. Nevertheless inductance and resistance are essentially different in nature and in their effects, and they are always considered separately, so

that it is helpful to think of them as actually separated in a circuit, as indicated in Fig. 42. A resistance is conventionally represented thus, $\sim\sim\sim\sim\sim$; an inductance thus, $\sim\circ\circ\circ\circ\sim$; and a condenser thus, $\text{---} \parallel \text{---}$.



PLANT OF THE TIBBE ELECTRIC COMPANY, WASHINGTON, MO.
National Brake & Electric Co.

922C

The current in the circuit, Fig. 42, is assumed to be harmonic, that is, to be a sine-wave current, and this current is represented by the line OI in Fig. 43.

A portion of the electromotive force of the alternator is used to overcome the resistance of the circuit. The portion of the electromotive force so used is an alternating electromotive force of which the effective value is RI ; it is in phase with the current, and is represented by the line RI in Fig. 43.

A portion of the electromotive force of the alternator is used to overcome the inertia or inductance of the circuit in causing the current to increase and decrease. The portion of the electromotive force so used is an alternating electromotive force of which the effective value is ωLI ; it is 90 degrees ahead of I in phase, and is represented by the line ωLI in Fig. 43. The quantity ω is equal to 2π times the frequency of the current I .

A portion of the electromotive force of the alternator is used to overcome what we have previously called the electro-elasticity of the condenser, or, in other words, to hold electric charge on the condenser plates at each instant. The portion of the electromotive force so used is an alternating electromotive force of which the effective value is $\frac{I}{\omega C}$; it is 90 degrees behind I in phase, and is represented by the line $\frac{I}{\omega C}$ in Fig. 43.

The total electromotive force E of the alternator is equal to the geometric (or vector) sum of the parts RI , ωLI , and $\frac{I}{\omega C}$. This vector sum is formed by subtracting $\frac{I}{\omega C}$ from ωLI , since it is opposite to ωLI in direction, and then adding RI and $(\omega LI - \frac{I}{\omega C})$ geometrically, as shown in Fig. 44, in which the line Oa represents $(\omega LI - \frac{I}{\omega C})$,




Fig. 43. Vector Diagram of Conditions in Fig. 42

and the line E represents the geometric sum of Oa and RI .

From Fig. 44 we have, by geometry:

$$E^2 = R^2 I^2 + \left(\omega LI - \frac{I}{\omega C} \right)^2$$

or

$$E^2 = I^2 \left[R^2 + \left(\omega L - \frac{1}{\omega C} \right)^2 \right]$$

or

$$I = \frac{E}{\sqrt{R^2 + \left(\omega L - \frac{1}{\omega C} \right)^2}} \quad (21)$$

The quantity $\omega L - \frac{1}{\omega C}$ is called the *reactance* of the circuit. The term ωL is often called *inductance reactance*; and the term $\frac{1}{\omega C}$ is often called *capacity reactance*. Inductance reactance is always positive, and capacity reactance is always negative. It is convenient to represent the reactance $\omega L - \frac{1}{\omega C}$ of a circuit by the single letter X ; that is

$$X = \omega L - \frac{1}{\omega C} \quad (22)$$

Therefore, writing X for $\omega L - \frac{1}{\omega C}$ in equation 21, we have

$$I = \frac{E}{\sqrt{R^2 + X^2}} \quad (23)$$

Furthermore, from the right triangle in Fig. 44 we have

$$\tan \theta = \frac{\omega L - \frac{1}{\omega C}}{R}$$

or

$$\tan \theta = \frac{X}{R} \quad (24)$$

in which θ is the angle of phase lag of the current I behind the electromotive force E ; X is the reactance of the circuit; and R is the resistance of the circuit.

Resistance, Reactance, and Impedance. Consider a harmonic alternating electromotive force E which produces a harmonic alternating current I in a circuit.

This electromotive force may be resolved into two components, one parallel and the other perpendicular to I , as shown, for example, in Fig. 43. The component of E parallel to I is equal to RI .

The resistance of an alternating-current circuit is sometimes defined as *that factor which, multiplied by the current, gives the component (of the electromotive force) which is parallel to I .*




Fig. 44. Complete Diagram of Conditions in Fig. 42

The component of E perpendicular to I is equal to $\omega LI - \frac{I}{\omega C}$, or is equal to XI .

The reactance of an alternating-current circuit may be defined as *that factor which, multiplied by the current, gives the component (of the electromotive force) which is perpendicular to I .*

The factor $\sqrt{R^2 + X^2}$, which, when multiplied by the current I , gives the total value of the electromotive force E , is called the impedance (denoted by Z) of the alternating-current circuit. Of course, E divided by Z gives the value of the current I .

NOTE. Resistance, reactance, and impedance are all expressed in ohms; we may, for example, speak of 10 ohms of resistance, 10 ohms of reactance, or 10 ohms of impedance. Thus, ohms are used in alternating-current work to express the three essentially different things—resistance, reactance, and impedance; and a specification of a certain number of ohms is not intelligible unless it is stated whether it is ohms of resistance, ohms of reactance, or ohms of impedance.

The reactance and the impedance of a circuit depend upon the frequency of the alternating current, as well as upon the physical constants L and C of the circuit, since the factor ω is equal to 2π times the frequency.

The reactance of a circuit may be positive or negative, according as ωL is larger than or less than $\frac{1}{\omega C}$. When reactance is posi-

tive, the inductance reactance ωL exceeds the capacity reactance $\frac{1}{\omega C}$, and the current is behind the electromotive force in phase, as shown in Fig. 44. When the total reactance is negative, however, the capacity reactance exceeds the inductance reactance, and the current is ahead of the electromotive force in phase, as shown in Fig. 45. The same results may be obtained from equation (24). If the total reactance X is negative, then $\tan \theta$ is negative, which means that θ is a negative angle, or that the electromotive force is behind the current in phase, or that the current is ahead of the electromotive force.

Special Cases of Electromotive Force and Current Relations. A clear understanding of the following examples as special cases of the general relations of electromotive force and current as discussed on pages 34 and 35, depends upon the following facts:

(a) That the effect of inductance in an alternating-current circuit becomes negligible when the inductance is very small, for then the reactance ωL due to the inductance is small, and the portion of the electromotive force required to overcome the inductance, namely, ωLI , Fig. 43, is also small.




Fig. 45. Conditions of Fig. 42 When Total Reactance is Negative

(b) That the effect of a condenser in an alternating-current circuit becomes negligible only when the capacity of the condenser is very large, for then the reactance $-\frac{1}{\omega C}$ due to the condenser is small, and the portion of the electromotive force required to overcome the electro-elasticity of the condenser, namely, $\frac{1}{\omega C}I$, Fig. 43, is also small.

The effect of an inductance may be rendered negligible by short-circuiting it with a low-resistance wire; and the effect of a

condenser also may be rendered negligible by short-circuiting it with a low-resistance wire.

CASE A. *Non-inductive or non-reactive circuits.* A circuit which does not contain a condenser and does not have any perceptible inductance is called a *non-reactive circuit*. The term *non-inductive* is frequently used in the sense in which non-reactive is here defined. A non-reactive circuit contains only resistance; and the total electromotive force required to produce a given alternating current I in a non-reactive circuit of which the resistance

is R ohms, is RI volts,* and the electromotive force and current are in phase with each other. Therefore, the relation between alternating electromotive force and current in a non-reactive circuit is precisely the same as in the case of direct currents. That is

$$E = RI$$

or

$$I = \frac{E}{R} \quad (25)$$

Fig. 46 represents a non-reactive circuit connected to an alternator A ; and Fig. 47 shows the relation between the electromotive force and current.

Any circuit in which the outgoing and returning wires are very near together, has very small inductance. An ordinary incandescent lamp, for example, has a negligible inductance. An incandescent lamp the resistance of which when hot is 220 ohms, takes half an ampere, effective, when connected to alternating-current supply mains between which the effective electromotive force, is 110 volts; the current is in phase with the electromotive force and the power in watts is equal to the product of effective volts times effective amperes, or 55 watts. Alternating-current voltmeters are always made as nearly as possible non-inductive.




Fig. 46. Diagram of a Non-Reacting Alternating Circuit



Fig. 47. E. M. F. and Current Relations for a Non-Reacting Alternating Circuit

*Effective values are always understood except where it is distinctly stated to the contrary.

CASE B. *Circuits containing resistance and inductance.* In this case the reactance X ($=\omega L$) is positive, and the current lags behind




Fig. 48. Alternating Circuit Containing Resistance and Inductance

the electromotive force in phase, as before pointed out. The tangent of the angle of lag is equal to $\frac{X}{R}$, according to equation (24); therefore, the angle of lag of the current is small when X is small compared with R , and the angle of lag approaches 90° when X is very large compared with R .

Fig. 48 represents a circuit containing resistance and inductance, connected to an alternator A ; and Fig. 49 shows the relation between the electromotive force and current.

Examples. 1. A non-inductive resistance takes 10 amperes from 220 volt, 60-cycle mains. What current will it take: (a) from 220-volt, 25-cycle mains; (b) from 110-volt, 60-cycle mains?

Since the resistance is non-inductive, the impedance is equal to the resistance, and $I = \frac{E}{R}$. Solving for R we obtain $R = \frac{220}{10} = 22$ ohms.

(a) The current will be $I = \frac{220}{22} = 10$ amperes.

(b) Since there is no inductance or capacity in the circuit, the impedance is independent of the frequency. Therefore, $I = \frac{110}{22} = 5$ amperes.

2. An impedance coil of negligible resistance takes 3 amperes from 220-volt, 60-cycle mains. What current will it take (a) from 220-volt, 25-cycle mains? (b) from 110-volt, 60-cycle mains?

In this case the resistance R is zero, so that the impedance is equal to the reactance, and $I = \frac{E}{X}$. Solving for X we obtain $X = \frac{220}{3} = 73.3$ ohms when the frequency is 60 cycles.

(a) When the frequency is reduced from 60 to 25 cycles, the reactance X is reduced in the same ratio since $X = 2\pi fL$. Therefore, the reactance at 25 cycles is $73.3 \times \frac{25}{60}$ ohms. The current is $I = \frac{220 \times 60}{73.3 \times 25} = 7.2$ amperes.

(b) Since frequency is again 60 cycles, $X = 73.3$, and $I = \frac{110}{73.3} = 1.5$ amperes.

A coil of wire usually has a very considerable inductance, especially if it is wound on a laminated iron core. In fact, a coil

wound on a laminated iron core usually has so large a reactance $X (= \omega L)$, that the angle θ , Fig. 49, is very nearly 90° .

Example. A certain coil has a resistance of 2 ohms and an inductance of 0.3 henry when provided with a laminated-iron core. This coil is connected to an alternator giving 1,000 volts effective electromotive force at a frequency of 133 cycles per second, so that the factor ω is equal to $2\pi \times 133$, or 835.7 radians per second; the reactance of the coil is 835.7×0.3 , or 250.7 ohms; the impedance is $\sqrt{2^2 + 250.7^2}$ or 250.7 ohms; the current is $\frac{1,000}{250.7}$, or 3.989 amperes; the current lags about $89\frac{1}{2}^\circ$ behind the electromotive force; and the power delivered to the coil is 1,000 volts \times 3.989 amperes \times $\cos 89\frac{1}{2}^\circ$ (0.008), which is equal to 31.9 watts ($= I^2 R$). The product EI , sometimes called *apparent watts*, is equal to 3,989 volt amperes.

This example illustrates one remarkable feature of alternating currents—namely, the very small amount of actual power that is delivered to a circuit of large reactance even though the electromotive force is large and the current considerable. In the case of a direct current, 3.989 amperes taken from 1,000-volt mains would mean an actual delivery of 3,989 watts of power, while in the above case the actual power delivered is only 31.9 watts. The ratio *true watts* \div *apparent watts* is called the *power factor* of a circuit; and in case of the coil here under discussion, this ratio is equal to about 0.008 ($= \cos \theta$).




Fig. 49. Diagram of E, M. F.s and Current Relations for Conditions in Fig. 48

One never encounters in practice a circuit in which the reactance is so large compared to the resistance as in the above example; that is, one never encounters one in which the power factor is so small as 0.008. Cases are often met with, however, where the reactance is from two to ten times as large as the resistance. Thus, one of the primary windings of a certain 110-volt induction motor has a resistance of 0.7 ohm and a reactance of 4.2 ohms. With zero load this

circuit, equation (23), takes $\frac{110}{\sqrt{0.7^2 + 4.2^2}} = \frac{110}{4.258}$, or 25.83 amperes;

the angle of phase lag of the current, according to equation (24), is about $80\frac{1}{2}^\circ$; and the power factor of the circuit is 0.164.

A circuit which contains a coil wound on an iron core takes more power than is expended in the mere heating of the wire, namely,




Fig. 50. Circuit Containing Resistance and Capacity

I^2R , for some power is consumed in the iron core on account of magnetic hysteresis and eddy currents. In the above examples this consumption of power in an iron core is neglected for the sake of simplicity.

The term *equivalent resistance* is used to designate a fictitious resistance which when multiplied by I^2 gives the actual power consumed by such a circuit, including both the power consumed in heating the wire, and that consumed by core loss. The equivalent resistance of such circuits has a value larger than the mere resistance of the copper winding.

CASE C. *Circuits containing resistance and a condenser.* In this case the reactance $X (= -\frac{1}{\omega C})$ is negative, and the current leads the electromotive force in phase, as before pointed out. The tangent of the angle of lead is equal to $\frac{X}{R}$, according to equation (24).

Therefore, the angle of lead of the current is small when X is small compared with R , that is, when ωC is large; while the angle of lead of the current approaches 90° when X is large compared with R , that is, when ωC is small.




Fig. 51. Diagram of E. M. F. and Current Relations for Conditions of Fig. 50

Fig. 50 represents a circuit containing resistance and a condenser connected to an alternator *A*; and Fig. 51 shows the relation between the electromotive force and current.

Example. A condenser with a capacity of 2 microfarads (which is large, as condensers go) is connected to alternating-current mains through a resistance coil of 200 ohms. The effective electromotive force between the

mains is 1,000 volts, and the frequency is 133 cycles per second, so that the factor ω is equal to $2\pi \times 133$ or 835.7 radians per second; the reactance of the condenser is $\frac{10^6}{2 \times 835.7} = 598.3$ ohms (negative); the impedance of the circuit is $\sqrt{200^2 + 598.3^2} = 630.85$ ohms; the current, according to equation (23), is 1.585 amperes; the current, according to equation (24), is $71^\circ 31'$ ahead of the electromotive force in phase; and the power delivered to the circuit is 1,000 volts \times 1.585 amperes $\times \cos 71^\circ 31'$, which is equal to 502.5 watts ($= I^2 R$).

If the above condenser is connected to the 1,000-volt, 133-cycle mains through a wire of negligible resistance, then the current will be $\frac{1,000 \text{ volts}}{598.3 \text{ ohms}}$ or 1.671 amperes; the current will be very nearly 90° ahead of the electromotive force in phase; the power factor $\cos \theta$, will be nearly zero; and of course the power delivered to the condenser will be nearly zero.

A circuit containing a condenser takes a little more power than is expended in the mere heating of the wire, namely, $I^2 R$, for some power is consumed in the insulating material between the condenser plates. This power consumed in the dielectric is said to be due to *dielectric hysteresis*. In the above examples, this consumption of power in the insulating material of a condenser is neglected for the sake of simplicity.

CASE D. *Circuit in which the inductance reactance ωL is balanced by the capacity reactance $\frac{1}{\omega C}$.* In this case equation (21) reduces to $I = \frac{E}{R}$; that is, the electromotive force acting upon the circuit has to overcome resistance only, as in the case of the non-reactive circuit. This case in which $\omega L - \frac{1}{\omega C}$ is equal to zero is considered again in the following article on resonance.

Electrical Resonance. Consider a circuit, like the one shown in Fig. 42, containing a given resistance R , a given induction L , and a given capacity C . Suppose that the alternator A is at first run at very slow speed so as to give very low frequency, and is then gradually increased in speed so as to cause the frequency to increase. This gradual increase of frequency will cause a gradual increase in the value of the factor ω (equal to 2π times the frequency); and as ω increases, the following relations between inductance reactance ωL and capacity reactance $\frac{1}{\omega C}$ will obtain:

(a) At first, when the frequency is very low (few cycles per second), the value of ω is small. Therefore, the inductance reactance ωL is small; the capacity reactance $\frac{1}{\omega C}$ is large; and the total net reactance $\omega L - \frac{1}{\omega C}$ is negative, and very nearly the same as $\frac{1}{\omega C}$ alone.

(b) As the frequency increases, the value of ω increases. Therefore, the inductance reactance ωL increases; the capacity reactance $\frac{1}{\omega C}$ decreases; and the total net reactance $\omega L - \frac{1}{\omega C}$ increases in value on account of the increase of ωL , and also on account of the decrease of $\frac{1}{\omega C}$. For a certain critical value of the frequency, ωL becomes equal to $\frac{1}{\omega C}$, so that the total net reactance is then zero. That is

$$\omega L - \frac{1}{\omega C} = 0$$

or

$$\omega L = \frac{1}{\omega C}$$

or

$$\omega^2 = \frac{1}{LC}$$

or

$$\omega = \frac{1}{\sqrt{LC}}$$

or, since ω equals $2\pi f'$, we have

$$f' = \frac{1}{2\pi \sqrt{LC}} \quad (26)$$

in which f' is the critical value of the frequency for which inductance reactance is balanced by capacity in the given circuit, L being the inductance of the circuit and C the capacity of the condenser. See Fig. 42.

(c) As the frequency increases beyond the critical value f' , the inductance reactance ωL continues to increase; the capacity reactance continues to decrease; and the net reactance $\omega L - \frac{1}{\omega C}$, now positive in value, continues to increase in value.

Now, imagine the electromotive force of the alternator to be constant in value, although increasing in frequency as the alternator is speeded up.* The current in the circuit will at first increase with increasing frequency until the critical frequency f' , equation (26), is reached, and then the current will decrease in value as the frequency increases, a maximum value of current being produced at the critical frequency f' . This production of a maximum current at the critical frequency




Fig. 52. Graphical Relation of Current and Frequency; E. M. F. Constant

f' is called *electrical resonance*. At critical frequency the reactance $\omega L - \frac{1}{\omega C}$ is zero; and the general equation (21) reduces to $I = \frac{E}{R}$, as explained in Case D, page 41. That is, the value of the current at the critical frequency is determined solely by the resistance of the circuit and for a given resistance has its maximum value.

The variation of current in a circuit like that shown in Fig. 42, with increasing frequency, electromotive force being kept constant in value, is shown graphically in Fig. 52, which is calculated from the following data: $E=200$ volts (effective); $R=2$ ohms; $L=0.352$ henry; and $C=20$ microfarads.

The critical frequency corresponding to these values of L and C is 60 cycles per second, according to equation (26). The maximum point of the curve is not a cusp, as would appear from the figure; but the curve is rounded at the top, the figure being drawn on too small a scale to show it.

It should be remarked that the conditions for complete resonance can be obtained only when C and L are constant and con-

*In practice this condition could be realized by adjusting the field rheostat of the alternator, or of the exciter, so as to reduce the exciting current as the speed of the alternator is increased.

centrated (not distributed), and when the electromotive force is harmonic. If the electromotive force is non-harmonic, it means that it is composed of a number of sine waves having different frequencies. It is evident, therefore, that ωL can never be made exactly equal to the fraction $\frac{1}{\omega C}$ unless there is but one fundamental frequency equal to $f = \frac{\omega}{2\pi}$.

Multiplication of E. M. F. by Resonance. When resonance exists in a circuit containing an inductance and a condenser in series, the alternating electromotive force ωLI between the terminals of the inductance, and the alternating electromotive force $\frac{I}{\omega C}$ between the terminals of the condenser, may each be much greater than the alternating electromotive force RI which acts upon the circuit. This




Fig. 53. Diagram Showing Multiplication of E. M. F.s by Resonance

fact is easily understood by means of the mechanical analogue. If even a very weak periodic force act upon a weight which is suspended from a spiral spring, the weight will be set into violent vibration, provided the frequency of the force is the same as the proper frequency of oscillation of the body. The forces acting on the spring may reach enormously greater values than the periodic force which maintains the motion of the system. Moreover, the forces which act upon the weight to produce its up-and-down acceleration may reach values very much larger than the periodic force which maintains the motion.

Example. A coil having an inductance of 0.352 henry and a resistance of 2 ohms, and a condenser of 20 microfarads capacity, are connected in series between alternating-current mains. The critical frequency of this circuit is 60 cycles per second, according to equation (26). The electromotive force between the mains is 200 volts, and its frequency is 60 cycles per second. The current in the circuit is $\frac{200 \text{ volts}}{2 \text{ ohms}}$, or 100 amperes, according to equation (21); the effective electromotive force between the condenser terminals is 13,270 volts effective ($= \frac{I}{\omega C}$); and the electromotive force between the terminals of the inductance is also 13,270 volts effective ($= \omega LI$).

The multiplication of electromotive force by resonance may be clearly understood with the help of the clock diagram, Fig. 53.




Fig. 54. An Alternator Delivering Current to a Long Transmission Line

The electromotive force ωLI required to overcome inductance reactance is equal and opposite to the electromotive force $\frac{I}{\omega C}$ required to overcome capacity reactance, as shown in Fig. 53, so that the geometric sum of ωLI , $\frac{I}{\omega C}$, and RI is, simply, RI . A transmission line has both inductance and capacity and, therefore, electrical resonance may occur on a transmission line. The phenomena of a transmission line, however, are very greatly complicated by the fact that the capacity is distributed; and a simple explanation of line resonance can be given only by approximation.

For example, an alternator *A*, Fig. 54, delivers current to a long transmission line. The resonance effects are nearly independent




Fig. 55. Diagram of Conditions Shown in Fig. 54 with Transmission Lines Insulated from Each Other

of whether the receiving apparatus at the end of the line, viz, at *B*, is connected into the circuit or not. We shall, therefore, consider that the receiving apparatus is disconnected and, furthermore, that the ends of the two transmission lines are insulated from each other.

A first approximation to the behavior of the line may be obtained by looking upon the distant end of the line bbb as a condenser purely and simply, while the near end of the line aaa is looked upon simply as an inductance.




Fig. 56. Circuit Showing Condenser and Inductance in Parallel

The transmission line shown in Fig. 54 is then equivalent to the combination shown in Fig. 55, which is identical with the combination shown in Fig. 42. The value of L may be taken as the inductance of, say, half the length of the line; and the capacity C may be taken as the capacity of the distant half of the transmission line. Then, if the alternator A gives a frequency equal to the critical value of these values of L and C , as per equation (26), we shall have resonance, and the electromotive force between the lines at the distant end (between the terminals of C , Fig. 55) may be greatly in excess of the electromotive force of the alternator A . This condition actually occurs in the practical operation of long transmission lines; and it is not an uncommon thing to have as much as 11,000 volts at the receiving end of a long transmission line when the electromotive force of the generator is but 10,000 volts.

Multiplication of Current by Resonance. An alternator A , Fig. 56, delivers current to a circuit which divides at the points a and b into two branches, one branch containing an inductance L and the other branch containing a capacity C , as shown. The two branches constitute a closed circuit in and of themselves; and if the frequency of the alternator is equal to the critical frequency of the circuit constituted by the two branches, that is, if the frequency of the alternator is equal to




Fig. 57. Vector Diagram for Multiplication of Current by Resonance

the frequency of the alternator is equal to

$$\frac{1}{2\pi\sqrt{LC}},$$

as per equation (26), then the small current I from the alternator will divide into two currents I_1 and I_2 in the respective branches, and the currents I_1 and I_2 may each be very much larger in value than the undivided cur-

rent I . The fact is that, because of resonance, a very large current is made to surge back and forth around the closed circuit formed by the two branches.

The multiplication of current by resonance may be clearly understood with the help of the clock diagram, Fig. 57. The line OE represents the electromotive force between the branch points and $a b$, Fig. 56; the line I_1 represents the lagging current which

the electromotive force E produces in the branch containing the inductance; the line I_2 represents the leading current which the electromotive force E produces in the branch containing the condenser; and the line I , which is the geometric sum of I_1 and I_2 , represents the total current in the undivided part of the circuit in Fig. 56.

For example, three similar 32-candle-power incandescent lamps A , B , and D , Fig. 58, each having 100 ohms resistance, are connected as shown, to 550-volt mains; L is an inductance of 0.597 henry; and C , a capacity of 2.49 microfarads. Then the current flowing through the lamp A is not quite 0.4 ampere, while one ampere of current flows through each of the lamps B and D .

Miscellaneous Considerations. *Condenser as Compensator for Lagging Current.* An alternator may be designed to develop a certain effective electromotive force E , and to deliver a certain effective

current I , at full load. The permissible power output of such an alternator would be EI watts to a non-reactive circuit having unity power factor ($\cos \theta = 1$); but if the receiving circuit is reactive, the permissible power output of the alternator is only $EI \cos \theta$,

where the power factor ($\cos \theta$) may in practice have a value of .8 or less. If a condenser C of sufficiently large capacity, Fig. 59, is connected across the terminals of an alternator A in parallel with




Fig. 58. Diagram of Circuit Showing Multiplication of Current by Resonance




Fig. 59. Diagram of Condenser Compensating for Lagging Current

an inductive receiving circuit RL , the effect of L will be neutralized; the current delivered by A will be in phase with the electromotive force of A ; and the permissible power output will be EI . The condenser is said to *compensate* for the lagging current taken by the inductive receiving circuit.

The compensation produced by a condenser is due to the fact that the alternating current taken by it is ahead of the electromotive force in phase, while that taken by the reactive receiving circuit is behind the electromotive force in phase.

Another advantage, aside from the increase of the permissible power output of the generator, that would result from this compensating of lagging current by means of a condenser, is that the electromotive force of the alternator would not fall off so much with increase of load as is the case when lagging current is not compensated for. The cost, however, of large condensers is so great that their use for compensation of lagging current is not commercially practicable, as may be seen from the following discussion:





Fig. 60. Vector Diagram of Conditions Shown in Fig. 59

Let I_r be the current delivered to the receiving circuit RL , Fig. 59. Let I_c be the current delivered to the condenser C ; this current is 90 degrees ahead of E in phase. Let I_a be the current delivered by the alternator A . It is desired that I_a be in phase with E , as shown in Fig. 60. Let $\cos \theta$ be the power factor of the receiving circuit RL .

From Fig. 60 it is evident that I_c is equal and opposite to that component of I_r , which is at right angles to E , namely, $I_r \sin \theta$. Therefore

$$I_c = I_r \sin \theta$$

Now, I_c is equal to $\frac{E}{\omega C}$ ($= \omega CE$), that is, is equal to the electromotive force between the condenser terminals divided by the reactance of the condenser. The value of $\sin \theta$ is $\frac{\omega L}{\sqrt{R^2 + \omega^2 L^2}}$; and $I_r =$



GROUP OF WESTINGHOUSE-PARSONS TURBINE UNITS IN THE 16,000 H. P. PLANT OF THE PHILADELPHIA RAPID TRANSIT CO.
The Westinghouse Machine Co.

$\frac{E}{\sqrt{R^2 + \omega^2 L^2}}$; so that, substituting the values of I_r and $\sin \theta$, the above equation for I_c becomes

$$\omega C E = \frac{\omega L E}{R^2 + \omega^2 L^2}$$

whence

$$C = \frac{L}{R^2 + \omega^2 L^2} \quad (27)$$

in which R is the resistance (in ohms) of the receiving circuit; L is the inductance (in henrys) of the receiving circuit; ω is a factor equal to 2π times the frequency in cycles per second; and C is the capacity (in farads) of the condenser required to compensate for the lagging current delivered to the receiving circuit. Suppose an alternator having an electromotive force of 1,100 volts and a frequency of 60 cycles per second, delivers 102.4 amperes of current to a receiving circuit of which the power factor is 0.871 (9.35 ohms resistance and 0.014 henry inductance). The capacity of a condenser, which will compensate for the lagging current in this case, may be calculated from equation (27) as follows:

$$\begin{aligned} C &= \frac{0.014}{9.35^2 + (2\pi \times 60)^2 \times 0.014^2} \\ &= 0.0001214 \text{ farad} = 121.4 \text{ microfarads} \end{aligned}$$

This condenser would take from the mains a current of 50.34 amperes, which would be 90 degrees ahead of the e. m. f. in phase, and this current would be equal and opposite to the wattless component of the 102.4 amperes of current delivered to the inductive circuit. Such a condenser would require about 114,000 leaves of tinfoil 8 inches \times 10 inches, separated by 114,000 leaves of paraffined paper, each 0.03 inch in thickness. This would give a stack of condenser leaves of about 400 feet total thickness; and the cost of material and labor would be at least \$10 per microfarad.

Such a condenser would be impracticable but a synchronous motor with over-excited field magnets behaves like a large condenser in that it takes an armature current which is ahead of the electromotive force in phase. The synchronous motor is often used in practice to compensate for lagging line current and when so operated is called a *rotary condenser*.

Circuits in Series. An alternator A , Fig. 61, delivers current to two coils (or elements) in series as shown. Let R_1 be the resistance and X_1 the reactance of coil 1. Let R_2 be the resistance




Fig. 61. Two Elements in Series in Alternating Circuit




Fig. 62. Diagram of E. M. F. Conditions for Fig. 61

and X_2 the reactance of coil 2. Let I be the current flowing through the circuit; E the electromotive force between the mains; E_1 the electromotive force between the terminals of coil 1; and E_2 the electromotive force between the terminals of coil 2. Let θ be the phase difference between E and I ; θ_1 the phase difference between E_1 and I ; and θ_2 the phase difference between E_2 and I , as shown in Fig. 62.

Of course θ_1 is the angle whose tangent is $\frac{X_1}{R_1}$; θ_2 is the angle whose tangent is $\frac{X_2}{R_2}$; and θ is the angle whose tangent is $\frac{(X_1 + X_2)}{(R_1 + R_2)}$, according to equation (24).

Example. Two impedance coils have resistances of 5 and 8 ohms and inductances of 0.01 and 0.2 henry, respectively. If these coils are connected in series across 220-volt, 60-cycle mains, find: (a) the current; (b) the voltages impressed across the coils; and (c) the phase relations between the current and the voltages impressed across the coils.

SOLUTION. We have $R_1=5$, $R_2=8$, $E=220$, $f=60$, $L_1=0.01$, $L_2=0.2$. Then $\omega=2\pi f=2\pi \times 60=377$ radians per second. The reactance of coil 1 is $X_1=\omega L_1=377 \times 0.01=3.77$ ohms, and the reactance of coil 2 is $X_2=\omega L_2=377 \times 0.2=75.4$ ohms. The total impedance of the circuit is $Z=\sqrt{(R_1+R_2)^2+(X_1+X_2)^2}=\sqrt{(5+8)^2+(3.77+75.4)^2}=80.23$ ohms, so that the current is

$$I = \frac{E}{Z} = \frac{220}{80.23} = 2.74 \text{ amperes}$$

To find the voltages E_1 and E_2 . (Sec Figs. 61 and 62.) The impedance of coil 1 is $Z_1 = \sqrt{5^2 + 3.77^2} = 6.262$ ohms and the impedance of coil 2 is $Z_2 = \sqrt{8^2 + 75.4^2} = 75.82$ ohms. The magnitude of the voltage E_1 is

$$E_1 = IZ_1 = 2.74 \times 6.262 = 17.16 \text{ volts,}$$

and the magnitude of the voltage E_2 is

$$E_2 = IZ_2 = 2.74 \times 75.82 = 207.7 \text{ volts}$$

The phase angle θ_1 between the current and E_1 is obtained from the relation $\tan \theta_1 = \frac{X_1}{R_1} = \frac{3.77}{5} = 0.754$, whence

$$\theta_1 = 37^\circ 1'$$

Similarly the phase angle θ_2 between I and E_2 is found to be $\theta_2 = \tan^{-1} \frac{75.4}{8} = \tan^{-1} 9.425$, or

$$\theta_2 = 83^\circ 56'$$

and $\tan \theta = \frac{X_1 + X_2}{R_1 + R_2} = \frac{79.17}{13} = 6.090$, whence

$$\theta = 80^\circ 41'$$

Referring to Fig. 62 it is evident that by taking the line (or vector) representing the current I as the axis of reference, the lines representing the electromotive forces, E_1 , E_2 , and E may each be resolved into two components, one parallel to or in phase with I and the other perpendicular to or in quadrature with I . Then the sum of the components of E_1 and E_2 parallel to I will be equal to the component of E parallel to I , and similarly the sum of the components of E_1 and E_2 perpendicular to I , will be equal to the vertical component of E . Expressing these statements in equation form and substituting the values, we have the following:

$$\begin{aligned} (E_1 \cos \theta_1) + (E_2 \cos \theta_2) &= (E \cos \theta) \\ (17.16 \cos 37^\circ 1') + (207.7 \cos 83^\circ 56') &= (220 \cos 80^\circ 40.3') \\ (13.71) + (21.98) &= (35.69 \text{ approx.}) \end{aligned}$$

and

$$\begin{aligned} (E_1 \sin \theta_1) + (E_2 \sin \theta_2) &= (E \sin \theta) \\ (17.16 \sin 37^\circ 1') + (207.7 \sin 83^\circ 56') &= (220 \sin 80^\circ 40.5') \\ (10.34) + (206.7) &= (217 \text{ approx.}) \end{aligned}$$

Circuits in Parallel. An alternator A , Fig. 63, delivers current to two coils (or elements) in parallel as shown.

Let R_1 be the resistance, and X_1 the reactance of coil 1; let R_2 be the resistance, and X_2 the reactance of coil 2; let E be the electromotive force between the coil terminals; let I_1 be the current in coil 1, I_2 the current in coil 2, and I the total current; and let θ be the angle of phase difference between E and I ; θ_1 the

phase angle between I_1 and E ; and θ_2 the angle between I_2 and E , as shown in Fig. 64.

The angles θ_1, θ_2 , are known from the relations

$$\tan \theta_1 = \frac{X_1}{R_1} \quad \tan \theta_2 = \frac{X_2}{R_2}$$

The branch currents are: $I_1 = \frac{E}{\sqrt{R_1^2 + X_1^2}}$ and $I_2 = \frac{E}{\sqrt{R_2^2 + X_2^2}}$

but since they are not in phase, they cannot be added algebraically to obtain the resultant current I , but must be added geometrically as is done in Fig. 64. The magnitude of I may be found by trigonometry thus: $I = \sqrt{I_1^2 + I_2^2 + 2I_1 I_2 \cos(\theta_2 - \theta_1)}$.

In the case of circuits in parallel the voltage across each branch is the same, and it is, therefore, convenient to determine all currents by their magnitudes and their relations with respect to this common




Fig. 63. Two Elements in Parallel in Alternating Circuit

voltage. Thus in Fig. 64 draw the line OE to represent the voltage in magnitude; it is convenient to draw it horizontal since the current vectors in the clock diagram are to be referred to this vector voltage as the axis of reference. The vectors OI_1 and OI_2 are then drawn from O to represent the currents I_1 and I_2 in magnitude and with the proper directions as determined by the phase angles θ_1 and θ_2 .

The magnitude and phase of the resultant current I may be obtained graphically from the clock diagram, but this method is not to be recommended where accuracy is sought.

To obtain by calculation the phase angle between the main current I and the voltage E , it is necessary to resolve I into its components parallel to and in quadrature with E .

The power component of the current I_1 is

$$I_1 \cos \theta_1 = \frac{R_1 I_1}{Z_1} = \frac{E}{Z_1} \times \frac{R_1}{Z_1} = E g_1$$

where $g_1 = \frac{R_1}{Z_1^2}$ is called the *conductance* of circuit 1.

Similarly the power component of I_2 is

$$I_2 \cos \theta_2 = \frac{R_2 I_2}{Z_2} = E g_2$$

The “reactive” or “wattless” component of the current I_1 is

$$I_1 \sin \theta_1 = I_1 \frac{X_1}{Z_1} = \frac{E}{Z_1} \times \frac{X_1}{Z_1} = E b_1$$

where $b_1 = \frac{X_1}{Z_1^2}$ is called the *susceptance* of circuit 1.




Fig. 64. Vector Diagram of Current Conditions for Fig. 63

Similarly the reactive component of the current I_2 is

$$I_2 \sin \theta_2 = I_2 \frac{X_2}{Z_2} = \frac{E}{Z_2} = E b_2$$

Since I is the *vector sum* of the two branch currents

$$I = I_1 + I_2$$

The power component of the resultant current is the sum of the power components of the two branch currents, or

$$I \cos \theta = I_1 \cos \theta_1 + I_2 \cos \theta_2 = E g_1 + E g_2 = E (g_1 + g_2)$$

and the reactive component of I is

$$I \sin \theta = I_1 \sin \theta_1 + I_2 \sin \theta_2 = E b_1 + E b_2 = E (b_1 + b_2)$$

Therefore

$$\tan \theta = \frac{I \sin \theta}{I \cos \theta} = \frac{b_1 + b_2}{g_1 + g_2}$$

and the magnitude of the vector I being the hypotenuse of a right-angle triangle, having a base $I \cos \theta$, and an altitude $I \sin \theta$, is

$$I = E \sqrt{(g_1 + g_2)^2 + (b_1 + b_2)^2}$$

By drawing a semicircle on OE as a diameter and extending the current vectors I_1 , I_2 , and I , till they meet the semicircle at B , A , and C in Fig. 64, some important relations may be deduced. Join the points A , B , and C with E , thus completing the triangles OAE , OBE , and OCE . They are all right-angle triangles because inscribed in semicircle.

A careful study of Fig. 64 will show that $OA = R_2 I_2$, $AE = X_2 I_2$, (see page 35), and that $\sqrt{OA^2 + AE^2} = OE = E$ from which $R_2 = \frac{OA}{I_2}$, $X_2 = \frac{AE}{I_2}$, and $Z_2 = \frac{OE}{I_2}$.

Similarly $OB = R_1 I_1$, $BE = X_1 I_1$, and $\sqrt{OB^2 + BE^2} = OE = E$ and $RI = OC$, $CE = XI$, and $\sqrt{OC^2 + CE^2} = E$ in which R is called the "equivalent resistance" of the total circuit, and X its "equivalent reactance." In other words, if the branched circuits were replaced by a single coil having a resistance equal to R and a reactance equal to X , the coil would take the same current from the mains as before, with the same angle of lag, and would absorb the same total power. The impedance of this single "equivalent coil" is not the sum of the impedances of the separate coils, but is $\frac{E}{I}$.

Example. An impedance coil having a resistance of 19.05 ohms and a reactance (at a frequency of 60 cycles) of 11 ohms is connected in parallel with a second impedance coil having a resistance of 22 ohms and a reactance of 38.1 ohms across 220-volt, 60-cycle mains. Find (a) the current in each coil and the total (or line) current; (b) the phase relation of the currents; (c) the power factor of the entire circuit and the power expended in it; and (d) the "equivalent" resistance and reactance of the circuit.

Solution. (a) To find the currents, we have

$$I_1 = \frac{E}{\sqrt{R_1^2 + X_1^2}} = \frac{220}{\sqrt{(19.05)^2 + (11)^2}} = \frac{220}{22} = 10 \text{ amperes}$$

and

$$I_2 = \frac{E}{\sqrt{R_2^2 + X_2^2}} = \frac{220}{\sqrt{(22)^2 + (38.1)^2}} = \frac{220}{44} = 5 \text{ amperes}$$

The above values are simply the *magnitudes* of the branch currents. Before they can be represented in a clock diagram, their directions must be found.

$$(b) \tan \theta_1 = \frac{X_1}{R_1} = \frac{11}{19.05} = 0.577, \text{ or}$$

$$\theta_1 = -30^\circ$$

The minus sign means a lagging current.

$$\tan \theta_2 = \frac{X_2}{R_2} = \frac{38.1}{22} = 1.732, \text{ or}$$

$$\theta_2 = -60^\circ$$

The angle of phase difference between I_1 and I_2 is

$$\theta_2 - \theta_1 = -60^\circ - (-30^\circ) = -30^\circ$$

The vector currents may now be drawn to scale as is done in Fig. 64. The resultant or vector sum of the currents I_1 and I_2 may be found by drawing the diagonal of the parallelogram on I_1 and I_2 as sides. The main current is then OI .

Its magnitude may be found by trigonometry; thus

$$I = \sqrt{I_1^2 + I_2^2 + 2I_1 I_2 \cos (\theta_2 - \theta_1)}$$

$$= \sqrt{10^2 + 5^2 + (2 \times 10 \times 5 \times 0.866)} = \sqrt{211.6} = 14.55 \text{ amperes.}$$

To find the phase of I , we have

$$\tan \theta = \frac{b_1 + b_2}{g_1 + g_2}$$

$$\text{where } b_1 = \frac{X_1}{Z_1^2} = \frac{11}{19.05^2 + 11^2} = \frac{11}{22^2} = 0.0227; \quad b_2 = \frac{X_2}{Z_2^2} = \frac{38.1}{(44)^2} = 0.01968;$$

$$g_1 = \frac{R_1}{Z_1^2} = \frac{19.05}{(22)^2} = 0.0394; \quad \text{and } g_2 = \frac{R_2}{Z_2^2} = \frac{22}{(44)^2} = 0.01136.$$

$$\tan \theta = \frac{0.0227 + 0.01968}{0.0394 + 0.0114} = \frac{0.04238}{0.0508} = 0.8359$$

or

$$\theta = 39^\circ 53'$$

which is the angle by which I lags behind E .

(c) The power factor of coil 1 is $\cos \theta_1 = \cos 30^\circ = 0.86603$ and the power expended in it is $I_1^2 R_1 = 10^2 \times 19.05 = 1905$ watts, or it is $E^2 g_1 = (220)^2 \times 0.0394 = 1905$ watts.

The power factor of coil 2 is $\cos \theta_2 = \cos 60^\circ = 0.5$ and the power expended in it is $I_2^2 R_2 = (5)^2 \times 22 = 550$ watts, or it is $E^2 g_2 = (220)^2 \times 0.01136 = 550$ watts.

The power expended in coils 1 and 2 = $1905 + 550 = 2455$ watts.

The power factor of the entire circuit (two branches) is

$$\cos \theta = \cos 39^\circ 53' = 0.76735$$

and the power expended in it is

$$EI \cos \theta = 220 \times 14.55 \times 0.76735 = 2455 \text{ watts}$$

(d) The "equivalent resistance" R is

$$\frac{OC}{I} = \frac{220 \cos 39^\circ 53'}{14.55} = \frac{168.81}{14.55} = 11.6 \text{ ohms}$$

The power absorbed in R is

$$I^2 R = (14.55)^2 \times 11.6 = 2455 \text{ watts}$$

The "equivalent reactance" X is

$$\frac{CE}{I} = \frac{220 \sin 39^\circ 53'}{14.55} = 9.7 \text{ ohms}$$

The current I lags behind the voltage E , by an angle θ given by

$\tan \theta = \frac{X}{R}$ or $\tan \theta = \frac{9.7}{11.6} = 0.836$ from which $\theta = -39^\circ 53'$ the same as found above.

Electromotive Force Losses in Transmission Lines. An alternator of which the electromotive force is E , delivers current over a transmission line of which the resistance is R_1 and the reactance (inductance reactance) is X_1 , to a receiving circuit of which the resistance is R_2 and the reactance is X_2 . The total electromotive

force used to overcome the resistance and the reactance of the transmission line is E_1 , and the electromotive force between the




Fig. 65. Diagram of E. M. F. Losses in Transmission Lines—Receiving Circuit Non-Reactive terminals of the receiving circuit is E_2 . The current delivered is I . Then the general relation between E , E_1 , and E_2 is as shown in Fig. 62, except that E_2 is usually very much larger than E_1 in value. There are three interesting and simple special cases of electromotive force losses in transmission lines, as follows:*

CASE 1. *When the receiving circuit is non-reactive.* In this case the electromotive force E_2 between the terminals of the receiving circuit is in phase with I , the power factor of the receiving circuit is unity, and the general diagram of Fig. 62 takes the form shown in Fig. 65. The total electromotive force E_1 consumed in the line is sometimes called the *impedance loss* or *drop* and its two components R_1I and X_1I , as shown in Fig. 65, are called the *resistance loss* and the *reactance loss*, respectively. Now, a careful inspection of Fig. 65 makes it evident that the numerical difference between the values of E and E_2 is very nearly equal to the resistance loss in the line R_1I ; and that the reactance loss in the line X_1I has little to do with the difference between the values of E and E_2 . Therefore, *when the receiving circuit is non-reactive, the difference in value between generator electromotive force E and receiver electromotive force E_2 is sensibly equal to the resistance loss of electromotive force in the line, and sensibly independent of the reactance loss of electromotive force in the line.*




Fig. 66. E. M. F. Losses When the Receiving Circuit is Highly Reactive

*This discussion applies to comparatively short lines, ten miles or less in length, inasmuch as the capacity of the line is not here taken into account.

CASE 2. *When the receiving circuit is highly reactive.* In this case the electromotive force E_2 between the receiving circuit terminals is nearly 90 degrees ahead of I in phase, and the general diagram of Fig. 62 takes the form shown in Fig. 66. A careful inspection of Fig. 66 makes it evident that the difference in value of E and E_2 is very nearly equal to the reactance loss in the line X_1I ; and that the resistance loss in the line R_1I has little to do with the difference between the values of E and E_2 . Therefore, *when the receiving circuit is highly reactive, the numerical difference in value between generator electromotive force E and receiver electromotive force E_2 is sensibly equal to the reactance loss of electromotive force in the line, and sensibly independent of the resistance loss of electromotive force in the line.*




Fig. 67. E. M. F. Losses with Large Capacity Reactance

CASE 3. *When the receiving circuit has large capacity reactance.* In this case the electromotive force E_2 between the receiving circuit terminals is nearly 90 degrees behind I in phase, and the general diagram of Fig. 62 takes the form shown in Fig. 67. A careful inspection of Fig. 67 makes it evident that the difference between the values of E and E_2 is very nearly equal to the reactance loss in the line X_1I , and that this reactance loss is added to the generator electromotive force E to give the receiver electromotive force E_2 . Inspection of Fig. 67 shows furthermore that the resistance loss in the line

R_1I has little to do with the difference in value of E and E_2 . Therefore, *when the receiving circuit has a high capacity reactance, the reactance loss in the line is sensibly equal to the rise in value of the electromotive force between generator and receiver, and this rise in value is sensibly independent of the resistance loss of electromotive force in the line.* It is somewhat confusing to speak of the electromotive force X_1I as reactance loss when the receiving circuit has a high capacity reactance; it would be better in this case to speak of X_1I as the reactance gain of electromotive force in the line.

Electromotive Force Losses in Alternator Armatures. Let E be the total induced electromotive force in the armature of an alternator. A portion E_1 of this electromotive force is used to overcome the resistance R_1 and the reactance X_1 of the armature; and the remainder E_2 is available at the terminals of the alternator for producing current in the outside circuit, of which the resistance is R_2 and the reactance is X_2 . The general relation between E , E_1 , and E_2 is as shown in Fig. 62, *except that E_2 is usually very much larger than E_1 in value.* There are three interesting and simple special cases of electromotive force losses in alternator armatures, as follows:

CASE 1. *When the receiving circuit is non-reactive.* In this case the electromotive force E_2 between the terminals of the alternator is in phase with the current I delivered by the machine, and the general diagram of Fig. 62 takes the form shown in Fig. 65, from which it is evident that when the receiving circuit is non-reactive, the numerical difference in value between the total induced electromotive force E and the terminal electromotive force E_2 of the machine is sensibly equal to the resistance loss of electromotive force R_1I in the armature, and sensibly independent of the reactance loss of electromotive force X_1I in the armature.

CASE 2. *When the receiving circuit is highly reactive.* In this case the electromotive force E_2 between the terminals of the alternator is nearly 90 degrees ahead of I in phase, and the general diagram of Fig. 62 takes the form shown in Fig. 66, from which it is evident that when the receiving circuit is highly reactive the numerical difference in value between the total induced electromotive force E and the terminal electromotive force E_2 of the machine is sensibly equal to the reactance loss of electromotive force X_1I in the armature, and sensibly independent of the resistance loss of electromotive force R_1I in the armature.

CASE 3. *When the receiving circuit has large capacity reactance.* In this case the electromotive force E_2 between the terminals of the alternator is nearly 90 degrees behind I in phase, and the general diagram of Fig. 62 takes the form shown in Fig. 67, from which it is evident that when the receiving circuit has a high capacity reactance the difference in value between E and E_2 is sensibly equal to X_1I , E_2 being larger than E , and sensibly independent of the resistance loss of electromotive force R_1I in the armature.

MEASURING INSTRUMENTS

Electrical measuring instruments may be divided into three classes, as follows:

(a) *Indicating* instruments which give the value of an electrical quantity at the time of observation, or which may be so manipulated as to give this value.

(b) *Integrating* instruments which combine the element of time with the element of electrical quantity. For instance, a watt-hour meter gives a reading proportional to the product of the average power in watts and the time in hours, or in other words, it measures the electrical energy expended in the circuit to which it is connected; it is not, therefore, a power meter.

(c) *Recording* instruments which trace a curve or other graphic record showing the variation of some electrical quantity, such as voltage, with time. It should be carefully noted that the name "recording wattmeter" is very commonly but incorrectly applied to the integrating watt-hour meter. The latter is not a recording instrument, nor is it a wattmeter. A true recording wattmeter would draw a curve showing the variation of the watts with time.

Electrical instruments may be also classified according to construction and method of use into: *switchboard*, *portable*, and *semi-portable* or *laboratory* types.

INDICATING INSTRUMENTS

Indicating electrical instruments may be divided into three groups, as follows: (1) Those adapted for direct currents only, a consideration of which is beyond the scope of this text; (2) those adapted for both direct- and alternating-current circuits, which class comprises hot-wire, electrostatic, and electromagnetic instruments, and electro-dynamometers; (3) instruments operating only on alternating current, which depend upon the interaction of induced and inducing currents, and are usually described as induction instruments.

Hot-Wire Ammeter and Voltmeter.* Instruments of the hot-wire type depend upon the expansion of a stretched wire when heated

*All voltmeters except the electrostatic voltmeter are essentially ammeters; that is, the electromotive force to be measured produces a current which actuates the instrument. The scale over which the pointer moves, may be arranged to indicate either the value of the current flowing through the instrument, or the value of the electromotive force acting between the terminals of the instrument.

by the passage of a current, which actuates a pointer moving over a divided scale. These instruments are adapted for both direct and alternating current for, when calibrated by *continuous currents or electromotive forces*, they indicate *effective values* of alternating currents or electromotive forces. This may easily be proved true by considering an alternating current and a continuous current C which give the same reading. *These currents generate heat in the wire at the same average rate*, which is C^2R for the continuous current, and $\overline{\text{average } i^2} \times R$ for the alternating current, i being the instantaneous value of the alternating current. Therefore, $C^2R = \overline{\text{average } i^2} \times R$; or $C^2 = \overline{\text{average } i^2}$; or $C = \sqrt{\overline{\text{average } i^2}}$.

The proof for electromotive forces is similar to this proof for currents.

Recent instruments of the hot-wire type have a working wire from $3\frac{3}{4}$ to 8 inches in length, of small size for voltmeters and of larger size for ammeters. The voltmeters have a non-inductive resistance connected in series, and the ammeters usually have the working wire connected in parallel with several sections in order to reduce the required drop of voltage in the shunt.

Hot-wire instruments are comparatively little used in this country in practical work, their *disadvantages* being relatively large power consumption, uncertainty of zero (on the scale), and errors due to change of surrounding temperature and to heating when left long in circuit; furthermore, to secure sensibility, the working wire must be operated at a fairly high temperature and may thus be easily damaged by sudden overloads which in other types of instruments would hardly do more damage than the bending of a pointer.

The *advantages* of hot-wire instruments which cause its continued use for certain classes of work are its independence of frequency, wave form, and stray magnetic fields; the fact that it may be calibrated on direct current; and the fact that shunts may be used with the ammeter on alternating current. For use in laboratories with unusual frequencies or wave forms, and where there are facilities for calibration on direct current, the hot-wire type has marked advantages. It should be noted, however, that for very high frequencies, such as those employed in wireless telegraphy, shunted hot-wire ammeters are not reliable. This is due to the fact that for

such high-frequency currents the effective resistance of the shunt—including the so-called “skin effect”—is much greater than for direct current, and that the current in the shunt will lag more behind the electromotive force than the current in the working wire. For these extreme frequencies, therefore, it is necessary to use a hot-wire ammeter so constructed as to permit the whole current to pass through the working wire which shall have its effective resistance at the frequency used practically equal to its resistance for direct current, thus eliminating the shunt altogether.

Fig. 68 is a general view of the hot-wire voltmeter of the Roller-Smith Company, and Fig. 69 is a diagram of its essential mechanism. In Fig. 69, a wire *a*, called the working wire, because it alone carries




Fig. 68. General View of a Hot-wire Voltmeter—Roller-Smith Company

current, is fastened at one end to a plate *c*, passed around a pulley *d* secured to a shaft *e*, and its free end brought back again and mechanically attached to, though electrically insulated from, the same plate *c*. The wires *a* and *b* are kept under tension by the spring *f* attached to the plate *c*, which is being constantly pulled in a direction at right angles to the axis of the shaft *e*, and is so guided that it can be moved in that one direction only. To the shaft *e* is secured an arm *g* which is forked at its lower end and counterweighted at its upper end. Between the forked ends of the arm *g* is another shaft *h* on which there is a small pulley and to which is attached the light

pointer *i*; a fine silk fiber passes around the pulley and is secured to the ends of the fork arms which are springy and keep the silk fiber taut.

The current to be measured passes through the wire *a* only, entering and leaving as shown by the arrow heads on the terminals near *c* and *d*. When *a* is heated by the current it expands, causing its tension to be less than the tension of *b*. The result is that the pulley *d* is rotated in a clockwise direction until the tensions in *a* and *b* are again balanced. When the pulley *d* is rotated, *g* is moved to the left and this causes the silk fiber to rotate the shaft *h* and the pointer *i*. From this construction and the ratio of the lever arms, it is evident that a very slight elongation of the wire *a* suffices to produce a considerable movement of the pointer *i*.

One of the objections to hot-wire instruments, viz, that the working wire is affected by changes in the temperature of the air thereby introducing an error in the measurements, is successfully overcome in this make of instrument by simple compensation. Thus, if the temperature of the surrounding air changes, the wires *a* and *b* are affected alike, both either contracting or expanding by the same amount, which causes a movement of the plate *c* back or forth in its path, but without any tendency to rotate the pulley *d*.

The entire moving system illustrated in Fig. 69 is mounted on a single base plate and, by means of a lever projecting through the instrument case, may be rotated slightly about a heavy shaft whose axis is in line with the axis of the pointer shaft *h*. The scale with its support being stationary, this device permits of correction for a bent pointer, or adjustment to zero on the scale without interfering with the mechanism in any way.

While the hot-wire instruments of the Roller-Smith Company are nearly dead-beat, an auxiliary damping device is usually furnished consisting of an aluminum disk swinging between the poles




Fig. 69. Diagram of Hot-wire Instrument

of a stationary permanent magnet. Hot-wire voltmeters are specially suited for measuring low electromotive forces up to about 75 volts. The switchboard hot-wire ammeters, reading from 25 up to 1,000 amperes, have separate shunts to which the instrument is connected by flexible leads.

Electrostatic Voltmeter. Instruments of the electrostatic type depend upon the attraction of oppositely charged bodies, and repulsion of similarly charged ones. Two metallic plates connected to the terminals of a battery, or any other source of electromotive force, attract each other with a force which is exactly proportional to the square of the electromotive force. As these forces are relatively small, instruments of this type are not well adapted for use as ammeters, and it is difficult to construct satisfactory voltmeters on the electrostatic principle for the ordinary low voltages of 110 to 220 volts. The electrostatic principle is especially adapted to the measurement of high voltages from about 10,000 up to 200,000 volts. The voltmeter consists essentially of a fixed metal plate and a movable plate delicately mounted on a jewelled pivot. The movable plate carries a pointer, which plays over a divided scale. The electromotive force to be measured is connected between the fixed plate and the movable plate, and the electrical attraction between the plates causes the movable plate to turn about its supporting pivot and move the pointer. *Such an instrument, when calibrated by continuous electromotive force, indicates effective values of alternating electromotive force, as may be seen from the following discussion:* A given deflection of the movable plate depends upon a definite average or constant force acting between the two plates. The force due to a constant electromotive force E is kE^2 , that is, the force is proportional to E^2 ; and the average force due to an alternating electromotive force e , is $k \times \text{average } e^2$. If these electromotive forces give equal deflections, the constant force kE^2 must be equal to the average force $k \times \text{average } e^2$; that is

$$kE^2 = k \text{ average } e^2$$


or

$$E^2 = \text{average } e^2$$

or

$$\sqrt{\text{average } e^2} = E$$





THREE 2,500- H.P. CROSS-COMPOUND CONDENSING CORLISS ENGINES,
OPERATING THREE-PHASE A.C. GENERATORS IN PARALLEL.
C. & G. Cooper Company.

The great advantage of this type of voltmeter is that it takes no current when used on direct-current circuits, and an extremely small current when used on alternating-current circuits. Its other advantages, like those of the hot-wire instruments, are that it is independent of changes in frequency, wave form, and stray magnetic fields. Furthermore, for very high voltages—up to several hundred thousand volts—the construction is relatively simple and cheap, and no auxiliary “potential” transformers are required for reducing the voltage to be measured. It has the disadvantage of small ratio of torque to weight of moving parts, so that errors due to friction of the moving element are relatively large and difficult to avoid. For this reason low-range electrostatic voltmeters are often made with the moving element suspended by a wire or strip instead of rotating on pivots.




Fig. 70. Diagram of Westinghouse Electrostatic Voltmeter


Excepting the electrostatic ground detector, which is essentially a voltmeter, this type of instrument has as yet been little used in commercial work outside of the laboratory. The adoption, however, of increasingly high voltages for long-distance transmission of power carries with it a demand for a reliable commercial form of this instrument. Great progress has lately been made towards putting the electrostatic voltmeter on a commercial basis.

Fig. 70 shows a diagrammatic view of the principle and arrangement of parts of the electrostatic voltmeter brought out by the Westinghouse Electric Company. Fig. 71 (a) shows the moving element.

The meter element consists of two stationary curved aluminum plates B_1 and B_2 , between which is suspended a movable vane $M_1 M_2$

controlled by a light spiral spring so adjusted that the pointer P remains at zero with no voltage on the meter, and gives the full scale deflection at the proper voltage for which the instrument is designed. The curved plates B_1 and B_2 are connected, as shown, to the inner plates of the condensers C_1 and C_2 , and so arranged with respect to $M_1 M_2$ that when a voltage difference exists between the terminals T_1 and T_2 , the induced $-$ charge on M_1 and the $+$ charge on M_2 being attracted by the $+$ charge on B_1 and the $-$ charge on B_2 , respectively, the moving element $M_1 M_2$ rotates counter-clockwise into the new position shown by the dotted lines in Fig. 70.

The condensers C_1 and C_2 are in series with the other parts of the instrument, the inner plate of each being connected to the fixed



(a) Old Form of Moving Element

(b) Modern Moving Element

Fig. 71. Westinghouse Electrostatic Voltmeter

plates B_1 and B_2 , and the outer plate of each to the terminals T_1 and T_2 . For high voltage readings the instrument is connected as a shunt across one of the two (or more) condensers in series, thus impressing any desired fraction of the total voltage upon the instrument terminals. For reading lower voltages, one or more of the condensers are short-circuited, thus permitting the same instrument to be used over a wide range. Fig. 71 (b) shows a modern element.

The meter is placed in a sheet-iron tank filled with transformer oil. This is necessary because oil has a far greater dielectric strength than air, and in this meter the distance between the parts, between

which there is a high voltage difference, is less than the distance at which arcing across in air would occur. The oil also acts to dampen the moving element, thus making the instrument dead-beat and easy to read.

The *electrostatic ground detector* is a modified electrostatic voltmeter. Its essential features are shown in Fig. 72. Two metal plates *A* and *B* are connected to the two mains *a* and *b* (usually through two high resistances *RR*); and a light movable metal plate *m*, suspended between *A* and *B*, is connected to ground (usually through a high resistance *R*). If both lines are equally well insulated from ground, the plates *A* and *B* are each at the same electrical pressure or potential, attracting the plate *m* equally so that it hangs midway between them. If one of the mains, say *a*, is grounded, its pressure or potential becomes equal to the potential of *m*, so that plate *A* no longer attracts *m*, and the plate *m* is, therefore, pulled to the right by the attraction of *B*, the movement being indicated by a pointer *p*.

The same results may be accomplished, when the plate *m* is entirely insulated from the ground, by having a grounded auxiliary stationary plate near *m*.

The essential features and mode of connection of the General Electric Company's electrostatic ground detector are shown in Fig. 73; and a general view of the instrument, with cover removed, is shown in Fig. 74.

Electromagnetic Ammeters and Voltmeters. Instruments of this type depend upon the action of a coil carrying the current to be measured, upon one or more pieces of soft iron. Such instruments are also called "moving-iron", "soft-iron", and "magnetic-vane" types. Instruments of this general type have been used for many years, the earlier ones having been constructed with heavy soft iron cores which were drawn into solenoids energized by the current to be measured. The pull on the plunger due to the current was balanced by a weight attached to a lever arm. The earlier design




Fig. 72. Diagram of Essentials of Electrostatic Ground Detector

sometimes referred to as the "plunger" type, was faulty, and has been since superseded by the modern designs which involve the




Fig. 73. Connecting Circuits for an Electrostatic Ground Detector

use of one or two thin vanes of soft iron mounted on a pivoted staff within the coil.

The soft-iron type of instrument is calibrated by the use of direct electromotive forces or currents, but it does not indicate accurately effective values of alternating electromotive forces, or




Fig. 74. General Electric Ground Detector with Cover Removed

currents. A soft-iron type meter (ammeter or voltmeter) should be calibrated, using alternating current of the same frequency as

that for which the meter is afterwards to be used, and of the same wave shape. Thus, if an instrument of the electromagnetic type is to be used as an ammeter for alternating currents of a given wave shape and frequency, it should be calibrated by currents of this wave shape and frequency, these currents, for the purpose of the calibration, being measured by a standard alternating-current ammeter, such as an electro-dynamometer.

The indications of an instrument of the electromagnetic type, however, do not vary greatly with wave shape and frequency, and such instruments are practically correct for any ordinary wave shape and frequency.

The ammeters are but slightly affected by even large changes in frequency; the voltmeters, on account of their relatively large inductance, are more affected than the ammeters. The error in the




Fig. 75. Mounted Coil of a Thomson Inclined-Coil Meter

voltmeter is not large over the ordinary range of frequencies, and may be computed for extreme frequencies from the measured values of resistance and inductance. A valuable feature of this type of instrument is its very small temperature coefficient. They are well adapted for commercial measurements on alternating current circuits, and for direct current when only approximate results (within 2 or 3 per cent) are needed. The electromagnetic voltmeter or ammeter cannot be checked accurately on direct currents, as even the average of reversed readings does not give an accurate test of the performance on alternating current. This is due to the hysteresis effect in the soft-iron vanes, thereby causing the instrument to read higher for decreasing direct currents than for increasing values. This difference may amount to several per cent. Another advantage of these instruments is their moderate price, and simple construction.

Thomson Inclined-Coil Meter. The Thomson inclined-coil meter of the General Electric Company is an example of the electromagnetic type. The working parts of this instrument are shown in Fig. 75. A coil A , through which flows the current to be measured, is mounted with its axis inclined as shown. A vertical staff mounted in jewel bearings and controlled by a hair spring, passes through the coil, and to this staff are fixed a pointer b and a vane of thin soft sheet iron a . This vane of iron is mounted obliquely to the staff. When the pointer is at the zero point of the scale, the iron vane a lies nearly across the axis of the coil; and when a current passes through the coil, the vane tends to turn until it is parallel to the axis of the coil, position a' in Fig. 75, thus turning the staff and moving the attached pointer over the calibrated scale. The vane




Fig. 76. Thomson Inclined-Coil Ammeter




Fig. 77. Working Parts of Thomson Inclined-Coil Ammeter

tends to turn into a position which makes the reluctance of the magnetic circuit a minimum.

Fig. 76 is a general view of a Thomson inclined-coil ammeter, and Fig. 77 is a view of the working parts of the instrument. The structural details of the inclined-coil voltmeter are identical with those of the ammeter, except that the voltmeter has fine wire in the inclined coil and usually an auxiliary non-inductive resistance in series with the inclined coil.

Roller-Smith Repulsion Ammeter. Another example of an ammeter of the electromagnetic type using the repulsion principle is illustrated in Figs. 78, 79, 80, which give a plan, sectional elevation, and detail, respectively. It is manufactured by the Roller-Smith Company. The current to be measured is led by cables to the

terminals a and a_1 and thence to the coil through heavy copper straps shown in dotted outline underneath the scale in Fig. 78. The terminal a_1 is thus electrically connected to the brass spool m to which is soldered the conducting strip j , Fig. 79, whose carrying capacity is adapted to the current for which the instrument is designed. The conductor j is wound about the spool upon a layer of insulating material to give the required number of turns and is finally brought to the post r , Fig. 78, which passes down through




Fig. 78. Plan of Roller-Smith Repulsion Ammeter

the insulating bushing l , and connects underneath with the copper strap terminating at a . The same method of winding is used in the case of voltmeters, except that instead of the copper straps, flexible leads are used to connect the spool to binding posts covered with hard rubber, and located outside of the case.

The moving element c is carried and supported by the structure shown at g , which is secured to the brass spool by the two hexagon-headed bolts as shown in Fig. 78. This construction enables the moving elements as well as the coils to be made up separately as occasion demands, and independently of the rest of the mechanism, and thus reduces the manufacturing cost.

The structure g consists of a casting into which is inserted a piece of brass tubing, having a solid bottom, for holding the lower

jewel screw. The side of the tube is used to support the fixed magnetic vane *b*. The moving iron vane *c* is fastened to the staff *i*, which also carries the pointer *e*, which moves over the divided scale. The vibrations of *e* are dampened by the vane *f*, Fig. 79, which is forced to move in the nearly air-tight box which forms an integral part of the casting. The controlling spring *d* is adjusted so that the pointer *e* is normally held at zero on the scale. If the pointer fails to return to zero, it may be brought there by means of the lever *h*, which is connected to a button on the outside of the case.




Fig. 79. Sectional Elevation of Repulsion Ammeter

The action of the instrument is as follows: when a current is passed through the coil winding *j*, it magnetizes both the fixed and movable vanes within the coil. Both vanes being made of very soft iron, are similarly magnetized and, therefore, repel each other. The movable vane *c* thus rotates in a clockwise direction carrying the pointer *e* to the right along the scale. This movement of the vane is opposed by the action of the controlling spring *d* resulting in the pointer coming to rest at a point depending upon the strength of the current passing in the coil. The design and arrangement of the movable and fixed soft iron vanes is such as to give the scale shown in Fig. 78, which is reproduced from an actual calibrated scale. The pivots of the moving system are of steel, tempered and highly polished, and the bearings are of highly polished sapphires.




Fig. 80. Detail Diagram of Repulsion Ammeter

Electrodynamometers. Of the four types of instruments for use on both direct and alternating currents, the electro-dynamometer is on the whole the most valuable. This instrument depends upon the force exerted by one circuit carrying a current upon another, or by a portion of a given circuit upon another portion of the same circuit. Instruments of this type usually contain one or more fixed coils which set up a magnetic field directly proportional

to the strength of the current flowing through them. Within this field is arranged a moving coil, or system of coils, through which current may be passed. If the two sets of coils are connected in series, the torque exerted upon the moving system, for a given relative position of the coil systems, is proportional to the square of the current, and is not dependent upon the direction of the current. Such an instrument, therefore, constitutes an ammeter which is equally correct on direct current, and on alternating or pulsating current of any frequency or wave form. The value of this type consists largely in this inherent accuracy on these different kinds of current. Since the fundamental electrical standards and precision methods of testing involve direct current only, the electro-dynamometer type, calibrated on direct current, may be used as a precision instrument for alternating current.




Fig. 81. Sectional Elevation of Siemens Electro-dynamometer

Electrodynamometer Used as an Ammeter. The electro-dynamometer consists of a fixed coil and a movable coil connected in series, through both of which the current to be measured flows. The current causes the fixed coil to exert a certain force upon the movable coil; and the value of the current is determined (a) by observing the angle ϕ through which a helical spring must be twisted by hand in order to balance the above-mentioned force; or (b) by allowing the force to turn the movable coil, thus moving a pointer over a divided scale. In the Siemens electro-dynamometer method (a) is used; while in many commercial forms of electro-dynamometer method (b) is used.




Fig. 82. Dial of Siemens Electro-dynamometer.

The essential features of the Siemens electro-dynamometer are shown in Figs. 81 and 82. The stationary coil *A* is supported by a clamp attached to the standard *S*; and

the movable coil B is hung by a thread, the plane of coil B being at right angles to the plane of coil A . The terminals of the movable coil dip into cups of mercury $a a$, and the current to be measured is sent through both coils in series. The force acting between the coils is balanced by carefully turning the torsion head c by hand, thus twisting a helical spring b , one end of which is attached to the coil B and the other to the torsion head c . The observed angle of twist necessary to bring the swinging coil to its zero position, is read off by means of the pointer d and the graduated scale e . The pointer f attached to the coil shows when it has been brought to its zero position. The observed angle of twist of the helical spring affords a measure of the force acting between the coils, and the current is proportional to the square root of this angle of twist. That is

$$I = k \sqrt{\phi} \quad (28)$$

in which I is the effective value of the alternating current; ϕ is the observed angle of twist of the helical spring b ; and k is a constant called the *reduction factor* of the instrument.

For example, a twist of 220° is required to balance the force due to 18.8 amperes in a certain Siemens electro-dynamometer; the reduction factor k of the instrument is, therefore, by equation (28), equal to $18.8 \text{ amperes} \div \sqrt{220}$, or 1.267. A certain current to be measured requires a twist of the torsion head of 165° , hence the value of the current is equal to $1.267 \times \sqrt{165}$, or 16.28 amperes.

The electro-dynamometer, when standardized by direct currents, indicates effective values of alternating currents; thus, a given deflection of the suspended coil depends upon a definite average or constant force acting between the coils. The constant force due to a constant current C is kC^2 (proportional to C^2); and the average force due to an alternating current is $k \times \text{average } i^2$; so that if these currents give equal deflections, we have $kC^2 = k \times \text{average } i^2$; or $C^2 = \text{average } i^2$; or $C = \sqrt{\text{average } i^2}$.

Electro-dynamometer Used as a Voltmeter. When used as a voltmeter the coils of the electro-dynamometer are made of fine wire, and an auxiliary non-inductive resistance is usually connected in series with the coils. When the inductance of the electro-dynamometer coils is small, such an instrument, *when calibrated by continuous electro-*

motive forces, indicates *effective values* of alternating electromotive forces.

When it is certain that the inductance of an electro-dynamometer is negligibly small, the instrument may be used in precise alternating electromotive force measurements. In order to determine this it will be necessary *to find the inductance error of the electro-dynamometer when used as a voltmeter*. An electro-dynamometer which has been calibrated by continuous electromotive forces indicates less than the effective value of an alternating electromotive force. Let E be the reading of an electro-dynamometer voltmeter when an alternating electromotive force (harmonic), of which the effective value is E , is connected to its terminals. That is, E is the continuous electromotive force which gives the same deflection as E ; and, since E gives the same deflection as E , it follows that the effective current produced by E is equal to the continuous current produced by E ; that is

$$\frac{E}{R} = \frac{E}{\sqrt{R^2 + \omega^2 L^2}}$$

in which R is the total resistance of the instrument; L its inductance; and $\omega = 2\pi f$, where f is the frequency of the alternating electromotive force. Solving the above equation for E , we have

$$E = \frac{\sqrt{R^2 + \omega^2 L^2}}{R} E$$

That is, the reading of the instrument must be multiplied by the factor $\frac{\sqrt{R^2 + \omega^2 L^2}}{R}$ to give the true effective value of a harmonic alternating electromotive force.

Induction Instruments. Instruments suitable for alternating current only, depend upon the interaction of inducing and induced currents, and are commonly described as "induction" instruments. They are usually designed with a laminated iron core around which one or more coils of wire are wound. An alternating magnetic flux is produced in the air gap of this core when current passes through the coils. The effect of a rotating magnetic field is secured, either by having currents differing in phase pass through two groups of coils, or by using a single inducing coil with fixed copper plates or

bands in which induced currents are generated. The resultant action of the flux due to the coil and that due to the induced currents in the fixed copper pieces, produces the effect of a rotating magnetic field. An aluminum disk or drum pivoted in the field tends to rotate with the rotating field. The motion of the drum or disk is opposed by a suitable spring in the case of indicating instruments, whereas retarding magnets and registering mechanism to read the total quantity that has passed through the meter are provided in the case of integrating instruments, such as the watt-hour meter.

Indicating or direct-deflection induction meters are made in portable form for commercial testing, but are more generally used for switchboard instruments, including ammeters, voltmeters, wattmeters, frequency meters, and power factor meters.




Fig. 83. Westinghouse Induction Voltmeter

The advantages possessed by portable induction indicating instruments are that they are not sensitive to external stray fields, that they have long (over 300°) open scales, that the moving element is simple, light, and strong, and has no windings and, therefore, needs no provision for leading current in and out.

The disadvantages of this type of meter are that its readings tend to vary more or less with changes in frequency and temperature, although in instruments of the latest design these errors have been greatly reduced.

These instruments should be calibrated under conditions (especially frequency) as nearly as possible like those under which they are to be used.

The construction and principle of induction indicating instruments is illustrated by the "Type F" *induction voltmeter* made by the Westinghouse Electric Company for switchboard service, shown in Fig. 83 with its case and dial removed. The view shows the fine wire primary coils of a current transformer wound about the two legs of an inverted U-shaped structure of laminated iron. The primary coils are connected in series with a high-resistance wire of

zero temperature coefficient, the object of which is to make the readings of the voltmeter more nearly independent of frequency. The secondary coil of the current transformer is wound directly under the primary coils and connected to the few turns of coarse wire marked "auxiliary coils," Fig. 83, on the pole pieces. The entire secondary circuit forms a closed winding. The poles constitute in effect a two-phase bipolar rotating field produced by two magnetic fluxes which are nearly at right angles to each other. One of these fluxes is due to the auxiliary coils carrying the secondary current and the other to the magnetizing component of the primary current. To vary the capacity of the meter, the number of primary turns and the size of wire, only, need to be changed. In the air gap between the poles is the moving element which is a very light aluminum drum mounted on a shaft having highly polished and hardened pivots resting in polished sapphire jewels. This shaft also carries the indicating pointer and control spring which opposes the torque by the moving element.

Type F voltmeters are made for circuits ranging in voltage from 150 up to 750 volts. For higher voltages, voltage transformers are required.

Fig. 84 is a general view of an *induction indicating ammeter* also made by the Westinghouse Electric Company for switchboard service. It is identical in principle with the voltmeter above described, practically the only difference being in the primary coils of the current transformer which have fewer turns of larger wire. They are wound for 5 amperes and can be connected to circuits where smaller currents are to be measured and the voltage is less than 1,000 volts. When the current exceeds 5 amperes, series or current transformers are used, having their secondaries wound for 5 amperes.

Wattmeter. A good wattmeter is the standard instrument for measuring power in alternating-current circuits. The wattmeter




Fig. 84. Westinghouse Induction Indicating Ammeter

is an electro-dynamometer, of which one coil a , Fig. 85, made of fine wire, is connected to the terminals of the circuit CC , in which the power to be measured is expended. The other coil b , made of large wire, is connected in series with CC , as shown. The fine-wire coil a is movable, and carries the pointer which indicates on a divided scale the watts expended in CC .




Fig. 85. Diagram of an Alternating Circuit Containing a Wattmeter

Such an instrument *when calibrated with continuous current and electromotive force indicates power accurately when used with alternating currents*, provided the inductance of the circuit ar is small. This is true whatever the wave shape of the electromotive force or current, and whatever the character of the receiving circuit CC . Thus the circuit CC may have any reactance, as may be seen from the following discussion: A given deflection of the movable coil a depends upon a certain average or constant force action between the coils. Consider a continuous electromotive force E , which produces a current $\frac{E}{r}$ in a , and a current C in CC and b . The force action between the coils is proportional to the product of the currents in a and b ; that is, the force action is $k \times \frac{E}{r} \times C$, where k is a constant.

Consider an alternating electromotive force of which the instantaneous value is e ; this produces a current $\frac{e}{r}$ through a (provided the inductance of a is zero), and a current i in CC and b . The instantaneous force action between the coils is $k \times \frac{e}{r} \times i$; and the average force action is $\frac{k}{r} \times \text{average } ei$. If this alternating electromotive force gives the same deflection as the continuous electromotive force, then

or

$$\frac{k}{r} \times \text{average } ei = \frac{k}{r} EC$$

$$\text{average } ei = EC$$

that is, the given deflection indicates the same power whether the currents are alternating or direct.

Power Factor. Let P be the true power delivered to the circuit CC as measured by a wattmeter; let E be the effective electromotive force between the terminals of CC as measured by an alternating-current voltmeter; and let I be the effective current flowing in CC as measured by an alternating-current ammeter.

Then the ratio $\frac{P}{EI}$ is called the *power factor* of the circuit CC .

Examples. 1. The primary coil of a certain 5-kilowatt transformer with secondary coil open-circuited takes 0.14 ampere from 1,000-volt mains; and the power as measured by a wattmeter is 100 watts. The power factor, therefore, is

$$\frac{100 \text{ watts}}{1,000 \text{ volts} \times 0.14 \text{ ampere}} = 0.714$$

2. One of the stator circuits of a polyphase induction motor running unloaded has a power factor of 0.6. It takes 2 amperes from 200-volt mains. The true power, as would be indicated by a wattmeter, is

$$P = 200 \text{ volts} \times 2 \text{ amperes} \times 0.6 = 240 \text{ watts}$$

Compensated Wattmeter. If a wattmeter is connected as shown in Fig. 85, it measures the power delivered to the circuit CC plus the power consumed in heating the circuit ar ; hence the wattmeter reading is greater than the power delivered to the circuit CC .

Again, if a wattmeter is connected as shown in Fig. 86, it measures the power delivered to the circuit CC plus the power consumed in heating the coil b ; hence, in this case also, the wattmeter reading is greater than the power delivered to the circuit CC .

The *compensated wattmeter*, which is of the direct-deflection type, manufactured by the Weston Electrical Instrument Company, is designed to eliminate the above-mentioned sources of error in the following manner, the connections being shown in Fig. 85. Let C be the current in CC , and let a be the current in a and r . Then the current in b is $C+a$, and the force acting upon the movable coil is proportional to the product $a(C+a)$, instead of being proportional to the product aC . In the compensated wattmeter, the wire leading over to the coil a , con-




Fig. 86. Diagram of Alternating Circuit Containing Wattmeter Improperly Connected

nected as shown, is laid alongside each and every turn of wire in coil b . Then current $C+a$ flows down through b ; current a flows back alongside the wire of coil b ; and the result is the same as if the current a were subtracted from the current $C+a$, so far as the magnetic action of the coil b is concerned.

Portable Torsion Wattmeter. A portable wattmeter of the torsion type manufactured by the Roller-Smith Company, Figs. 87 and 88, is of the electro-dynamometer type but without the mercury cups of




Fig. 87. Roller-Smith Portable Torsion Wattmeter

the Siemens instrument, the current being led into and out of the fine wire movable (voltage) coil through the springs s and s_1 . Like the Siemens instrument, it is operated by rotating a torsion head through the nut k , Fig. 88, until the tension of the controlling springs s and s_1 balances the torque of the movable element a . The attainment of a balance between the two opposing forces is indicated when the needle h attached to the moving element registers with the zero mark on the scale. The amount of torsion required to bring the needle h back to zero is indicated by the scale reading of the index pointer e , which is secured to the torsion head j .

Referring to Fig. 88, the terminals for the current (fixed) coils c are shown at p , and those for the voltage (movable) coil a at p_1 .

The current coils *a* are clamped to and supported by a metal frame which is built up in sections, each section being carefully screwed and locked together, and the joints insulated to prevent the formation of eddy currents in the frame. The moving or voltage coil *a* is clamped to and supported by the staff *g*. The lower controlling spring *s*₁, is fastened to an arm which is rotated by the torsion head *j* by means of the rubber covered nut *k* projecting through the glass top of the wattmeter. The spring *s*₁ has its outer convolution secured to a lever which projects through the side of the case. By adjusting this lever, correction to zero may be made. The staff *g* is of brass with hardened and polished pivots resting in polished sapphire bearings. The improved construction of the torsion head ball bearing shown at *f* requires only the slightest turning effort, and unevenness




Fig. 88. Vertical Section of Roller-Smith Portable Torsion Wattmeter

in manipulation is obviated. Vibrations of the movable element are dampened by the vane which is enclosed in the nearly air-tight box *b*.

On the side opposite the dampening vane and just counterbalancing its weight is the needle *h* which passes up through a slot in the brass scale pan and indicates the position of the moving system on the dial. The scales of these instruments are about 10 inches long covering an arc of over 300 degrees, a feature which is favorable to accuracy of reading. Another advantage of this type of wattmeter is that the movable element is always brought back to the same position with respect to the field produced by the fixed coils when readings are being taken. This feature eliminates the error caused by a varying angle between the movable and fixed coils, and is of special importance when measuring power in circuits having different power factors.

A short scale shown at the top of Fig. 87 is drawn on either side of the zero line for the needle *h*. It is used when measuring the power of a fluctuating load and indicates the watts to be added or subtracted from the watts shown by the index pointer *e*.

These torsion-type wattmeters are made for standard maximum voltages of 150, 300, and 600 volts. For higher voltages, multipliers (large non-inductive resistances) to be connected in series with the voltage coil of the wattmeter are furnished. These wattmeters are made either for one current or for two different currents. The two-current instruments are furnished with binding posts arranged for connecting the current coils either in series or in parallel.

A torsion-type *polyphase* wattmeter, also made by the Roller-Smith Company, consists of two instrument mechanisms superimposed and having the two movable coils secured to a common staff; it gives accurate readings on two- or three-phase circuits, whether the load is balanced or not, and is equally useful on single-phase and on three-wire circuits.

INTEGRATING INSTRUMENTS

The *watt-hour meter* is an instrument for summing up (integrating) the total electrical work or energy expended in a circuit in a given time. It registers on suitable dials the energy in terms of kilowatt hours. These meters are often referred to as "recording wattmeters," though incorrectly, for they are not wattmeters, nor do they record. Commercial watt-hour meters may be divided into two classes, according to the principle they employ: (a) electro-dynamometer type, (b) induction type. They are all motor meters. Some are adapted to operate on direct current only, some on alternating current only (the induction type), and others on either kind of current.

Thomson Watt-Hour Meter. The Thomson watt-hour meter, made by the General Electric Company, is a small electric motor without iron, the field and armature coils of which constitute an electro-dynamometer. It is furnished with a small commutator and brushes, and though it may be used on both direct- and alternating-current circuits, it is principally used for direct-current work. For alternating currents the induction type of meter is usually employed.

The field coils *BB* of this motor, Fig. 89, are connected in

series with the circuit CC , in which the work to be measured is expended. The armature A , together with an auxiliary non-inductive resistance R , is connected between the terminals of the circuit CC , as shown. Current is led into the armature by means of the brushes dd pressing on a small silver commutator e .

The stationary and movable coils are connected to the mains and receiving circuit, that is, to the load, exactly as are the stationary and movable coils of the indicating wattmeter; and the torque which the stationary (field) coils exert upon the movable coil (armature) is proportional to the watts delivered; that is, is proportional to the rate at which energy is being delivered to the receiving circuit.

The instrument is so constructed that the speed of its armature is proportional to the torque that drives it. Therefore, the rate of




Fig. 89. Diagrammatic View of Thomson Watt-Hour Meter

turning of the armature is proportional to the rate at which energy is delivered to the circuit CC . Hence, *the total number of revolutions turned by the armature in a given time is proportional to the total energy expended in the circuit CC .*

To make the armature speed proportional to the driving torque, the armature is mounted so as to be free, as nearly as possible, from ordinary friction; and an aluminum disk f , Fig. 89, is mounted on the armature spindle so as to rotate between the poles of permanent steel magnets MM . To drive such a disk requires a driving torque proportional to its speed.

Starting Coil. In the above discussion it is assumed that the torque which opposes the motion of the armature *A*, Fig. 89, is proportional to the speed of the armature. In fact, however, this opposing torque may be considered as consisting of two parts: (1) the torque required to overcome friction; and (2) the torque required to overcome the damping action of the magnets on the aluminum disk. The first part of the torque may be taken to be approximately constant, while the second part is accurately proportional to the speed. Therefore, an arrangement for exerting on the armature a constant torque, sufficient to overcome friction, would largely eliminate errors due to friction. This is accomplished in the Thomson meter by supplementing the field coils *B*, Fig. 89, with an auxiliary field




Fig. 90. General View of Thomson Watt-Hour Meter

coil, called a *starting coil*, connected in the armature circuit. So long as the electromotive force between the mains does not vary, the current in the starting coil is constant and it, therefore, exerts a constant torque upon the armature. If, however, the electromotive force between the mains varies, the torque, due to the starting coil, varies with the square of the electromotive force.

Example. A certain watt-hour meter will not run, even if started by a slight impulse from the hand, until the delivered power reaches 37.5 watts; that is, the running friction of the watt-hour meter is equal to the driving torque produced by 37.5 watts of delivered power. This meter is adjusted (by moving the damping magnets) so as to read correctly when the delivered

power is 500 watts. What will the instrument indicate when run for four hours with constant delivery of 200 watts of power?

Solution. Express driving torque in terms of watts of power delivered to the receiving circuit, since the driving torque is proportional to the watts delivered. Let us express speed in terms of watt hours indicated by the dials per hour. Now, the speed is proportional to that part of the driving torque which is used to overcome the retarding action of the damping magnets. In the problem under consideration, the total driving torques are 500 watts and 200 watts, respectively; and since the running friction absorbs $37\frac{1}{2}$ watts of torque, the torques available for overcoming the retarding action of the damping magnets are, respectively, $(500 - 37\frac{1}{2})$ watts and $(200 - 37\frac{1}{2})$ watts. The speed in the first case is 500 watt hours per hour. Let x be the speed (watt hours indicated per hour) in the second case. Then

$$(500 - 37\frac{1}{2}) : (200 - 37\frac{1}{2}) :: 500 : x$$

This gives a value of 175.6 watt hours per hour for x , so that the watt hours recorded in four hours run will be 4×175.6 watt hours per hour, or 702.4 watt hours. The actual total of watt hours delivered is of course 4 hours \times 200 watts, or 800 watt hours.

The effect of running friction in a watt-hour meter is to cause the instrument to read low for an amount of delivered power that is less than the delivered power for which the damping magnets are adjusted to give a correct reading.

Fig. 90 shows a general view of a Thomson watt-hour meter. Fig. 91 shows the connections of a Thomson watt-hour meter to two-wire supply mains, and Fig. 92 shows the connections to three-wire supply mains.

Induction Watt-hour Meter.

The single-phase induction watt-hour meter has many advantages over the type using commutator and brushes, and in one form or another is very extensively used in




Fig. 91. Thomson Watt-Hour Meter Connected to a Two-Wire Current Supply




Fig. 92. Thomson Watt-Hour Meter Connected to a Three-Wire Current Supply

measuring electrical energy. In principle and operation it is merely a small single-phase induction motor having stationary shunt and series windings so related and arranged with respect to the laminated iron core as to produce a rotating field, which acting upon a closed movable secondary causes it to rotate. The shunt or voltage winding, consisting of a large number of turns of fine wire wound on a laminated iron core, has a high inductance and, therefore, the current in it lags about 90 degrees behind the impressed line voltage. The series, or current, winding composed of but a few turns of coarse wire, has a very low resistance and inductance and, therefore, the current in it will be in phase with the impressed voltage, if the circuit in which the energy is being measured, is non-inductive. Thus the field produced by the shunt winding will lag approximately 90 degrees behind that of the series winding, on a non-inductive load. When, therefore, the alternating current in the series coil has its maximum value, the current in the shunt coil has its minimum value. If it were not for the iron core loss and copper (I^2R) loss in the shunt coil, the angle of lag would be exactly 90°. In commercial meters provision is made for making this angle 90°, whatever the power factor of the circuit may be. The strength of the rotating field flux, that is, the resultant produced by the series and shunt coils together, assuming a lag of exactly 90°, is proportional to the product of the currents in the two coils and, therefore, proportional to the product of the current and the voltage in the circuit being measured. At any power factor less than unity, the resultant field flux is proportional to this product multiplied by the sine of the angle of phase difference between the two meter currents. If the current in the voltage coil is exactly in quadrature with the voltage of the metered circuit, at any power factor the sine of the angle of phase difference between the currents in the meter circuits will be equal to the cosine of the angular displacement between the current and voltage in the metered circuit. Under these conditions, therefore, the strength of the shifting field is proportional also to the power factor of the circuit. In other words, the strength of the rotating field is proportional to the product of the volts, amperes, and power factor and is, therefore, a measure of the actual power.

Single-Phase. A view of a typical single-phase watt-hour

Thus, at one instant the shunt pole tips A , C , and A' are maximum $+$, $-$, and $+$, respectively, because the instantaneous value of the current is maximum, while the value of the series flux is zero. At $\frac{1}{4}$ period later the shunt current is zero, giving zero magnetic potential at the pole tips, while the series current has reached a maximum value, giving maximum $-$ and $+$ at the pole tips B and D . At the next $\frac{1}{4}$ period the shunt current is again maximum but in a direction opposite to what it was at the beginning, making the pole tips A , C , and A' $-$, $+$, and $-$, respectively, while the series current




Fig. 94. Westinghouse Single-Phase Watt-Hour Meter with Case Removed

again is zero. Continuing, the other relations of $+$ and $-$ poles shown in Fig. 96 are obtained. It will be observed from the table that both the $+$ and $-$ signs move constantly in the direction from A' to A , indicating a shifting of the field in this direction, the process being repeated during each cycle.

The losses in the meter coils are very low, particularly when compared with the high torque developed. The potential coils

have a loss of 1.4 to 1.8 watts per phase and the series coil produces a drop of only 0.4 volt at full load.

The *moving element* consists of a thin aluminum disk which rotates about a vertical shaft in the air gap in which the rotating magnetic flux is produced. The disk acts like the squirrel-cage rotor (armature) of an induction motor. Currents are induced in it which combine with the rotating field to produce a torque proportional to the power in the circuit. This torque is counterbalanced by that due to

the generator action of the permanent retarding magnets in inducing currents in the disk, so that the speed is exactly proportional to the torque. In this meter the disk performs two distinct functions. It serves not only as the armature of a motor, but also as the retarding or generator element, the disk being rotated by the meter field at one edge while it is retarded by the permanent magnet field at the opposite edge.

The *power factor adjustment*, Fig. 94, consists of a short-circuited loop enclosing part or all of the shunt field flux. The flux induces a current in the loop which, acting with the current in the shunt coil, produces a slightly lagging field. By shifting the position, or changing the




Fig. 95. Diagram of Electromagnetic Circuit of Westinghouse Single-Phase Watt-Hour Meter

START	A +	B 0	C -	D 0	A*
1/4 PERIOD	0	-	0	*	0
1/2 PERIOD	-	0	*	0	-
3/4 PERIOD	0	*	0	-	0
FULL PERIOD	*	0	-	0	+




Fig. 96. Diagram of Relation between Field Fluxes for One Cycle

resistance, of this loop, the lag may be so adjusted that the shunt field flux is exactly 90 degrees behind the voltage in phase. This adjustment, however, makes the meter correct at or near one particular frequency only. This type of meter should be calibrated and adjusted at or near the frequency at which it is to be used. When such a meter has been adjusted to read correctly at or near some particular frequency, such as 60 cycles, it will read too low at higher frequencies, as is shown by the lowest of the curves in Fig. 97.





Fig. 97. Curves Showing Per Cent of Variation in Registration of Single-Phase Watt-Hour Meter for Variation in Load, Voltage, and Frequency

The three curves of Fig. 97 show graphically the per cent of variation in registration of these meters due to any per cent of variation in load, voltage, and frequency.


All meters of this type have some initial bearing friction which if not compensated for would require a portion of the driving torque of the meter to overcome it, and would result in no rotation at very small loads, and in general the meter registration would be too low at light loads. *Compensation for initial friction* especially when the meter is running on light loads is, therefore, important and consists in providing a constant torque adjustable to the exact value of the

frictional torque, and one entirely independent of the load on the meter. The compensating torque, moreover, must not be so great as to cause the moving element to rotate or "creep" when no current is passing in the series coil.




[Fig. 98. Westinghouse "Type C" Polyphase Induction Watt-Hour Meter


Compensation for meter friction, or "light load adjustment," is made by slightly unbalancing the magnetic fluxes in the two limbs of the shunt magnetic circuit. To do this a short-circuited loop is placed in each air gap and by moving either of the two screws shown at *C*, Fig. 93, and at *C'*, Fig. 98, the position of the loops may be changed, so that one loop will enclose and choke back more of the




No.1=1,111,100




No.6 =99,700




No.2= 999,900




No.7=9,912,100




No.3=1,000,100




No.8= 9,928,000




No. 4= 9,999,500



No.9=9,918,100



No.5 =909,100.



No.10=9,928,300.

Fig. 99. Illustrative Watt-Hour Meter Readings

flux than the other loop, and thus produce a slight torque in the disk. This slight torque depends only on the voltage which is practically constant, and is entirely independent of the load current.

Polyphase. The polyphase induction watt-hour meter is virtually two independent single-phase meter elements having a common shaft. Each meter element exerts a torque on the shaft and the combined torque is, therefore, proportional to the sum of the electrical energy in the two phases being measured, regardless of the phase relation between the phases. These polyphase meters when properly connected indicate the true energy in a polyphase system, whatever the degree of unbalance between the phases may be, and for any power factor.

Fig. 98 shows a Westinghouse "Type C" polyphase induction watt-hour meter with covers removed. It is evident that it is practically two single-phase watt-hour meters combined to make one instrument.

Directions for Reading Watt-Hour Meter Dials. To read correctly the dial of a watt-hour meter, some care is necessary. The figures marked under or over a dial (1,000, 10,000, etc.), are the amounts recorded by a complete revolution of the hand; therefore, one division on a dial indicates one-tenth of the amount indicated above or below. A complete revolution of the first hand (the one to the extreme right) in No. 6, Fig. 99, for example, indicates 1,000, and moves the second hand one division of the second dial. The first hand, in the position given, indicates 700—not 7,000.

In deciding on the reading of a hand, the hand before it (to the right) must be consulted. Unless the hand before it has reached or passed the 0, or in other words completed a revolution, the other has not completed the division on which it may appear to rest. For this reason, ease and rapidity are gained by reading a meter from right to left. For example, in No. 2, the first dial (the extreme right) reads 900. The second apparently indicates 0; but, since the first has not completed its revolution, but indicates only 9, the second cannot have completed its division; hence the second dial also indicates 9. The same is true of the hand of the third dial; the second, being 9, has not quite completed its revolution; so the third has not completed its division and, therefore, we again have 9. The same holds true of the hand of the fourth dial. The last hand (the extreme

left) appears to rest on 1; but since the fourth is only 9, the last has not completed its division and, therefore, indicates 0. Putting the figures down from right to left, the total reading is 999,900, though one might erroneously read 1,999,900, making a mistake of 1,000,000 units.

The hands sometimes become slightly misplaced, as shown in Nos. 8, 9, and 10. In No. 8 we have on the first dial (the extreme right) 0; we, therefore, put down three zeros thus, 000. The hand of the second dial is misplaced; for inasmuch as the first registers 0,




Fig. 100. Graphical Chart for Calculating Customers' Bills

the second should rest exactly on a division; therefore, we know that it should have reached 8, making 8,000. The remaining hands are correct, and make a total of 9,928,000.

In No. 9 the second hand is misplaced; for since the first indicates 1, the second should have just passed a division, and, as it is nearest to the 8, we know it should have just passed that figure. The remaining three hands are approximately correct. The total reading is 9,918,100.

In No. 10 the second hand is behind its correct position. The total indication is 9,928,300.

By carefully following these directions one will find little difficulty in reading a meter even if the hands become misplaced. The above directions apply to watt-hour meters of all kinds—induction type as well as Thomson meters.

Calculations of Customers' Bills. The consumption of energy in watt hours being known, the exact amount of the bill can at once be read from a *price chart*, one of which is shown in Fig. 100. Dollars and cents are read from the vertical line at the left, while the horizontal line at the bottom of the chart indicates thousands of watt hours. To determine the amount to be charged for, say 28,000 watt hours at $12\frac{1}{2}$ cents per 1,000 watt hours, follow the




Fig. 101. High Potential Testing Transformer of the General Electric Company


vertical line marked 28 to its intersection with the diagonal line marked $12\frac{1}{2}$ cents. From the intersection of these two lines, follow the horizontal line to the left, and find \$3.50, which is the amount of the bill for 28,000 watt hours at $12\frac{1}{2}$ cents per 1,000 watt hours. In practice, of course, the price chart would be drawn to a large scale for accuracy in reading.

Spark Gauge. The high electromotive forces used in break-down tests are usually measured by means of the spark gauge. This consists of an adjustable air gap, which is changed until the electromotive force to be measured is just able to strike across

in the form of a spark. The electromotive force is then taken from empirical tables such as Table VIII, Part III, page 192, which are based upon previous measurements of the electromotive force required to strike across various widths of gap. In the spark gauge of the General Electric Company, the spark gap is between metal points, one of which is attached to a micrometer screw whereby the gap space may be adjusted and measured. The striking distance in any spark gauge varies greatly with the condition of the points. It is, therefore, necessary to see that the points are sharp and well polished before taking measurements.

Fig. 101 is a general view of the high-potential testing transformer of the General Electric Company. The spark gauge is shown mounted on top of the instrument. While being used, the gauge is protected by a cover. The function of this cover is to keep the observer's fingers from the dangerous high-voltage points of the gauge; and the cover, moreover, acts as a switch which automatically disconnects the gauge from the high-voltage terminals of the transformer when the cover is removed.





5,000 K. W.. 4-1,000 VOLT, THREE-PHASE, ENGINE TYPE A. C. GÉNÉRATORS—69th STREET STATION
INTERBOROUGH RAPID TRANSIT COMPANY, NEW YORK, N. Y.
Westinghouse Electric & Manufacturing Co.

ALTERNATING-CURRENT MACHINERY

PART II

ALTERNATORS

Fundamental Equation of Alternator. The equation expressing the effective electromotive force of an alternator in terms of the useful magnetic flux per pole, the number of poles, the number of armature conductors, and the speed of the armature, is called, from its importance in calculations in designing, the *fundamental equation of the alternator*. This equation is

$$E = \frac{K p \Phi n Z}{10^8} \text{ volts} \quad (29)$$

in which E is the effective electromotive force of the alternator; K is what we shall call the electromotive force factor of the machine and its value depends upon the ratio of breadth of pole face to pole pitch, and upon the distribution of windings upon the armature core;




Fig. 102. Concentrated or Uni-coil Winding

p is the number of poles of the field magnet; Φ is the useful magnetic flux per pole, that is, the number of lines of magnetic flux that cross the gap from one pole into the armature; n is the speed of the armature in revolutions per second; and Z is the total number of conductors on the surface of the armature.

We shall discuss this equation for the simplest case first, that is, when the armature conductors are concentrated in one slot per pole. This type of winding is called a concentrated, or uni-coil, winding, illustrated in part in Fig. 102.

A given conductor cuts $p\Phi$ lines of force in passing all of the poles in one revolution, and since the armature makes n revolutions per second, the given conductor cuts $np\Phi$ lines of force per second. Now, by definition, the cutting of one line of force per second induces

Copyright, 1911, by American School of Correspondence.

in a conductor one c. g. s. (centimeter-gram-second) unit of electromotive force. Therefore, there is an average of $np\Phi$ c. g. s. units of electromotive force induced in one armature conductor; but since there are Z armature conductors in series between the collector rings, the average electromotive force between collector rings is $Znp\Phi$ c. g. s. units, or $\frac{Znp\Phi}{10^8}$ volts.

The factor by which the average electromotive force must be multiplied to give the effective electromotive force is called the *form factor of the electromotive force curve of the alternator*. Therefore, if K is this form factor, we have

$$\text{effective } E = \frac{KZnp\Phi}{10^8} \text{ volts}$$

Since $\frac{Z}{2} = T$, or $Z = 2T$ and since $pn = 2f$, this equation may be written so as to give the electromotive force (effective) of the alternator in terms of the number of turns T of wire on the armature, and of the frequency f , as follows:

$$E = \frac{4K\Phi f T}{10^8} \text{ volts} \quad (30)$$

For example, an alternator has 200 turns of wire on its armature and 1,000,000 lines of magnetic flux from each field pole. It is run to give a frequency of 125 cycles per second. The value of the factor K is 1.11, assuming a sine-wave electromotive force curve and concentrated winding. The effective electromotive force of this alternator, therefore, is

$$\frac{4 \times 1.11 \times 10^6 \times 125 \times 200}{10^8} = 1,110 \text{ volts}$$

Electromotive Force Factor K in Equation (29). When the magnetic flux in the air gap is distributed in the ideal way explained below and represented in Fig. 103, the factor K is called the *phase constant* of the winding.

When the winding is concentrated, the factor K is called the *form factor* of the electromotive force curve. This factor K depends in general upon the manner in which the magnetic flux is distributed

in the air gap, and upon the manner in which the armature windings are distributed around the armature.

CASE 1. *When a harmonic electromotive force is induced in each turn of the armature winding.* This is the case—never fully realized




Fig. 103. Ideal Distribution of Magnetic Flux




Fig. 104. Armature Winding Diagram. Four Slots per Pole

in practice—when the magnetic flux-density—that is, the field intensity in the gap space between the pole faces and the iron of the armature core—is zero at the points *a*, Fig. 103, and when this field intensity increases to a maximum at *c* and at *c'* in such a manner that the field intensity at any point *b* is proportional to the sine of the angle β .

Consider an armature rotating in a magnetic field distributed in the ideal way above specified. Suppose the winding to be arranged in slots spaced as shown in Fig. 104, four slots per pole. Fig. 105 shows one group *a b c d* of these slots drawn to a larger scale. Two wires on the armature, at a distance apart equal to the distance between adjacent north poles, and subtending the angle q , Fig. 105, have induced in them two electromotive forces. These electromotive forces are to be thought of as differing in phase by 360° , because of the fact that the electromotive force in a given conductor passes through a complete cycle while the conductor moves from the center of a given north pole to the center of the next north pole.




Fig. 105. Enlarged Section of Fig. 104

Therefore, the phase difference of the electromotive forces induced in the wires placed in slot a , and those induced in the wires placed in

slot b , is $\frac{s}{q} \times 360$; or, in other words, this angle is:

$$\frac{\text{width of tooth} + \text{width of slot}}{\text{circumference of armature} \div \text{number of pairs of poles}} \times 360$$

The lines A and B in the clock diagram, Fig. 106, represent in magnitude and phase the electromotive forces induced in the wires




Fig. 106. Clock Diagram of Induced E. M. F.'s for Fig. 105

in slots a and b , respectively, Fig. 104. Similarly, the lines C and D in Fig. 106 represent the electromotive forces induced in the wires in slots c and d , respectively, Fig. 104. If, now, the windings in the slots a , b , c , and d , Fig. 104, are as in practice

connected in series, the total electromotive force produced by all the windings will be represented by the line E in Fig. 106. The line E is the closing side of the polygon of which the sides A , B' , C' , and D' are drawn respectively, parallel and equal to the electromotive force lines A , B , C , and D . The value of K , which, in the case of the ideally distributed field flux here considered, is called the *phase constant* of the winding, is equal to the ratio $\frac{E}{4A}$; that is, the value of K is equal to the ratio of the length of the line E to four times the length of one of the lines A , B , C , or D .

CASE 2. *When a harmonic electromotive force is not induced in each turn of the armature winding.* We shall discuss, (a) the case of a *concentrated* winding in which case K is simply the *form factor* of the electromotive force wave; and (b) the case of a *distributed* winding.

(a) Fig. 107 shows a developed view of a four-pole alternator having four armature conductors a , b , c , and d , represented by the symbols \ominus and \oplus depending upon whether the induced electromotive forces are directed *towards* or *away from* the reader, respectively. Of course, these four conductors are connected in series between the collecting rings (not shown in the figure) and in tracing

the circuit from one collecting ring to the other, one would pass down along conductor *a*, then across to conductor *b*, up *b*, then across to conductor *c*, down *c*, then across to conductor *d*, up *d*, and then to the other collecting ring.

Let time be reckoned from the instant when conductor *a* is in the position shown; and let time be plotted as abscissas, and successive values of the induced electromotive force as ordinates, in the diagram *AB*, Fig. 107. Suppose that the intensity of the magnetic field in the gap space between pole faces and armature core is uniform, and that it terminates sharply at the pole tips, that is, that there is no spreading of the lines of force such as is shown in Fig. 103; as a matter of fact, however, the field always does spread. The armature conductors move with uniform velocity to the right, and the ratio of breadth of pole face, 6 inches, to pole pitch, 10 inches, is .6.

Then, during each cycle the duration of which is 20 units of time, the successive instantaneous values of the induced electromotive force are: constant, positive, and equal to *E* for 6 units of time;




Fig. 107. Development and E. M. F. Curve for a Four-Pole Alternator

zero for 4 units of time; constant, negative, and equal to *E* for 6 units of time; and again zero for 4 units of time. The average value of the electromotive force during the first half cycle is, therefore, equal to

$$\frac{(E \times 6) + (0 \times 4)}{10} = .6 E \text{ volts}$$

The squares of the successive instantaneous values of the induced electromotive force are: constant, positive, and equal to E^2 for 6 units of time; zero for 4 units of time; and so on. The average value of the squares of the successive instantaneous values of the induced electromotive force during half a cycle is, therefore, equal to

$$\frac{(E^2 \times 6) + (0^2 \times 4)}{10} \text{ volts}^2 = .6 E^2 \text{ volts}^2$$

or

effective value of induced electromotive force = $\sqrt{.6} \times E$ volts

The value of K (form factor), in this particular case of a *concentrated* winding, is

$$K = \frac{\text{effective value}}{\text{average value}} = \frac{\sqrt{.6} E}{.6 E} = 1.29$$

The value of K for a concentrated winding may be calculated, as in the above example, for any breadth of pole face.

(b) The value of K , in the case of a *distributed* winding, is cal-




Fig. 108. Development and E. M. F. Curve of Four-Pole Alternator with Two Conductors for Each Field Pole

culated as follows, assuming, for the sake of clearness, a ratio of pole breadth to pole pitch of $\frac{12}{20} = 0.6$.

Fig. 108 shows a four-pole alternator with two armature conductors a and b for each field pole. (Only two of these conductors are shown in the figure.) The curve of the electromotive force induced in all the a conductors is shown by the rectangular waves AB . This electromotive force has a constant, positive value E

for 12 units of time; then a zero value for 8 units of time; then a constant, negative value E for 12 units of time; and so on.

The curve of the electromotive force induced in all the b conductors is shown by the rectangular waves CD . This electromotive force rises from zero to the full value E at the instant when the conductors b are in the position of a , as shown in the figure; that is, the electromotive force induced in conductors b rises from zero to its full value E , 7 units of time before the corresponding rise of the electromotive force occurs in conductors a .

The total electromotive force curve EF is found by adding corresponding ordinates of the curves AB and CD . A careful inspection and comparison of AB and CD shows that the total electromotive force of the alternator is zero for 1 unit of time, equal to E for 7 units of time, equal to $2E$ for 5 units of time, and equal to E for 7 units of time, during each half cycle of 20 units of time. Therefore, the average value of the electromotive force EF during half a cycle is

$$\frac{(0 \times 1) + (E \times 7) + (2E \times 5) + (E \times 7)}{20} = \frac{24}{20} \times E = 1.2 E$$

Referring to the curve EF , Fig. 108, it is evident that the squares of the successive instantaneous values of the total electromotive force of the machine are as follows: 0^2 for one unit of time, E^2 for seven units of time, $(2E)^2$ for five units of time, and E^2 for seven units of time, during each half cycle of twenty units of time. Therefore, the average value of the squares of the electromotive force EF during half a cycle, is

$$\frac{(0^2 \times 1) + (E^2 \times 7) + (4E^2 \times 5) + (E^2 \times 7)}{20} = \frac{34}{20} \times E^2$$

and the effective value of the electromotive force EF is

$$\sqrt{\frac{34}{20}} \times E = 1.304 E$$

The value of K for the special case under consideration, as shown in Fig. 108, is the ratio

$$\frac{\text{effective electromotive force}}{\text{average electromotive force}} = \frac{1.304}{1.2} = 1.087$$

which is simply the form factor of the electromotive force curve of the alternator. The form factor of a sine wave electromotive force has already been shown to be 1.11.

NOTE.—The factor K is the same thing as form factor whenever the distance ab , Fig. 108, between the remotest conductors of a group of conductors is less than the distance cd between the pole tips, on the assumption that the magnetic lines of force do not spread into the spaces between the pole tips.

Armature Reaction. The current that circulates in an alternator armature has magnetizing action; and the actual useful flux Φ per pole is due to the combined magnetizing action of the field coils and of the armature coils. This magnetizing action of the armature current with respect to its effect upon the useful flux Φ , is called *armature reaction*. In case the current in the armature *lags behind* the electromotive force—when, for example, the outside receiving circuit has inductance, as when the alternator




Fig. 109. Portion of Armature and Field Coil for Single-Phase Alternator

supplies current to induction motors—the effect of armature reaction is to *reduce* the useful flux Φ from each pole: In case the current in the armature is *ahead of* the electromotive force in phase (a condition that obtains when the alternator supplies current to an over-excited synchronous motor or to any receiving apparatus over a long transmission line, or, in general, when the receiving apparatus acts like a condenser), the effect of armature reaction is to increase the useful flux Φ from each pole.

To state the matter in another way, it may be said that the effect of a lagging armature current is to oppose the magnetizing action of the field coils. On the other hand, the effect of a leading current in the armature is to help the magnetizing action of the field coils.

In an alternator the invisible variations in phase difference between the armature current and the electromotive force, due to the varying character of the receiving apparatus, correspond, in their influence on armature reaction, to the visible variations in the position of the brushes of a direct-current generator.

Fig. 109 represents a single-phase alternator of the revolving armature type running in the direction indicated by the curved arrow. The electromotive force induced in the armature coil A is zero at the instant when the armature is in the position shown; and if the armature current is in phase with the induced electromotive force, the current also will be zero at this instant.

In considering armature reaction we shall discuss three cases, as follows:

1. Armature current in phase with the electromotive force
2. Armature current lagging behind the electromotive force.
3. Armature current leading the electromotive force.

CASE 1. As the armature tooth A , Fig. 109, passes by the field pole N , the current in the armature coil on A is reversed in direction. If the current is in phase with the electromotive force induced in the armature, this reversal of direction of current occurs at the instant when the tooth A is squarely under N . In this case the armature current flowing in coil A just previous to the reversal, that is, when the tooth A is approaching N , *opposes* by its magnetizing action the flux from N ; and after reversal the current in the coil A *helps* the flux from N . Therefore, the former or demagnetizing action of coil A is balanced by the subsequent magnetizing action; and the only effect of the armature current in A is to weaken the one side of the pole N , and to strengthen to an equal extent the other side, thus leaving the useful flux Φ unchanged.

CASE 2. When the current lags behind the electromotive force, the reversal of current in the coil A occurs at a later instant than in Case 1, that is, when the coil A has passed beyond the center of the pole N . Hence, the demagnetizing action of the current in coil A before reversal lasts for a longer time than the magnetizing action of the current in coil A after reversal, and the demagnetizing action exceeds the magnetizing action. Therefore, the resultant effect of the armature reaction is to decrease the useful flux Φ from the pole N .

CASE 3. When the current is in advance of the electromotive force in phase, the reversal of current in the coil A occurs at an instant earlier than in Case 1, that is, before the coil A has reached the center of the pole N . Hence, the demagnetizing action of the

current in coil A before reversal lasts for a shorter time than the magnetizing action of the current in coil A after reversal, and the magnetizing action exceeds the demagnetizing action. Therefore, the resultant effect of the armature reaction is to increase the useful flux Φ from the pole N .

Armature Inductance. The value of the inductance of an alternator armature varies with the position of the armature coils with respect to the field-magnet poles, so that the inductance of an armature increases and decreases at a frequency twice* as great as the frequency of the electromotive force of the alternator. It is helpful to remember that inductance is proportional to the product of the magnetic flux into the number of turns threaded by this flux, divided by the amperes passing through the turns. The armature of the alternator shown in Fig. 1, page 2, for example, has about three or four times as much inductance when the armature teeth are squarely under the field poles as it has when the armature teeth are midway between field poles. That is, the magnetic flux produced through the armature teeth by a given current is three or four times as great in the first case as in the second case. This fluctuation of armature inductance makes it very difficult to predetermine the electromotive force and, in general, the behavior of a machine. In the following discussion the armature inductance is assumed to be constant.

The inductance of an alternator armature is proportional to the linear dimensions of the armature, other things being equal; and the inductance of an armature of given size and given total number of turns is much greater when the winding is concentrated than it is when the winding is distributed.

A moderate amount of armature inductance is advantageous in alternators which are to be run in parallel; and in case of a short-circuit, the armature inductance keeps the current from becoming excessive. On the other hand, armature inductance is more or less objectionable in an alternator which is to be used to supply current at constant electromotive force, on account of the electromotive force that is lost in the armature.

*The electromotive force of an alternator passes through a cycle when an armature coil passes from a north pole of the field to the next north pole. The inductance passes through a cycle of values when an armature coil passes from one field pole to the next field pole.

The inductance of an armature is best determined by sending through it when at rest, from an outside source, a measured alternating current I , and measuring the electromotive force E (volts drop) between the collecting rings. Then

$$E = I\sqrt{R^2 + \omega^2 L^2}$$

or, solving for L , we have

$$L = \frac{1}{I\omega} \sqrt{E^2 - (IR)^2} \quad (31)$$

Knowing the armature resistance and the frequency $\frac{\omega}{2\pi}$, we can find L from equation (31). The value of L thus calculated depends greatly upon the position in which the armature is held, as explained above, and also upon the degree of field excitation.

For example, the armature of a certain single-phase alternator has a resistance of 0.2 ohm measured between collector rings. An electromotive force of 100 volts at a frequency of 125 cycles per second ($\omega = 785$ radians per second) applied to the collecting rings of the armature at rest, produces an effective current of 100 amperes. Therefore, the inductance of the armature, as calculated by use of equation (31), is

$$L = \frac{1}{100 \times 785} \sqrt{100^2 - 20^2} = 0.00125 \text{ henry}$$

Electromotive Force Lost in Armature Drop. The electromotive force between the collecting rings of an alternator with given load, is less than the electromotive force between rings at zero load, with given field excitation, because of two electromotive force losses that occur, and because of the effect of armature reaction.

(a) The loss of electromotive force, or the drop, is due, in the first place, to the resistance of the armature. This loss is equal to IR ; it is in phase with I ; and it is precisely analogous to the electromotive force lost in a direct-current armature due to the resistance of the armature. This IR drop is of relatively small value and importance.

(b) The loss of electromotive force, or the drop, is due, secondly, to the inductance of the armature. This loss is equal to ωLI , and it is 90 degrees ahead of I in phase.

(c) The demagnetizing action of the armature current on the field lessens the useful flux, and thus indirectly causes a falling-off in the induced electromotive force.

The result of the actions (b) and (c) above is to cause a loss of electromotive force in the armature of the same character in each case in so far as phase relations with current are concerned. Therefore, it is convenient to attribute the total effect of (b) and (c) to a fictitious armature inductance L' , which is, of course, larger in value than the armature inductance L in equation (31). The inductance reactance $\omega L'$ corresponding to this equivalent inductance L' , is called the *synchronous reactance* of the armature.

Alternator Regulation. Given an alternator, having constant field excitation. It has a certain electromotive force between collecting rings when its current output is zero. As the current output increases, the electromotive force between collector rings generally decreases, because of the actions already described; and, conversely, as the current output decreases, the terminal electromotive force rises. The *increase* of electromotive force from full load to zero load, with constant full-load field excitation and constant speed of driving, expressed as a percentage of the full-load terminal electromotive force, is called regulation of the alternator.

For example, a certain alternator gives 1,100 volts between its collector rings at full-load current and full-load field excitation. When the current output is decreased to zero by opening the main switch, leaving the field excitation and speed unchanged, the terminal electromotive force rises to 1,166 volts. The regulation is, therefore,

$$\frac{1,166 - 1,100}{1,100} \times 100 = 6 \text{ per cent}$$

The regulation of a given alternator varies greatly with the character of the receiving circuit to which it delivers current. When the receiving circuit has large inductance reactance (as in the case of under-loaded transformers and induction motors), the terminal electromotive force, under increasing load, falls off very much more than when the receiving circuit is non-inductive (as, for example, when the receiving circuit consists of incandescent lamps supplied through fully loaded transformers). In other words, the regulation of an alternator is larger (*i. e.*, poorer) for in-

ductive receiving circuits than for non-inductive receiving circuits. If the receiving circuit has large capacity reactance (as, for example, when the receiving circuit consists of over-excited synchronous motors), the terminal electromotive force of the alternator will rise with an increase of the current output; and the regulation of the alternator will be negative. In practice, the receiving circuit never as a whole has capacity reactance.

For example, a given alternator having a regulation of 8 per cent on a non-inductive receiving circuit (unity power factor), has a regulation of about 21 per cent on an inductive receiving circuit having a power factor of 0.9 and a regulation of about 26 per cent at a power factor of 0.8 (lagging).

Field Excitation. In most alternating-current systems the voltage at the points from which current is distributed is kept constant or approximately constant. This requires that the voltage at the terminals of the alternator be somewhat increased as the amount of current (or load) is increased, the amount of the increase in electromotive force depending on the volts lost in the line. If the field excitation of an alternator be kept constant while the current taken from the armature is increased, the voltage at the terminals will decrease, just as in the case of a direct-current shunt generator. Hence, in order to keep the voltage at the terminals constant, or to cause a rise of voltage with increasing current output, it becomes necessary to increase the field excitation with increasing current output.

There are in general three methods in use for accomplishing this voltage control.

(1) By varying the field excitation with the load.

(a) Through control of the field-exciting current of the alternator by a rheostat operated either by hand or automatically from the alternator.

(b) Through control of the exciter itself by the main current from the alternator with or without a rheostat. This is accomplished in one of the three following ways: *first*, compounding the exciter with rectified current supplied to its field circuit; *second*, by supplying the armature circuit of the exciter with alternating current from the alternator (compensated field method); and *third*, by an external regulator for varying the exciter field current by rapidly

short-circuiting its field rheostat, the duration of the periods of short-circuit depending on the terminal voltage of the alternator (Tirrill regulator).

(2) By interaction between the fields of the alternator and its exciter. This is Heyland's method which is used abroad but not in this country. Use is made of the stray flux from the alternator field which is arranged to strengthen the field of the exciter and thus obtain a compounding effect. The reaction on the field of the exciter is proportional to the armature reaction of the alternator and the terminal voltage of the exciter follows closely the variations in the load on the alternator.

(3) By utilizing the magnetic flux due to the armature current so that the armature reaction of the alternator increases the




Fig. 110. Diagram Showing Method of Separate Excitation


total flux per pole, and thus increases the voltage of the alternator as the load increases. The exciting field current itself is not varied. This is Walker's method and it has been used by the British Westinghouse Company.

Of the above methods the first includes practically all that are used at present in this country. The tendency is to abandon the

attempts to design alternators to be inherently self-regulating and to avoid as far as possible all special devices internal to the alternator and its exciter for securing automatic voltage control, and to adopt instead an automatic regulator external to the alternator.

Under method (1) will be described the three commonest ways of voltage control employed at present, namely, separate excitation; composite excitation, and the automatic regulator, external to the alternator.

CASE 1. Separate excitation. The simplest method is that illustrated by the diagram, Fig. 110, in which *A* represents the armature winding, the terminals of which T_1 and T_2 are connected to the collector rings, which in turn are connected to the line wires through the brushes.



VIEW IN ENGINE ROOM OF THE CORN PRODUCTS REFINING COMPANY SHOWING GENERATORS AND EXCITERS
Courtesy of *Alts-Chalmers Company, Milwaukee, Wis.*

The field of the alternator is excited by a set of coils on the pole pieces. These coils are represented by F ; and current is supplied to these coils from a small direct-current dynamo E , called the *exciter*. This exciter is a small direct-current shunt-wound or compound-wound dynamo furnished with an adjustable rheostat r in series with its field f . An adjustable rheostat R is placed in the alternator field circuit also. When the electromotive force of the alternator decreases, its field may be strengthened by cutting out resistance in either R or r , or in both.

Regulation by r alone is generally used in large machines, since the exciter's field current is relatively small, while the alternator field current is usually large and hence would cause a large $I^2 R$ loss if passed through a rheostat. Separate excitation is still used in some of the older electric lighting stations.

CASE 2. *Composite excitation.* The electromotive force of an alternator excited as in Case 1 falls off greatly with increasing current output; and to counteract this tendency automatically, an auxiliary field excitation is sometimes provided, which increases with the current output of the machine. For this purpose the whole or a portion of the current given out by the machine is rectified,* and sent through the auxiliary field coils. This arrangement is shown in Fig. 111.




Fig. 111. Diagram Showing Method of Composite Excitation

The field winding of the alternator has two sets of coils F and C . The coils F are separately excited as in Case 1. The coils C , known as the "series" or "composite coils," are excited by the main current from the alternator. One terminal of the armature winding is connected directly to a collecting ring. The other armature terminal connects to one set of alternate bars of the rectifying

*Connections to field coils are reversed with every reversal of main current, so that, in the field coils, the current is uni-directional.

commutator *B*. From the rectifier the current is led through the winding *C*, thence back to the rectifier, and thence to the other collecting ring. The shunt *S*, within the commutator, may be used when it is desired to rectify only a part of the current. There is also a shunt *S'* which may be used to regulate the amount of current flowing through the coil *C*.

The alternating-current rectifier is an arrangement for reversing the connections of the field circuit with each reversal of the current from the alternator, so that the current may flow always in the same direction in the field circuit. The rectifier is a commutator mounted on the armature shaft. This commutator has as




Fig. 112. Diagram Showing Composite Excitation with Transformer

many bars as there are poles on the field magnet of the alternator. These bars are wide, and are separated by quite narrow spaces filled with mica insulation. Let these bars be numbered in order around the commutator. The even-numbered bars are connected together, and the odd-numbered bars are connected together. The connecting wire leading from one terminal of the alternator armature to one of the collector rings is cut; and the two ends thus formed are connected, one to the even-numbered bars (shown in full black in Fig. 111) of the rectifying commutator, and the other to the odd-numbered bars (shown white in Fig. 111).

The field circuit that is to receive the rectified current is connected to two brushes which rub on the rectifying commutator, these brushes being so spaced that one touches an odd-numbered bar when the other touches an even-numbered bar. The brushes are carried in a rocker arm, which is moved forwards or backwards until the brushes are passing from one bar to the next at the instant that the alternating current from the alternator is passing through the value zero. The proper adjustment of the brushes is indicated by a minimum of sparking.

Fig. 112 shows an alternator *A* with two sets of field coils *F* and *C* as before. One armature terminal is connected to a collect-




Fig. 113. Two-Phase Alternator Diagram with Composite Field Excitation with Balanced Receiving Circuits

ing ring; and the other armature terminal connects to the primary of a transformer *T*, and thence to the other collecting ring. The terminals of the secondary coil of *T* connect to the bars of the rectifying commutator *B*, from which the composite field winding *C* is supplied. The transformer *T* is usually placed inside the armature.




Fig. 114. Three-Phase Alternator Diagram with Composite Field Excitation with Balanced Receiving Circuits

Composite field excitation is, however, not satisfactory in case of polyphase alternators, unless the receiving circuits supplied from the alternators are approximately balanced. Unbalancing of the receiv-

ing circuits changes the electromotive forces generated in the different phase windings of the armature, by different amounts; and composite excitation, applied to the magnetic field as a whole, cannot, properly, correct the different electromotive force variations of the several phases.

In cases where the receiver circuits are approximately balanced, the current for the composite field excitation is taken through a rectifying commutator from the secondary coil of a series (or current) transformer which has two or three distinct primary coils, one for each phase. This arrangement applied to a two-phase alternator is shown in Fig. 113, and applied to a three-phase alternator in Fig. 114. The effect of the several primary coils on the series transformer is to balance up the slight differences of the several poly-phase currents, in so far as their action upon the composite excitation is concerned. This method has been used by the Westinghouse Company in the case of alternators of small capacity.

CASE 3. *Automatic regulator.* There are on the market a number of automatic devices which are designed to change the field strength of a generator in accordance with a change in generator voltage. The most successful of these devices is the Tirrill regulator manufactured by the General Electric Company. This regulator differs from other types of regulators in that it does not make use of the principle of switching resistances in and out of the field circuit by the step-by-step method. The Tirrill regulator controls the generator voltage by rapidly opening and closing a shunt circuit connected across the exciter field rheostat, the duration of such periods of short-circuit being varied automatically. The field rheostat is first turned in until the exciter voltage is much reduced and the regulator circuit is then closed. This short-circuits the rheostat through contacts in the regulator, causing the voltage of the exciter and the generator to immediately increase. At a predetermined point the regulator contacts are automatically opened which causes the field current of the exciter to again pass through the rheostat. The resulting decrease in voltage is quickly checked by another closing of the regulator contacts, which continue to vibrate to and fro thus keeping the generator voltage within the desired limits.

Fig. 115 is a front view of a Tirrill regulator "form A2" designed for alternators having exciters of small capacities. Fig. 116 is a rear

view of the regulator showing the resistance box and iron brackets for mounting it at the end of the switchboard if desired, although it is recommended that it be mounted directly on the switchboard. A diagram of the electrical connections for a Tirrill regulator with an alternator and its exciter is shown in Fig. 117.

The regulator has a direct-current control magnet, an alternating-current control magnet, and a relay. The direct-current control magnet is connected to the exciter bus bars. This magnet has a fixed stop-core in the bottom and a movable core in the top which is attached to a pivoted lever having at the opposite end a flexible contact pulled downward by four spiral springs. For clear-

ness, however, only one spring is shown in the diagram. Opposite the direct-current control magnet is the alternating-current control magnet which has a potential winding connected by means of a potential transformer to the alternating-current generator or bus bars. There is an adjustable compensating winding on the alternating-current magnet connected through a current transformer to the principal lighting feeder. The object of this winding is to raise the voltage of the alternating-current bus bars as the load increases. The alternating-current control magnet has a movable core and a lever and contacts similar to those of the direct-current control magnet, and the two combined produce what is known as the "floating main contacts."




Fig. 115. Front View of Tirrill Regulator




Fig. 116. Back View of Tirrill Regulator

The relay consists of a U-shaped magnet core having a differential winding and a pivoted armature controlling the contacts which open and close the shunt circuit across the exciter field rheostat. One of the differential windings of the relay is permanently connected across the exciter bus bars and tends to keep the contacts open. The other winding is connected to the exciter bus bars through the floating main contacts and when the latter are closed neutralizes the effect of the first winding and allows the relay contacts to short-circuit the exciter field rheostat. Condensers are connected across the relay contacts to prevent severe arcing and possible injury.

The *cycle of operation* is as follows: The circuit shunting the exciter field rheostat through the relay contacts is opened by means of a single-pole switch at the bottom of the regulator panel and the




Fig. 117. Diagram of Electrical Connections for Tirrill Regulator

rheostat turned in until the alternating-current voltage is reduced 65 per cent below normal, which so weakens both of the control magnets that the floating main contacts are closed. This closes the relay circuit and demagnetizes the relay magnet, releasing the relay armature, and the spring closes the relay contacts. The single-pole switch is then closed and as the exciter field rheostat is short-circuited, the exciter voltage will at once rise and bring up the voltage of the alternator. This will strengthen the alternating-current and direct-current control magnets, and at the voltage for which the counterweight has been previously adjusted, the main contacts will open. The relay magnet will then attract its armature and by opening the shunt circuit at the relay contacts will throw the full resistance into the exciter field circuit tending to lower the exciter

and the alternator voltage. The main contacts will then be again closed, the exciter field rheostat short-circuited through the relay contacts, and the cycle repeated. This operation is continued at a high rate of vibration due to the sensitiveness of the control magnets and maintains not a constant but a steady exciter voltage.

One of the advantages of this regulator is that in controlling the voltage of the alternator by operating entirely on the field circuit of the exciter, the heating losses are far smaller and the efficiency correspondingly higher than is the case with those regulators which operate directly on the alternator field.

Another advantage is that several alternators may be operated in parallel using but one regulator, if all use the same exciter. On the other hand if, as is more usual, several exciters are used in parallel, one regulator and an equalizer rheostat for each additional exciter are necessary.

If two or more exciters, not operating in parallel, are used, a separate regulator must be installed for each exciter. The Tirrill "form F" regulator is made for large installations, and is furnished with several relays varying from two to twelve, according to the size, the capacity, and the characteristics of the exciters used. While these "form F" regulators differ more or less in detail according to special conditions, the main features of operation are the same as in the "form A2" regulator.

The standard voltage for exciters is 125 volts, and in some cases as high as 250 volts. Tirrill regulators are designed for a range of from 70 to 140 volts in the first case, and for a range of from 140 to 280 volts in the second case.

With the growing use of these automatic regulators external to the alternator, it has been found desirable by manufacturers to minimize their efforts to design alternators of low inherent regulation, especially in the case of turbo-alternators and machines of large rated output. A low inherent regulation is today considered an expensive and unnecessary luxury, for by some sacrifice in this quality a relatively large gain in rated capacity becomes possible, and in many cases a higher efficiency.

The advent of the automatic regulator has thus enabled designers to effect considerable improvement in alternators by relieving them of the troublesome question of low inherent regulation, and

permitting them to give greater weight than ever to the important matters of increasing output and efficiency.

POLYPHASE ALTERNATORS AND SYSTEMS

SINGLE-PHASE SYSTEM

Limitations. As long as alternating current was generated, transmitted, and used for electric lighting only, the single-phase system gave complete satisfaction, simplicity in the generating, transmitting, and receiving apparatus being its most striking and valuable feature.

In the earlier days of the electric lighting industry, there was very little, if any, demand for current to operate motors for power purposes. Since that time, however, there has developed an ever-increasing demand for current *for power purposes*, fully equaling, if not exceeding, that for lighting work. With the advent of this new condition, the great obstacle to the use of the single-phase alternating-current system became manifest. Single-phase constant-speed motors are difficult to make self-starting* under load, especially in units of large size; and hence the use of the single-phase system for general power purposes, with the apparatus now available, is not practicable.

It was in 1888, in Italy, that Ferraris discovered the important principle of the production of a rotating magnetic field by means of two or more alternating currents displaced in phase from one another, and he thus made possible, by means of the induction motor, the use of polyphase currents for power purposes. *The most important advantage of polyphase alternating currents over the simple single-phase system is that alternating-current motors can be satisfactorily operated by them.* It was mainly the requirements of the induction motor that led to the development of the polyphase system.

TWO-PHASE SYSTEM

Two-Phase Alternator. The simplest form of polyphase generator consists of two similar and independent single-phase armatures mounted rigidly on one and the same shaft, one beside the other, in such a manner that the electromotive forces at the terminals of

*This statement does not include the single-phase series commutator motor which is especially adapted to railway motors.

the respective armatures arrive at their maximum values 90 degrees, or one-fourth of a period, apart. The currents from such a machine are said to have a *two-phase* relationship. The two separate armatures are supposed to revolve inside the same crown of field magnet poles.

Fig. 118 shows an end view of such an arrangement, but armature *B* is here shown inside of armature *A* for the sake of clearness. As will be seen in the figure, armatures *A* and *B* are so mounted on the shaft that the slots of *A* are midway *under* the poles *N*, *S* when the slots of *B* are midway *between* the same poles. With this arrangement, the electromotive force generated in the armature coils of *A* and *B* are so related in their variations that the electromotive force of *A* is at its maximum when the electromotive force of *B* is zero. Or in other words, the two electromotive forces are 90 degrees apart in phase, or are in quadrature (at right-angles) to each other.

A careful study of Fig. 118 will show that the electromotive forces induced in armatures *A* and *B* are 90 degrees apart in phase. Thus the figure shows the armature *A* in the position in which its windings (in the slots) are cutting lines of magnetic flux from the field poles at a maximum rate, while the armature *B* is shown in the




Fig. 118. Diagram of Two-Phase Alternator with Two Separate Armatures

position in which its windings are midway between the field poles where they do not cut any magnetic flux at all. Therefore, the electromotive force in the windings of the armature *A* is at its maximum value, while the electromotive force in the windings of armature *B* is zero at the same instant. That these electromotive forces generated in the windings of *A* and *B* differ in phase by 90 degrees, may also be shown as follows: The electromotive force generated by a conductor on armature *A* passes through a complete cycle of changes as it moves from the center of one north pole to the center of the next north pole. The interval between the centers of two adjacent north poles, a "double pole pitch," corresponds then to 360 "electrical" degrees. Therefore, the phase (space) difference between the conductors

on A and B is seen to be $\frac{1}{4}$ of 360 degrees, or 90 electrical degrees.

The two equal, but distinct and independent electromotive forces generated by such a two-phase alternator are generally




Fig. 119. Diagram Showing Method of Combining Separate Armature Windings on One Core

used to supply two distinct and separate currents to two distinct and independent circuits. When so used the system is called a *two-phase, four-wire system*. We shall see later that it is possible to interconnect the two circuits in such a manner that one of the four line wires may be omitted.

In practice the actual two-phase alternator is constructed by placing both the armature windings of A and B upon one

and the same armature core, instead of on separate cores. To accomplish this the armature core has twice as many slots as either A or B in Fig. 118. Fig. 119 shows such an armature. The slots marked $a_1, a_2, a_3, \text{etc.}$, contain the conductors comprising phase A ; whereas the slots marked $b_1, b_2, b_3, \text{etc.}$, contain the conductors comprising phase B . The A winding passes in slot a_1 from front to back of the armature core; then towards the reader (that is, from back to front) in slot a_2 ; then from front to back in a_3 , from back to front in a_4 , and so on. The various conductors in slots $a_1, a_2, a_3, \text{etc.}$, are joined in series by connectors (at front and back), and the two ends of




Fig. 120. Distributed or Multi-Coil Winding for Two-Phase Alternator

the final series are connected to two collector rings.

The B winding passes in slot b_1 , from front to back of the armature core; then towards the reader, that is, from back to front, in slot b_2 ; then from front to back in b_3 , from back to front in b_4 , and

so on. The various conductors in slots $b_1, b_2, b_3,$ etc., are joined in series, and the two ends of the final series are connected to two collector rings, which rings are distinct from the pair of rings to which the A winding is connected.

The armature windings A and B just described are of the *concentrated* or *uni-coil* type, page 100, having only one slot per pole for each winding, *i. e.*, per phase. *Distributed* or *multi-coil* windings also are frequently used for two-phase alternators. Thus, Fig. 120




Fig. 121. Diagram of Collector Ring System for Two-Phase Alternator

shows an end view of a portion of a two-phase armature with its A and B windings each distributed in two slots per pole. The coils belonging to winding A are lightly shaded, and those belonging to winding B are darkly shaded in the figure. The connections between the coils of the A winding are shown in the figure by the full lines, while the connections of the B winding are shown by the dotted lines.

Two-phase alternators are usually provided with two sets of collector rings; one ring, however, may be made to serve as a common connection for the two armature windings, as shown in Fig. 121. The lines A and B in the clock diagram, Fig. 122, represent the generator electromotive forces, a represents the current in main 1, b represents the current in main 2, and c , which is the vector sum of a and b , represents the current in the common main 3. If $a = b$, it is evident that $c = a\sqrt{2} = b\sqrt{2}$.

THREE-PHASE SYSTEM

Three - Phase Alternator. Consider three similar single-phase armatures $A, B,$ and $C,$ mounted side by side on the




Fig. 122. Clock Diagram of E. M. F.'s and Currents for Two-Phase Alternator

same shaft and revolved in the same field, each armature having as many slots as there are field poles. Fix the attention upon a certain armature slot of $A,$ and let time be reckoned from the instant that this slot is squarely under an N pole. Let t be the time which elapses as this

armature slot passes from the center of one N pole to the center of the next N pole. The armature B is to be so fixed to the shaft that

its slots are squarely under the poles at the instant $\frac{1}{3} t$; and the armature C is to be so fixed that its slots are squarely under the poles at the instant $\frac{2}{3} t$. While a slot passes from the center of one N pole to the center of the next N pole, the electromotive force passes through one complete cycle. Hence, the electromotive forces given by three armatures arranged as above, will




Fig. 123. Clock Diagram of Three-Phase E. M. F.'s and Currents

be 120 degrees apart in phase, as shown in Fig. 123, in which the lines A , B , and C represent the respective electromotive forces. The currents given by the armatures to three similar receiving circuits lag equally behind the respective electromotive forces, and are represented by the dotted lines a , b , and c . This combination of three single-phase alternators is called a *three-phase alternator*. In practice the three distinct windings A , B , and C are placed upon one

and the same armature body. For this purpose the armature core has three times as many slots as A , B , or C .




Fig. 124. Arrangement of Slots for Three-Phase Alternator Armature

Fig. 124 shows the arrangement of the slots for such a winding. The slots belonging to phase A are drawn in heavy lines, and are marked a_1 , a_2 , etc. Those belonging to phase B are shown dotted, and those belonging to phase C are shown in light lines. The A winding would pass up slot a_1 , down a_2 ,

up a_3 , etc.; the B winding, up b_1 , down b_2 , up b_3 , etc.; and similarly for winding C .

The windings A , B , and C here described are of the concentrated type, having only one slot per pole for each winding. Dis-

tributed windings also are frequently used for three-phase alternators. Thus Fig. 125 shows a portion of a three-phase armature with its *A*, *B*, and *C* windings each distributed in two slots per pole. The coils belonging to windings *A*, *B*, and *C*, respectively, are differently shaded to distinguish them. The manner of connecting the coils of each winding is described on page 145.




Fig. 125. Portion of Diagram of Windings for Three-Phase Alternator Armature

If the three circuits of a three-phase alternator are to be entirely independent, six collector rings must be used, two for each winding; however, the circuits may be kept practically independent by using four collector rings and four mains, as shown in Fig. 126. The main 4 serves as a common return wire for the independent currents, in mains 1, 2, and 3. When the three receiving circuits are equal in resistance and reactance, that is, when the system is balanced, the three currents are equal, and are 120 degrees apart in phase (each current lagging behind its electromotive force by the same amount as the others); and their sum is at each instant equal to zero. In this case, main 4, Fig. 126, carries no current. Therefore, main 4 and the corresponding collector ring may be dispensed with, the three windings connected together at the point *N*, called the *common junction* or *neutral point*. This arrangement, shown in the symmetrical diagram, Fig. 127, is called the “*Y*” or “*star*” scheme of connecting the three windings or phases *A*, *B*, and *C*.

Another scheme for connecting the three windings *A*, *B*, and *C* (also for balanced loads), called the “*Δ*” (delta) or “*mesh*” scheme, is illustrated in Fig. 128. Winding (or phase) *A* is connected between rings 3 and 1; winding (or phase) *B* between rings 1 and 2; and winding (or phase) *C* between rings 2 and 3.




Fig. 126. Collector Ring System for Three-Phase Alternator

The direction in a circuit in which the electromotive force or current is considered as a positive electromotive force or current,

is called the *positive direction* through the circuit. This direction is chosen arbitrarily. The arrows in Figs. 127 and 128 indicate the positive directions in the mains and through the windings. It must be remembered that these arrows represent not the actual directions of the electromotive forces or currents at any given instant, but merely the directions of *positive* electromotive forces or currents. Thus, in Fig. 127, the currents are considered positive when flowing from the common junction towards the collecting rings, and the currents are never all of the same sign.

Y-Connected Armatures. *Electromotive Force Relations.* We shall consider the electromotive force between mains 1 and 2, Fig. 127, to be positive, when it tends to send current through a receiving circuit from main 1 to main 2. Similarly, the electromotive force




Fig. 127. The "Y" Scheme of Connecting Three Phases in Three-Phase Alternator




Fig. 128. Diagram of "Δ" Scheme for Connecting Phases in Three-Phase Alternator

between mains 2 and 3 is considered positive, from main 2 to main 3; and the electromotive force between mains 1 and 3 is considered positive, from main 3 to main 1. Passing through the windings A and B from ring 2 to ring 1, Fig. 127 (which is the direction in which an electromotive force must be generated to give an electromotive force acting upon a receiving circuit from main 1 to main 2), the winding A is passed through in the positive direction, and the winding B in the negative direction. Therefore, the electromotive force from main 1 to main 2 is $A - B$. Similarly the electromotive force from main 2 to main 3 is $B - C$, and the electromotive force from main 3 to main 1 is $C - A$. These differences are shown in the clock diagram, Fig. 129. The electromotive force between mains 1 and 2 (namely, $A - B$) is 30 degrees behind A in phase, and its effective

value is $2E \cos 30^\circ = \sqrt{3} E$, where E is the common value of each of the electromotive forces A , B , and C . Similar statements hold concerning the electromotive forces between mains 2 and 3, and those between mains 3 and 1. Hence, *the electromotive force between any pair of mains leading from a three-phase alternator with a Y-connected armature is equal to the electromotive force generated per phase multiplied by $\sqrt{3}$.*

Current Relations. In the Y connection, the currents in the mains are equal to the currents in the respective windings or armature phases, as is evident from Fig. 127.

Δ -Connected Armatures. Electromotive Force Relations. In Δ -connected armatures the electromotive forces between the mains




Fig. 129. Clock Diagram of E. M. F.s for Three-Phase "Y" Winding




Fig. 130. Clock Diagram for Currents in " Δ " Connected Three-Phase Armature

or collector rings are equal to the electromotive forces of the respective windings, as is evident from Fig. 128.

Current Relations. Referring to Fig. 128, we see that a positive current in winding A produces a positive current in main 1, and that a negative current in winding B produces a positive current in main 1; therefore, the current in main 1 is $a-b$, where a is the current in winding A , and b is the current in winding B . Similarly, the current in main 2 is $b-c$, and the current in main 3 is $c-a$. These differences are shown in Fig. 130. The current in main 1 (namely $a-b$) is 30 degrees behind a in phase; and its effective value is $\sqrt{3} I$, where I is the common effective value of the currents,

a, b, c , in the different phases. Similar statements hold for the currents in mains 2 and 3; so that the current in each main from a Δ -connected armature is $\sqrt{3}$ times the current in each winding.

Receiving Circuits to Three-Phase Mains. Dissimilar Circuits (Unbalanced System).




Fig. 131. "Y" Method of Connecting Receiving Circuits

When the receiving circuits which take current from three-phase mains are dissimilar, that is, do not each have equal resistance and reactance, four mains should be employed, as indicated in Fig. 126; each receiving circuit being connected from main 4 to one of the other mains. A common example of an unbalanced system

is where a mixed load of induction motors and incandescent lamps is connected unsymmetrically to three-phase receiving mains. It is, however, desirable to keep the three windings A, B , and C of the alternator almost equally loaded; and in practice the receiving circuits are so disposed as to satisfy this condition as nearly as possible.

Similar Circuits (Balanced System). When three-phase currents are used to drive induction motors, synchronous motors, or rotary converters, each one of these machines takes current equally from the three mains; and since three-phase currents are utilized chiefly in the operation of the machines mentioned, the system is usually balanced. In this case three mains only are employed, and each receiving unit has three similar receiving circuits connected to the mains according to either the Y or the Δ method. The Y method of connecting receiving circuits is shown in Fig. 131. One terminal of each receiving circuit is connected to a main, and the other terminals are connected together at the neutral point N . In this case the current in each receiving circuit is equal to the current in the main to which it is connected. The electromotive force between the terminals of each receiving circuit, as A , is





Fig. 132. "Δ" Method of Connecting Receiving Circuits

equal to $\frac{E}{\sqrt{3}}$, where E is the electromotive force between any pair of mains.



1,000 K. W. FREQUENCY CHANGING SET
National Brake & Electric Co.

1037 D

TABLE III
 Δ - and Υ -Connection Data in Mains

	E. M. F. between Mains	Current in Each Main	Power Rating
Δ connection.....	E_w	$\sqrt{3} I_w$	$\sqrt{3} E_w I_w$
Υ connection.....	$\sqrt{3} E_w$	I_w	$\sqrt{3} E_w I_w$

The Δ method of connecting receiving circuits is shown in Fig. 132. Here the three receiving circuits are connected between the respective pairs of mains; the electromotive force acting on each receiving circuit is the electromotive force between the mains; and the current in each receiving circuit is $\frac{I}{\sqrt{3}}$, where I is the current in each main.

Examples. 1. The three windings or phases of a three-phase induction motor are Υ -connected to three-phase mains. The voltage between mains is 500, and each main delivers 25 amperes to the motor. It is required to find the current in each phase of the motor, and the electromotive force acting on each phase of the motor.

Solution. Since the windings are Υ -connected, the current in each is the same as the current in each main, namely, 25 amperes; and the electromotive force acting on each phase of the motor winding is $\frac{500}{\sqrt{3}}$, or 288.7 volts. The power input is $P = \sqrt{3} \times 500 \times 25 = 21650$ watts.

2. The three phases of the above three-phase induction motor are Δ -connected to three-phase mains. The voltage between mains is 288.7, and the current in each main is 43.3 amperes. It is required to find the current in each phase of the motor, and the electromotive force acting on each phase of the motor.

Solution. Since the windings are Δ -connected, the electromotive force acting on each phase is the same as the voltage between the mains, namely, 288.7 volts; and current in each phase of the motor is $\frac{43.3}{\sqrt{3}}$ or 25 amperes. The power input is $P = \sqrt{3} \times 288.7 \times 43.3 = 21650$ watts, the same as before.

Summary of Electromotive Force and Current Relations for Δ and Υ Connections. Let E_w be the rated electromotive force of each winding, and I_w the rated full-load current output of each phase of the winding of a three-phase alternator, then, for a generator with non-inductive load, the data is as given in Table III.

Let E be the electromotive force between mains of a three-

TABLE IV
 Δ - and Υ -Connection Data in Receiving Circuits

	E. M. F. between Terminals of Each Receiving Circuit	Current in Each Receiving Circuit	Total Power Input
Δ connection.....	E	$\frac{I}{\sqrt{3}}$	$\sqrt{3} EI$
Υ connection.....	$\frac{E}{\sqrt{3}}$	I	$\sqrt{3} EI$

phase system, and let I be the current in each main, then, for three receiving circuits, the data is as given in Table IV.

The permissible power output or rating of a three-phase alternator is the same whether its armature windings are Υ -connected or Δ -connected.

The power output of a three-phase generator is $\sqrt{3} \times \text{electromotive force between mains} \times \text{current in one main} \times \text{power factor of the receiving circuits}$.

MEASUREMENT OF POWER

In alternating-current circuits, power cannot in general be measured by means of an ammeter and a voltmeter, as in the case of direct current, because the power expended is generally less than the product of effective electromotive force and effective current on account of the difference in phase between the electromotive force and the current.

A well-designed wattmeter is the standard instrument for measuring power in alternating-current circuits, and the methods involving its use are the most generally satisfactory.

NOTE.—The discussion of the wattmeter given on page 78 applies primarily to the use of the wattmeter for the measurement of power delivered in single-phase systems.

The several circuits of a polyphase system are often entirely separate and independent; and in such cases the total power delivered to a receiving apparatus is found by measuring the power delivered to each separate receiving circuit. The total power delivered is the sum of the amounts delivered to the different receiving circuits.

In order to measure the power delivered to one of the receiving circuits of a polyphase system, the current coil of the wattmeter is to be connected *in series* with this receiving circuit, and

the pressure (or voltage) coil of the wattmeter is to be connected *between the terminals* of this receiving circuit. In some cases this connection of the voltage coil cannot be made, because one terminal of the receiving circuit may be out of reach in the interior of the apparatus.

Balanced Systems. In general, the several circuits which receive current and power from polyphase mains are more or less unlike in both resistance and reactance, and take different amounts of current and power from the mains. It is, however, desirable that the several receiving circuits be alike, so that they may take equal currents and equal amounts of power from the mains. When this condition is realized, the system is said to be *balanced*.

For example, when independent groups of lamps are supplied from polyphase mains, each group taking current directly, or through a transformer, from one phase of the polyphase system, the system is said to be *unbalanced* when the number of lamps is not the same in the several groups. In general, the supply of power to several separate, independent, and unrelated receiving circuits, such as independent groups of lamps and single-phase motors, leads to the unbalancing of a polyphase system. Apparatus, such as polyphase induction motors, synchronous motors, and rotary converters which are especially designed to take power from polyphase mains, is always provided with two or three similar receiving circuits so as to take equal amounts of current and power from each phase of the system. When such polyphase apparatus takes power from polyphase mains only, the system is always very nearly balanced.

If a polyphase system were exactly balanced it would be sufficient to measure the power delivered by one phase only; but since a balanced condition of a system is seldom exactly realized in practice, there may be considerable error introduced by assuming that a system is balanced, and by calculating the total power from the wattmeter reading of power delivered by one phase only.

In balanced or approximately balanced polyphase systems, the measurement of power by use of a single wattmeter is best accomplished by special arrangement of connections as follows:

Three-Wire Two-Phase Systems. The current coil of the wattmeter should be connected in the middle main as shown in Fig. 133. After a reading is taken with the pressure coil connected between

middle and lower mains, this connection is quickly changed to the upper main, as indicated by the dotted line, and the wattmeter again read. The sum of the two successive readings gives the total power. If this method is used, the system should not only be balanced, but no change in the load should occur between readings.




Fig. 133. Diagram of Power Connection for Three-Wire Two-Phase Induction Motor

For example, the power taken by a two-phase induction motor is measured by a wattmeter connected as shown in Fig. 133. When the wattmeter is connected as shown by the full line in the figure, it reads 9,900 watts. When the wattmeter is connected as shown by the dotted line, it reads 1,415 watts. The total watts delivered are, therefore, 11,315 watts, the two phases of the motor being assumed to be balanced. Each phase of the motor receives, therefore, $\frac{11,315}{2} = 5,657$ watts. The current delivered to each phase, as measured by an alternating-current ammeter is 32.14 amperes; and the electromotive force acting on each phase of the motor, that is, between the terminals of each receiving circuit, is 220 volts. The apparent power (volt-amperes) delivered to each phase is 220




Fig. 134. Diagram of Power Connection for Three-Wire Three-Phase System

volts \times 32.14 amperes = 7,071 apparent watts; and the power factor of each receiving circuit is

$$\frac{5,657 \text{ watts}}{7,071 \text{ apparent watts}}, \text{ or } 0.80$$

The two readings of a wattmeter, connected as shown in Fig. 133, are unequal, even though the receiving circuits are balanced, because of the effect of lagging currents; or, in other words, because the two receiving circuits are inductive.

It is to be carefully noted that, in general, neither reading of the wattmeter measures the power delivered to either one of the receiving circuits.

Three-Wire Three-Phase Systems. The current coil of the wattmeter should be connected in series with one (any one) of the three mains, as shown in Fig. 134. After one reading of the wattmeter is taken with the voltage coil connected to main 2, as indicated by the full line, the connection is quickly changed to main 1, as indicated by the dotted line, and a second reading of the watt-




Fig. 135. Power Connection of Four-Wire Two-Phase System

meter is taken. The total power delivered to the three similar (that is, balanced) phases, is equal to the sum of the two readings.

Unbalanced Systems. In general, any receiving apparatus is sufficiently unbalanced to require the measurement of power to be made on the assumption that the receiving circuits are unbalanced.

Four-Wire Two-Phase. When four mains are used, two for each separate phase, then two wattmeters are required, one for measuring the power delivered by each phase. Each of these wattmeters is connected exactly as in the case of single-phase delivery of power, as shown in Fig. 135. The sum of the readings $W_1 + W_2$ of the two wattmeters gives the total power delivered. Two readings should, of course, be taken as nearly simultaneously as possible.

Three-Wire Two-Phase. When a two-phase system is balanced or unbalanced and has three supply mains, one main acting as the




Fig. 136. Diagram of Power Connection for Three-Wire Two-Phase System

common return for the other two, then the arrangement shown in Fig. 136 gives the best results. The total power delivered to the receiving circuit is the sum $W_1 + W_2$ of the readings of the two wattmeters. The readings should be taken as nearly simultaneously as possible.




Fig. 137. Diagram of Power Connection for Six-Wire Three-Phase System

Six-Wire Three-Phase. When six mains are used, two for each separate phase, then three wattmeters are required, one for measur-

ing the power delivered by each phase. Each of these wattmeters is connected exactly as in the case of single-phase delivery of power, as shown in Fig. 137.

In practice, six wires are never used for three-phase systems on account of complications and the excessive amount of copper required.

Three-Wire Three-Phase. When three mains are used in a three-phase system, two wattmeters are sufficient for the complete measurement of the power delivered to any three-phase receiving unit, whether the receiving circuit is balanced or unbalanced, or whether it is connected Y or Δ .

Fig. 138 shows two wattmeters connected for measuring the power delivered to a Δ -connected three-phase receiving system. The algebraic sum of the readings of the two wattmeters gives the




Fig. 138. Diagram of Power Connection for Three-Wire Three-Phase System

total power delivered independent of balance or lag. When the current lag in the circuit is less than 60 degrees, *i. e.*, when the power factor is greater than 0.5, then the arithmetical *sum* of the readings of the two wattmeters gives the total power. But if the lag is greater than 60 degrees, *i. e.*, when the power factor is less than 0.5, the relation of the currents in the current coil and pressure coil of one of the wattmeters causes it to give a negative reading; hence the arithmetical *difference* of the readings of the two instruments gives the power.

There may be a difficulty in determining which condition exists in some cases, especially when the power delivered to partially loaded induction motors whose power factor is low, is to be measured. In such cases one may determine whether the sum or difference of readings is to be taken by interchanging the position of the in-

struments without changing the relative connections of their current and pressure coils. If the deflections of both pointers are now reversed, the difference of the original readings gives the true power, but if the deflections are in the same direction as before, the sum of the original deflections is the correct power.

To prove the accuracy of these deductions, let the positive direction in the mains 1 and 2 and in the three receiving circuits be chosen as indicated by the arrows in Fig. 138. These directions are chosen symmetrically with respect to the two wattmeters. Let the instantaneous currents in the receiving circuits be i' , i'' , and i''' , as shown in the figure. Let a be the instantaneous current in main 1, and let b be the instantaneous current in main 2. Then, from the arbitrary choice of signs,

$$\begin{aligned} a &= i' + i''' \\ b &= i'' - i''' \end{aligned}$$

The reading W' of the upper wattmeter is equal to the average value of the product of the current a , which flows through the current coil of the instrument, and the electromotive force e' , which is acting upon the pressure coil of the wattmeter. That is

$$W' = \text{average } (ae')$$

Similarly, the reading W'' of the lower wattmeter gives

$$W'' = \text{average } (be'').$$

Substituting the above values of a and b in the expressions for W' and W'' , and adding results, we have

$$W' + W'' = \text{average } (e'i') + \text{average } (e''i'') + \text{average } (e' - e'')i'''$$

But, from the figure, $e' - e'' = e'''$; hence

$$W' + W'' = \text{average } (e'i') + \text{average } (e''i'') + \text{average } (e'''i''')$$

Although a formal proof of the principle of the two-wattmeter method has not been given for a Y-connected circuit, it is not necessary to show independently that it holds for both cases. A little consideration will show that if the electromotive forces acting between the three wires, the currents flowing in them, and their phase relations are given, there is then a perfectly definite amount of power transmitted along the three lines, and it is quite immaterial whether this power is being delivered to circuits connected Δ or Y.

ARMATURE WINDINGS

In general, any direct-current armature winding may be used for the armature of an alternator; but the desirability of generating comparatively high voltages in the armature so as to avoid the use of step-up transformers, makes it necessary to abandon the styles of winding best suited to direct-current machines, and to use windings specially adapted to the conditions of alternating-current practice.

Comparing the armature windings used for direct-current machines with those for alternators, we find, *first*, that all the re-entrant (or closed-coil) direct-current windings must necessarily be either two-circuit or multiple-circuit windings, *i. e.*, they must have at least two paths in parallel through the armature between brushes; and *second*, that the armatures of alternators (and synchronous motors) may, and generally do, from practical considerations, have one-circuit windings, *i. e.*, windings having one circuit per phase. It follows, therefore, that any direct-current winding may be used for alternating-current machines; but the converse statement, that any alternating-current winding may be used for direct-current machines, is not true in general. In other words, the windings of alternating-current armatures are essentially non-re-entrant (or open-circuit) windings. The only exceptions are the Δ -connected (or mesh-connected) polyphase windings, and the short-circuited windings of "squirrel-cage" induction motors, both of which are re-entrant (or closed-circuit) windings. The Δ -connected polyphase windings are, therefore, the only windings that can be used for the armatures of rotary converters.

In the type of winding generally employed for alternators, a number of distinct coils are arranged on the armature; in these coils alternating electromotive forces are induced as they pass the field-magnet poles, and the several coils are connected in series between the collecting rings.

Classification. *According to Shape of Core.* Armatures for alternators, just as in the case of direct-current machines, may be divided into drum armatures; ring armatures; and disk armatures. Of these the ring and the disk armatures are seldom used in America although they are to some extent adopted in European practice.

The ring and the disk types of the armature are mechanically less stable than the drum type; and the ring armature, moreover, other things being equal, requires more wire to be wound upon it for a given output than in the case of the *drum armature*, and possesses, therefore, a greater inductance than the latter type. Drum armatures, whether the alternators are of the revolving or stationary armature type, have laminated iron cores similar in construction to the armature cores for direct-current machines. Disk armatures, on the other hand, are usually made up without iron, thus introducing constructional difficulties.

According to Construction of Core. With reference to the construction of their cores, the armatures of alternators may be classified, as in the case of direct-current machines, into smooth-core armatures and toothed-core armatures.

In the *smooth-core armature* the conductors, arranged in flat coils, lie on the surface of the armature core, and the coils in some cases are bent down over the ends of the core, where they are fastened by end plates or by blocks of wood or fiber. The spaces in the centers of the coils are filled with wooden blocks either screwed to the cores or held in place by the binding wires. In other cases the coils are flat or "pancake" shaped, and of the same length as the armature core. In the latter case they are laid upon the cylindrical surface of the armature core, and are securely bound with wire bands.

The form of the wave of electromotive force produced by smooth-core armatures is very nearly harmonic (sinusoidal) or slightly flat-topped. The inductance of a smooth-core (or surface-wound) armature is considerably less than that of a toothed-core armature. Although much used in earlier designs, the smooth-core armatures owing largely to their comparatively weak mechanical structure, have been superseded in modern practice by the toothed-core constructions.

One or another of the forms of *toothed-core armature* is now almost universally used in practice. The conductors are laid in slots or grooves, the sides and bottom of which are first carefully insulated by troughs of mica-canvas, micanite, or other suitable insulating material. The insulated conductors (cotton covered) are generally wound into coils on "formers," each coil being care-

fully taped, and then impregnated with insulating compound (or varnish). The coils are then thoroughly dried by baking in ovens.

The conductors being enclosed in slots between teeth which project more or less over the conductors, the toothed-core type is often called *iron-clad*. This construction has three great advantages over the smooth-core type:

- (a) It allows the length of air gap from iron of pole-face to iron of armature core to be reduced to a minimum; just enough for mechanical clearance. Other things being equal, this means a saving in the copper required to magnetize the field.
- (b) It protects the embedded conductors from injury.
- (c) It affords an admirable way of supporting and securing the conductors firmly in place against the action of centrifugal force; and, further, it shields the conductors almost completely from the racking action of the magnetic drag due to the magnetic field.

The shape and number of the slots in a toothed armature core have a marked effect on the shape of the electromotive force wave, and upon the regulation of the alternator. The shape of the wave is affected by the distribution of the magnetic flux in the air gap. The regulation is affected by the inductance of the armature coils, and the inductance depends on the number and shape of the armature slots.

Fig. 139 shows a portion of an armature-core disk or stamping for a 12-pole, uni-tooth (one slot per pole per phase), three-phase alternator. The armature winding adapted to this uni-tooth core is, of course, the uni-coil or concentrated winding. The armature coils are held in place in the slots by wedges of wood or fiber driven in from the ends of the core and fitting into notches near the tops of the teeth, as shown in the figure. This construction, now almost universally adopted by manufacturers, avoids the necessity for any binding wire on the armature core.




Fig. 139. Portion of Stamping for Twelve-Pole Uni-Tooth Three-Phase Alternator

Alternators with uni-tooth armature cores are characterized by large armature inductance and by peaked-wave shapes of the induced electromotive forces; also by marked variations in the shape of the wave of induced electromotive force, according to the magnitude and power factor of the load.

On account of their comparatively large inductance, uni-tooth armature constructions require a relatively large increase in the field-exciting current in passing from no load to full load output. In other words, regulation is poorer than for multi-tooth armature cores.

According to present practice in design, the great majority of alternators are constructed with armature-core stampings having two or three or more slots per pole per phase. Fig. 140 shows a portion of an armature-core stamping for a 12-pole, three-phase alternator. It has three slots per pole per phase. The slots are open, which, together with the distributed (multi-coil) type of winding, results in a low armature inductance. This means that a relatively small increase in the field-exciting current is required in passing from no load to full load output.

Alternators with multi-tooth armature cores are especially adapted for long-distance transmission where step-up transformers are used. The regulation is better than with the uni-tooth core construction; and the wave shape of the electromotive force generated by the distributed winding approaches a sine wave, which is the best wave shape for the long-distance transmission of power.




Fig. 140. Portion of Stamping for Twelve-Pole Three-Phase Alternator

This is because of the fact that the nearer a given curve of electromotive force approaches a sine curve, the less the likelihood of a dangerous rise of voltage (resonance) occurring at the distant end of a long transmission line because of the capacity (condenser) effect. A long transmission line has a series of frequencies of electrical oscillation just as a stretched violin string has a series of frequencies of mechanical vibration. If the frequency of the current delivered by an alternator happens to coincide with any of these "proper" frequencies of the transmission line, the line will have violent electrical oscillations set up in it, and excessive voltages will occur at certain points along the line. A sine wave of electromotive force has only one frequency. Any other kind of an alternating electromotive force is composed of a series of sine waves of ascending frequencies (the harmonics or over-tones in music), all combined into a resultant wave form. There is, therefore, more danger that one out of all

the frequencies may coincide with one of the "proper" line frequencies than that the single frequency of a sine wave may so coincide.

According to Progression of Winding. With reference to the progress of the winding from slot to slot, armature windings may be divided into spiral or ring windings; lap windings; and wave windings. These terms have the same meaning when applied to alternator windings as they do when applied to the windings of direct-current machines.

According to Disposition of Coils. With reference to the disposition of the coils around the periphery of the core, we have to distinguish between two general classes, viz, *concentrated*, or *uni-coil*, windings, and *distributed*, or *multi-coil*, windings.

Concentrated, or *uni-coil*, windings, as the name implies, consist of one coil per pole per phase. The armature conductors are thus grouped in bundles, and usually placed in slots, there being one slot per pole for each phase.

Examples of concentrated windings are illustrated in Figs. 1 and 102, in which the armature conductors are shown as lying in one slot per pole. Fig. 1 shows adjacent sides of two different armature coils lying in one slot. In some cases, each slot is filled by one side of a single armature coil, giving one slot per phase per pair of poles. Such windings are sometimes called "half-coiled" or "hemi-tropic."

Distributed, or *multi-coil*, windings consist of several coils per pole per phase. The armature conductors are distributed in two or more slots per pole per phase.

Examples of distributed windings are shown in Figs. 120 and 125. Fig. 120 shows an end view of a two-phase winding distributed in two slots per pole per phase. Fig. 125 shows an end view of a three-phase winding distributed in two slots per pole per phase.

Concentrated windings are less expensive to make; and they give a greater effective electromotive force (at zero load) for a given number of conductors, other things being equal, than distributed windings. This is on account of the fact that all the conductors of a concentrated winding cut the field flux simultaneously, while the various conductors of a distributed winding do not cut the field flux simultaneously.

Concentrated windings have greater inductance than distributed windings for the same total number of conductors, and also cause a greater armature reaction for a given current than distributed windings do. Consequently the terminal electromotive force of an alternator falls off more with a concentrated winding than with a distributed winding, when the current output is increased.




Fig. 141. Completed Armature with Strap Winding, Four Slots Per Phase

Therefore, an alternator with a concentrated winding has a poorer (higher) regulation than an alternator with a distributed winding; and although a concentrated winding may give a higher electromotive force at zero load, it may actually give a lower electromotive force at full load.

According to Form of Conductor. According to the form of the conductors used, armature windings may be divided into three classes, viz, *wire winding*; *strap winding*; and *bar winding*.




Fig. 142. Portion of Bar-Wound Armature, One Bar Per Slot

Wire winding, which is usually employed in high-voltage machines of low-current output, consists of machine-wound coils, which are entirely formed and insulated before being placed in the armature slots.

Strap winding is used for machines of lower voltage and of greater current output, and it consists of copper strap, forged into the required shape and carefully insulated.

Both the wire and strap windings are placed in the slots without any mechanical bending, thus preventing damage to the insulation. In armature cores having the slots partially closed, the winding is slipped in from the end; but in cores having open slots, wedges of hard fiber secure the coils in place.

Fig. 141 is an illustration of strap winding distributed in four slots per pole per phase. The completed armature, ready for direct connection to a steam engine, is shown in the figure, and is intended to revolve inside of a stationary field-magnet structure. The four collector rings indicate that the armature is wound for two phases. It is manufactured by the Westinghouse Electric Company.

Bar windings are held in place by the overhanging tips of the teeth. The bars, after being carefully insulated, are slipped into

the slots from one end of the armature. The end connections of the bar winding are bolted and soldered to the bars after the conductors are in place.

Bar windings are usually arranged with either one or two bars per slot. There are no band wires on the armature core.

Fig. 142 shows a portion of a bar-wound revolving armature having one bar per slot.





Fig. 143. Concentrated Single-Phase Armature Winding

Single-Phase Windings. Fig. 1 shows a common type of single-phase winding having one coil per pole. Fig. 143 shows another type of concentrated single-phase winding, having one coil to each pair of poles or one slot per pole. The sketch *b* is a sectional view of a portion of the armature core, showing one of the slots containing the conductors forming one side of a single armature coil and standing opposite to a field pole. In the main diagram the heavy sector-shaped figures represent the coils, and the light lines represent the connections between the terminals of the coils. The radial parts of the sector-shaped figures represent the portions



THE STEAM TURBINE vs. THE STEAM ENGINE

The Curtis steam turbine, with generator, seen in the right background, is rated at 5,000 kw. 6,000 volts, at 500 r. p. m., whereas each of the enormous generators connected to vertical compound engines, shown at the left, has a rated capacity of only 2,500 kw. View taken in Waterside Station of the New York Edison Company, New York City.

of the coils that lie in the slots, and the curved parts represent the ends of the coils. The circles at the center of the figure represent the collecting rings, one being shown inside the other for clearness. The arrows represent the direction of the current at a given instant. All electromotive forces induced under N poles are in one direction, and all electromotive forces induced under S poles are in the opposite direction. These remarks apply to Figs. 143 to 150 inclusive.




Fig. 144. Single-Phase Armature Winding, Two Slots Per Pole

Fig. 144 represents a single-phase winding distributed in two slots per pole, all the coils being connected in series. The sketch *b*, is a sectional view of a portion of the armature core, showing two slots.

Two-Phase Windings. The two-phase winding consists of two independent single-phase windings on the same armature, each being connected to a separate pair of collecting rings, as shown in Figs. 145 and 146. Fig. 145 shows a two-phase concentrated winding, one slot per pole for each phase. Fig. 146 shows a two-phase winding distributed in two slots per pole for each phase. In each of the figures (145 and 146), the winding of one of the phases is shown by dotted lines, to distinguish it from that of the other.




Fig. 145. Two-Phase Concentrated Armature Winding




Fig. 146. Two-Phase Armature Winding, Two Slots Per Pole Per Phase

Three-Phase Windings. The three-phase winding consists of three independent single-phase windings on the same armature,

the terminals of the individual windings being connected according to the Y scheme or Δ scheme, as explained on page 145. Fig.




Fig. 147. Three-Phase Concentrated Winding Y-Connected




Fig. 148. Three-Phase Concentrated Winding Δ -Connected

147 shows a three-phase concentrated winding (one slot per pole for each phase), Y-connected. Fig. 148 shows the same winding Δ -connected. In Figs. 147 and 148 the winding for phase A is shown by heavy full lines; the winding for phase B is shown by light full lines; and the winding for phase C is shown by dotted lines.

The Y connection gives $\sqrt{3}$ times as much electromotive force between collecting rings as the Δ connection for the same total number of conductors per phase, and is the more suitable for high electromotive force machines. The Δ connection, on the other hand,

is especially adapted for machines for large current output. The line current is $\sqrt{3}$ times as great as the current in each winding in a Δ -connected armature.




Fig. 149. Three-Phase Bar Winding, Two Slots Per Pole Per Phase

Fig. 149 shows a three-phase bar winding distributed in two slots per pole for each phase. The sketch *b*, is a sectional view of one slot containing a single conductor in the form of a rectangular bar.

Fig. 150 shows a three-phase coil winding distributed in two slots per pole for each phase and arranged in two layers, there being as many coils on the armature as there are slots, so that portions of

two coils lie in each slot, one above the other. The portions of the coils represented by full lines lie in the upper parts of the slots, and the adjacent dotted portions lie in the bottoms of the same slots. The sketch *b* is a sectional view of one slot showing two half-coils one above the other, thus constituting a two-layer winding.

The method of connecting up the separate windings of a three-phase alternator is as follows:

Y CONNECTION. The terminals of the individual windings which are to be connected to the common junction and to the collecting rings, may be determined as follows: Consider the instant when winding *A* is squarely under the poles, as shown in Fig. 147. The electromotive force in this winding (and the current also, if the circuit is non-inductive) is a maximum, and the currents in the other two phases *B* and *C* are each half as great. If winding *A* is connected so that its current is flowing away from *k*, windings *B* and *C* must be connected so that their currents flow towards *k*.

Δ CONNECTION. The three windings form a closed circuit when Δ connected. The total electromotive force around this circuit at any instant must be zero. Consider the instant when winding *A* is squarely under the poles, as shown in Fig. 148. The electromotive force in this winding is a maximum, and the electromotive forces in the other two windings are each half as great. Then winding *A* is connected to any pair of rings, say 1 and 2; winding *B* is connected to ring 3 and ring 1 (or 2); and winding *C* is connected to ring 3 and ring 2 (or 1); these connections are made so that the electromotive forces at the given instant are in the directions indicated by the arrows in Fig. 148.




Fig. 150. Three-Phase Coil Winding, Two Slots Per Pole Per Phase

COMMERCIAL TYPES OF MACHINES

Alternators are of three types, differing in the means employed for causing the conductors to cut the magnetic flux from the field magnet, viz, *revolving-armature type*; *revolving-field type*; and *inductor type*.

Of these three types the one which experience has proven the fittest to survive is the revolving field type and it is today generally adopted by manufacturers as the standard. Alternators of the revolving armature type are still manufactured to supply special

demands and for small isolated electric plants, and they may be found in satisfactory operation in many of the older and smaller electric central stations.

The inductor type is rarely if ever built today. In this type both the field winding and the armature (core and winding) are stationary, and the magnetic flux produced by the field winding is caused to move past the armature conductors by means of a revolving iron structure furnished with polar projections called the *inductor*. The advantages of this type, viz, absence of moving wires, collecting devices and brushes, with the consequent minimum cost of attendance are outweighed by the disadvantages of increased size, weight, and cost, and by the lower efficiency and poorer (higher) regulation especially when supplying current to inductive loads such as induction motors or other apparatus having a power factor less than unity. On account of these disadvantages the manufacture and use of inductor alternators have been virtually discontinued.

The revolving-armature type of alternator is limited to a general power and lighting distribution where only a moderate voltage is required. Machines of this type are comparatively cheap to build. They can be automatically compounded by the use of composite field windings without any complication of parts, which is not the case with the revolving field type. They can be furnished with an auxiliary armature winding and small commutator for exciting their fields, thus dispensing with any external exciter.

The revolving-armature type, on the other hand, is not suitable for generating either high or low voltages, on account of the difficulties of insulating the armature conductors and collecting rings in the first case (high voltage), and of collecting a large armature current in the second case (low voltage).

The advantages of the revolving field type over the revolving armature type are as follows:

- (1) The revolving field type gives more space for the armature winding, and thus permits the stationary armature to be easily insulated to withstand a testing pressure of over 30,000 volts.

Large alternators with stationary armatures have been built to generate voltages up to 20,000; but it is doubtful whether, on the whole, it is economical to build them for voltages greater than about 13,000.

(2) The insulation of the armature is relieved from the strains due to centrifugal force at high speeds. Furthermore, a revolving field can be made stronger and more compact than a revolving armature and, therefore, the revolving-field type of alternator is much the better suited to the high speeds employed in alternators driven by steam turbines.

(3) The number of collecting rings is reduced to a minimum, viz, two, and the amount of electrical energy transmitted through them is only about two per cent of that which would have to be transmitted through the collector rings of a revolving armature alternator of the same capacity. The voltage between the collector rings is also relatively small, being either 125 volts, or 250 volts in the larger machines.

REVOLVING-ARMATURE ALTERNATORS

In this type of alternator, the field magnet is stationary, while the armature is mounted on a shaft and is driven (by means of a belt or mechanical coupling) by the prime mover, which may be either a steam engine, a steam turbine, or a water wheel. The current induced in the armature conductors is delivered to the external circuit through collector rings on which brushes rub. The armature may be wound for a single-phase current (having two collector rings), for two-phase currents (having four collector rings), for three-phase currents (having three collector rings), etc. The revolving-armature type is used almost exclusively for alternators of small output and moderate voltage.

Although single-phase alternators, and especially those of the revolving-armature type have been virtually superseded by poly-phase machines of the revolving-field type, still there are today a number of the older fashioned alternators in regular use in some of the smaller electric lighting stations. For this reason some of the typical features of these machines will be described before considering the more modern designs.

Fort Wayne Single-Phase. Fig. 151 shows a 90-kilowatt 1,100-volt 8-pole single-phase belt-driven alternator manufactured by the Fort Wayne Electric Company, of Fort Wayne, Indiana. It is designed to be driven at a speed of 900 revolutions per minute; hence the frequency of its electromotive force is $\frac{8}{2} \times \frac{900}{60} = 60$ cycles per sec-

ond. The figure shows the two collector rings adjacent to the armature, also the rectifying commutator with its brushes for supplying




Fig. 151. Fort Wayne Electric Company 90 Kw. 8-Pole Single-Phase Belt-Driven Alternator

uni-directional current to the coarse wire coils of the composite field winding.}

The *exciter* is a shunt-wound 4-pole-2-kilowatt direct-current generator running at a speed of 1,400 revolutions per minute. It is shown belted to a pulley on the alternator shaft. The current from this exciter is led to the fine wire coils of the composite field winding. Each field pole of the alternator is provided with two coils wound on one and the same spool—one of coarse wire, supplied with current from the rectifying commutator; and the other of fine wire, supplied with current from the exciter.

The *field structure, base-plate, and pedestals* are cast in one piece, and the whole machine rests upon a cast-iron sub-base. This sub-base is provided with slide rails along which the machine may be moved by means of a screw turned by a ratchet and lever, as shown—this for the purpose of adjusting the tension of the main driving belt. The *field poles* are “built up” of sheet-iron stampings and are held together by long bolts. These field poles are arranged in the mould in which the field frame is cast, and are thus cast-welded to the frame.

The *field coils* are machine wound on spools, with insulated copper wire, the coarse wire coils being wound on top of the fine wire coils. The *field spools* are held in position




Fig. 152. German Silver Resistance Coils in Shunt with Coarse Wire Field Coils

on the field poles by brass collars fixed to the outer ends of the poles.

The coarse wire coils, connected in series, are supplied with uni-directional current from the rectifying commutator; and the entire set is shunted with resistance consisting of a strip of German silver wound on an insulated form, Fig. 152, and mounted on an insulated block inside the hollow pedestal on the collector end of the machine.

The *armature* is of the iron-clad ring type built up of small overlapping sheet-steel punchings, annealed and japanned to reduce the loss caused by hysteresis and eddy currents.

The *armature winding* is of the concentrated or uni-coil type. The coils are wound by hand directly on each armature tooth, insulated copper ribbon being used. Armature coils are generally wound on formers, and afterwards sprung into place in the slots on the armature core.

Westinghouse Uni-Coil Armature. Figs. 153 and 154 show a Westinghouse single-phase uni-coil armature very much like the one used in the alternator shown in Fig. 151. The coils of the West-




Fig. 153. Westinghouse Single-Phase Uni-Coil Armature Core

inghouse alternator, however, are machine-wound on formers; and, after being taped, varnished, and baked, they are spread out slightly so as to pass over the teeth, and are forced into place in the deep slots, being securely held there by wooden wedges. Fig. 153 shows the core unwound, and Fig. 154 the method of placing coils in this type of machine. The armature teeth are T shaped, and partially overhang the armature coils, thus protecting the coils from injury. There are, of course, the same number of armature teeth as field poles in the uni-coil armature. Thus Figs. 144 and 145 show an armature core for an eight-pole field.

Fig. 155 shows the completed armature of which the core and coils are shown in Figs. 153 and 154. At the ends of the armature are two brass shields for protecting the ends of the armature coils.




Fig. 154. Westinghouse Single-Phase Armature with Coils in Place

The ring-oiling, spherical-seated, self-aligning bearings are shown on the shaft in Fig. 155; and at the end of the shaft are shown the two

collecting rings and the rectifying commutator. The wires leading to the collector rings and to the rectifying commutator are led through the shaft, which is made hollow.




Fig. 155. Westinghouse Single-Phase Uni-Coil Armature Complete




Fig. 156. Westinghouse Single-Phase Armature Core and Coils. Distributed Winding



Fig. 157. Westinghouse Single-Phase Distributed Winding Armature Complete

Westinghouse Armature with Distributed Winding. Figs. 156 and 157 show a single-phase Westinghouse alternator armature with distributed winding. Three armature coils are shown in Fig. 156

separately and also grouped together. The manner of grouping shown is carried out when the armature coils are assembled on the armature core; and there are as many of these groups of armature coils as there are poles in the field. Fig. 157 shows the finished armature with end shields, collecting rings, and rectifying commutator.

In assembling the stampings of an armature core a stiff, corrugated stamping (or its equivalent) is inserted at intervals between groups of the flat sheet-iron stampings, thus leaving radial air ducts from the inside to the outside of the armature core. These are known as *ventilating ducts*, and their object is to permit of a free circulation of




Fig. 158. Field Structure of a Westinghouse 180-Kw. Alternator

cool air through the armature core and coils, thus preventing excessive rise of temperature. The motion of the armature causes air to be drawn in through the end shields to the interior of the armature, whence it is thrown out through the radial ducts, as in the case of a ventilating fan. Four of these spaces between stampings can be seen in Figs. 156 and 157; and the armature "spider" and end shields at each end, as

shown, are provided with apertures for admitting cool air.

Field Structure for Westinghouse 180-Kw. Alternator. Fig. 158 shows the field structure of a Westinghouse 180-kilowatt alternator before the field coils have been placed upon it. The field poles (laminated) are shown projecting radially inwards from the cast-iron, ring-shaped yoke. The yoke is cast in two pieces, and the upper half is bolted to the lower half, as shown in the figure. The yoke is divided in this way in order that the upper half may be unbolted and may be lifted off by means of the eye-bolt on the top of the machine, thus giving easy access to the armature for inspection and repairs.

General Electric Three-Phase Alternator. Fig. 159 shows a view of a 25-kilowatt three-phase revolving-armature type of alternator

built by the General Electric Company for use in small isolated plants. The alternator is belt-driven at 1,800 r. p. m. and, therefore, requires four poles to give a frequency of 60 cycles.

The view shows three collector rings mounted on the armature shaft for the collection of the three-phase currents, and a commutator between the rings and the armature core. The special feature of this machine is that it requires no separate exciter, for the armature is wound with two distinct windings, one of which is con-




Fig. 159. General Electric 25-Kw. Three-Phase Alternator

nected to the commutator and supplies the exciting current to the field coils. The main armature winding generates the three-phase alternating currents and is connected to the three collector rings. The field structure consists of laminated pole pieces cast into a rigid stationary frame. The field-magnet cores are wound with coils which furnish a magnetic flux which is common to both alternator and exciter armature windings. These machines are built in three sizes and rated at 7.5, 15, and 25 kw. at unity power factor, and at

6, 12, and 20 kw., respectively, at 0.8 power factor. Standard voltages are 120, 240, 480, and 600 volts at 60 cycles, and their ratings are based on either two- or three-phase operation. For single-phase operation any one of the phases may be used, but the rating then is only 70 per cent of the polyphase rating on account of the heating.

REVOLVING-FIELD ALTERNATORS

In this type of alternator, the armature is stationary, and the armature windings are arranged in slots on the inner face of the armature structure, the latter forming a closed ring inside of which the multipolar field magnet revolves. The armature structure consists of an external frame of cast iron or steel supported on a bed-plate. The armature core proper consists of a ring built up of relatively small stampings of sheet iron dovetailed into the external frame and pressed together between two flanges by bolts. The external frame in this type of alternator does not to any perceptible extent carry lines of force, that is, it does not form a part of the magnetic circuit, but serves only as a support for the laminated armature core.

Construction. *Frame.* When a given type of alternator has been standardized by a manufacturer, it is customary to lay out a complete line of machines, which differ in weight by fifteen or twenty per cent between consecutive sizes. The capacity of a given frame is dependent upon speed, voltage, and specified performances.

Frames are made in two general styles, one called the *box type* and the other the *skeleton type*. The box type consists of a single casting for the smaller sizes until an outside diameter of about 8 feet is reached. Above this diameter the frame castings are usually divided into upper and lower sections, split construction being necessary on account of the limitation imposed in handling and shipping.

The skeleton type consists of two side castings between which substantial spacing rods are set at suitable intervals. For manufacturing reasons the skeleton type is preferred for certain sizes of machines, as its construction readily permits of changes being made in the assembling of the armature-core laminations without necessitating a change in the patterns.

The main point to be looked after in alternator frames is a design that will give the maximum of rigidity. The only function

of the frames of rotating-field alternators is to hold rigidly in place the parts composing the stationary element. The frame is further designed with openings at the back of the laminations to give thorough ventilation. The frames contain dovetailed slots into which the laminated iron for the stationary part is pressed. The laminated




Fig. 160. Allis-Chalmers Revolving Field Alternator with Rotor Removed

iron, however, carries all the magnetic flux and the frame is simply for the purpose of holding it in position.

Armature. The armature (stator) core consists of sheet-iron laminations carefully selected and annealed before assembling in order to reduce core loss. The punchings are stacked together and held rigidly in place by heavy steel clamping fingers, the outer circumference of the laminations being dovetailed for fastening to the

frame and the inner circumference being slotted to receive the armature windings. The punchings are separated at intervals by ventilating plates, which give opportunity for air to circulate freely through the ducts thereby created and out at the open back of the frame. Heavy end plates are supplied at both ends of the laminations so as to prevent their bulging out at the ends.




Fig. 161. Allis-Chalmers Revolving Field Alternator with One Bearing Removed and Rotor in Foreground

Bed Plate and Bearing Pedestals. Alternators may be divided into three types depending upon the method of driving, viz, engine type, coupled type, and belted type. In the engine type the revolving element is mounted directly on an extended engine shaft. In the coupled type, as the name indicates, the alternator is entirely self-contained and is designed to be coupled directly to a prime mover, usually a water wheel. In the belted type the alternator is self-

contained and mounted entirely separate from the prime mover and connected therewith by a belt.

The almost universal practice is to make the bed plate, the individual bearing pedestals and the frame all separate. The parts are properly machined and bolted together. This practice enables the manufacturer to use the same parts for the various types of machines, and to vary the combinations of bed plate, bearing pedestal, and frames to suit any case that may arise. For some of the smaller belted machines a bracket bearing support instead of pedestal on a bed plate is used. This allows the size of the bed plate to be reduced to a minimum.

Fig. 160 shows a frame of the box type with the laminations and windings placed therein complete. Fig. 161 shows the same alternator with one of the end brackets containing a bearing removed and the rotor (revolving field) in the foreground. This alternator is for belt driving and is called "Type AB" by the Allis-Chalmers Company who manufacture it.

Fig. 162 is a section of an alternator showing the method of dovetailing the core laminations to the stator frame. Heavy clamping rings or end plates are mounted on both sides of the core by means of bolts, and supporting fingers extend along the teeth on either side of the slots, as shown in Figs. 163 and 164.

An ample circulation of air for cooling is provided by means of ducts formed by suitable spacing blocks inserted at intervals between the laminations, as may be seen in Figs. 163 and 165.

Armature Coils. The armature coils are wound on formers and, the slots being open, the coils can be easily removed and replaced in case of injury. They are taped and impregnated with an insulat-




Fig. 162. Portion of General Electric Alternator Showing Method of Dovetailing Core Laminations.

ing compound. After being tested, the coils are inserted in the armature slots which are lined with horn fiber and retaining wedges of wood are dovetailed into V-shaped notches on either side of the slot, as shown in Figs. 163 and 165.

Supporting Ring. Where heavy windings project beyond the laminations, an additional support is provided by means of an insulated metal ring, to which the outer ends of the coils are fastened; the coils are thereby protected from mechanical displacement, or distortion due to the magnetic disturbances caused by violent fluctua-





Fig. 163. Armature Coil Support Construction—General Electric Alternator

tions of the load or short-circuits. Fig. 165 shows a section of a supporting ring of this type and indicates the method of connecting the coils to it. In order to admit of the prompt replacement of damaged coils, sufficient space is usually provided between the alternator bearings to allow ample movement of the stator to permit of ready access to both stator and rotor coils. Where space economy necessitates the use of a short shaft, access to the windings may be procured by disconnecting some of the coils and lifting the upper half of the stator.





INTERIOR OF THE POWER HOUSE OF THE FRASER RIVER LUMBER COMPANY, SHOWING 750-Kw. TURBO-GENERATOR, EXCITER, AND SWITCHBOARD

Courtesy of Allis-Chalmers Company, Milwaukee, Wis.

Terminals. Flexible leads are brought through the frame of the machine near the bottom and connected directly to the line or to terminal blocks which are mounted on the frame. The former arrangement is usually employed.

Rotating Field. The construction of the rotating field is very similar to that of the stationary armature except that the punchings are dovetailed into a rotating spider instead of a stationary frame.

Fig. 166 is a view of a laminated *field core* in process of construction, showing how the laminations are assembled with overlapping




Fig. 164. Armature Coil Support Construction—General Electric Alternator

joints, and are fastened to the supporting structure. Three individual stampings are shown separate in the figure.

In assembling the stampings that form the built-up structure of *field poles* and *yokes*, the stampings break joints, in order to enable the structure to resist centrifugal force without bringing undue stress upon the central supporting structure. The stampings are perforated with a number of holes, as shown. These holes register in the built-up structure, and bolts are passed through them in order




Fig. 165. Portion of General Electric Stationary Armature Showing Method of Connecting Armature Coils




Fig. 166. Method of Constructing Laminated Field Cores

to clamp the laminations together. At intervals of about 3 inches, the laminations are separated by a corrugated lamination (or its equivalent), which serves to form ventilating ducts that extend inwardly to large openings in the cast-iron segments. These ventilating ducts in the revolving field register or coincide with corresponding ducts in the external stationary armature.

The field-pole tips are beveled so as to produce a distribution of magnetic flux which will give approximately a sine wave electromotive force at no load (under load conditions the wave would be somewhat distorted).

For alternators of relatively small rated output, from about 30 to 200 kilowatts, and designed for belt driving at a high speed, another type of construction is used by the Westinghouse Company in their "Type G" generators.

The central portion of the revolving part, shown in Fig. 167, is a laminated spider, built up of thin steel plates assembled upon a mandrel and firmly riveted together under hydraulic power.

The core is accurately bored and the spider is pressed upon the shaft in the same manner as a cast-steel spider. The poles, one of which is shown in Fig. 168, are also built up of steel laminations of the same thickness as those of the spider, and riveted together. Each pole is dovetailed into the spider and retained by two taper steel keys. Fig. 169 shows the rotor core with pole pieces assembled on the spider.




Fig. 167. Field Spider Showing Laminated Construction




Fig. 168. One of the Field Poles Which Fits into the Core of Fig. 167

The pole pieces are thereby securely held in place during operation; but poles and coils may be easily taken out when desired, by knocking out the steel keys.




Fig. 169. Rotor Core with Pole Pieces Assembled on Spider




Fig. 170. Rotor of Fig. 169 with Field Coils in Place

by knocking out the steel keys. The field coils of these "type G" alternators are wound with wire, and the complete rotor or revolving field for the 30- and 50-kilowatt machines is shown in Fig. 170. The pole pieces of this type of alternator rated above 50 kilowatts up to 200 kilowatts are provided with practically closed slots in the pole face for the copper bars of a "squirrel-cage" winding. The slots are plainly shown in Fig. 167, and the rotor with the cage winding in place is shown in Fig. 171. This winding, also called an "amortisseur" winding, acts as an effective damper to prevent hunting between machines operated in parallel. The collector rings for conveying through brushes the direct current for exciting the field coils, shown to the right in Fig. 171, are of cast iron, insulated from the iron bushing over which they are shrunk by V-shaped mica. Another rotor construction is often employed in the case of

large alternators designed for engine driving. In such machines the revolving field structure consists of laminated pole pieces bolted

to a cast-steel or iron ring, which is connected to the hub by arms of suitable section, as shown in Fig. 172. The pole pieces are built of sheet iron, spreading at the pole face so as to secure not only a large sectional area for the magnetic flux passing from the poles into the steel ring, but also to hold the field coils in place.

In Fig. 172 is shown the revolving field of an alternator built by the General Electric Company for direct connection to reciprocating engines. In Fig. 173 is shown the laminated pole piece and one of the strip-wound field coils, and in Fig. 174 is shown a complete pole piece with its coil ready for bolting to the face of the supporting structure.

Field Coils. The field coils are wound on spools or in moulds. Wire is used for the smaller generators and in those of larger capacity a single strip of flat copper bent on edge is usually employed, as shown in Fig. 173, so that the edge of every turn is exposed to the




Fig. 171. Rotor with Squirrel-Cage Winding

air to facilitate radiation, and hence cooling. The strap-wound coils are insulated between turns with asbestos strip forming a fireproof coil which is practically indestructible. The wire coils are wound dry and treated with insulating varnishes. In every case the insulation provided is easily sufficient for the low voltage to which the field winding is subjected.

Excitation. The direct current for exciting the field magnet is carried in to the revolving-field structure by means of brushes rubbing on collector rings to which are connected the terminals of the field coils. The latter are all connected in series.

Alternators are usually separately excited by 125-volt direct current. This voltage is generally regarded as standard, is easily




Fig. 172. Rotor Construction with Laminated Pole Pieces Bolted to Cast-Iron or Steel Ring

handled, and lends itself readily to the operation of lights and small auxiliary machines in power stations. For large alternators a voltage




Fig. 173. Laminated Pole-Piece and Strip-Wound Field Coil for Rotor of Fig. 172

of 250 has frequently been employed and field coils can be wound for this voltage when required. The lower voltage is generally

to be preferred, principally because it permits the use of strap-wound field coils. For generators large enough to employ field coils of this type at the higher voltage, 250-volt excitation is not objectionable. The limitation is based on the fact that very thin copper strap cannot be successfully bent edgewise.

Water-Wheel-Driven Alternators. Alternating-current generators which are designed to be directly connected to water-wheels are usually driven at speeds of from about 150 to 600 revolutions per minute, depending upon the size and type of water wheel used. The customary range of speeds in water-wheel-driven alternators is, therefore, intermediate between the slow-speed range of the engine-driven type and the high-speed range of the steam turbine-driven type. Alternators of the water-wheel type are built both with horizontal and with vertical shafts according to conditions. The form of foundation used varies with the service for which they are intended. For the machines with horizontal shafts, cast-iron or channel iron bases are used, and in some cases simple foundation plates are provided for the stator with separate sole plates for the bearing standard. For vertical shaft alternators the base is constructed either for mounting directly on the turbine casing or on separate foundations above the wheel pit. The shafts are keyed to the rotor and are arranged for coupling to the water-wheel shaft.




Fig. 174. Completed Field Coil for Rotor of Fig. 172

The style of bearings adopted depends upon the size of the alternator. Some of the smaller machines are furnished with end shield bearings but the standard form for horizontal shaft alternators is a pedestal bearing arranged for oil-ring lubrication. Large machines are often provided with water-cooled bearings which consist of a number of short tubes extending horizontally through the oil well

below the bearing through which the cooling water is conducted, thereby reducing the temperature of the oil.

Vertical shaft alternators are arranged for direct connection to the water-wheel shaft and are usually provided with one or two guide bearings. Step or suspension bearings arranged for forced oil circulation are also standard. The standard water-wheel type of alternator is wound for three phases, but it can be adapted for two phases without change, except in the armature coils and punchings. Where single-phase operation is required, the three-phase winding




Fig. 175. View of General Electric Water-Wheel-Driven Alternators

is furnished, the single-phase current being taken off from any two of the three armature terminals. When thus used the alternator full-load rating at unity power factor is only about 70 per cent of the full-load three-phase rating.

Where transformers are used to step-up the voltage for long-distance power transmission, it is considered good practice to install alternators wound for the standard voltages of 2,300 or for 6,600 volts, but where current is to be transmitted at the generator voltage, armature windings for 11,000 volts, 60 cycles, or for 13,200 volts, 25 cycles, are considered standard.

Fig. 175 is a general view of three water-wheel-driven alternators manufactured by the General Electric Company and installed in a hydroelectric power plant at Spokane, Washington. The alternators are each rated at 2,250 kilowatts, 60 cycles, 2,300 volts, 138 revolutions per minute and are wound with three phases. Each machine has $\frac{60 \times 2 \times 60}{138} = 52$ poles. The view shows the excitors directly mounted on an extension of the main shaft, and supported on a bracket which is bolted to the iron base.

These alternators may be furnished either with or without direct-connected excitors. When arranged for direct connection, the armature of the exciter is carried on the generator shaft. In




Fig. 176. General Electric Alternator with Direct-Connected Exciter Bracketed to the Same Base

the smaller sizes the magnet frame is bolted to the bearing bracket, as shown in Fig. 176, but in the larger sizes special construction is used, depending upon the conditions of the particular installation. Fig. 176 also shows clearly the coupling for direct connection to the water wheel at the right, and the box type of frame with ventilating apertures. This General Electric alternator is rated at 3,000 kilowatts, 2,300 volts, and 514 revolutions per minute.

Fig. 177 is a general interior view of the new hydroelectric plant of the Connecticut River Power Company at Vernon, Vermont. Five vertical shaft water-wheel-driven alternators are used, each

being rated at 2,500 kilowatts 2,300 volts, 60 cycles, and 133 revolutions per minute. The two small vertical shaft generators, located between the first and second large units, are exciters, each driven independently by a small water wheel installed below the main floor level. This practice of using exciters driven independently of the main water wheels is to be recommended, as it is a safeguard against a general shutting down of the plant due to accident to one or more of the main machines.




Fig. 177. Interior View of Connecticut River Power Company's Hydroelectric Plant

Fig. 178 shows an armature structure for a 600-kilowatt Allis-Chalmers "water-wheel type" alternator, with a three-phase winding in place. This winding is distributed in two slots per pole per phase. The coils that constitute one of the phases are those of which the ends show most distinctly. The sides of the coils belonging to the other two phases lie in the remaining slots, four of which are surrounded by each pair of coils belonging to the first phase. The manner of connecting the coils belonging to each phase is explained on page 145. This armature structure, Fig. 178, has two extensions cast as part of the frame, which are intended to rest upon a foun-

dation on a level with the floor. The lower part of the ring is designed to extend below the level of the floor into a pit. In the same figure is shown also a metal shield which is screwed to the frame and serves to protect the ends of the armature coils.




Fig. 178. Stationary Armature for 600-Kw. Allis-Chalmers "Water-Wheel Type" Alternator

Steam Turbine-Driven Alternators. This type of machine, often called a turbo-alternator, has been in the past few years greatly improved and developed. The steam-turbine has already largely supplanted the reciprocating engine in all large steam-electric stations and the present general tendency is away from the low-speed engine-

TABLE V
Turbine Speeds for Alternators

POLES	2	4	6	8	10
60 cycles	3600	1800	1200	900	720
25 cycles	1500	750			

driven alternators and towards the high-speed turbine-driven alternator. The steam turbine operates most efficiently at high speeds, so in order to accommodate the generators to these conditions with the standard frequencies of 25 to 60 cycles, the number of field poles must be reduced to a minimum. For this reason 60-cycle generators have been built with two poles for 3,600 revolutions per minute in capacities up to 2,500 kilowatts, and with four poles for 1,800 revolutions per minute up to 10,000 kilowatts.

25-cycle alternators are necessarily limited to a maximum speed of 1,500 revolutions per minute, even with only two poles. Two-pole alternators have been built in sizes up to 7,500 kilowatts, and even larger machines are possible. Table V gives the revolutions per minute which have been used for turbo-alternators.

The steam turbine is an essentially high-speed machine and the alternator designed to be driven by it must be constructed with special attention to the effects of high speed. This requirement has developed many interesting though difficult problems in design, such as constructions able to withstand the enormous centrifugal forces developed in the rotor, amounting to 4,000 pounds on each pound of material near the surface of the rotor. The important matters of securing perfect balance and freedom from vibration at high speeds, of adequate ventilation, and lubrication of bearings, have been successfully met.

Advantages. The most important advantages of steam turbines over reciprocating steam engines are:

- (1) High economy at all loads.
- (2) Economy in floor space and building material.
- (3) Moderate initial cost and low maintenance expense.
- (4) Simplicity of construction; absence of all small clearances; absence of thrust balancing pistons with their heavy and uncertain leakages.
- (5) Maintenance of efficiency and general durability.

- (6) Ability to effectively utilize the large increase of available energy incident to the use of high steam pressure and high vacuum
- (7) Ability to use high superheat without mechanical difficulties.

Fig. 179 is a general view of a Westinghouse-Parsons three-phase four-pole turbo-alternator rated at 1,000 kilowatts, 60 cycles, 4,400 volts, and 1,800 revolutions per minute, as installed for the Public Service Corporation of Columbus, Ohio. The steam turbine is shown at the right and is directly connected through a horizontal shaft to the alternator at the left. This alternator is of the revolving field type as is the universal practice with turbine-driven machines.




Fig. 179. General View of Westinghouse-Parsons Three-Phase Four-Pole Turbo-Alternator

Stator. Except in the largest sizes, the stator frames are made in one piece. The large machines are divided horizontally, the two halves being bolted together, and the stator laminations are assembled as if the frame were solid. The frame consists of a heavy casting with internal strengthening ribs and is bored out to receive the laminated iron core. The internal ribs are provided with dovetail slots into which the laminations are fitted. The frame is designed to provide a rigid mechanical support for the stator core. The cast-iron frame does not form a part of the magnetic circuit. The two-

part frames have faced joints and the two parts are secured and keyed together so that they form practically a single piece. The armature or stator is built up of punchings of soft sheet steel of a high magnetic quality. Ventilating plates are provided at suitable intervals, forming air ducts in the core. The core is slotted to receive the armature winding, the shape of the slot depending upon the capacity of the machine and the character of the winding. Either open or partly closed slots are used, the edges of the former being grooved at the top to receive the retaining wedges holding the coils in place. At the




Fig. 180. Method of Bracing Armature Coils

ends, the teeth are supported by finger plates and heavy retaining plates which are pressed into place and keyed. Closed end bells are provided which cover the ends of the armature coils and the moving parts of the machine between the frame and ventilating system. The end bells close each end of the generator and form a duct through which cool air is drawn into the machine and forced out through ventilating ducts in the stator into the interior of the frame, from which the air passes down through the bed plate and escapes. In the large generators the air also escapes through openings in the top of the frame. The rotor of the machine is provided with a fan at each end to draw the air into the machine. Form-wound armature coils are used and the winding is of wire, strap, or bar copper, depending upon the capacity and voltage of the machines. The coils are insulated before they are assembled on the machine. The slots are provided with a lining of fibrous material and the coils are wedged into the slots by wedges fitted in grooves in the sides of the slots or below the overhanging tips of the teeth. The armature coils are firmly braced at the ends of the frame in such a

from which the air passes down through the bed plate and escapes. In the large generators the air also escapes through openings in the top of the frame. The rotor of the machine is provided with a fan at each end to draw the air into the machine. Form-wound armature coils are used and the winding is of wire, strap, or bar copper, depending upon the capacity and voltage of the machines. The coils are insulated before they are assembled on the machine. The slots are provided with a lining of fibrous material and the coils are wedged into the slots by wedges fitted in grooves in the sides of the slots or below the overhanging tips of the teeth. The armature coils are firmly braced at the ends of the frame in such a

manner as to insure them against displacement, as shown in Fig. 180.

Rotor. The revolving field or rotors are constructed with two, four, or six poles, according to the frequency and capacity of the




Fig. 181. Four-Pole Rotor for 10,000-Kw. Machine

machine. The fields are of small diameter and are designed with special care to avoid windage losses and to facilitate ventilation. The poles of the two-pole and four-pole rotors are machined from the disk or disks forming the central body, and the slots to receive the field coils and the grooves for the binding wedges are milled. This construction is illustrated in Fig. 181, which is a view of a four-pole rotor for a 10,000-kilowatt machine designed for a speed of 750 revolutions per minute. The six-pole rotors are built up by bolting poles to a central body. The rotors are carefully balanced after




Fig. 182. Two-Pole Rotor Shaft

they are wound. In some designs the rotor is pressed and keyed on to the shaft, and in others the shaft is formed of steel, cast or forged integral with the rotor core. For two-pole machines the

rotor is generally made from a solid cylinder and the shaft is made in two portions and secured to each end of the rotor by heavy bronze flanges and suitable bolts, as shown in Fig. 182.




Fig. 183. Curtis Vertical-Shaft Turbo-Alternator of 5,000-Kw. Capacity

The field consists of copper strap embedded in slots cut in the poles, as shown in Fig. 181. The coils are wound directly in place under a heavy tension. A groove is cut in both sides of the slots and brass wedges are driven in to hold the coils in place. The coils are heavily insulated with material of high dielectric and mechanical strength, applied in several layers. The winding and insulation are tightly wedged into place.

Curtis Turbo-Alternator. A general view of a Curtis steam turbine alternator, built by the General Electric Company, is shown in Fig. 183. This unit is rated at 5,000 kilowatts, 13,000 volts, 25 cycles, and 750 revolutions per minute. As is usual with Curtis turbo-alternators of large size, this is of the vertical type. The generator is located at the top of the unit and the turbine wheels




Fig. 184. Two Views of Stationary Armature of Curtis Alternator

are below. The stationary armature with the clamping devices for rigidly supporting the coils is shown in Fig. 184.

Fig. 185 is a view of a smooth core rotor for a 9,000-kilowatt vertical type of Curtis turbo-alternator. A feature of interest is the method employed for the attachment of the shields for the end windings. The outer retaining cylinders are secured to the inner shell by a large number of short bolts which remove a part of the stress of the end windings from the outer shell. The rotor is so

designed that it acts as a powerful fan, forcing air throughout the parts of the generator requiring ventilation.

The *advantages* claimed for the vertical shaft type of Curtis turbine for large machines are:

- (1) The relative positions of revolving and stationary parts are definitely fixed by the step-bearing.
- (2) The stationary part is symmetrical, and free from distortion by heat.
- (3) The shaft bearings are relieved from all strain, and friction is practically eliminated.
- (4) The shaft is free from deflection, and can be made of any size without reference to bearings.





Fig. 185. Smooth Core Rotor for 9,000-Kw. Curtis Turbo-Alternator

- (5) The turbine structure affords support and foundation for the generator.
- (6) The cost of foundations is small, and their support is naturally simple.
- (7) Much floor space is saved.
- (8) All parts of the machine are accessible.

For high speed machines and turbines connected to direct-current generators, the horizontal shaft has some advantages. The fact that many electric generators of the horizontal type have already been developed for such conditions is frequently responsible for

the selection of the horizontal type of unit. In the smaller sizes this type is standard. The characteristics of the Curtis turbine specially adapt it for driving horizontal shaft generators. The shaft is very short, of small diameter, and has a comparatively low surface speed in the bearings, resulting with the light weight of the revolving parts in low bearing friction and small tendency to wear.



THREE 500 K. W. COUPLED TYPE A. C. GENERATORS, 6,800 VOLTS, 25 CYCLES
Westinghouse Electric & Manufacturing Co.

ALTERNATING-CURRENT MACHINERY

PART III

ECONOMY FACTORS IN ALTERNATORS

CONDITIONS AFFECTING COST

Speed. The most important factor in determining the cost of an alternator for a given rated output, is its speed, inasmuch as a low-speed machine must be much larger than a high-speed machine of the same rated output. Belt-driven machines are always run at the highest speed compatible with safety to the alternator itself; while, on the other hand, the speed of a direct-connected alternator, being determined by the speed of the engine or water wheel, is usually less than is necessary for safe running. Therefore, a belt-driven machine is usually cheaper than a direct-connected machine of the same rated output. Very large machines must be direct-connected, inasmuch as belt driving is out of the question for large machines on account of the excessive cost of very large belts, the great amount of floor space required, the power lost in the belt, the expense of attendance and maintenance, and the noise. Direct-connected alternators, especially machines of large rated output, except turbo-alternators, are usually designed with the rotating member (armature or field) of large diameter, in order that the permissible speed of the alternator may be approximately the same as the proper speed of the driving engine or water wheel. The steam turbine being inherently a high-speed machine requires an alternator built for high speed, which means a rotor of small diameter.

Voltage. A second factor affecting cost is the voltage that is to be developed in the armature. A machine for high voltage must have a large number of armature conductors, and these conductors must be highly insulated, that is, the insulation must occupy a

Copyright, 1911, by American School of Correspondence.

relatively large portion of the winding space in the slots. This requires a large machine for a given power output, on account of the space wasted, as it were, in insulation. To offset this disadvantage, a high-voltage alternator does not require the use of step-up transformers, the voltage generated in the alternator being suited for the transmission of power to moderate distances, that is, the extra cost of the alternator may be more than offset by the saving in the cost of the step-up transformers.

Regulation. A third factor affecting cost is found in the requirements of close regulation and high efficiency. Thus an alternator of given power output may be made smaller in size and, therefore, cheaper, if high efficiency and low regulation are not demanded. High efficiency and low regulation mean a liberal use of iron and copper in order to secure a minimum loss of power and electromotive force in a machine. Furthermore, the efficiency of a given size of alternator for given output may be increased at the expense of regulation, or *vice versa*. The increasing adoption of a satisfactory automatic voltage regulator for alternators makes it unnecessary as well as expensive to specify a low inherent regulation, as explained on page 117.

Frequency. A fourth factor affecting cost is the frequency required. With given speed an increase of frequency means an increase in the number of field poles and in the number of armature coils and, therefore, an increase in the cost of construction. This element of cost is most prominent in very slow-speed direct connected alternators. For example, a 60-cycle alternator, direct-connected to an engine running at 300 r. p. m., must have 24 poles to give the required frequency. To reduce the frequency to 25 cycles would require only 10 poles, with a corresponding reduction in the cost of the field-magnet copper and of labor. On the other hand, lowering the frequency of an alternator, while keeping the speed constant, would require an increase in the useful flux per pole and a corresponding increase in the cross-sectional areas of the field yoke, the field poles, and the armature core. This would mean an increase in the amount of iron to be used in the machine. The frequencies in most general use today are 60 cycles and 25 cycles. 60-cycle apparatus is generally lower in price and should always be chosen for general lighting and power service.

POWER LOSSES

The power losses in an alternator consist of the following parts:

- (a) Loss due to brush, journal, and air friction. Air friction is usually called *windage*.
- (b) Power consumed in heating the field windings by the exciting current.
- (c) Power loss in heating the armature windings by the armature current or currents.
- (d) Hysteresis loss in all iron that is subject to variations of magnetization and eddy currents in all metal parts subject to such variations.

Friction and windage loss can be determined only by experiments upon the finished machine.

The power consumed in the field windings is I^2R , where I is the field current and R is the resistance of the field circuit. The field rheostat is properly a part of the machine, and the losses occurring in it are, therefore, a part of the machine losses. This same formula may be used to calculate power consumed in each field winding of a composite-field alternator.

The power lost in heating the armature windings is $I^2R \times$ the number of phases, where I is the current in each phase and R is the resistance of each phase.

The power lost by eddy currents and hysteresis may be approximately calculated by the method employed for the corresponding calculation in the case of a transformer.

EFFICIENCY

The efficiency of an alternator is the ratio *output of power* \div *input of power*. Since the mechanical input of power is equal to the output of power plus all the losses of power, we have also

$$\text{efficiency} = \frac{\text{output}}{\text{output} + \text{losses}}$$

At zero load (zero output), the efficiency of an alternator is, therefore, zero; the efficiency increases with increasing load, reaches a maximum, and falls off for large loads. An alternator may be designed to give its maximum efficiency at any prescribed fraction of full load; it is generally desirable, however, to design the machine to give its maximum efficiency at approximately full load.

The efficiency of a large alternator at full load is usually greater than the efficiency of a small alternator. For example, the large alternators in the great power stations at Niagara Falls have efficiencies of over 98 per cent. A well-designed 50-kilowatt alternator has an efficiency of about 90 per cent.

Practical and Ultimate Limits of Output. The dotted curve, Fig. 186, is the characteristic curve of a given alternator. This curve shows the relation between the current output (plotted as abscissas) and the electromotive force between the collecting rings (plotted as ordinates, using scale to the left), the field excitation being kept constant. The ordinates of the full-line curve (scale shown to the right in the figure) represent the power outputs (in kilowatts) corresponding to the different current outputs assuming




Fig. 186. Characteristic Curves of an Alternator

a non-inductive receiving circuit. The maximum output of the alternator, in this case, is 68 kilowatts when the current output is 38 amperes and the corresponding electromotive force is 1,790 volts. In practice the allowable power output of an alternator is limited to a smaller value than this maximum output by one or the other of the following considerations:

(a) Electric lighting and power service usually demands an approximately constant electromotive

force; and it is not permissible to take from an alternator a current so large as greatly to reduce its electromotive force. This difficulty may be largely overcome by providing for an increase of field excitation of the alternator with increase of load, as is done in the alternator with a composite field winding, or by means of the Tirrill voltage regulator.

(b) The current delivered by an alternator generates heat in the armature of the alternator; and the temperature of the armature rises until it radiates heat as fast as heat is generated in it by the current. Excessive heating of the armature endangers the insulation of the windings by charring, and it is not permissible to take from an alternator a current so large as to heat its armature more than 40° or 50° C. above the temperature of the air; this heating, therefore, fixes the allowable output and rating of an alternator.

Influence of Power Factor upon Output. Alternators are rated according to the power they can deliver steadily to a non-inductive receiving circuit without overheating. The amount of power which an alternator can satisfactorily deliver to an inductive receiving circuit is less than that which it can deliver to a non-inductive receiving circuit, because of the phase difference of electromotive force and current. The cosine of the angle of phase difference ($\cos \theta$) is called the "power factor" of the receiving circuit, as before pointed out. The power factor of incandescent lighting circuits is very nearly unity if the transformers are all operating at approximately full load.

A transformer having its primary coil connected to alternating-current mains, but furnishing no current from its secondary coil, has a power factor of from about 0.3 with a frequency of 25 cycles to about 0.7 with 60 cycles. The power factor increases with the secondary lamp load, until, in the neighborhood of full load, the power factor is nearly unity.

Induction motors, like transformers, have a maximum power factor at full load, which rarely exceeds 0.9; this factor under partial loads falls to 0.7 or even less; and at starting it is a minimum around 0.3.

A mixed load consisting of transformers and induction motors more or less fully loaded, has an average power factor of from 0.8 to 0.85.

It should be carefully noted that alternators are rated in kilovolt-ampere output, that is, a 100-k.v.a. alternator should deliver its full energy output of 100 kilowatts at unity power factor; but if the power factor should be only 0.8, the true power output would be reduced to 80 kilowatts, although the armature current and the I^2R loss would be about the same as if the machine were delivering 100 kilowatts at unity power factor. To find the actual power output of an alternator the "apparent power," or kilovolt-amperes, must be multiplied by the power factor of the load.

RATING AND OVERLOAD CAPACITIES

Previous to the definite recommendations of the American Institute of Electrical Engineers in the matter of overload capacities as given below, there were great differences among different manu-

facturers in the rating of alternators. Thus, one maker might have sold a certain alternator as a 50-kilowatt alternator, although the machine might have been capable of delivering 50 per cent overload (or 75 kilowatts) for several hours without dangerous rise of temperature; whereas another maker might have sold an exactly similar machine as a 75-kilowatt alternator.

As an illustration of the difference of permissible rating of a given alternator according to conditions of service, the following is taken from the practice of one of the large American manufacturing companies.

A certain alternator has twenty poles, and runs at 150 r. p. m. When this machine is rated at 300 kilowatts, its maximum rise of temperature will not exceed 35°C. (by thermometer) when it is operated continuously with non-inductive full load; its maximum rise of temperature will not exceed 55°C. when it is run for two hours at 50 per cent overload non-inductive. Its full-load regulation will be 6 per cent with non-inductive load, and 18 per cent with 80 per cent power factor.

When this same machine is rated at 360 kilowatts, its maximum rise of temperature will not exceed 40°C. (by thermometer) when it is operated continuously with non-inductive full load; its maximum rise of temperature will not exceed 55°C. when it is run for two hours at 25 per cent overload non-inductive. Its full load regulation will be 8 per cent with non-inductive load, and 22 per cent with 80 per cent power factor.

In general the rated power output of any alternator may be 20 per cent higher with a permissible rise of temperature of 40°C. and a regulation of 8 per cent on non-inductive full load, than with a permissible rise of temperature of 35°C. and a regulation of 6 per cent on non-inductive full load.

American Institute Rules. In order to establish a definite and uniform basis for rating alternators and for guaranteeing their performance in service under normal full load as well as overload, the following rules have been adopted by the American Institute of Electrical Engineers. The numbers on the left are the paragraph numbers of the revised (1907) report of the Institute Committee on Standardization.

RATING

- 65 **RATING BY OUTPUT.** All electrical apparatus should be rated by output and not by input. Generators, transformers, etc., should be rated by electrical output; motors by mechanical output.
- 66 **RATING IN KILOWATTS.** Electrical power should be expressed in kilowatts, except when otherwise specified.

- 67 **APPARENT POWER, KILOVOLT-AMPERES.** Apparent power in alternating-current circuits should be expressed in kilovolt-amperes as distinguished from real power in kilowatts. When the power factor is 100 per cent, the apparent power in kilovolt-amperes is equal to the kilowatts.
- 68 **RATED (FULL-LOAD) CURRENT** is that current which, with the rated terminal voltage, gives the rated kilowatts, or the rated kilovolt-amperes. In machines in which the rated voltage differs from the no-load voltage, the rated current should refer to the former.
- 69 **DETERMINATION OF RATED CURRENT.** The rated current may be determined as follows: If P = rating in watts, or apparent watts if the power factor be other than 100 per cent, and E = full-load terminal voltage, the rated current per terminal is:
- 70 $I = \frac{P}{E}$ in a direct-current machine or single-phase alternator.
- 71 $I = \frac{1}{\sqrt{3}} \times \frac{P}{E}$ in a three-phase alternator.
- 72 $I = \frac{1}{2} \times \frac{P}{E}$ in a two-phase alternator.
- 73 **NORMAL CONDITIONS.** The rating of machines or apparatus should be based upon certain normal conditions to be assumed as standard, or to be specified. These conditions include voltage, current, power-factor, frequency, wave shape and speed; or such of them as may apply in each particular case. Performance tests should be made under these standard conditions unless otherwise specified.
- 74 (a) **Power Factor.** Alternating-current apparatus should be rated in kilowatts, at 100 per cent power factor; *i. e.*, with current in phase with terminal voltage, unless a phase displacement is inherent in the apparatus or is specified. If a power factor other than 100 per cent is specified, the rating should be expressed in kilovolt-amperes and power factor, at rated load.
- 75 (b) **Wave Shape.** In determining the rating of alternating-current machines or apparatus, a sine wave shape of alternating current and voltage is assumed, except where a distorted wave shape is inherent to the apparatus.

LIMITING TEMPERATURE RISE

- 272 **GENERAL.** The temperature of electrical machinery under regular service conditions, should never be allowed to remain at a point at which permanent deterioration of its insulating material takes place.
- 273 **LIMITS RECOMMENDED.** It is recommended that the following maximum values of temperature elevation, referred to a standard room temperature of 25 degrees centigrade, at rated load under normal conditions of ventilation or cooling, should not be exceeded.
- 274 (A) **MACHINES IN GENERAL.** In commutating machines, rectifying machines, pulsating-current generators, synchronous machines, synchronous commutating machines and unipolar machines, the temperature rise in the parts specified should not exceed the following:

- 275 Field and armature, 50°C.
- 276 Commutator and brushes, by thermometer, 55°C.
- 277 Collector rings, 65°C.
- 278 Bearings and other parts of machine, by thermometer, 40°C.
- 279 (B) *ROTARY INDUCTION APPARATUS*. The temperature rise should not exceed the following:
- 280 Electric circuits, 50°C., by resistance.
- 281 Bearings and other parts of the machine 40° C., by thermometer.
- 282 In squirrel-cage or short-circuited armatures, 55° C., by thermometer, may be allowed.
- (C) *STATIONARY INDUCTION APPARATUS*.
- 283 (a) *Transformers for Continuous Service*. The temperature rise should not exceed 50 degrees centigrade in electric circuits, by resistance; and in other parts, by thermometer.
- 284 (b) *Transformers for Intermittent Service*. In the case of transformers intended for intermittent service, or not operating continuously at rated load, but continuously in circuit, as in the ordinary case of lighting transformers, the temperature elevation above the surrounding air-temperature should not exceed 50° C., by resistance in electric circuits and by thermometer in other parts, after the period corresponding to the term of rated load. In this instance, the test load should not be applied until the transformer has been in circuit for a sufficient time to attain the temperature elevation due to core loss. With transformers for commercial lighting, the duration of the rated-load test may be taken as three hours, unless otherwise specified.
- 285 (c) *Reactors*, induction- and magneto-regulators—electric circuits by resistance and other parts by thermometer, 50°C.
- 286 (d) *Large Apparatus*. Large generators, motors, transformers, or other apparatus in which reliability and reserve overload capacity are important, are frequently specified not to rise in temperature more than 40° C. under rated load and 55° C. at rated overload. It is, however, ordinarily undesirable to specify lower temperature elevations than 40 degrees centigrade at rated load, measured as above.
- (E) *LIMITS RECOMMENDED IN SPECIAL CASES*.
- 289 (a) *Heat Resisting Insulation*. With apparatus in which the insulating materials have special heat-resisting qualities, a higher temperature elevation is permissible.
- 290 (b) *High Air Temperature*. In apparatus intended for service in places of abnormally high temperature, a lower temperature elevation should be specified.
- 291 (c) *Apparatus Subject to Overload*. In apparatus which by the nature of its service may be exposed to overload, or is to be used in very high voltage circuits, a smaller rise of temperature is desirable than in apparatus not liable to overloads or in low-voltage apparatus. In apparatus built for conditions of limited space, as railway motors, a higher rise of temperature must be allowed.
- 292 (d) *Apparatus for Intermittent Service*. In the case of apparatus intended for intermittent service, except railway motors, the temperature

elevation which is attained at the end of the period corresponding to the term of rated load, should not exceed the values specified for machines in general. In such apparatus the temperature elevation, including railway motors, should be measured after operation, under as nearly as possible the conditions of service for which the apparatus is intended, and the conditions of the test should be specified.

OVERLOAD CAPACITIES

- 293 **PERFORMANCE WITH OVERLOAD.** All apparatus should be able to carry the overload hereinafter specified without serious injury by heating, sparking, mechanical weakness, etc., and with an additional temperature rise not exceeding 15°C., above those specified for rated loads, the overload being applied after the apparatus has acquired the temperature corresponding to rated load continuous operation. Rheostats to which no temperature rise limits are attached are naturally exempt from this additional temperature rise of 15°C. under overload specified in these rules.
- 294 **NORMAL CONDITIONS.** Overload guarantees should refer to normal conditions of operation regarding speed, frequency, voltage, etc., and to non-inductive conditions in alternating apparatus, except where a phase displacement is inherent in the apparatus.
- 295 **OVERLOAD CAPACITIES RECOMMENDED.** The following overload capacities are recommended.
- 296 (a) *Generators.* Direct-current generators and alternating-current generators, 25 per cent for two hours.
- 297 (b) *Motors.* Direct-current motors, induction motors and synchronous motors, not including railway and other motors intended for intermittent service, 25 per cent for two hours, and 50 per cent for one minute.
- 298 (c) *Converters.* Synchronous converters, 25 per cent for two hours, 50 per cent for one-half hour.
- 299 (d) *Transformers and Rectifiers.* Constant-potential transformers and rectifiers, 25 per cent for two hours; except in transformers connected to apparatus for which a different overload is guaranteed, in which case the same guarantees shall apply for the transformers as for the apparatus connected thereto.
- 300 (e) *Exciters.* Exciters of alternators and other synchronous machines, 10 per cent more overload than is required for the excitation of the synchronous machine at its guaranteed overload, and for the same period of time. All exciters of alternating-current, single-phase, or polyphase generators should be able to give at its rated speed, sufficient voltage and current to excite the alternator, at the rated speed, to the full-load terminal voltage, at the rated output in kilovolt-amperes and with 50 per cent power factor.
- 301 (f) *A Continuous-Service Rheostat,* such as an armature- or field-regulating rheostat, should be capable of carrying without injury for two hours, a current 25 per cent greater than that at which it is rated. It should also be capable of carrying for one minute a current 50 per cent greater than its rated load current, without injury. This excess of capacity is intended for testing purposes only, and this margin of capacity should not be relied upon in the selection of the rheostat.

ALTERNATOR TESTING

Alternating-Current Testing in General. In the commercial testing of alternating-current apparatus, as in that of direct-current apparatus, the object of the tests is to determine the performance of the apparatus under normal working conditions. Care must be taken, therefore, to carry out each test under the normal working conditions with respect to speed, voltage, frequency, etc. Errors of observation may be greatly reduced by taking a series of observations instead of a single observation or a single set of observations. The observations of this series should be plotted point for point, and a smooth curve drawn through the points in such a way that the points will be equally distributed on both sides of the curve.

Different classes of apparatus require different tests; moreover, the same test may be performed differently on different kinds of machines. For the sake of convenience the tests necessary for each class of alternating-current apparatus will be considered under its own heading.

In general every piece of electrical apparatus must satisfy two vital requirements, namely, (a) it must have insulation of sufficient strength to stand safely the voltage at which it is intended to be operated; and (b) it must not overheat under normal working conditions.

Faulty insulation must be carefully guarded against, since, by the breaking down of the insulation, the apparatus must be put out of service. For example, in the case of transformers for lighting service, a breakdown of the insulation between the primary and the secondary coils endangers the life of persons coming in contact with fixtures on the secondary circuit. Overheating a machine causes a gradual deterioration of the insulation, which may finally result in a complete breakdown of the apparatus. Overheating must, therefore, be avoided.

Insulation Testing. There are three distinct kinds of insulation tests: (a) *the determination of the electrical resistance of the insulation in ohms*; (b) *the subjecting of the insulation of an apparatus to a prescribed voltage in excess of the rated voltage of the apparatus*. This test is intended to insure that the apparatus will operate safely at its rated voltage. It is frequently called the "test of dielectric

strength;" and (c) *the subjecting of the insulation to a voltage which is increased until the insulation is punctured or breaks down.* This is called the "break-down test."

Insulation Resistance. The insulation resistance test, or in other words, the determination, in ohms, of the resistance of an insulating coating, cover, material, or support is usually made by measuring with a sensitive galvanometer the very small current that is forced through the insulation by a known direct or steady electromotive force. The value of the resistance is equal to the impressed electromotive force divided by the current.

The resistance in ohms of the insulation is of only secondary importance as compared with the dielectric strength or the resistance to rupture by high voltage. Insulation resistance tests should, if possible, be made using the electromotive force for which the apparatus is designed.

The insulation resistance of the complete apparatus should be such that the rated voltage of the apparatus will not send more than $\frac{1}{1000}$ of the full load current, at the rated terminal voltage, through the insulation. Where the value found in this way is more than 1 megohm, it is usually sufficient.

Dielectric Strength. The test of dielectric strength may be made as follows: The terminals of the secondary coil of a step-up "high potential" transformer are connected to the terminals of a spark gauge and to the terminals of the insulation to be tested, as shown in Fig. 187. The figure shows that the apparatus under test and the spark gap are connected in parallel between the terminals of the secondary (high voltage) coil of the testing transformer. The spark gauge, page 95, is set at a sparking distance corresponding to the voltage to be used in the test; and the voltage is increased gradually by adjusting the water rheostat in series with the primary (low-voltage) coil of the transformer, and is then to be continuously applied for a prescribed period, usually one minute, until either the insulation is punctured or the desired voltage is reached, as will be indicated by the sparking across the gap between the needle points.

Fig. 187 shows the electrical connections for carrying out a test of dielectric strength on a certain commercial transformer, marked in the figure "apparatus under test." It will be seen that

one terminal of the high-voltage coil of the testing transformer is connected to one terminal of the primary coil (at the left) of the transformer under test, and the other terminal of the high-voltage coil of the testing transformer is connected to one of the four terminals of the secondary coils of the transformer under test. The high voltage is, therefore, applied to the insulation between the primary and secondary coils of the transformer under test.




Fig. 187. Diagram of Connections for Dielectric Strength Test with High Potential Transformer

The use of a water rheostat in series with the primary (low voltage) coil of the testing transformer, as shown in Fig. 187, for varying the impressed voltage, is open to some objection. Such a resistance is liable to seriously affect the wave form of the electromotive force, thereby causing its maximum value to bear a different and unknown ratio to its effective value. The most approved way of securing voltage control is by adjusting the field excitation of the alternator supplying the testing transformer with current. Another method, though not as satisfactory, is by using a transformer with a variable ratio of primary to secondary turns.

Tests of dielectric strength are made with voltages ranging from 1½ to 10 times the rated terminal voltage of a piece of apparatus, according to the rated voltage and output of the apparatus. For example, a transformer of any output whose rated terminal voltage is 20,000 would, according to the recommendations of the American Institute of Electrical Engineers, be tested with 40,000 volts, whereas a 1,000-volt transformer would be tested with 3,500 volts. An induction motor under 10 h. p. rated at 110 volts would be tested with 1,000 volts.

Break-Down. The break-down test is frequently applied in the




Fig. 188. Curve Showing Relation between Sparking Distance and Voltage

testing of small samples of insulating material. For example, a sheet of fuller board, mica-canvas, oiled linen or cloth, would be clamped between sheets of metal connected to the terminals of the high-voltage coil of the testing transformer, and the voltage would be increased until the insulation was punctured, the voltage causing puncture being recorded. A basis is thus obtained for the acceptance or rejection by the purchaser of a lot of insulating material.

Table VI gives, in inches and in centimeters, the sparking distances in air between opposed sharp needle-points, corresponding to various *effective sinusoidal* voltages. The voltages are expressed in kilovolts (1 kilovolt=1,000 volts). Fig. 188 is a curve

TABLE VI .

Sparking Distances for Various Voltages

Kilovolts Square Root of Mean Square	Distance		Kilovolts Square Root of Mean Square	Distance	
	Inches	Cms.		Inches	Cms.
5	0.225	0.57	140	13.95	35.4
10	0.47	1.19	150	15.0	38.1
15	0.725	1.84	160	16.05	40.7
20	1.0	2.54	170	17.10	43.4
25	1.3	3.3	180	18.15	46.1
30	1.625	4.1	190	19.20	48.8
35	2.0	5.1	200	20.25	51.4
40	2.45	6.2	210	21.30	54.1
45	2.95	7.5	220	22.35	56.8
50	3.55	9.0	230	23.40	59.4
60	4.65	11.8	240	24.45	62.1
70	5.85	14.9	250	25.50	64.7
80	7.1	18.0	260	26.50	67.3
90	8.35	21.2	270	27.50	69.8
100	9.6	24.4	280	28.50	72.4
110	10.75	27.3	290	29.50	74.9
120	11.85	30.1	300	30.50	77.4
130	12.90	32.8			

plotted from the data given in the table and shows graphically the relation between sparking distance and voltage. The voltage corresponding to a given sparking distance varies greatly with the sharpness of the needle-points, and with the shape of the electromotive force wave.

Sometimes the value of the voltage applied to the apparatus is not measured by the spark gauge, but is inferred from the reading of a low-reading voltmeter connected between the points *A* and *B* in Fig. 187. Thus, if there are 100 times as many turns of wire in the secondary (high-voltage) coil of the testing transformer as in the primary coil, then the readings of the voltmeter connected as specified must be multiplied by 100. The best practice is to connect an electrostatic voltmeter in parallel with the spark gap and to check its readings against the sparking distances in accordance with Table VI. It should be noted, however, that the voltmeter gives effective values while the spark gap gives maximum values of the voltage.

Characteristic Curves. Saturation Curve. The saturation curve of a generator shows the relation between the volts generated in the armature and the amperes of field current (or ampere-turns of the field) for a constant armature current. The armature current may be zero, in which case the curve is called the *no-load saturation curve*, or sometimes the *open-circuit characteristic curve*. Observations for a saturation curve may be taken with full-load current in the armature; but this is rarely done, except in alternators of comparatively small output. If a full-load saturation curve is desired, it can be approximately calculated from the no-load saturation curve and the curve for synchronous impedance, as will be explained later.




Fig. 189. Diagram of Connections for Saturation Curve Test of Alternator

The diagram of connections for determining the no-load saturation curve is shown in Fig. 189. The alternator is represented as a three-phase machine of the revolving-field type (armature is stationary). The field winding is connected through slip-rings d and e , and brushes f and g , to an ammeter A , and through an adjustable resistance r , to the exciter or other direct-current source. A voltmeter V_1 is connected across the field-winding terminals to measure the voltage applied to the field winding. The voltmeter V_2 , for measuring the voltage generated by the machine, is connected directly to two of the armature terminals, a and c , in the case of a low-voltage machine. If the voltage generated is greater than the capacity of the voltmeter, a multiplying coil or a

step-down potential transformer may be used to reduce the electromotive force to be measured. For very high voltages a potential transformer must be used.

A series of observations of the electromotive force between the terminals of one of the phases, such as *a* and *c*, is made for




Fig. 190. Saturation Curve for 2000-Kw. Alternator

different values of the field current. Eight or nine points along the curve are usually sufficient, the series extending from zero electromotive force to about fifty per cent above normal rated voltage. The points should be taken more closely together in the vicinity of normal voltage than at other portions of the curve. Care must be taken that the generator is run at its rated speed, and this speed must be kept constant. Deviations from constant speed may be most easily detected by the use of a tachometer.

If the machine is two-phase or three-phase, the voltmeter may be connected to any one phase throughout a complete series of observations. The voltage of all the phases should be observed for normal full-load excitation by connecting the voltmeter to each phase successively, keeping the field current constant at normal voltage. This is done in order to see how closely the voltage of the different phases agree.

The observations required for the determination of the saturation curve are volts at armature terminals, V_2 ; amperes in field, A ; volts at field terminals, V_1 ; and speed.

Fig. 190 shows a saturation curve taken from a 2,000-kilowatt three-phase alternator of the revolving-field type, having 16 poles, and generating 2,000 volts and 576 amperes per phase, when run at 300 revolutions per minute.




Fig. 191. Set of Curves for Two-Phase 135-Kw. Inductor Alternator

Fig. 191 gives a number of curves for a two-phase 135-kilowatt 2,400-volt 60-cycle inductor alternator. In particular, the no-load saturation curve is shown giving the relation of the field current to the voltage between armature terminals of one phase. This curve shows that nearly 7 amperes of field current is required to give rated voltage, namely 2,400, at no load. The field current required to give rated voltage at full non-inductive load is 8.8 am-

peres, as is explained on page 202. From the saturation curve it is evident that this full-load field current will produce about 2,625 volts at no load.

*Synchronous Impedance Curve.** The synchronous impedance curve shows the relation between armature voltage and armature current, the armature being short-circuited so that the only condition that limits the




Fig. 192. Curve Showing Synchronous Impedance Drop for 2,000-Kw. Alternator

current for a given voltage generated is the synchronous impedance of the armature. This is materially different from the impedance of the armature when the machine is standing still.

The connections for this test are similar to those for the saturation curve, except that the voltmeter (or potential transformer) connected to the armature is replaced by an ammeter. If the current is beyond the capacity of the ammeters at hand, a current transformer may be connected in

place of the ammeter, and the ammeter may be connected to its secondary.

A series of observations is to be taken of the current in the armature, with the latter short-circuited through the ammeter, for different field currents, commencing at a very low value, and increasing the field current by successive steps until the armature current has reached a value of 100 per cent above its rated full-load value. The last few readings must be made quickly to pre-

*See page 108.

vent undue heating of the armature. The armature winding should be at approximately normal temperature when the test is made. The speed should be kept approximately at the rated speed of the machine. It is not as essential to keep the speed constantly at rated value as when observations are being made for the determination of the saturation curve. The observations to be recorded are: *amperes in the armature; amperes in field; volts at field terminals; and speed.*

Fig. 192 shows a curve giving the relation between electromotive force induced in the armature and the current in the armature when short-circuited through an ammeter. This figure relates to the same 2,000-kilowatt alternator whose saturation curve was given in Fig. 190. The electromotive forces plotted in this figure are not observed values, but the field excitations required to produce them are observed, and the electromotive forces corresponding to these field excitations are taken from the saturation curve.

The total electromotive force induced in the armature for a given value of the field current may be read off from the no-load saturation curve of the machine, obtained as previously described. A curve may then be plotted with the electromotive force induced in the armature as ordinates, and the observed armature currents (on short-circuit) as abscissas. This curve is sometimes called the *synchronous impedance curve*, although it does not explicitly show the values of the synchronous impedance of the armature. The synchronous impedance of the armature for a given value of armature current may, however, be derived from this curve by dividing the total electromotive force induced in the armature (ordinate) by the corresponding value of the short-circuited armature current (abscissa). For example, the synchronous impedance corresponding to 576 amperes (which is the full-load current per phase of the machine) is

$$\frac{1,145 \text{ volts}}{576 \text{ amperes}} = 1.99 \text{ ohms}$$

Synchronous impedance is used as a basis for the predetermination of the regulation of the machine, thereby avoiding the trouble and expense of an actual test of regulation under full load. The synchronous impedance of an alternator armature is very nearly equal to the synchronous reactance of the armature, inas-

much as the armature resistance is usually small. Moreover the electromotive force required to overcome synchronous reactance is very nearly equal to the electromotive force required to overcome synchronous impedance.

Determination of Resistance of Armature. In the case of a three-phase armature, the resistance per phase cannot be measured




Fig. 193. Diagram for Armature when Y-connected

directly between collector rings, since there are two phases in series between collector rings in a Y-connected armature; while in case of a Δ -connected armature, two phases in series are in parallel with the third phase between any two collector rings.

The resistance per phase can be measured either directly by Wheatstone bridge and galvanometer, or by the "fall of potential" method. In the case of a Y-connected armature, the resistance per phase is one-half the resistance between terminals, provided that the resistance of all the phases are *alike*. In case the resistances of the phases are *unequal*, the resistance of any phase may be deduced as follows:

The resistance between terminals *A* and *B*, Fig. 193, is

$$R_{AB} = a + b \quad (i)$$

The resistance between terminals *B* and *C* is

$$R_{BC} = b + c \quad (ii)$$

The resistance between terminals *C* and *A* is

$$R_{CA} = c + a \quad (iii)$$

Then

$$a = R_{AB} - b \quad (iv)$$

$$b = R_{BC} - c \quad (v)$$

$$c = R_{CA} - a \quad (vi)$$

Substituting (vi) in (v) we obtain

$$b = R_{BC} - R_{CA} + a \quad (vii)$$

Substituting (vii) in (iv) we obtain

$$a = R_{AB} - R_{BC} + R_{CA} - a$$

from which

$$a = \frac{R_{AB} - R_{BC} + R_{CA}}{2}$$

Similarly we find

$$b = \frac{R_{BC} - R_{CA} + R_{AB}}{2}$$

and

$$c = \frac{R_{CA} - R_{AB} + R_{BC}}{2}$$

$$\text{If } R_{AB} = R_{BC} = R_{CA}, \text{ then } a = b = c = \frac{R_{AB}}{2}.$$

For a Δ -connected armature with *equal* resistances per phase, the resistance per phase equals $\frac{2}{3}$ times the resistance between terminals. The general expression for the resistance of any phase can be deduced as in the above case for Y connection. In this case there are two circuits between A and B , one through the phase a , and the other through phases b and c in series, as shown in Fig. 194. Remembering that the joint resistance of two (or more) circuits in parallel is the reciprocal of the sum of the reciprocals of the resistances of the several branches, we have




Fig. 194. Resistance Diagram for Δ -Connected Armature

$$R_{AB} = \frac{1}{\frac{1}{a} + \frac{1}{b+c}}$$

$$R_{BC} = \frac{1}{\frac{1}{b} + \frac{1}{c+a}}$$

$$R_{CA} = \frac{1}{\frac{1}{c} + \frac{1}{a+b}}$$

From these three equations the three unknown quantities a , b , and

c , may be found by algebraic elimination as in the case of the Y connection.

Regulation.* The saturation and synchronous impedance curves of an alternator together with the resistance per phase of the armature, are all the data required for the computation of the regulation of an alternator. The direct determination of regulation by observation would be as follows:

The alternator would be run at normal rated speed, delivering rated full-load current with rated full-load electromotive force at its terminals. The main circuit would then be opened, thus reducing the current output to zero. The excitation would be left unchanged, and the rise of terminal electromotive force would be observed. Then

$$\text{regulation in per cent} = \frac{\text{rise of terminal electromotive force}}{\text{rated full-load terminal electromotive force}} \times 100$$

This direct determination of regulation by observation is not feasible with large machines, on account of the large amount of power required. In all practical testing the regulation may be determined indirectly by calculation as follows:

When the alternator is operating at full load, the total electromotive force induced in the armature exceeds the terminal electromotive force by the amount lost in overcoming armature resistance, and by the amount lost in overcoming the synchronous reactance† of the armature.

Let E be the total induced electromotive force in the armature of an alternator, E_t the terminal electromotive force at full load, IR the electromotive force lost in overcoming armature resistance, and XI the electromotive force lost in overcoming the synchronous reactance of the armature. The electromotive force required to produce the current I through the short-circuited armature may be found from the "synchronous impedance curve" Fig. 192, by taking the ordinate corresponding to the value of I (abscissa). The electromotive force so found is nearly equal to XI on account of the relative smallness of armature resistance, and especially on account of the fact that IR and XI are at right angles to each other. In other words, the synchronous impedance is in most practical cases approximately equal to the synchronous reactance.

Therefore, the electromotive force found from the synchronous impedance curve may be taken as the value of XI .

Knowing the electromotive force lost in overcoming the synchronous reactance, we can find from the saturation curve the amount of field excitation (abscissa) required to produce this electromotive force (ordinate). This field excitation is represented by the line OB , Fig. 195. Take from the satura-

*See page 108.

†See page 108.

tion curve the field excitation corresponding to rated terminal voltage at full load, and represent it by the line OA , Fig. 195. Next find the geometric sum OC , of OA and OB . This OC represents the field excitation required at full load to produce rated terminal electromotive force. The electromotive force produced by this excitation at zero load may be taken from the saturation curve. The difference between the rated electromotive force of the alternator and the electromotive force so found, is the rise of electromotive force from full load to zero load; and this rise divided by the rated electromotive force and multiplied by 100 gives the regulation of the alternator in per cent.

The diagram, Fig. 195, applies to a non-inductive receiving circuit. When the receiving circuit is inductive, the angle BOA , Fig. 195, should be $90-\theta$, in which θ is the angle of lag of the current behind the electromotive force at the terminals of the alternator. The cosine of this angle is the power factor of the receiving circuit.

The above method for calculating regulation is much used in practice, and is recommended by the Committee on Standardization of the American Institute of Electrical Engineers; but the rule is ambiguous and open to criticism. Its application to general practice may be shown by the following:

The synchronous impedance and saturation curves shown in Figs. 190 and 192 are taken from tests upon a Δ -connected, three-phase, 2,000-kw., 16-pole, 2,000-volt, revolving-field alternator having a

speed of 300 r. p. m. The full-load armature current is 576 amperes per phase. The armature resistance per phase is 0.009239 ohms. Hence, the IR drop in the armature = $(576 \times 0.009239) = 5.3$ volts. $E_t = 2,000$; $E_t + IR = 2,000 + 5.3 = 2005.3$ volts.

From the saturation curve, Fig. 190, we find that it requires 83.5 amperes in the field winding to generate this 2,005.3 volts at no load. This represents the component OA in Fig. 195. From the synchronous impedance curve, Fig. 192, we find that 1,137 volts in the armature are required to force the full-load current of 576 amperes per phase through the armature. From the saturation curve, we find that 1,137 volts correspond to 43 amperes in the field winding. The component OB in Fig. 195 is, therefore, 43 amperes. The full-load field current OC is

$$OC = \sqrt{OA^2 + OB^2} = \sqrt{43^2 + 83.5^2} = 93.8 \text{ amperes}$$

This field current would produce at zero load an electromotive




Fig. 195. Vector Diagram for Field Excitation in a Non-Inductive Receiving Circuit

force of 2,169 volts, as shown by the saturation curve. Therefore, according to the definition of regulation, we have

$$\text{Regulation} = \frac{2,169 - 2,000}{2,000} \times 100 = \frac{169}{2,000} \times 100 = 8.45 \text{ per cent}$$

If the regulation had been desired at a power factor other than unity (for instance, at 85 per cent power factor), the field current OB , Fig. 195, would not be taken at right angles to OA to find the resultant field current OC at full load, but the angle BOA would be decreased by the angle whose cosine is 0.85, or by 31.75° . The resultant field current OC is represented as before, by the diagonal of the parallelogram; but it is no longer equal to the square root of the sum of the squares of OA and OB . The angle BOA , Fig. 194, now is 58.25° and, therefore,

$$OC^2 = OA^2 + OB^2 + 2 \overline{OA} \times \overline{OB} \cos 58.25^\circ$$

whence

$$OC = 112 \text{ amperes}$$

By referring to the saturation curve, we find that a full-load field current of 112 amperes would produce 2,375 volts at no load. Hence, the regulation at 85 per cent power factor is

$$\frac{2,375 - 2,000}{2,000} \times 100 = \frac{375}{2,000} \times 100 = 18.75 \text{ per cent}$$

This example illustrates the general fact already explained, that the electromotive force at the terminals of an alternator suffers a greater decrease in value on an inductive load (power factor less than unity) than on a non-inductive load (power factor unity) for the same current output.

Regulation Curve. Fig. 191 shows the regulation curves of a two-phase, 135-kilowatt, 2,400-volt, 60-cycle inductor alternator. The lower regulation curve shows the regulation of the alternator at 100 per cent power factor, that is, on non-inductive load; and the upper regulation curve shows the regulation of the alternator at 70 per cent power factor. The abscissa of a given point on one of these regulation curves represents a given current output per phase of the machine; and the ordinate of the point represents the voltage obtained at the armature terminals when this armature current

is reduced to zero, the field current being kept constant at that value which gives the rated voltage of 2,400 volts with the given current output per phase.

For example, with full-load current output, namely 28.1 amperes per phase and 100 per cent power factor, the voltage rises from 2,400 to 2,625 (the ordinate of the regulation curve for 100 per cent power factor corresponding to the abscissa representing 28.1 amperes of armature current) when the load is thrown off (armature current reduced to zero), the field current remaining unchanged. From these data the full load regulation of the machine on 100 per cent power factor is found to be

$$\frac{225}{2,400} \times 100 = 9.4 \text{ per cent}$$

With half-load current output, namely 14.05 amperes per phase, and 70 per cent power factor, [the voltage rises from 2,400 to 2,650 when the load is thrown off, the field current remaining unchanged. From these data the half-load regulation of the machine at 70 per cent power factor is found to be

$$\frac{250}{2,400} \times 100 = 10.4 \text{ per cent}$$

These curves show that the regulation of the machine is higher on inductive loads than on non-inductive loads.

American Institute Rules. The following are the recommendations of the American Institute of Electrical Engineers concerning the regulation of electrical apparatus and prime movers.

DEFINITIONS

- 187 **REGULATION.** The regulation of a machine or apparatus in regard to some characteristic quantity (such as terminal voltage, current, or speed) is the ratio of the deviation of that quantity from its normal value at rated load to the normal rated load value. The term "regulation," therefore, has the same meaning as the term "inherent regulation," occasionally used.
- 188 **CONSTANT STANDARD.** If the characteristic quantity is intended to remain constant (*e.g.*, constant voltage, constant speed, etc.) between rated load and no load, the regulation is the ratio of the maximum variation from the rated load value to the no-load value.
- 189 **VARYING STANDARD.** If the characteristic quantity is intended to vary in a definite manner between rated load and no load, the regulation is

- the ratio of the maximum variation from the specified condition to the normal rated-load value.
- 190 NOTE (a) If the law of the variation (in voltage, current, speed, etc.) between rated load and no load is not specified, it should be assumed to be a simple linear relation; *i. e.*, one undergoing uniform variation between rated load and no load.
- 191 NOTE (b) The regulation of an apparatus may, therefore, differ according to its qualification for use. Thus, the regulation of a compound-wound generator specified as a constant-potential generator, will be different from that which it possesses when specified as an over-compounded generator.
- 192 In CONSTANT-POTENTIAL MACHINES, the regulation is the ratio of the maximum difference of terminal voltage from the rated-load value (occurring within the range from rated load to open circuit) to the rated load terminal voltage.
- 193 In CONSTANT-CURRENT MACHINES, the regulation is the ratio of the maximum difference of current from the rated-load value (occurring within the range from rated-load to short-circuit, or minimum limit of operation), to the rated-load current.
- 194 In CONSTANT-POWER APPARATUS, the regulation is the ratio of maximum difference of power from the rated-load value (occurring within the range of operation specified) to the rated power.
- 195 In CONSTANT-SPEED DIRECT-CURRENT MOTORS and INDUCTION MOTORS, the regulation is the ratio of the maximum variation of speed from its rated load value (occurring within the range from rated load to no load) to the rated-load speed.
- 196 The regulation of an induction motor is, therefore, not identical with the slip of the motor, which is the ratio of the drop in speed from synchronism, to the synchronous speed.
- 197 In CONSTANT-POTENTIAL TRANSFORMERS, the regulation is the ratio of the rise of secondary terminal voltage from rated non-inductive load to no-load (at constant primary impressed terminal voltage) to the secondary terminal voltage at rated load.
- 198 In OVER-COMPOUNDED MACHINES, the regulation is the ratio of the maximum difference in voltage from a straight line connecting the no-load and rated-load values of terminal voltage as function of the load current, to the rated-load terminal voltage.
- 199 In CONVERTERS, DYNAMOTORS, MOTOR-GENERATORS and FREQUENCY CONVERTERS, the regulation is the ratio of the maximum difference of terminal voltage at the output side from the rated-load voltage, to the rated-load voltage on the output side.
- 200 In TRANSMISSION LINES, FEEDERS, ETC., the regulation is the ratio of the maximum voltage difference at the receiving end, between rated non-inductive load and no load to the rated-load voltage at the receiving end (with constant voltage impressed upon the sending end).
- 201 In STEAM ENGINES, the regulation is the ratio of the maximum variation of speed in passing slowly from rated-load to no-load (with constant steam pressure at the throttle) to the rated-load speed.

- 202 In a HYDRAULIC TURBINE or OTHER WATER-MOTOR, the regulation is the ratio of the maximum variation of speed in passing slowly from rated-load to no-load (at constant head of water; *i. e.*, at constant difference or level between tail race and head race), to the rated load speed.
- 203 In a GENERATOR-UNIT, consisting of a generator united with a prime-mover, the regulation should be determined at constant conditions of the prime-mover; *i. e.*, constant steam pressure, head, etc. It includes the inherent speed variations of the prime-mover. For this reason the regulation of a generator-unit is to be distinguished from the regulation of either the prime-mover, or of the generator contained in it, when taken separately.

CONDITIONS FOR AND TESTS OF REGULATION

- 204 SPEED. The *regulation of generators* is to be determined at constant speed, and of alternating apparatus at constant impressed frequency.
- 205 NON-INDUCTIVE LOAD. In apparatus generating, transforming, or transmitting alternating currents, regulation should be understood to refer to non-inductive load, that is, to a load in which the current is in phase with the e. m. f. at the output side of the apparatus, except where expressly specified otherwise.
- 206 WAVE FORM. In alternating apparatus receiving electric power, regulation should refer to a sine wave of e. m. f., except where expressly specified otherwise.
- 207 EXCITATION. In commutating machines, rectifying machines, and synchronous machines, such as direct-current generators and motors, alternating-current and polyphase generators, the regulation is to be determined under the following conditions:
- (1) At constant excitation in separately excited fields.
 - (2) With constant resistance in shunt-field circuits, and
 - (3) With constant resistance shunting series-field circuits; *i. e.*, the field adjustment should remain constant, and should be so chosen as to give the required full-load voltage at full-load current.
- 208 IMPEDANCE RATIO. In alternating-current apparatus, in addition to the non-inductive regulation, the impedance ratio of the apparatus should be specified; *i. e.*, the ratio of the voltage consumed by the total internal impedance of the apparatus at full-load current, to its rated full-load voltage. As far as possible, a sinusoidal current should be used.
- 209 COMPUTATION OF REGULATION. When in synchronous machines, the regulation is computed from the terminal voltage and impedance voltage, the exciting ampere-turns corresponding to terminal voltage plus armature-resistance-drop, and the ampere-turns at short-circuit corresponding to the armature-impedance-drop, should be combined vectorially to obtain the resultant ampere-turns, and the corresponding internal e. m. f. should be taken from the saturation curve.

Heat Test. The heat test is made by running the generator under full-load conditions until a constant temperature has been reached. When this condition has been attained the machine is

shut down, and the temperature of the various parts is taken by thermometers placed against the heated surfaces. The resistances of the armature and field windings are also measured while hot. By comparing these "hot" resistances with the same resistances previously measured at room temperature, the temperature rise of the armature and field coils can be computed. The method recommended by the Standardization Committee of the American Institute of Electrical Engineers for making these computations is as follows:

The fundamental relation between the increase of resistance in copper and the rise of temperature may be taken as

$$R_t = R_0 (1 + 0.0042t)$$

where R_0 is the resistance of the copper conductor at 0°C . and R_t is the corresponding resistance at $t^\circ\text{C}$. This is equivalent to taking a temperature coefficient of 0.42 per cent per degree C. temperature rise above 0°C . For initial temperatures other than 0°C ., a similar formula may be used substituting the proper coefficient corresponding to the actual initial temperature. The formula thus becomes at 25°C .

$$R_{i+r} = R_i \left(1 + \frac{0.3801r}{100} \right)$$

where R_i is the initial resistance at 25°C . R_{i+r} the final resistance, and r the temperature rise above 25°C .

In order to find the temperature rise in degrees centigrade from the initial resistance R_i at the initial temperature $i^\circ\text{C}$. and the final resistance R_{i+r} , we may use the formula

$$r = (238.1 + i) \left(\frac{R_{i+r}}{R_i} - 1 \right) \text{ degrees C.}$$

Example. The "cold" resistance of the armature of a generator is measured and found to be 0.046 ohm at a temperature of 20.5°C . After a heat run under full load the resistance is found to be 0.052 ohm. What is the rise in temperature?


In this case the initial temperature i is 20.5°C ., the final resistance R_{i+r} is 0.052 ohm, and the initial resistance R_i is 0.046 ohm. The temperature rise is, therefore,

$$r = (238.1 + 20.5) \left(\frac{0.052}{0.046} - 1 \right) = 33.72 \text{ centigrade degrees}$$

which means that the final temperature of the armature is

$$i + r = 20.5 + 33.72 = 54.22^\circ\text{C}$$

The temperatures of the following generator parts are usually recorded:



SOME OF THE GENERATORS IN THE WORLD'S LARGEST CENTRAL STATION

View taken in Fisk Street Station of the Commonwealth Electric Company, Chicago, Ill. The total capacity of the station is 176,000 kw. Of the four turbo-generators here shown, that furthest in the background has a capacity of 9,000 kw; the other three, 7,500 kw. each.

Armature coils	Field coils
Armature laminations	Pole tip (leading)
Armature ventilating ducts	Pole tip (trailing)
Frame	Field yoke
Bearings	Room

Small generators are usually run at full load, delivering their output to water rheostats. During the heat run, thermometers, placed on different parts of the machine, are read regularly. If the generator is of the revolving-armature type, a thermometer is placed against the field winding, and another thermometer is so placed that the hot air issuing from the ventilating ducts will come in contact with it. If the generator be of the revolving-field type, thermometers are placed against the armature coil, on the armature laminations, and in the ventilating ducts. When these thermometers do not show an increasing temperature, and the resistance of the field, as determined from the field ammeter and voltmeter, has become constant, the machine is considered as having attained its ultimate temperature, and is shut down for the application of thermometers, which should be ready for immediate application, as the machine cools rapidly. The time taken by a machine to reach constant temperature varies from 3 to 4 hours in the case of a small machine, and from 12 to 18 hours for very large ones.

The following maximum values of temperature elevation have been recommended by the Standardization Committee of the American Institute of Electrical Engineers:

- Field and armature, 50°C. by resistance
- Commutator and brushes, 55°C. by thermometer
- Collector rings, 65°C. by thermometer
- Bearings and other parts of machine, 40°C. by thermometer

The rise of temperature should be referred to the standard conditions of a room temperature of 25°C., a barometric pressure of 760 mm., and normal conditions of ventilation; that is, the apparatus under test should neither be exposed to draft nor enclosed, except where expressly specified.

If the room temperature during the test differs from 25°C., the observed rise of temperature should be corrected by $\frac{1}{2}$ per cent for each degree C. Thus, with a room temperature of 35°C., the observed rise of temperature has to be decreased by 5 per cent; and with a room temperature of 15°C., the observed rise of tem-

perature has to be increased by 5 per cent. The thermometer indicating the room temperature should be screened from thermal radiation emitted by heated bodies or from drafts of air. When it is impracticable to secure normal conditions of ventilation on account of an adjacent engine, or other sources of heat, the thermometer for measuring the air temperature should be placed so as to fairly indicate the temperature which the machine would have if it were idle, in order that the rise of temperature determined shall be that caused by the operation of the machine.

The temperature should be measured after a run of sufficient duration to reach practical constancy. This is usually from 6 to 18 hours, according to the size and construction of the apparatus. It is permissible, however, to shorten the time of the test by running a lesser time on an overload in current and voltage, then reducing the load to normal, and maintaining it thus until the temperature has become constant.

In making a heat test of a large alternator it is customary to imitate full-load conditions, electrically and magnetically, so as to produce all the heating effects that would occur under actual full load, but without taking any actual electrical power from the alternator. To be able to do this is of great advantage from two standpoints: *first*, that of convenience; and *second*, that of economy. To accomplish this desirable result, the generator is usually run on short-circuit with a number of the field spools connected in opposition to (or "bucked" against) the remainder; or, in other words, with the effective number of poles reduced.

To determine the proper number of field-magnet spools to be connected in opposition, we proceed in the following manner:

It was previously explained that from the saturation and synchronous impedance curves of a generator, we could determine the field current required to produce rated voltage at full load. In the case of the 2,000-kw. generator, of which the curves are given in Figs. 190 and 192, the normal full-load field current was found to be 93.8 amperes. This field current would, if the armature were short-circuited, produce, according to Fig. 192, an armature current of more than 1,050 amperes, which is greatly in excess of rated full-load current. If the field current were reduced to 43 amperes, the armature current would be normal; but the field current and,

therefore, the magnetic density in the field magnet and the armature core, and the consequent iron losses in the armature, would be very much below normal.

We may reduce the excessive current in the short-circuited armature to its normal full-load value by reducing the effective number of field poles in the ratio of 93.8 to 43 instead of by reducing the field current in this ratio. The alternator has 16 field poles, and to reduce this number in the ratio of 93.8 to 43, would give $\frac{16 \times 43}{93.8} = 7.34$ poles; but inasmuch as there must be an integral and even number of field poles, the closest approximation to the desired number is 8 effective poles. If, therefore, we reverse the connections of any four (adjacent) field coils, the four poles produced by these reversed field coils will be reversed in polarity; and the electromotive forces induced in the armature conductors under these reversed poles will be reversed, and will balance the electromotive forces induced in the armature conductors under four of the unreversed field poles, so that the electromotive forces induced in the armature conductors under the remaining eight poles only, will be effective in producing current in the armature, that is, only eight field poles will be effective.

If, under these conditions, we short-circuit the armature of the alternator, it will take approximately the full-load field current of 93.8 amperes to produce full-load current in the armature, and the heat test can then be made under full-load conditions, namely, full-load armature current, full-load field current, and full-load iron losses, while the machine is running on short-circuit and, therefore, delivering no power. Only the power represented by the losses occurring in the machine need be supplied to drive it. This is a method often used in practice. If the normal field current does not give normal armature current, after the spools are connected in opposition as described, the effect of a slight excess of armature current may be approximately balanced by a slight deficiency of field current, or *vice versâ*.

Core Loss and Friction Test. For this test the generator is driven by a motor at normal speed on open circuit. The power required to drive it, its field current being zero, is measured. The power so measured is the power lost in friction and windage. Then

the field current is increased, step by step, until the terminal electromotive force has increased to from 25 to 50 per cent above its normal rated full-load value; the terminal voltage is observed at each step, the armature being on open circuit (main switch open). The power required to drive the machine at each of these observed voltages is determined. This power is used to supply friction and windage loss and iron (or core) loss at the observed voltage.

The difference, therefore, between the power required to drive the machine at a given voltage on open circuit, and the amount of power required to drive the machine without field excitation, that is, to supply the friction and windage loss, represents the iron loss, or core loss, at the given voltage. Fig. 196 shows the no-load core-loss curve for the 2,000-kw. alternator of which the saturation curve and the synchronous impedance curve are given in Figs. 190 and 192, respectively.




Fig. 196. No-Load Core-Loss Curve for 2,000-Kw. Alternator

The most convenient way to measure the power delivered to the alternator is to drive it by a motor and measure the electrical input to the motor. If we determine the losses occurring in the motor the difference between the input to the motor and these losses is the power delivered to the alternator. Fig. 197 shows a diagram of

complete connections for the carrying out of the core loss test. A is the alternator under test. Its voltage is measured by the voltmeter V_1 connected to the secondary of the potential transformer T . Its field current, supplied by the exciter E , is measured by the ammeter A_1 and controlled by the resistance R_E in the field of the exciter. The power is supplied to the motor M by the direct-current generator G . The power is measured by the ammeter A_2 and the voltmeter V_2 . The motor M is separately excited, its field current being measured by the ammeter A_3 . This field current is kept constant by adjusting the rheostat R_F .

As the field current and the voltage of the generator under test are increased, the load on the driving motor M is increased also, since the hysteresis and eddy current loss in the generator, which must be supplied by the motor, are increased. As the load on the motor increases, it will slow down if its field current and the voltage between its brushes remain constant. However, the alternator to be tested must be run at constant speed, and its speed is controlled by varying the voltage at the motor terminals by means of the field rheostat R_G of the direct-current generator G . In the figure the field rheostat R_G of the generator G , is shown beside the alternator A . It is placed at this point for convenience, so that the observer stationed at the alternator may readily keep the speed under control.




Fig. 197. Diagram of Connections for Core-Loss Test of Alternators

The input to the motor armature in watts is equal to the product of the readings V_2 and A_2 . Part of this input is consumed in supplying the various losses in the motor armature, including friction and windage; and the remainder is converted into useful mechanical power, and is transmitted by the belt (not shown in Fig. 197) to the pulley of the alternator A , which is being tested. In other words, the watts input to A is equal to the input to the armature of M minus the various losses in the armature of M . The losses in the armature of M consist of hysteresis, eddy current,

friction, windage, and I^2R losses. Since the alternator is to be run at constant speed, the motor will also run at constant speed if there is no belt slip, which should be the case; and since the motor runs at constant speed and at a constant field excitation, all the losses in the motor armature will be constant in value, whatever its load, except the I^2R loss. This I^2R loss varies because the current I varies for different loads on the motor. If the speed of the motor were controlled by varying its field current, instead of varying the voltage applied at its terminals, the above-mentioned losses in the motor armature would not remain constant; hence the latter method is adopted.

If the motor be run free, *i. e.*, with belt off, the output of the motor will be zero and, therefore, the power input must be used up entirely in supplying the losses. Let E be the voltage at motor brushes, and I the current in the motor armature when it is running free (or unloaded), then $EI = \text{stray power} + I^2R$, where "stray power" equals the sum of all the constant losses in the motor armature, *i. e.*, hysteresis, eddy current, friction, and windage losses. Hence, stray power = $EI - I^2R$.

The mechanical or useful output of the motor at a given load, the voltage applied to its brushes being E_1 , and its armature current being I_1 , is

$$\text{output} = E_1I_1 - I_1^2R_1 - \text{stray power}$$

That is, the mechanical output is equal to the total electrical input minus the total losses.

The stray power can be determined once for all by running the motor free, or at no load, at the speed and with the field current used in the test when E and I were observed. Thus, we may determine the power required to drive A (the machine to be tested) with zero field excitation of A , in which case we obtain its friction and windage losses; and we may determine the power required to drive A at any given field excitation and voltage, in which case we obtain the sum of the friction, windage, and core (or iron) losses.

In carrying out these tests, therefore, the following order is found most convenient:

(1) The motor is made to drive the alternator with zero field current in the latter; and a number of observations are taken, as indicated in the tabular arrangement below. This is to determine the *friction* and *windage loss* of the alternator.

(2) The alternator is excited to produce a series of values of terminal voltage, for each of which a similar set of observations is taken; and so on, until the voltage of the alternator has been increased to about 25 per cent above normal rated voltage.

(3) The motor is now shut down and its belt thrown off, and it is then run unloaded in order to determine its own stray-power losses.

(4) Finally the motor is shut down, and the resistance of its armature is measured.

For each set of readings the following observations should be recorded:

Motors	{	Volts at brushes Amperes in armature Amperes in field Speed	Alternator	{	Volts at terminals Amperes in field Speed
--------	---	--	------------	---	---

The amperes in the field of the motor, and the speed of the motor and generator are recorded merely to show whether they have been kept constant during the test. For the best results the motor should have a rated capacity of from 15 to 20 per cent of the rated capacity of the machine to be tested.

Example. In a core-loss test of the 2,000-kw. alternator above referred to, the following observations were taken: With zero field excitation of the alternator, the voltage applied to the motor armature and the current in the motor armature were 510 volts and 48 amperes, respectively. When the alternator was excited to give 2,070 volts between its terminals, the volts applied to, and the current in, the motor armature were 511 volts and 117 amperes, respectively. With the motor running unloaded the voltage applied to, and the current in, the motor armature were 509 volts and 11.5 amperes, respectively. The resistance of the armature of the motor was 0.056 ohm. Find:

(a) The *stray-power loss* of the driving motor, from the readings taken above when the motor was running unloaded.

Solution. Motor input was 509 volts \times 11.5 amperes = 5,853 watts. But by definition, stray power = $EI - I^2R$. Hence

$$\text{stray power} = 5,853 - 0.056 \times (11.5)^2 = 5,846 \text{ watts}$$

(b) The *friction and windage loss* of the alternator.

Solution. Power supplied to motor when driving alternator at full speed with zero field excitation was 510 volts \times 48 amperes = 24,480 watts; and the useful output of the motor or the power used to drive the alternator was the power input to the motor minus stray-power loss and minus I^2R loss in its armature. Therefore

$$\text{friction and windage loss} = 24,480 - 5,846 - [(48)^2 \times 0.056] = 18,505 \text{ watts}$$

(c) The *core (or iron) loss* of the alternator.

Solution. Power supplied to motor when driving the alternator at full speed, field excited to give 2,070 volts between alternator terminals, was 511 volts \times 117 amperes = 59,787 watts. The useful output of the motor in this case was 59,787 watts - 5,846 watts - $[(117)^2 \times 0.056] = 53,175$ watts; and this is equal to the sum of friction and windage loss and iron loss. Therefore

$$\text{core loss of alternator} = 53,175 - 18,505 = 34,670 \text{ watts}$$

The core loss of the alternator was calculated for *each* value of the field excitation of the alternator in a manner similar to the above. These various core losses are plotted as ordinates of the curve in Fig. 196, the abscissas being the electromotive forces between alternator terminals corresponding to the various field excitations. This curve shows that at the rated full-load voltage, namely, 2,000 volts, the core loss of the alternator is 30.5 kilowatts or 1.525 per cent of the rated full-load output of the alternator.

Calculation of Efficiency. *2,000-Kw. Alternator.* Since the efficiency of an alternator is the ratio of the output to the output plus the losses, as explained on page 181, we may now calculate the efficiency of the alternator, having made all necessary tests. In the case of the 2,000-kw. alternator referred to above, for which the curves have been given, the following losses occur:

(1) *Friction and windage loss.* The loss was found under (b) in the example just given to be 18,505 watts.

(2) *I^2R loss in armature at full load.* The resistance of each phase of the armature winding of the given alternator was measured and found to be 0.00924 ohm, and the full-load rated current is 576 amperes per phase. Therefore, the I^2R loss per phase is

$$(576)^2 \times 0.00924 = 3,065 \text{ watts}$$

Hence, the total I^2R loss for all three phases is

$$3 \times 3,065 \text{ watts} = 9,195 \text{ watts}$$

(3) *I^2R loss in the field.* The resistance of the field winding of the given alternator is 0.966 ohm, and the full-load field current is 93.8 amperes. Hence, I^2R loss in the field is 8,500 watts.

(4) *Core loss.* The core loss on open circuit at full-load excitation was found to be 30,500 watts. This is somewhat less than the core loss would be with full-load excitation and with full-load armature current.

Therefore, the sum of all the losses is

Friction and windage loss	18,505
I^2R loss in armature	9,195
I^2R loss in the field	8,500
Core loss	30,500
Total loss	<u>66,700</u> watts

The rated full-load output being 2,000 kilowatts, we have

$$\text{efficiency at full load} = \frac{2,000,000}{2,000,000 + 66,700} = 96.8 \text{ per cent}$$

If the efficiency at any fractional part of full load is desired, it may be calculated as follows:

$$\frac{\frac{1}{2} \text{ rated full-load output}}{\frac{1}{2} \text{ rated full-load output} + \text{losses at half load}}$$

(1) Friction and windage loss is approximately the same at half load as at full load.

(2) I^2R loss in the armature is one-fourth as great as at full load since the armature current is half as great.

(3) I^2R loss in the field is slightly less at half load than at full load, inasmuch as field current is slightly less.

(4) Core loss at half load is slightly less than core loss at full load.

135-Kw. Inductor Alternator. Fig. 191 shows the efficiency curve of a two-phase, 135-kilowatt, 2,400-volt, 60-cycle inductor alternator. The ordinates of this efficiency curve represent the efficiencies of this alternator corresponding to different current outputs per phase, the latter being plotted as abscissas. The efficiencies shown by this curve apply to the machine when it delivers power to non-inductive receiving circuits (100 per cent power factor). When the power factor is less than 100 per cent, the efficiencies are less than the efficiencies shown by the curve.

At full-load current output of 28.1 amperes per phase and 100 per cent power factor, the efficiency as represented by the ordinate of the curve is 93 per cent. At half-load current output of 14.05 amperes per phase, the efficiency is 90½ per cent. At full load the several losses in this machine are as follows:

(1) *Friction and windage loss* (obtained by experiment), 2,000 watts.

(2) *I^2R loss in the armature* (calculated from hot resistance of armature 1.46 ohm per phase, and full-load armature current 28.1 amperes per phase) is

$$2 \times (28.1)^2 \times 1.46 = 2,305 \text{ watts}$$

(3) I^2R loss in the field (calculated from hot resistance of field coil 9.35 ohms, and full-load field current 8.8 amperes) is

$$9.35 \times (8.8)^2 = 724 \text{ watts}$$

(4) Core loss (determined by experiment using the method described on page 209), 5,000 watts.

The total loss is, therefore

Friction and windage loss	2,000 watts
I^2R loss in armature	2,305 watts
I^2R loss in field	724 watts
Core loss	5,000 watts
Total loss	<u>10,029 watts</u>

Therefore

$$\text{efficiency at full-load} = \frac{135,000}{135,000 + 10,029} = 93 \text{ per cent}$$

SYNCHRONOUS MOTORS

Motors designed to be operated with alternating currents may be divided into two classes: synchronous motors and induction motors. Both kinds are in common use; and although there are a few other motors which do not come under the above classification, yet by far the larger part of all the motors run with alternating currents belongs to one or the other of these classes. The induction motor, pages 371-420, having properties which adapt it to a much wider field of application than is possible with the synchronous motor, is much the more commonly used.

Any Alternator a Synchronous Motor. When a given armature conductor of an alternating-current generator is under a north pole of the field magnet, the current in the conductor is in a direction such that the force which the field exerts on the wire opposes the motion of the armature. When the given conductor has moved sufficiently to be under a south pole of the field magnet, the current will have reversed in direction, and the force which the field exerts on the wire will still oppose the motion of the armature. The work done in driving the armature against these opposing electromagnetic forces is the work that goes to maintain the alternating current delivered by the alternator.

Consider an alternator driven by a small engine or auxiliary motor. Let an alternating current from an outside source be forced through the revolving armature of the alternator, the field magnet of which is supplied with a direct current from an exciter. Then the motion of the revolving armature will be helped by the alternating current if the following conditions are satisfied:

(a) If the speed of the armature is such that a given armature conductor moves from the middle of a north pole to the middle of a south pole during the time of one alternation (half a cycle) of the supplied alternating current.

(b) If the direction of the supplied alternating current, when the given conductor is under a north pole, is such that the force exerted upon the conductor by the field helps the motion of the armature.

This is evident when we consider that the current reverses every time the given conductor passes from one field pole to the next, and that this reversed current will be acted upon by the reversed polarity of the next pole with a force always in the direction of the motion.

When the alternator speed has been carefully adjusted so that the conditions (a) and (b) are satisfied, the driving engine or auxiliary motor may be disconnected; the armature of the alternator will continue to revolve at constant speed (the frequency of the supplied alternating current being constant), and the revolving armature may deliver power by belt to drive machinery. An alternator used in this way is called a *synchronous motor*.

Any alternator may be used as a synchronous motor without alteration of any kind. Electrically and mechanically, the synchronous motor is the same as the alternating-current generator. In fact the same machine is often used indifferently as motor or generator according to circumstances. Composite field winding is never provided on an alternator which is to be used as a synchronous motor.

Synchronous motors may be designed to operate either on single-phase or polyphase systems, and are called synchronous because they always run in synchronism with, *i. e.*, at the same frequency as, the alternator supplying the current to them. The speed of the motor cannot change unless the speed of the generator changes; but it is not necessarily the same speed as that of the gen-

erator. The speed of the motor will be the same as the speed of the generator only when the motor happens to have the same number of poles as the generator. The speed at which a synchronous motor will run when connected to an alternator supplying current at a frequency f , is

$$s = \frac{2 \times f \times 60}{p}$$

where s is speed of the motor in revolutions per minute; f is frequency of the alternating-current supply; and p is number of poles on the motor field. For example, if a 10-pole motor were run from a 60-cycle alternator, the speed of the motor would be

$$\frac{2 \times 60 \times 60}{10} = 720 \text{ r. p. m.}$$

Moreover, it follows that if the motor had the same number of poles as the alternator, the speed of the motor would be just the same as the speed of the alternator, and any variation in the speed of the latter would cause a corresponding change in the speed of the motor; or if the motor had half as many poles as the generator, its speed would be double that of the latter, and any change in the speed of the generator would cause a proportional change in that of the motor; in other words, the cyclic speeds must be the same.

Advantages. The synchronous motor, especially in units of large output, possesses a number of features which make its use at times preferable to that of the induction motor. Its advantages may be briefly summed up as follows:

- (a) Unvarying speed at all loads.
- (b) Power factor, variable at will by change of the exciting current, can be made approximately unity at any load.
- (c) The current in the armature can be made to lead the electromotive force by over-exciting the field magnets, thus producing the same effect as a large condenser. The leading current in the armature can be used to neutralize the unfavorable effects of inductance (which causes lagging currents) in other parts of the system.
- (d) The synchronous motor is cheaper to build, especially at low speeds, than the induction motor.
- (e) Its efficiency is generally higher than that of the induction motor.
- (f) It is specially adapted to high-voltage winding.

Disadvantages. The synchronous motor, on the other hand, has several disadvantages, as follows:

- (a) It is not adapted to work requiring variable speed, as no independent speed regulation is possible.
- (b) It has small starting torque; hence it is not suitable for work requiring large starting torque, or frequent starting of the load.
- (c) It has a tendency to "hunt."
- (d) It requires an exciting current which must be supplied by an outside source.
- (e) It requires the most skilful and intelligent attention.

Synchronous motors are used where power is required in large amounts, and where the motor does not have to be started and stopped frequently.

Comparison of Synchronous and D. C. Motors. Synchronous motors behave differently from direct-current motors. Thus, if the field of a direct-current motor be weakened, the motor will speed up in order to keep the counter-electromotive force at a proper value. But if the field strength of a synchronous motor be changed, the speed cannot change, because the motor must run in synchronism with the alternator that supplies it with current. What then does enable a synchronous motor to adjust itself to changes of load and field strength? It is the change of phase difference between the armature current and the applied electromotive force.

Suppose a synchronous motor is running light, *i. e.*, unloaded, and suppose further that there is no friction, hysteresis, or eddy-current losses; then, if this motor be run up to synchronism, and its field adjusted to such a strength that the counter-electromotive force of the motor is equal and opposite to that of the generator, no current will flow through the circuit when the circuit is closed. At any instant the electromotive force that causes current to flow in the circuit is the difference between the instantaneous electromotive force of the alternator and the counter-electromotive force of the motor. On loading the motor, its armature will lag a small fraction of a revolution behind that of the alternator, so that the counter-electromotive force of the motor will no longer be in opposition to that of the alternator. The result is that there will be a current of a magnitude such as to produce the torque necessary to enable the motor to carry its load. The greater the load on the motor, the greater the lag of its armature, and hence the greater

the difference in phase between the applied and the counter-electromotive forces; this, in turn, permits a larger current to flow to supply the additional torque required. If, however, too great a load is put on the motor, the slipping behind of the armature will become sufficiently great to throw the motor out of synchronism, or to cause the motor to "break down," when it will stop. In other words, the motor, under these conditions, cannot exert sufficient torque to handle the load.

Starting the Motor. *Single-Phase Circuit.* If a single-phase alternator be electrically connected to alternating-current supply mains, the machine will not start up and run as a motor, because the current in its armature is rapidly reversing, thus tending to turn the armature first in one direction and then in the other direction in rapid succession. Such a synchronous motor, therefore, whether loaded or unloaded, must always be started and brought up to full speed by an engine or other outside source of power, since it develops no starting torque whatever when thrown in circuit at a standstill.

Polyphase Circuit. If a polyphase alternator, on the other hand, is connected to polyphase supply mains, the machine will start and run up to full speed if it has little or no belt load. This self-starting property of the polyphase synchronous motor is explained as follows:

As one of the polyphase currents through the armature of the machine dies away, it leaves a slight amount of residual magnetism in the field-magnet structure if the field magnet is not excited by direct current. This residual magnetism acts upon the growing current of the other phase (or phases), and produces a torque tending to turn the armature. This action of the polyphase alternator is essentially the same as the action of the induction motor.

A polyphase alternator which is to be used as a synchronous motor develops but little starting effort when connected directly to the supply mains, hence it is generally started, especially in larger sizes, by means of a small engine or auxiliary motor, and then thrown into circuit, after which its load is connected to it through a friction clutch, thus allowing it to be thrown on gradually. In smaller sizes the machine is generally self-starting without load, the load being thrown on afterwards.

Exciter. The exciter of a synchronous motor (a small direct-current dynamo) is usually belted to, or mounted upon, the synchro-

nous motor shaft, so that when the synchronous motor has been brought up to full speed either by separate starting or by self-starting, the exciter is in full operation and is in readiness to supply current for exciting the field magnet of the synchronous motor.

Separate Starting. In the case of the single-phase machine, the power for starting is always derived from a source entirely independent of the single-phase supply. In the case of the polyphase machine, the power for starting is usually developed by a small induction motor supplied with polyphase currents from the mains that supply currents to the synchronous motor itself. In other words, the method of separate starting is essentially the same for both single-phase and polyphase machines, the procedure being exactly the same as for starting and adjusting an alternator that is to be connected in parallel with another alternator already in operation.

Self-Starting of the Polyphase Type. In the self-starting of the polyphase synchronous motor, its armature terminals may be connected directly to the polyphase supply mains with its field unexcited. When the machine reaches synchronous speed (driving its exciter), the field is connected to the exciter. The machine is then in full operation as a synchronous motor, and its load may be gradually thrown on.

The objection to this mode of starting is that the machine takes excessively large lagging currents at starting; and this generally causes a drop in the supply voltage great enough to disturb seriously the general system of distributing mains from which the synchronous motor receives its currents. This excessive demand for current at starting is objectionable when the motor takes a large proportion of the generator output, or is used in connection with a lighting service, especially when the motor is started and stopped at frequent intervals.

To avoid an excessive demand for current at starting, an *auto-starter* or *compensator* is frequently employed. The starting compensator for a two-phase synchronous motor consists of two transformers (three transformers for a three-phase machine) having their primaries connected across the respective phases of the supply mains, their secondaries being provided with a number of taps so that, at starting, a fraction of the full supply voltage can be applied

to the armature terminals of the synchronous motor. This fraction is usually from 40 to 60 per cent of the full voltage; and a switching device is provided by means of which the change from fractional to full voltage can be quickly made when the synchronous motor reaches full speed. This starting compensator is also used in connection with induction motors. The transformers used in the starting compensator are always autotransformers.


The self-starting of a polyphase synchronous motor (by induction-motor action) depends upon the magnetizing action on the unexcited field magnet poles by the armature currents. Therefore, a polyphase alternator having high armature reaction, that is, large magnetizing action on the field for a given armature current, as in the case of an armature with concentrated windings or a machine with small air gaps, will give a large starting torque when used as a self-starting synchronous motor. The revolving field-structures of self-starting synchronous motors are usually provided with squirrel-cage windings to increase the starting torque when used with starting compensators, and to reduce the tendency to hunt.


Usually less than one minute is required to bring even large synchronous motors to full speed by either method of starting.

At the time of starting, the armature and field windings of a synchronous motor are related to each other as are the primary and the secondary of an alternating-current transformer. The result is, that when the field coils have many turns of wire, a dangerously high electromotive force may be induced in them.

This production of high voltages in the field coils of a self-started polyphase synchronous motor may be, to a great extent avoided, by using few turns of large wire in the field winding, thus necessitating the use of a low-voltage exciter. For this reason exciters giving an electromotive force as low as 50 volts are frequently used. Another method of obviating the danger referred to, is to provide short-circuited metal rings around the field poles. These rings limit the changes of magnetism in the pole-pieces, and thereby prevent the formation of excessively high induced voltages in the field coils.

In synchronous motors of the stationary field type, the field circuit may be broken up into many separate parts so as to divide up the induced electromotive force. Thus, Fig. 198 shows the





MOTOR GENERATOR SET.

1,200 H.P. Induction Motor, Direct-Connected to 400 K.W. D.C. Generator.
General Electric Co.

stationary field of an alternator (synchronous motor) with the terminals of each field spool brought out to convenient switches on the frame of the machine. During starting these switches are open, and when the machine has reached synchronous speed, they are all closed, thus connecting all the field spools in series to the exciter.

Hunting Action. When the load on a synchronous motor is suddenly increased, the motor slows down momentarily and falls behind the generator in phase. When the motor has fallen behind sufficiently to take in power enough to enable it to carry its load, it is still running slightly below synchronism; it, therefore, falls still further behind, and takes an excess of power from the generator,




Fig. 198. Diagrammatic View of Stationary Field of a Synchronous Motor

which quickly speeds it above synchronism. It then gains on the generator in phase until it is taking in less power than is required for its load, when it again slows down, and so on. This oscillation of speed above and below synchronism, called *hunting*, is accompanied by great changes in the current supplied to the synchronous motor, and by rapid rise and fall of the electromotive force between the terminals of the motor. It is frequently a source of great annoyance, especially where several synchronous motors, or rotary converters, are run in parallel from the same mains.

Hunting is frequently produced by the periodic changes in the speed of the engine that drives the generator. Thus the engine momentarily increases its speed as the steam acts upon the piston

at each stroke, and diminishes its speed in the intervals between the strokes.

The hunting of a synchronous motor is a phenomenon of the same nature as the hunting of a steam engine having an over-sensitive governor. When the load on the engine is suddenly increased, the engine slows down momentarily, causing the governor to admit more steam than is needed for the increased load. The result is that the engine quickly speeds up, causing the over-sensitive governor to shut off too much steam, so that the engine slows down again, and so on. Hunting is associated with more or less violent shifting of the resultant magnetic flux in the air gap under the poles. This

is due to the fluctuations in the armature current, caused by the flow of the "corrective" current between generator and alternator while hunting occurs.

Reduction by Use of Dampers. Hunting is greatly reduced or entirely eliminated by the use of heavy copper frames or dampers in the neighborhood of the poles. One form of damper is shown in Fig. 199, which




Fig. 199. Portion of Revolving Field Showing Copper Frame Dampers

is a view of a portion of the revolving field of an alternator. The dampers consist of rectangular copper frames driven into place under the overhanging tips of two adjacent poles. A damper is provided between each pair of adjacent poles, all around the field, both in the alternator and in the synchronous motor.

Another form of damper which has been found very effective is called the "squirrel-cage" damper. Heavy bars of copper are placed in slots at the surface of the poles and their ends bolted to two closed copper rings, so as to short-circuit all the bars. This cage-damper applied to a rotor for use as a synchronous motor is illustrated in Fig. 200, which relates to a 200-kilowatt "type E" machine of the Westinghouse Company.

The principle of the damping action is that the shifting magnetic

field sets up induced currents in the short-circuited frames or bars of the damper, and these currents react on the magnetic field so as to oppose the shifting of the flux and thereby dampen the hunting oscillations. The electrical effect of the dampers is analogous to the mechanical effect produced by immersing the bob of a swinging pendulum in a heavy oil which resists the motion of the bob.




Fig. 200. Rotor of a Synchronous Motor Provided with "Squirrel-Cage" Form of Damper

Torque and Power Output. A given synchronous motor operating with given applied voltage is capable of developing a definite maximum torque, or of delivering a definite maximum amount of power. An attempt to take more than this maximum power from the machine, causes the machine to fall out of step, that is, out of proper phase relation, with respect to the supply voltage; and the motor accordingly stops. A properly designed synchronous motor will, however, carry a reasonable overload before reaching the above-mentioned maximum at which the machine stops.

The maximum power that can be delivered by a synchronous motor is greatly increased by increase of the applied voltage, and greatly decreased by a decrease of the applied voltage. In fact the maximum power output is proportional to the square of the applied voltage; therefore, the voltage of supply should never be allowed to fall much below the normal or rated value.

Field Excitation and Power Factor. While the power factor of a non-synchronous (induction) alternating-current motor is fixed by its design, and its current is always lagging behind the applied electromotive force, the current delivered to a synchronous motor may be made either lagging or leading at will. This remarkable control of the phase of the current is accomplished by varying the




Fig. 201. Curve Showing Variation of Armature Current with Field Excitation

strength of the field excitation.

An increase in the field excitation of a synchronous motor will cause a corresponding increase in the counter-electromotive force generated in the motor armature. By properly adjusting the field excitation, this counter-electromotive force of the motor can be made considerably greater

than the electromotive force applied at the motor terminals. The result is that an increased but leading current, that is, one ahead of the applied voltage, as in a condenser, flows in the armature. On the other hand, a field excitation below the normal amount produces an increased but lagging current, that is, one behind the applied voltage, as in an inductance coil. If the field excitation is normal, that is, of such a value that the current in the motor armature is exactly opposed in phase to the counter-electromotive force (unity power factor), then the effective value of this current will be a minimum; and hence the efficiency of the motor, generator, and transmission lines will be a maximum because the I^2R losses will be minimum.

Considered simply as a motor, without reference to the trans-

mission system as a whole, the most efficient point of operation is with unity power factor, or, in other words, with a field excitation which will make the armature current a minimum.

The effect upon the armature current, produced by varying the field excitation, is shown by the curves in Fig. 201. Up to a certain point, as the excitation is increased, the armature current is lagging, and decreases to a minimum value. Further increase of the exciting current causes the armature to take more current, which is now ahead of the applied electromotive force in phase, that is, is now leading. There is one value of the exciting current for which the armature current is a minimum. In motors of good regulation this value of the exciting current varies but slightly with different loads.

Use as a Condenser. A synchronous motor with its field magnet over-excited takes a current which is ahead of the applied electromotive force in phase. Such a machine may, therefore, be connected




Fig. 202. Diagram Showing Synchronous Motor Used as a Condenser

across the terminals of an inductive receiving circuit, as shown in Fig. 202, so as to compensate for lagging current delivered to the receiving circuit, thus reducing the line current to the lowest value that will suffice to transmit the power taken by the receiving circuit. The clock diagram, Fig. 203, shows how the leading current I_2 taken by the synchronous motor M , Fig. 202, gives, when combined with the current I_1 delivered to the receiving circuit, a resultant line current I , which is in phase with the electromotive force E between the mains.

A synchronous motor used primarily for compensating the lagging current delivered to an inductive receiving circuit is called a *rotary condenser* or a *synchronous compensator*. The rotary condenser is especially useful when induction motors or lightly loaded

transformers or both, are supplied over a long transmission line. In such cases the reduction of the line current to the smallest possible value effects considerable saving in the matter of power losses in the transmission line. The use of a rotary condenser is also an advantage in that the regulation of voltage at the receiving end of the transmission line is improved.

A given synchronous motor is most effective as a rotary condenser when it is not required to deliver any mechanical power as a motor, that is, when it is run at zero load. When a synchronous motor is to be used to deliver mechanical power, as well as to take a leading current for the purpose of compensating the lagging current taken by the inductive receiving circuit, it is customary to limit the load on the motor to 70.7 per cent of its full-load rating, that is, its rating if it were to be used as a motor only, and not as a rotary condenser. When the motor takes in its full-load rated current, but only 70.7 per cent of its full-load rated power, its field being




Fig. 203. Clock Diagram of Current Relations in Synchronous Motor

over-excited, then its current is 45 degrees ahead of the e. m. f.; the power factor of the motor is 70.7 per cent; the power component of the current, that is, the component which is in phase with the supply electromotive force, is 70.7 per cent of the full current; and the wattless component of the current (the component which is 90 degrees ahead of the supply electromotive force in phase) is also 70.7 per cent of the full-load current.

For example, a synchronous motor rated at 100 kilowatts at 1,000 volts would have a full-load rated current of 100 amperes, the field of the machine being excited to give unity power factor. If this machine is to be operated as a rotary condenser, its field excitation will have to be increased. If the machine is to carry a load of 70.7 kilowatts, and at the same time to take as large a leading wattless current as possible (without, however, exceeding the full-load rated current of 100 amperes), then the field will have to be over-excited to such an extent as to cause the machine to take its full rated current of 100 amperes at 70.7 kilowatts load. In this

case the power component of the 100-ampere current will be 70.7 amperes; the wattless component of the 100-ampere current will be 70.7 amperes $\left[100 = \sqrt{(70.7)^2 + (70.7)^2}\right]$; and the power factor of the over-excited motor will be 70.7 per cent.

MOTOR TESTING

The difference between a synchronous motor and an alternating-current generator consists mainly in the method of operating; any alternator will run as a synchronous motor, and *vice versa*. Therefore, all the tests described on pages 188-216, with reference to alternators, may be applied in a similar manner to synchronous motors.

In making a heat test on a small synchronous motor, it is usually run at full load as a motor.

In the case of large synchronous motors, the "heat-run" or test is usually made by running the machine as a generator on short-circuit, with a portion of its field coils connected in opposition, as described on page 205 on the heat test of alternators.

The efficiency of a synchronous motor is calculated in the same manner as that of an alternator, page 214.

Phase Characteristic. Regulation for alternators, as described on page 200, is not calculated in the case of a synchronous motor; but the determination of the "phase characteristic" of a synchronous motor corresponds to, and is substituted for, the regulation test. A "phase characteristic" is a curve showing the relation between the armature current and the field current of a synchronous motor, the test being carried out under constant conditions with respect to voltage, frequency, and load. Phase characteristics are shown in Fig. 201.

Phase characteristics are usually taken at no load, although it not infrequently happens that it is desired to obtain a phase characteristic at full load. To make the test at no load, it is simply necessary to run the motor unloaded, supplying alternating currents of the proper voltage and frequency to the armature terminals of the motor. The field current is then varied by successive steps, both above and below its normal value, until the armature current has attained rated full-load value, both for leading and for lagging current. For each value of the field current, simultaneous observations are made of the amperes in the armature, the volts supplied

to the armature terminals, the amperes in the field, and the speed. The normal field current is that value for which the armature current has the lowest value.

If a phase characteristic at full load is desired, the most convenient way of loading the motor is to cause it to drive a direct-current generator of known efficiency, by means of a belt connecting their respective pulleys. The power output of the direct-current generator can be accurately measured by means of an ammeter and a voltmeter. Knowing the output, and the efficiency of the direct-current generator at any output, the mechanical *input*, to the generator, that is, $\frac{\text{output}}{\text{efficiency}}$, can be calculated. This input to the generator is evidently equal to the mechanical output of the synchronous motor, the power lost in the belting being negligible.

The load on the motor must be kept constant throughout the test. The armature current for a full-load phase characteristic cannot be varied through such a wide range of values as at no load, owing to the inability of the armature windings of the motor to carry the excessive current without over-heating.

Pulsation Test. This test is to determine whether or not the synchronous motor has a decided tendency to hunt. For this test the synchronous motor is supplied with alternating current or currents from a very steadily driven alternator over an "artificial transmission line." This "artificial line" consists simply of a resistance equal to the resistance* of the transmission line over which the synchronous motor is to be supplied with current when finally installed.

The synchronous motor is driven at zero load, taking current through the artificial line, the tendency to hunt being greatest at zero load. The connections are the same as in the test for phase characteristic. The hunting action is indicated by the swinging to and fro of the pointers of the ammeters and voltmeters. The field current of the motor is varied from considerably below to considerably above rated full-load field current. For each value of the field current, the indications of the instruments are carefully observed; the pulsations of the instruments are noted.

*Usually the transmission line has a resistance such as to give a 10 per cent drop of electromotive force when full-load current is delivered to the motor.

NOTE. During this test, care must be taken that the alternator supplying the power to drive the motor under test, does not pulsate, for, if it does, the pulsations of the instrument pointers would not then give a reliable indication of the performance of the motor itself under normal working conditions.

Break-Down Test. As its name implies, this test is to determine the maximum power that a synchronous motor will deliver at its pulley, before falling out of synchronism and stopping. As in the case of the full-load phase characteristic, the power output of the motor is most conveniently absorbed and measured by belting the motor to a direct-current generator, and measuring the electrical output of this generator. For further description and details of the break-down test, the reader is referred to the article on the break-down test for induction motors.

Self-Starting Test. The object of a starting test on a synchronous motor is to determine:

- (a) The voltage and current required to start the motor.
- (b) The time required for the motor to reach synchronous speed (synchronism).
- (c) The electromotive force induced in the field-magnet windings at the instant of starting.

The starting test is made on polyphase motors only, for, as previously stated, single-phase synchronous motors are not inherently self-starting, but must, even in the smaller sizes, be provided with special starting devices.

The synchronous motor to be tested is connected to mains supplying alternating currents of the proper frequency. Arrangement is made to adjust the voltage applied to the armature terminals of the motor by means of potential (voltage) regulators connected in the armature circuits between the supply mains and the armature terminals. An ammeter is connected in series with each phase winding of the armature, that is, two ammeters are needed for a two-phase motor, and three ammeters for a three-phase motor. A voltmeter is connected to the terminals of the secondary coil of a small step-down potential transformer, the primary coil of which is connected to the terminals of the field winding of the motor. A voltmeter is also connected between the supply mains.

The test is made with no current in the field and the field circuit open.* The voltage applied to the armature terminals is slowly

*The primary of the potential transformer takes but little current, and the field circuit, to all intents and purposes, is open.


increased until the motor starts to revolve. At the instant that the motor starts, the readings of all the instruments are recorded as follows: volts between armature terminals; amperes in the armature (each phase); and volts induced in field windings.

After the motor starts, the voltage applied to the armature terminals is kept constant; and the time required for the motor to attain synchronous speed, reckoned from the instant it starts, is observed. The exact instant that synchronism is reached, is indicated by violent swings of the pointers of the ammeters as well as those of the voltmeters connected to the armature terminals. At synchronism, another set of observations is taken.

In order to find the most unfavorable position of the armature and the corresponding starting current, and the time required to reach synchronous speed from this most unfavorable position, the above procedure is repeated for a series of initial positions of the armature, chosen as follows:

The circumference of the armature between the centers of two adjacent field poles is divided into a number of equal parts, this number not being a multiple of the number of phases, nor of the number of slots per pole per phase; usually there are seven parts. The starting positions thus chosen will include every possible position that a magnet pole may have relative to an armature slot. These parts are marked by chalked lines, and the various starting positions of the armature relative to the field-magnet poles are determined by setting each of the marks in succession into coincidence with a given field pole tip.





Hamburg Central Power Station
Hamburg, Germany

ALTERNATING-CURRENT MACHINERY

PART IV

TRANSFORMER

Description. The transformer consists of two separate and distinct coils of wire insulated from each other, and wound upon one and the same laminated iron core. Fig. 242, page 273, shows a sectional view of a commercial type of transformer. In practice, one of the coils receives alternating current from a high (or low) voltage source of supply; and the other coil delivers alternating current to a receiving system at a low (or high) voltage. When the transformer receives alternating current at high voltage and delivers it at low voltage, we have what is called *step-down transformation*; when the transformer receives alternating current at low voltage and delivers it at high voltage, we have what is called *step-up transformation*.

The coil of a transformer which receives alternating current from a source of supply, is called the *primary coil*; and the coil which delivers alternating current is called the *secondary coil*. In Fig. 242, each limb of the core is wound with half of the secondary coil (coarse wire) next to the core, and with half of the primary coil (fine wire) over the secondary.

The alternator, as we have already seen, is a machine in which an alternating electromotive force is produced by the cutting of a permanently established magnetic flux by wires on account of the motion of the flux relative to the wires.

The transformer, on the other hand, is an arrangement whereby an alternating electromotive force is produced in a stationary coil of wire (secondary) by reversals of magnetic flux through a stationary iron core, these reversals of flux being produced by alternating current supplied to the primary coil of the transformer.

Copyright, 1911, by American School of Correspondence.

Physical Action. *Without Load.* When the secondary of a transformer is on open circuit, it can of course, deliver no current; and the transformer is said to be operating at *zero load*. Under these conditions, only a small amount of alternating current flows through the primary coil. This current causes repeated reversals of magnetic flux through the iron core. These reversals of magnetic flux induce electromotive forces in both coils. The electromotive force thus induced in the primary coil is opposite in direction, and very nearly equal, to the electromotive force applied to the primary coil. Only the difference between the applied electromotive force and the opposing induced electromotive force is available for producing current through the primary coil; and since this difference is small, the primary current is small at zero load. The primary current at zero load is called the *no-load current* of the transformer.

With Load. Whether the secondary coil of a transformer is delivering current or not, the reversals of magnetic flux in the transformer core always induce an alternating electromotive force in the coil. When alternating current is taken from the secondary of a transformer, the transformer is said to be *loaded*. The action of this secondary current as it flows through the secondary coil, is to oppose the magnetizing action of the slight current already flowing in the primary coil, thus decreasing the maximum value reached by the alternating magnetic flux in the core, and thereby decreasing the induced electromotive forces in both coils. The amount of this decrease, however, is very small, inasmuch as a very small decrease of the induced electromotive force in the primary coil greatly increases the difference between electromotive force applied to the primary coil and the opposing electromotive force induced in the primary coil, so that the primary current is greatly increased. In fact, *the increase of primary current due to the loading of the transformer is just great enough (or very nearly) to exactly balance the magnetizing action of the current in the secondary coil*; that is, the flux in the core must be maintained approximately constant by the primary current whatever value the secondary current may have.

Electromotive Force Relations. The electromotive forces induced in the respective coils of a transformer are proportional to the number of turns of wire in each; and from the above discussion, it is evident that the electromotive force induced in the primary coil

is sensibly equal to the supply electromotive force, whether the transformer is loaded or not. Therefore

$$\frac{E'}{E''} = \frac{Z'}{Z''} \tag{32}$$

in which E' is the electromotive force applied to the primary, E'' is the electromotive at which the secondary coil delivers alternating current, Z' is the number of turns of wire in the primary coil, and Z'' is the number of turns of wire in the secondary coil.

Current Relations. The magnetizing action of the primary current I' of a transformer having Z' turns of wire in its primary coil, may be expressed by the product $Z'I'$, that is, by ampere-turns; and similarly, the magnetizing action of the secondary current I'' may be expressed by the product $Z''I''$, where Z'' is the number of turns of wire in the secondary coil. Therefore, since the magnetizing actions of the two coils are equal (and opposite), we have

$$Z'I' = Z''I''$$

or

$$\frac{I'}{I''} = \frac{Z''}{Z'} \tag{33}$$

in which Z' and Z'' are the turns of wire in the respective coils; I'' is the current delivered by the secondary coil; and I' is the increase of current taken by the primary coil over and above the no-load current, due to the fact that the secondary coil is delivering current.

Now in most commercial transformers the no-load current is quite small; and, neglecting this current entirely, the only current in the primary coil would be the increase of primary current due to the fact that the secondary coil is delivering current. Therefore, equation (33) expresses, with sufficient accuracy for most purposes, the relation between the actual primary current I' and the secondary current I'' .

Summary of Electromotive Force and Current Relations. A transformer which delivers current I'' to a receiving circuit, takes an amount of current equal to $I'' \times \frac{Z''}{Z'}$ ($= I'$) from the source of supply. The electromotive force of the source of supply is E' , and the electromotive force at which the secondary delivers current is equal to $E' \times \frac{Z''}{Z'}$ ($= E''$).

Example. A certain transformer rated at $5\frac{1}{2}$ kilowatts has 660 turns of wire in its primary coil and 66 turns of wire in its secondary coil. The primary coil is connected between 1,100-volt supply mains. Therefore, the secondary electromotive force, by equation (32) is

$$E'' = \frac{Z''}{Z'} \times E' = \frac{66}{660} \times 1,100 = 110 \text{ volts}$$

If ten lamps, each taking half an ampere, are connected to the secondary coil, the secondary current will be 5 amperes; and the primary current, by equation (33) will be

$$I' = \frac{Z''}{Z'} \times I'' = \frac{66}{660} \times 5 = .5 \text{ ampere}$$

The power delivered to the lamps by the secondary coil is equal to $E'' I''$ since the lamp circuit is non-inductive. That is:

$$\text{Power delivered to lamps} = 110 \text{ volts} \times 5 \text{ amperes} = 550 \text{ watts.}$$

The power delivered to the primary coil in this case (non-inductive secondary circuit), is equal to $E' I'$. That is:

$$\text{Power delivered to primary} = 1,100 \text{ volts} \times 0.5 \text{ amperes} = 550 \text{ watts.}$$

If 100 lamps, each taking half an ampere, are connected to the secondary coil, the secondary current will be 50 amperes, and the primary current will be 5 amperes; the power delivered to the lamps will be 5,500 watts, and the power delivered to the primary coil will also be 5,500 watts.

The above calculations ignore the following actions which take place in an actual transformer: (a) losses of electromotive force in overcoming the resistances of primary and secondary coils; (b) losses of power (I^2R) in the primary and secondary coil; and (c) loss of power in the iron core, due to hysteresis and eddy currents.

Automatic Action of the Transformer. When the load on a transformer is increased, the primary of the transformer automatically takes additional current and power from the supply mains in direct proportion to the load on the secondary. When the load on the secondary is reduced, for example, by turning off lamps, the power taken from the supply mains by the primary coil is automatically reduced in proportion to the decrease in the load. This automatic action of the transformer due to the balanced magnetizing action of the primary and secondary currents is illustrated in the above example.

Ideal and Practical Transformer. The foregoing discussion of electromotive force and current relations in a transformer is based upon the following assumptions:

(a) That the no-load current of the transformer is negligible, and that it represents no power taken from the supply mains; or, in other words, that eddy-current and hysteresis losses are absent.

(b) That the resistance of the coils is negligible, so that the electromotive force applied to the primary coil is wholly balanced by the opposing electromotive force in the primary coil, and so that the whole of the electromotive force induced in the secondary coil is available at the terminals of that coil.

(c) That all the magnetic flux which passes through the primary coil passes through the secondary coil also; or, in other words, that there is no *magnetic leakage*.

A transformer that would meet these conditions would be an ideal transformer. A well-designed transformer operating on moderate load does approximate quite closely to the ideal transformer in its action; and equations (32) and (33) are much used in practical calculations. For some purposes, however, it is desirable to consider the action of the transformer, taking account of coil resistances, of eddy currents and hysteresis, and of the fact that some lines of magnetic flux pass through one coil without passing through the other (magnetic leakage). The extent to which a well-designed transformer deviates from an ideal, is exemplified by the following actual results obtained with the $5\frac{1}{2}$ -kilowatt transformer used in the example on the preceding page.

At no load, the value of E'' is 109.8 volts; the no-load current is 0.129 amperes; and the power taken from the mains by this no-load current (core loss) is 100 watts. This core loss is nearly constant at all loads.

When 100 lamps, taking 50 amperes of current, are connected to the secondary, then E'' is 107.2 volts. The I^2R loss in the primary coil is 65 watts; and the I^2R loss in the secondary is 65 watts. Therefore, the power delivered to the lamps is 5.36 kilowatts; the power taken from the supply mains is $5,360 + 100 + 65 + 65$, which is equal to 5,590 watts; and the full-load efficiency of the transformer is 96 per cent.

Maximum Core Flux. In the designing of transformers and in the predetermination of core loss, it is necessary to calculate the maximum value reached by the alternating magnetic flux through the transformer core. This maximum value of the core flux may be easily and accurately calculated in the following manner:

Let Φ be the maximum value of the core flux (equal to the product BA of maximum flux density and sectional area of the core) E the effective value of the electromotive force applied to the primary coil, Z the number of turns of wire in the primary coil, and f the frequency of the applied electromotive force, in cycles per second. Now consider the instant when the core flux is at its maximum posi-

tive value Φ . After a quarter of a cycle, or after $\frac{1}{4f}$ second, the flux is reduced to zero. The average rate of change of the flux during this quarter of a cycle is equal to

$$\frac{\text{total change of flux}}{\text{elapsed time}} = \frac{\Phi}{\frac{1}{4f}} = 4f\Phi$$

which is equal to the *average* electromotive force (in c. g. s. units) induced in each turn of wire in the primary coil. Therefore, the total electromotive force induced in the Z turns of wire in the primary coil is $4f\Phi Z$ c. g. s. units, or $4f\Phi Z \div 10^8$ volts, since 10^8 c. g. s. units equal 1 volt.

The average value of the induced electromotive force is equal (very nearly) to the average of the electromotive force applied to the primary coil; and it must be multiplied by the form factor* of the electromotive force curve to give the effective value E of the applied electromotive force. The form factor of a sine-wave electromotive force is 1.11. Therefore

$$E = 1.11 \times \text{average value} = 4.44f\Phi Z \div 10^8 \text{ volts}$$

Hence, solving for Φ , we obtain the equation

$$\Phi = \frac{E \times 10^8}{4.44 \times Z \times f} \quad (34)$$

Example. In the $5\frac{1}{2}$ -kilowatt transformer used as an illustration on page 236, there are 660 turns of wire in the primary coil, that is $Z = 660$. This primary coil is connected to alternating-current supply mains so that the electromotive force applied to the primary coil is 1,100 volts (effective). The frequency of the electromotive force is 125 cycles per second ($=f$). On the assumption that the electromotive force wave is a sine curve, we have, using equation (34),

$$\Phi = \frac{1,100 \times 10^8}{4.44 \times 660 \times 125} = 300,000 \text{ lines of magnetic flux}$$

This is the maximum value of the alternating magnetic flux in the transformer core.

The cross-sectional area A of the transformer core is $15\frac{1}{2}$ square inches, so that the maximum value of the magnetic flux-density in the core is

$$\frac{\Phi}{A} = \frac{300,000}{15\frac{1}{2}} = 19,350 \text{ lines per square inch}$$

This is equivalent to a flux-density of 3,000 lines per square centimeter.

*See page 15.

Ideal Transformer Action Graphically Represented. CASE (a) *Without Load.* The line $O\Phi$ in the clock diagram, Fig. 204, represents the alternating magnetic flux in the core of a transformer, the line OE' represents the electromotive force applied to the primary coil, and the line OE'' represents the electromotive force induced in the secondary coil. When the transformer is at zero load, the current in the primary coil (the no-load current) lags greatly behind the applied electromotive force E' , as shown in the figure, in which the line OI_0 represents the no-load current. The electromotive forces induced in both primary and secondary coils are 90 degrees behind the core flux $O\Phi$ in phase, and the electromotive force OE' applied to the primary coil, being at each instant opposite to the electromotive force induced in the primary, is 90 degrees ahead of $O\Phi$ in phase.




Fig. 204. Clock Diagram for Transformer without Load

CASE (b) *With Load, Receiving Circuit Nearly Non-Inductive.* The lines $O\Phi$, OE' , OE'' , and OI_0 in Fig. 205 represent alternating core flux, primary applied electromotive force, secondary induced electromotive force, and no-load current, exactly as in Fig. 204. The line OI'' represents the secondary current lagging slightly behind the secondary electromotive force OE'' ; and the line OA represents the increase of primary current due to the loading of the transformer. The total primary current is represented by the line OI' , which is the vector (or geometric) sum of OA and OI_0 . The current OA is exactly opposite to OI'' in phase; and the product of this current OA and the primary turns Z' balances the magnetizing action $Z''I''$ of the secondary current. As is evident from Fig. 205, the loading of a transformer (non-inductive load) not only increases the value of the primary current, but reduces its angle of lag behind the primary applied electromotive force. Thus, at zero-




Fig. 205. Clock Diagram for Transformer with Load

load the primary current is OI_0 ; and when the transformer is loaded (non-inductive load) the primary current becomes OI' .




Fig. 206. Clock Diagram for Transformer with Load—highly Inductive Receiving Circuit.

CASE (c) *With Load, Receiving Circuit Highly Inductive.* In Fig. 206 the line OI'' represents the current delivered by the secondary coil of a transformer to a highly inductive receiving circuit; the line OA represents the increase of primary current due to the load; and OI' represents the total primary current. In this case, also, the part OA of the primary current is exactly opposite in phase to the secondary current OI'' .

Influence of Coil Resistances and Magnetic Leakage. The foregoing discussion takes account of the no-load current of a transformer. This no-load current is the only factor that affects the ideal relation, equation (33), between primary and secondary currents in a transformer. Coil resistances and magnetic leakage are, on the other hand, the only things that affect perceptibly the ideal relations, equation (32), of primary and secondary electromotive forces.




Fig. 207. Clock Diagram Showing Effects of Coil Resistance and Magnetic Leakage

Magnetic leakage is equivalent, in its effect upon the action of a transformer, to an outside inductance (a choke coil) connected in series with the primary coil. Let L' be this inductance (in henrys) which is equivalent to the magnetic leakage of a transformer. Then $\omega L'$ (ω equals 2π times the frequency) is the reactance (in ohms) of this inductance.

The effects of coil resistances and magnetic leakage upon the ideal relation between E' and E'' are shown in the clock diagram, Fig. 207.

The total electromotive force OE' applied to the primary coil is used (a) to overcome the resistance R' of the

primary coil; (b) to overcome the electromotive force induced in the primary coil by the leakage flux; and (c) to balance the electromotive force induced in the primary coil by the magnetic flux $O\Phi$, which passes through both coils.

The part (a) of OE' is equal to $I'R'$, and it is in phase with I' . The part (b) of OE' is equal to $\omega L'I'$, and it is 90 degrees ahead of I' in phase. The part (c) of OE' is represented by the line OA' . The total electromotive force induced in the secondary coil is equal to $OA' \times \frac{Z''}{Z'}$. This electromotive force is represented by the line OB . A portion of this total induced electromotive force OB is used to overcome the resistance R'' of the secondary coil; and the remainder OE'' is available at the terminals of the secondary coil to force current through the secondary receiving circuit.

From Fig. 207 it is evident that the ratio $\frac{E''}{E'}$ is less than its ideal value $\frac{Z''}{Z'} (= \frac{OB}{OA'})$ because of the "resistance loss" $I'R'$ of electromotive force in the primary coil, because of the "leakage loss" $\omega L'I'$ of electromotive force in the primary coil, and because of the "resistance loss" $I''R''$ of electromotive force in the secondary coil.

Performance. With Non-Inductive Load. When a transformer secondary delivers current to a non-inductive circuit, then OI'' , Fig. 207, is parallel to OB , and OI' is nearly parallel to OE' , so that $R'I'$ is nearly parallel to OE' , and $\omega L'I'$ is nearly at right angles to OE' . Therefore, the difference in value between OE' and OA' is nearly equal to $I'R'$, and nearly independent of $\omega L'I'$. Therefore, the falling off of the secondary voltage E'' , with increase of load, is due almost wholly to $I'R'$ and to $I''R''$ when the receiving circuit is non-inductive, and is not due, to any perceptible extent, to magnetic leakage.

With Highly Inductive Load. When a transformer secondary delivers current to a highly inductive circuit, then OI'' , Fig. 207, is nearly at right angles to OB , and OI' is nearly at right angles to OE' , so that $I'R'$ is nearly at right angles to OE' ; $\omega L'I'$ is nearly parallel to OE' ; and further, $I''R''$ is nearly at right angles to OB . Therefore, the difference in value between OE' and OA' is nearly equal to $\omega L'I'$, and nearly independent of $R'I'$, while OB is nearly equal to OE'' . Therefore, the falling off of the secondary voltage E'' , with

increase of load, is due chiefly to $\omega L'I'$, that is, to magnetic leakage, when the receiving circuit is highly inductive, and is not due to any great extent to coil resistances.

Example. The primary of a certain 10-kilowatt (1,000-volt : 100-volt) transformer has a resistance of 1.5 ohms, and the secondary coil has a resistance of 0.015 ohms. The secondary coil delivers 100 amperes to a non-inductive receiving circuit; and, ignoring no-load current, the primary takes 10 amperes from 1,000-volt mains. The IR loss of electromotive force in the primary coil is, therefore, 1.5 ohms \times 10 amperes = 15 volts, so that the portion OA' , Fig. 207, of the primary applied voltage is very nearly 1,000 - 15 = 985 volts. Therefore, the total electromotive force OB induced in the secondary coil is $\frac{Z''}{Z'} \times 985$ volts = 98.5 volts. The IR loss of electromotive force in the secondary coil is 0.015 ohms \times 100 amperes = 1.5 volts, so that the electromotive force between the terminals of the secondary coil is 98.5 volts - 1.5 volts, or 97 volts. In this case, the secondary receiving circuit is non-inductive, and the portion $\omega L'I'$ of the primary applied voltage is nearly at right angles to E' . This loss of voltage $\omega L'I'$ has, therefore, no appreciable effect in lessening the value of the available part OA' of the primary applied voltage E' .

The leakage reactance $\omega L'$ of the above transformer is 5 ohms. If the secondary coil delivers 100 amperes of current to a very highly inductive receiving circuit, then this 100 amperes is nearly 90 degrees behind OB , Fig. 207, in phase; and the primary current of 10 amperes is nearly 90 degrees behind OA' in phase. Therefore, the leakage voltage loss $\omega L'I'$, which is equal to 50 volts, is nearly parallel to OA' , so that OA' is very nearly equal to 1,000 volts - 50 volts, or 950 volts, and E'' is very nearly equal to $\frac{Z''}{Z'} \times 950$ volts, or 95 volts. In this case, $I'R'$ and $I''R''$ are nearly at right angles to OA' and OB , and these resistance losses of voltage do not have an appreciable effect in lessening the secondary terminal voltage E'' .

The above discussion of the effects of coil resistances and of magnetic leakage shows that the ratio of E' and E'' is very nearly equal to its ideal value $\frac{Z''}{Z'}$ when the primary and secondary currents of a transformer are small, that is, when the load on the transformer is zero.

TRANSFORMER CONNECTIONS

Parallel—Constant-Voltage Transformers. In systems of distribution where alternating currents are delivered to a number of units (groups of lamps, for example) all at constant voltage, each unit (each group of lamps) is supplied from the secondary of a separate and distinct transformer; and the primaries of the respective transformers are connected in parallel across the constant-voltage

mains that lead out from the supply alternator. This arrangement is shown in Fig. 208, in which $P, P', P'',$ etc., are the transformer primaries; $S, S', S'',$ etc., are the corresponding secondaries; and $A, A', A'',$ etc., are the separate receiving units or groups of lamps. For this kind of service, where the primary of a transformer is supplied at constant voltage, and it is desired that the transformer shall deliver current to a receiving unit at sensibly constant voltage irrespective of load, *i. e.*, irrespective of the number of lamps, the transformer must be designed so that a very slight decrease of induced electromotive force in the primary will permit the necessary current to flow through the primary coil. This requires that the coils of the transformer shall have as little resistance as possible, and that the primary and secondary coils shall be wound close together, so that no perceptible portion of the magnetic flux that is forced through the core by the magnetizing current may flow out of the core between the coils, instead of passing through the secondary coil as well as through the primary coil. A transformer




Fig. 208. Diagram of Connections of Constant-Voltage Transformers in Parallel

specially designed to realize these two conditions is sometimes called a *constant-potential* or *constant-voltage transformer*.

A constant-voltage transformer is necessary if it is desired to transform a given voltage in a determinate ratio so as to be able to infer the value of the given voltage from the measured value of the transformed voltage. Specially designed transformers, however, are not always necessary for this purpose, for the reason that the voltmeter used for measuring the transformed voltage usually takes very little current, and it is the currents in a transformer that disturb the ideal ratio of voltage transformation.

Multi-Coil Type. Most commercial transformers are now made with two (or more) primary coils, and with two (or more) secondary coils. Each of the primary coils of such a transformer may be

adapted to direct connection to 1,100-volt mains, and be wound with wire large enough to carry, say, 10 amperes without undue heating. In this case, if these two primary coils are properly connected in parallel they constitute in effect a single primary coil, suited for direct connection to 1,100-volt mains, and capable of taking 20 amperes without undue heating. On the other hand, if these two




Fig. 209. Proper Parallel Connections for Transformers




Fig. 210. Improper Parallel Connections for Transformers

primary coils are properly connected in series, they constitute in effect a single primary coil suited for direct connection to 2,200-volt mains, and capable of taking 10 amperes of current without undue heating. Each of the secondary coils of such a transformer may likewise be adapted to deliver 100 amperes at 110 volts, in which case the two secondaries, if properly connected in parallel, constitute in effect a single secondary coil adapted to deliver 200 amperes at 110 volts; whereas, if the two secondaries are properly connected in series, they constitute in effect a single secondary adapted to deliver 100 amperes of current at 220 volts.

Two coils of a transformer (primary or secondary) are properly connected in parallel when the current which divides between them flows around the core in the same direction in both coils, that




Fig. 211. Proper Series Connections for Transformers




Fig. 212. Improper Series Connections for Transformers

is, so that both coils magnetize the core in the same direction. Proper and improper connections in parallel are shown diagrammatically in Figs. 209 and 210. See also "Polarity Test," page 315.

Two coils of a transformer (primary or secondary) are properly connected in series when the current which flows through them flows around the core in the same direction in both coils. Proper and improper connections in series are shown diagrammatically in Figs. 211 and 212.

When two primaries of a transformer improperly connected in parallel are connected to the supply mains, the currents in the coils oppose each other in their magnetizing action on the core. The result is that the core is not perceptibly magnetized; but little opposing electromotive force is induced in the coils (by leakage flux); and the two improperly connected coils constitute a short-circuit when they are connected to the supply mains.

When two primaries of a transformer, improperly connected in series, are connected to the supply mains, the current which




Fig. 213. Proper Transformer Connections to a Three-Wire System

flows through the two coils will have equal and opposite magnetizing actions in the two coils. The core flux will, therefore, be practically zero, and no counter-electromotive force will be induced in the windings to balance the applied electromotive force. The flow of current is, therefore, hindered only by the coil resistances and by the electromotive forces induced by the leakage flux. The result is that two coils improperly connected in series constitute a short-circuit when they are connected to the supply mains.

Two secondary coils improperly connected in parallel give rise to short-circuit conditions. Two secondary coils improperly connected in series do not lead to short-circuit conditions, but give zero electromotive force between their terminals.

Edison Three-Wire System—Single-Phase. The Edison three-wire system, extensively used in direct-current distribution, is commonly used in alternating-current distribution. Fig. 213 shows two transformers properly connected for supplying current to a three-wire system; and Fig. 214 shows two transformers improperly connected for supplying current to a three-wire system. In the proper connection, the middle secondary main *c* carries only the difference of the currents in the outside mains *a* and *b*; and in the improper connection, the current in the middle secondary main is the sum of the currents in the outside mains. The proper connection gives




Fig. 214. Improper Transformer Connections to a Three-Wire System

double voltage between the outside secondary mains and the improper connection gives zero voltage between outside secondary mains.

The Edison three-wire system must not be confused with the two-phase and three-phase three-wire systems. The advantages of the Edison three-wire system when used for the distribution of single-phase alternating currents, are exactly the same as the advantages of this system when used for the distribution of direct currents, namely, a great saving in the copper required in the distributing mains. This saving, in general, amounts to five-eighths of the copper that would be required for a two-wire system using

one-half the total voltage between outside mains. As explained on page 5, the amount of copper required varies inversely as the square of the voltage used.

Single-phase current may be supplied to Edison three-wire distributing mains by a single transformer having two secondary coils properly connected in series to the outside mains, the middle main being connected to the junction of the two secondary coils. An "autotransformer" or "balance coil" having a tap at the middle point of its single winding is often used. (See page 252.)




Fig. 215. Connections for "Banked" Transformers

Banking of Transformers. Two service mains may be supplied with current by two or more transformers with their primaries connected in parallel between the supply mains, and with their secondaries properly connected in parallel to the service mains. Fig. 215 shows two transformers properly "banked" so as to supply current to the two service mains *a* and *b*. In many large transmission systems, such as the Niagara-Buffalo, a dozen or more large transformers may be banked (on each phase) for step-up or step-down transformation.

It is very important to note, however, that proper connections alone will not insure satisfactory parallel operations. Perfect oper-

ation of two or more transformers in parallel means that each of the separate units contributes to the total load an amount of power proportional to its rated output, and that the numerical sum of the currents in the separate units is equal to the line (total) current. To secure this desirable result, two conditions must be fulfilled: (a) the ratio of primary turns to secondary turns must be the same in all the units, and (b) the voltage drop from no load to full load must be the same, both in magnitude and phase, for all the units.

If condition (a) is not fulfilled, there will be a difference at all loads in the secondary voltages, and the transformer having the highest voltage will carry the largest load. Condition (b) is fulfilled if all the transformers have the same impedance volts (ZI) and the same ratio of resistance to impedance. If the transformers in parallel have the same impedance volts, it follows that the magnitude of the current furnished by each will be inversely as its impedance. If further they have the same ratio of reactance to resistance, it follows that the currents delivered by each will have the same phase, and the total current will then be the numerical sum of the individual currents.

Given two or more transformers, having the same ratio of primary to secondary turns and having relatively small magnetizing currents, to be banked so as to operate in parallel; the division of the total load between them depends chiefly upon the total impedances between the bus bars, including with each transformer its connecting wires and any meters or relays through which the current may pass. In any case where transformers banked in parallel do not divide the total load according to their rated capacities, a proper division of the current may be effected by increasing the impedance in the circuit of the transformer which delivers more than its share of the total current. This may be easily done by inserting a suitable choke coil (a coil of wire wound on a laminated iron core) in series with either its primary or secondary lead wires.

When the ratio of reactance to resistance is unequal in the transformers, the phases of the secondary currents are not the same, so that the transformers may deliver equal currents, and still not deliver equal amounts of power to the circuit. It follows that a wattmeter connected with its series (current) coil in circuit with only one of, say, two transformers of equal rating will not measure

half of the total power. It will measure more than half or less than half according to the value of $\cos \theta$ in the expression $EI \cos \theta$, where

$$\tan \theta = \frac{\text{reactance}}{\text{resistance}}.$$

From the above discussion it is evident that special care must be taken in banking transformers for parallel operation to see that the several units are delivering their proper share of the total current output. Furthermore, it is not safe to assume that transformers even of the same rated capacity and of the same make will share a given load equally when operated in parallel. The only safe procedure in such cases is to measure the voltage, current, and watts of the several transformers.

Series-Current Transformers. In some of the older systems of distribution by alternating currents, it was desired that each




Fig. 216. Connections for Transformers in Series

receiving unit (arc lamp, for example) should receive a constant current equal to the whole, or to a definite fractional part, of the constant current delivered by an alternator. This condition can be realized by supplying each unit or group of units from the secondary of a separate and distinct transformer, the primaries of all the transformers being connected in series as shown in Fig. 216, in which P, P', P'', P''' , etc., are the primaries of the respective transformers; S, S', S'', S''' , etc., are the transformer secondaries; and A, A', A'', A''' , etc., are the receiving units. For this kind of service, where the primary of a transformer is supplied with a *definite* current, and it is desired that the transformer shall deliver to a receiving unit a current which is equal to an invariable fractional part of the primary current, irrespective of variations of resistance in this unit, the transformer must be designed to take as small a magnetizing current as possible, for, according to the discussion on page 235, it is the magnetizing current that disturbs the ideal relation of primary

to secondary current in a transformer. A transformer which is specially designed to realize this condition is sometimes called a *current transformer*.

The transformer used in connection with the composite field excitation of an alternator, as shown in Fig. 112, is a current transformer which delivers a current equal to a definite fraction of the current output of the alternator to the rectifying commutator.

The current transformer is frequently used for sending current equal to a definite fractional part of an alternating current through an ammeter from the reading of which, together with the known ratio of current transformation, the value of the whole alternating current is deduced.

The current transformer here described must not be confused with the so-called *constant-current transformer* which receives variable




Fig. 217. Diagram of Connections for Transformer in Series with a Number of Lamps

current from a constant voltage supply, and delivers a constant current to a group of receiving units connected in series, the delivered current being constant irrespective of increase or decrease in the number of receiving units.

The connection of a transformer primary in series in a circuit containing many other elements (lamps) so that the current passing through the primary does not vary much with the varying resistance of the circuit to which the secondary of the transformer delivers current, gives rise to actions which are not very familiar to electrical engineers, for the reason that this arrangement is now seldom used in practice. The actions, however, which are interesting, are as follows:

Fig. 217 represents a transformer primary P connected in series in a circuit containing many elements e', e'', e''' , etc., (lamps).

The action will be described in two steps, viz, (a) on the assumption that the magnetizing current of the transformer is always negligible, and (b) without the aid of this simplifying assumption.

(a) If the magnetizing current is always negligibly small, then the current in A is equal to a fixed fractional part of the sensibly constant current in the main circuit, so that any increase of the resistance or reactance of A must be accompanied by a corresponding increase of the voltage E'' , which is pushing current through A ; and this must be accompanied by a corresponding increase of the voltage E' between the terminals of the primary coil P . Thus, if A has zero resistance and zero reactance, then E'' is zero, and E' is zero. That is, the current in the main circuit flows through P without any opposition at all, just as if P were a connection of zero resistance.

If the resistance or reactance of A is increased, E'' (and also E') must increase, which means that the current in the main circuit encounters greater and greater opposition in flowing through P .

If the circuit of A is opened (infinite resistance), then, on the above assumption of negligible magnetizing current, the opposition to the flow of current in P becomes infinite, so that breaking the circuit of A is equivalent to breaking the main circuit.

(b) As a matter of fact, as the resistance or reactance of A is increased, causing an increase of E'' and E' , the magnetism of the transformer core must increase proportionally with E'' and E' in order that these increased voltages may actually be induced in the transformer coils; and this increase of magnetism of the core requires more and more magnetizing current.* The magnetizing current, therefore, is not always negligible irrespective of the resistance of A . In fact, when the resistance of A is infinite (open circuit), there is no secondary current; all the current in the coil P is magnetizing current; and the voltage E' , which opposes the flow of current through P , rises only to that value which corresponds to the degree of magnetism of the core that can be produced by the magnetizing action of the whole primary current. The transformer then becomes simply a choke coil.

Autotransformer. Given a source of supply of alternating

*It must be remembered that the magnetizing current is that part of the primary current whose magnetizing action is not balanced or annulled by the secondary current as explained on page 235.

current. This current may be delivered to a receiving unit in three ways:

- (a) By connecting the unit directly to the supply mains.
- (b) By connecting the unit to the secondary of a transformer of which the primary is connected to the supply mains.
- (c) By a combination of methods (a) and (b).

The combination method may be realized with any ordinary transformer; which, when so used, is called an *autotransformer*, or *compensator*.

NOTE. It will appear in the following discussion that when the voltage of the supply differs but little from the desired service voltage, the combination method is much preferable to the method in which the transformer alone is used, because of the fact that a smaller transformer suffices, and because the combination method involves less energy loss. This combination or autotransformer method is quite simple of treatment when attention is confined to a particular case; but it is complicated when attempt is made to give it a general discussion, that is, when attempt is made to discuss all the theoretically possible ways in which a given ordinary transformer may be used as an autotransformer.

In Fig. 218 *A* and *B* are alternating-current supply mains, between which the voltage is, say 100; *C* and *D* are service mains,





Fig. 218. Connections for Auto Step-Up Transformer

to which it is desired to deliver alternating current at 90 or 110 volts; *P* and *S* are the primary and secondary coils of an ordinary transformer. The primary *P* is connected to *A* and *B* as shown.

The secondary *S* has one-tenth as many turns as *P*, therefore, the voltage induced in *S* is one-tenth of the voltage acting on *P*, or 10 volts. Let the dotted arrows represent the directions of the induced electromotive forces in the two coils at a given instant. Then the long heavy arrow will represent the direction of the voltage between the mains at the same instant, inasmuch as the induced voltage in the primary coil of a transformer is always opposed to the supply voltage.

Auto Step-Up Transformation. The 10 volts induced in the coils, Fig. 218, will help push current into the service mains if we connect from supply main *A*, out of which the current at the given instant is tending to flow, to terminal *g* of coil *S*; connect from



TWO 1,000-Kw. MOTOR GENERATOR SETS WITH EXCITER AND BALANCER SETS IN THE PLANT OF THE MERCHANTS HEAT AND LIGHT CO., INDIANAPOLIS

Courtesy of Allis-Chalmers Company, Milwaukee, Wis.

terminal f to service main C ; and connect from service main D to supply main B , as shown by the dotted lines. In this case, the voltage induced in the coil S is added to the supply voltage, and the service voltage is, therefore, 110 volts.

Auto Step-Down Transformation. The 10 volts induced in the coil S will oppose the flow of current into the service mains if we connect from supply main A to terminal f , connect from terminal g to service main C , and connect from service main D to supply main B , as shown by the dotted lines in Fig. 219. In this case the induced voltage in the coil S is subtracted from the supply voltage, and the service voltage is now 90.

Current Relations. In Figs. 218 and 219 the directions of the induced voltages in P and S are shown by the dotted arrows. These induced voltages are in the same direction in the two coils. The currents in the two coils of a transformer are, on the other hand, always in opposite directions, inasmuch as they balance the magnetizing action of each other. Suppose for the sake of concreteness that 10 amperes are delivered to the service mains. Then we have the following relations:

(a) Ten amperes flow through S , Fig. 218, in the same direction as the induced electromotive force of ten volts, so that one ampere (one-tenth as much current, since there are ten times as many turns in P as in S) flows through P in opposition to the induced or counter-electromotive force of 100 volts. Therefore, the coil P takes 100 watts from the supply mains, which power is transferred to the coil S by ordinary transformer action, whence it is given out (ten volts pushing ten amperes) in assisting the flow of current to the service mains. The total power delivered to CD is evidently 1,100 watts (10 amperes at 110 volts), and of course the total power taken from the supply mains is 1,100 watts (11 amperes at 100 volts).

(b) Ten amperes flow through S , Fig. 219, in a direction opposite to the ten volts of induced electromotive force, so that one ampere flows through P in the same direction as the induced electromotive force of 100 volts. Therefore, of the 1,000 watts delivered by the supply mains in forcing the ten amperes through S and through the service mains, 100 watts are delivered to the coil S , and 900 watts are delivered to the service mains (10 amperes at 90 volts). The 100 watts delivered to S are transferred by transformer action to the coil P , and delivered by P back to the supply mains.

It is to be particularly noted that only 100 watts are involved in the




Fig. 219. Connections for an Auto Step-Down Transformer

above as genuine transformer action, although 900 or 1,000 watts are actually delivered to the service mains.

The autotransformer is used commercially for many purposes. A common use is as a "balance coil" in a three-wire distribution from a two-wire supply, and it is also used as a balancer in connection with rotary converters for supplying a three-wire direct-current service as explained on page 355. Compensators are also used for the operation of low-voltage tungsten lamps in parallel for house lighting, for electric signs, for arc lamps, as voltage regulators for mercury-vapor rectifiers, as explained on page 324. Autotransformers are also widely used as "starting compensators" for alternating-current motors. In such cases they supply a reduced voltage (usually half voltage) to the motor circuits while the armature is accelerating from rest. Each autotransformer is usually provided with several taps so that a number of low voltages may be obtained at will.

Autotransformers are used for supplying a varying voltage to single-phase commutator motors used on electric cars and locomotives, and thus for controlling the speed of the motors.

TRANSFORMERS IN POLYPHASE SYSTEMS

A polyphase transmission system is essentially the utilization of two or three entirely separate and distinct single-phase transmis-




Fig. 220. Transformer Connections on a Two-Phase System




Fig. 221. Transformer Connections on a Three-Wire Two-Phase System

sion systems of which the separate and distinct electromotive forces or currents are maintained in definite phase relations with each other by mechanical connections in the generator. Step-up or step-down transformation in a polyphase system is accomplished, in general, by a separate and distinct transformer of the ordinary type for each phase.

Two-Phase System. Fig. 220 shows a two-phase system in which the current of each phase *A* and *B* is transmitted over an




Fig. 222. Connections for Three Transformers with Primaries Connected to Three-Wire Three-Phase Mains

entirely independent circuit, and the electromotive force of each phase is stepped down (or up) by an ordinary transformer $P'S'$ and $P''S''$, respectively. Fig. 221 shows what is called the *three-wire, two-phase system*, in which one line wire is used as a common return wire for both phases, and where two ordinary transformers $P'S'$ and $P''S''$ are used for stepping the voltage down (or up). These two figures contain all that is essential in the step-down or step-up transformation of a two-phase system.




Fig. 223. System Shown in Fig. 222 with One Transformer Removed

Three-Phase System. The usual transmission line for a three-phase system consists of three wires, each wire being in effect a com-

mon return for currents that pass out over the other two. In this case, the usual arrangement for step-down (or step-up) transforma-




Fig. 224. Diagrammatic View of Two Separate Transformers for Step-Up or Step-Down Transformation—Two-Phase System

tion is to connect the three primaries of three ordinary transformers to the supply mains, using either Y or Δ connections; and to connect the three secondaries to the service mains, using either Y or Δ connections. Furthermore, the primaries may be Y -con-

nected and the secondaries Δ -connected, or *vice versa*. The Δ connections of both primaries and secondaries are preferred in practice, inasmuch as with this arrangement the complete three-phase, step-down (or step-up) transformation is still effected even though one transformer may be entirely disconnected because of burn-out or breakdown. In this case the two remaining transformers are said to be connected in **V**. In such a case, however, the two remaining transformers do not have two-thirds of the transforming capacity of all three, but only $\frac{2}{3}$ of $\frac{2}{3} = 0.567$ as much, or a little over one-half the capacity.

Fig. 222 shows three ordinary transformers $P'S'$, $P''S''$, and $P'''S'''$, with their primaries Δ -connected to three-wire, three-phase supply mains 1, 2, and 3; and with their secondaries Δ -connected to three-wire, three-phase service mains a , b , and c .




Fig. 225. Two Transformers for Two-Phase System with Common Magnetic Return Circuit

Fig. 223 shows the arrangement of Fig. 222 with one of the transformers $P'''S'''$ omitted (any one of the three may be omitted), thus giving the **V** connection. This arrangement is operative for three-phase, three-wire step-up or step-down transformation, except that its power capacity is

only about 57 per cent of the power capacity of the arrangement in which three similar transformers are used.

Transformers with Compound Magnetic Circuits. Let *A* and *B*, Fig. 224, be the two separate transformers to be used for step-up or step-down transformation on a two-phase system. Each iron core may have its own return circuit for the magnetic flux; or a single magnetic return *C* may be used for the two, as shown in Fig. 225. In the latter case only 1.4 as much iron need be used for the common return as would have to be used for each single magnetic return.




Fig. 226. Three Transformers for Three-Phase System with Common Return Circuit

Similarly, three transformers *A*, *B*, and *C*, Fig. 226, used for step-up or step-down transformation on a three-phase system, may be combined magnetically so that each transformer core is the magnetic return for the other two, as shown. Commercial examples of polyphase transformers are described on pages 292 and 293.

Phase Transformation. If a two-phase* supply is connected to the similar primaries of two transformers, an electromotive force of any desired value and of any desired phase may be produced. Fig. 227 shows the two-phase supply mains connected to the similar primaries *P'* and *P''* of two separate transformers. On core *A* is wound a secondary coil *a*, and on core *B* is wound a secondary coil *b*; these two secondary coils are connected in series, and the desired electromotive force *E* is produced by the two secondary coils in conjunction. In order that the desired electromotive force *E* may be produced by coils *a* and *b* jointly, the following conditions must be fulfilled:




Fig. 227. Connections for Phase Transformation from Two-Phase Supply Mains

*Or three-phase supply. The discussion of phase transformation is, however, much simpler with a two-phase supply.

Let the vectors A and B in the clock diagram, Fig. 228, represent the two two-phase electromotive forces; and let E represent the desired electromotive force. Then coil a , Fig. 227, must be wound with a sufficient number of turns of wire to produce the component a of E ; and coil b must be wound with a sufficient number of turns of wire to produce the component b of E . See




Fig. 228. Vector Diagram of E.M.F. Relations for Fig. 227

Fig. 228.

If it is desired that the resultant electromotive force E be in the second, third, or fourth quadrant, the coil a or the coil b , or both coils a and b must be reversed as indicated in Fig. 229. It, therefore, follows that by correctly proportioning and connecting the coils a and b , any desired value and position of the resultant electromotive E may be produced.

The general two-phase, three-phase transformer consists of two separate transformers with similar primary coils P' and P'' which are connected to the respective phases of the two-phase supply mains, as shown in Fig. 227; and each of the three-phase electromotive forces is produced by a pair of properly proportioned and properly connected secondary coils (one coil on each transformer) connected in series. Each pair of secondary coils constitutes one unit of the three-phase system, and these three units may be either Y-connected or Δ -connected to three-wire, three-phase service mains.

The general two-phase, three-phase transformer is greatly




Fig. 229. Vector Diagram of E.M.F. Relations for E in any Quadrant

simplified if we choose to have one of the three-phase electromotive forces in phase with one of the two-phase electromotive forces. Thus, if E , Fig. 228, is in phase with B , then E may be produced by a single secondary coil on core B ,

instead of being produced by a pair of secondary coils, one on each core.

Scott Transformer. The two-phase, three-phase transformer permits of still further simplification if the Δ -connection of the three-phase units is excluded, that is, if the three-phase units are to be adapted only for Y-connection to the three-phase mains. This ultimate simplification is realized in the Scott transformer.

The transformer shown in Fig. 227 may be converted into a Scott transformer by replacing its windings with the windings shown in Fig. 234. The two similar primary coils *A* and *B*, which are connected to the respective phases of a two-phase system, are placed on cores *A* and *B*, respectively. Coils *b*, *a*, and *c* are the three secondaries




Fig. 231. Diagram of Divided Secondary in Scott Transformer

which are Y-connected to the three-phase mains. *b* is placed on core *B* and gives the electromotive force *b*, Fig. 230. It is to be noticed that coils *a* and *c* are formed by bringing out a connection at the mid-point of one large coil, Fig. 231. *a* and *c* are placed on core *A*, Fig. 227, and give the electromotive forces *a* and *c*, Fig. 230.

The number of turns on *a* and *c* are equal. The number of turns on *b* are made to equal $\sqrt{3}$ times the turns on either *a* or *c*, i. e., if *a* and *c* each have 50 turns, *b* will have approximately 87 turns.

The points 1, 2, and 3, Fig. 230, are at the angles of an equilateral triangle. The point *O* represents the common junction point of the three terminals, one from each of the coils *a*, *b*, and *c*. The other terminals of these coils are connected to the three-phase mains represented by the figures 1, 2, and 3, Figs. 230 and 234.

Review page 124, Book II, to get a clear idea of the electromotive force and current relations in three-phase systems Y-connected.




Fig. 230. Vector Diagram of E.M.F. Relations in Three Secondaries of Scott Transformer




Fig. 232. Vector Diagram of E.M.F. Relations in Scott Transformer




Fig. 233. Y Connections for Three Secondaries of Scott Transformer for Two-Phase System

From these relations and keeping in mind the ratios of the windings of the coils in Fig. 234, it may be seen that the electromotive force a helps to push current in a receiving circuit from main 1 to main 2; while electromotive force b opposes a in this respect. Therefore, the electromotive force from main 1 to main 2 is $a-b$, as shown in Fig. 232. Similarly the electromotive force b helps to push current in a receiving circuit from main 2 to main 3, while electromotive force c opposes b in this respect. Therefore, the electromotive force from main 2 to main 3 is $b-c$, as shown in Fig. 232. Lastly the electromotive force c helps to push current in a receiving circuit from main 3 to main 1, while the electromotive force a opposes c in this respect. Therefore, the electromotive force from main 3 to main 1 is $c-a$, as shown in Fig. 232.

An inspection of Fig. 232 will show that $a-b=b-c=c-a$. Therefore, if E is allowed to represent the value of each, this discussion shows that the electromotive forces between mains 1 to 2, 2 to 3, and 3 to 1 have the common value E volts, and are 120 degrees apart in phase, provided

$$b = E \cos 30^\circ$$

and

$$a = c = E \sin 30^\circ$$

But the ratios of the windings were so proportioned that this *is* true.




Fig. 234. Complete Connections of Scott Transformer

Hence the e. m. f. s are 120 degrees apart and result in a balanced three-phase circuit.

A clear idea of the Scott transformer may now be obtained as follows: Two similar cores have similar primary coils, which are connected to the respective phases of a two-phase system. One of these cores has a secondary winding b , one end of which is connected to one of the three-phase mains (main 2, as shown in

Fig. 233), and the other end of which is connected to the middle point of the secondary winding ac , which is wound on the other core. The terminals of the winding ac are connected to the remaining two of the three-phase mains (mains 1 and 3, as shown in Fig. 233).

The entire secondary winding ac has $\frac{2}{\sqrt{3}}$ times as many turns of wire as the coil b , that is, 1.16 times as many turns. The complete connections of the Scott transformer are shown in Fig. 234.

The three-phase system requires less line copper than either the single-phase or the two-phase system to transmit a given amount of power with a given line voltage and with a given loss. Hence, for the long-distance transmission of electric power, the three-phase system is universally adopted in this country. For the local distribution of electric power, on the other hand, the two-phase system offers certain advantages. It is often the case, therefore, that two-phase alternators are used to generate alternating currents at a central station, and that two-phase currents are used for power and lighting purposes in the neighborhood of the station. When, however, power is to be transmitted to points fifteen or more miles distant, it becomes desirable, as explained above, to use the three-phase system. It is in such cases, especially, that phase transformation is used. The Niagara-Buffalo transmission is the earliest as well as one of the most extensive examples of this practice. Power is generated by large two-phase alternators at 2,200 volts. A large part of this power is distributed to factories and chemical works in the vicinity of the central power plant. A large amount of power also is transmitted to Buffalo, a distance of eighteen miles, by means of three-phase alternating currents derived from the two-phase alternators by two-phase, three-phase transformation. Scott transformers are used; and the two-phase currents at a voltage of 2,200 are stepped up to 22,000 volts, and at the same time are transformed to three-phase currents. At Buffalo, the three-phase, high-voltage currents are stepped down to about 2,200 volts, and are transformed back into two-phase currents, also by Scott three-phase two-phase transformers. The 2,200-volt two-phase currents are then distributed by feeders and service mains for lighting and power purposes throughout the city.

PRACTICAL CONSIDERATIONS

Transformer Losses. The power output of a transformer is less than its power intake because of the losses in the transformer. These losses are: (a) the iron or core losses due to eddy currents and hysteresis; and (b) the copper losses due to the resistances of the primary and secondary coils.

(a) *Iron Losses.* The iron losses are practically the same in amount at all loads. They depend upon the frequency and range of the flux density B , upon the quality and volume of the iron, and upon the thickness of the laminations. Dr. C. P. Steinmetz has found by exhaustive experiments that for ordinary sheet steel the hysteresis loss may be expressed in watts as

$$W_h = \eta V f B^{1.6} \times 10^{-7} \quad (35)$$

in which f is the frequency in cycles per second; B is the maximum flux density in the iron core, in lines per square centimeter; V is the volume of the iron, in cubic centimeters; and η is a coefficient depending upon the magnetic quality of the iron. For plain electrical sheet steel used for transformer cores the value of η is about 0.0021. For silicon-steel, now much used in constructing the cores of transformers, the value of η may be taken as about 0.00093.

The eddy current loss, in watts, is

$$W_e = b V f^2 t^2 B^2 \times 10^{-7} \quad (36)$$

in which t is the thickness of the laminations, in centimeters; and b is a constant depending upon the specific electrical resistance of the steel. For ordinary sheet steel the value of b is 1.65×10^{-11} , and for silicon-steel 0.57×10^{-11} . Insufficient insulation between laminations causes excessive eddy current loss, and results in a much higher loss than equation (36) indicates. The equation is derived on the condition of perfect insulation between laminations, a condition which is hardly ever realized in practice.

Equations (35) and (36) may be used for calculating the approximate hysteresis and eddy-current losses in any mass of laminated iron subjected to periodic magnetization, such as alternator armatures and the rotor and stator iron in an induction motor, but the losses thus calculated are usually smaller than the actual losses. It is preferable when possible to find by a wattmeter test the actual total core loss per pound of steel at different flux densities and

TABLE VII
Transformer Efficiencies, Losses, Etc.

KV-A.	WATTS LOSS		PER CENT EFFICIENCY				PER CENT REGULATION				* Exciting Current
	Iron	Copper	Full Load	¾ Load	½ Load	¼ Load	100 % P. F.	90 % P. F.	80 % P. F.	60 % P. F.	
½	15	13	94.7	94.4	93.2	88.7	2.62	3.21	3.28	3.16	8.0
1	20	24	95.8	95.7	95.1	92.0	2.42	3.03	3.12	3.04	5.5
1½	25	35	96.0	96.0	95.5	92.7	2.36	2.96	3.07	3.00	4.0
2	30	42	96.5	96.5	96.2	93.8	2.12	2.76	2.88	2.86	3.6
2½	33	51	96.8	96.8	96.5	94.5	2.08	2.71	2.83	2.83	3.3
3	34	64	96.8	97.0	96.8	95.2	2.16	2.79	2.91	2.88	3.0
4	40	75	97.2	97.3	97.1	95.7	1.90	2.77	3.00	3.12	2.5
5	45	93	97.3	97.5	97.3	96.1	1.90	2.76	2.99	3.11	2.3
7½	62	125	97.6	97.7	97.6	96.4	1.70	2.60	2.84	3.00	2.2
10	80	148	97.8	97.9	97.7	96.5	1.51	2.42	2.68	2.89	1.9
15	105	212	97.9	98.0	97.9	97.0	1.44	2.36	2.63	2.85	1.6
20	131	268	98.0	98.1	98.0	97.1	1.39	2.51	2.87	3.21	1.5
25	147	319	98.2	98.3	98.2	97.4	1.33	2.45	2.82	3.17	1.3
30	163	374	98.2	98.4	98.3	97.6	1.32	2.45	2.82	3.16	1.2
37½	197	433	98.3	98.4	98.4	97.7	1.20	2.34	2.72	3.09	1.2
50	240	550	98.4	98.6	98.5	97.9	1.15	2.29	2.68	3.07	1.0

*In per cent of full load current.

frequencies. Curves may then be plotted one for each frequency, using total core loss in watts per pound as abscissas, and B as ordinates.

(b) *Copper Losses.* The copper losses, in watts, are

$$W_c = R'I^2 + R''I'^2 \tag{37}$$

This loss is nearly zero when the transformer is not loaded; it increases with the square of the current; and becomes excessive when the transformer is greatly overloaded.

Transformer Efficiency. The ratio *power output ÷ power intake* is called the *efficiency* of a transformer.

Table VII, shows the efficiencies, losses, and regulation of a recent series of combined core- and shell-type transformers designed and manufactured by a large American company. These transformers are designed for a frequency of 60 cycles per second and primary voltages of 1,100 or 2,200 volts, according to whether the two

halves of the primary coil are connected in parallel or in series. The secondary voltages are 110 or 220 volts.

Fig. 235 shows graphically the relation between the efficiency and the output for a 7.5-kilowatt, core-type transformer designed for primary voltages of 1,040 and 2,080, and secondary voltages of 104 and 208, and a frequency of 60 cycles per second. The core loss is 86.5 watts and the total copper loss at full load is 117.8 watts. The high efficiency throughout a wide range of load is worthy of note and is typical of all well-designed transformers.

Fig. 236 shows graphically the various losses and the efficiency of a Westinghouse air-blast transformer rated at 550 kilowatts used




Fig. 235. Graphic Relation between Efficiency and Output for a Coil Type Transformer

to step up from 500 volts to 10,500 volts at a frequency of 25 cycles per second (3,000 alternations per minute).

In Fig. 236, the curve representing the iron loss is plotted as a horizontal straight line because the iron loss for a given transformer is practically constant for all loads. The curve representing the copper loss is a parabola.

The efficiency of a given transformer is a maximum at that load for which the iron loss is equal to the copper loss. This load is evidently the abscissa of the point at which the iron-loss line intersects the copper-loss curve. As seen in Fig. 236, the maximum efficiency occurs at about 101 per cent of full load; at any other load (for the given transformer) the efficiency will be less than at 101 per cent of full load.

The transformer output (non-inductive receiving circuit) is $E''I''$. The internal loss is $W_h + W_e + W_c$, so that the intake is $E''I'' + W_h + W_e + W_c$, and the efficiency is

$$\text{efficiency} = \frac{E''I''}{E''I'' + W_h + W_e + W_c} \quad (38)$$

A complete calculation of efficiency is worked out on page 314.

All-day Efficiency. Usually a transformer is connected to the mains continuously, and current is taken from the secondary for a few hours only, each day. In this case the iron loss is incessant and the copper loss is intermittent. The total work given to the transformer during the day may greatly exceed the total work given out by it, especially if the continuous iron losses are not reduced to as




Fig. 236. Efficiency Curves for a Westinghouse Air-Blast Transformer

low a value as possible. The ratio *total energy given out by the transformer ÷ total energy received by the transformer during the day* is called the “all-day efficiency” of the transformer. In other words it is the ratio $\frac{\text{total watt-hours output}}{\text{total watt-hours input}}$ during the day. The all-day efficiency is given by the formula

$$\text{all-day efficiency} = \frac{E''I'' \times t}{E''I'' \times t + (W_h + W_e) \times 24 + W_c \times t} \quad (39)$$

in which *t* is the number of hours during the day of 24 hours that the transformer is loaded, and *I''* is the average current delivered by the secondary while the transformer is loaded. The other symbols have the same significance as on pages 262–264.

Since the iron loss of a given transformer is continuous as long as the transformer is connected to the primary supply mains, it follows that to obtain a high all-day efficiency, it is necessary to use a transformer whose iron loss is as small as possible. In general, if a transformer is to be operated at light loads the greater part of the day, as is the case in electric lighting service, it is much more economical to use a transformer designed for a small iron loss than for a small full-load copper loss. In very small transformers, the iron and the copper losses are made about equal, but for outputs of about 5 kilowatts and upwards, the iron loss is often made only about one-half as great as the full-load copper loss. This is illustrated by the data in the second and third columns in Table VII.

On the other hand, in cases where transformers are to be used to supply a load of induction motors, and the conditions are such that the transformers are operated at or near full load during most of the day, it is more economical to use transformers designed to give equal iron and copper losses at full load.

In general, a given transformer works at the maximum efficiency when it is operating at a load such that its iron loss is equal to its total copper loss.

Transformer Regulation. The secondary terminal voltage of a transformer falls off in value with increasing load, and rises with decreasing load. The rise of secondary terminal voltage from rated non-inductive load to no load (at constant primary applied terminal voltage), expressed in per cent of the secondary terminal voltage at rated load, is called the *regulation* of a transformer.

Example. A certain 5-kw. transformer gave a secondary terminal voltage of 200 volts at rated non-inductive load; when the load was reduced to zero, the voltage rose to 203 volts.

In accordance with the above definition, the regulation of this transformer is

$$\frac{(203-200)}{200} \times 100 = 1.5 \text{ per cent}$$

The regulation of the average distributing transformers on the market at present varies from about 1 per cent to 3.5 per cent, and when operated on power factors as low as 60 per cent, the regulation in some cases is as high as 4 per cent. In incandescent lighting it is especially important to have transformers with a low regulation, otherwise the voltage at the lamps will fluctuate excessively as the

load changes. This means unsatisfactory illumination for the consumer, and more frequent lamp renewals for the lighting company. Thus, for lighting work it is important to specify a low regulation.

The regulation of a transformer is lower when used for supplying a non-inductive load (such as incandescent lamps), than when supplying an inductive load (such as induction motors). For a given kind of load the regulation of large transformers is lower than for small sizes. These matters are clearly brought out by a careful study of the values of regulation given in Table VII. The method of calculating regulation is explained on page 313.

Practical and Ultimate Limits of Output. When the secondary current of a transformer is increased, the secondary electromotive force drops off, and the power output increases with the current, reaching a maximum as in the case of the alternator. This maximum power output is the ultimate limit of output of the transformer. Practically, the output of a transformer is limited to a much smaller value than this maximum output, (a) because of the necessity of cool running; (b) because in most cases it is necessary that the secondary electromotive force be nearly constant; and (c) because the efficiency of a transformer is low at excessive outputs.

Small transformers have relatively large radiating surfaces; and in such transformers the requirements of a small (good) regulation, as a rule, determine the allowable output.

Large transformers, on the other hand, have relatively small radiating surfaces, and their allowable output is limited by the permissible rise in temperature. Some transformers ranging in rated output from 100 to 1,250 kilowatts are provided with air passages through which air is made to circulate by a fan. Transformers which are not cooled by an air blast up to about 500 kilowatts capacity are submerged in oil, which, by convection, carries heat from the transformer to its enclosing case, where it is radiated. Very large transformers are not only submerged in oil, but are also water-cooled.

Rating of Transformers. A transformer is rated according to the power it can deliver continuously to a non-inductive receiving circuit without undue heating; and the ratio of transformation, together with a specification of the frequency and effective value of the primary electromotive force to which the transformer is adapted, are also given by the manufacturer.

In order to secure uniformity in the rating of transformers by manufacturers, the American Institute of Electrical Engineers recommends the following rules concerning the allowable rise of temperature:

(1) In transformers for *continuous service*, the temperature rise should not exceed 50°C. as measured by change of electrical resistance of primary and secondary coils and by thermometer in other parts.

(2) In transformers intended for *intermittent service*, or not operating continuously at full load, but continuously in circuit, as in the ordinary case of lighting transformers, the temperature elevation above the surrounding air temperature should not exceed 50°C. as measured by resistance in electric circuits, and by thermometer in other parts, after the period corresponding to the term of full load. In this instance, the test load should not be applied until the transformer has been in circuit for a sufficient time to attain the temperature elevation due to core loss. With transformers for commercial lighting, the duration of the full load test may be taken as three hours, unless otherwise specified.


The *over-load rating* of a transformer is recommended to be 25 per cent for two hours; and it is based upon an allowable increase of temperature of 15° C. above that specified for full load, as given above. This extra rise of temperature is to be measured after the transformer has been operating for two hours on 25 per cent over-load, the transformer having previously acquired the temperature corresponding to full-load continuous operation.

When, however, transformers are to be used with other apparatus for which an over-load capacity in excess of 25 per cent is guaranteed, the same guarantee should apply to the transformers.

Abnormal Conditions of Operation. Transformers are frequently used under conditions departing more or less widely from the conditions specified by the manufacturer in regard to values of primary and secondary voltages, frequency, and current output. Thus, if a transformer is used with a primary applied voltage in excess of the rated value (frequency being unchanged), the core flux will be increased according to equation (34) and the core losses will be increased according to equations (35) and (36).

If, on the other hand, a transformer is used with a frequency less than the rated frequency (the voltage applied to the primary being unchanged), the core flux will be increased according to equation (34), and the hysteresis loss in the core will be increased according to equation (35); whereas, the eddy-current loss is unchanged.





250 K.W. 720 R.P.M. NATIONAL MOTOR-GENERATOR SET
With Starting Motor.

736 A

The increase of core loss due to increase of primary applied voltage, or to decrease of frequency, or to both, may be compensated for by reducing the allowable current output, and thereby reducing the copper loss, in order that the total heating of the transformer may not exceed the normal amount.

Examples. A given transformer is rated at 5 kilowatts, and is designed to take current from 1,100-volt mains at a frequency of 60 cycles per second. Under these conditions hysteresis loss W_h , eddy current loss W_e , and copper loss W_c , will be called normal.

(a) The transformer is loaded so that the output is 6 kilowatts at the rated electromotive force and frequency. Find W_c in terms of normal.

(b) The transformer is used at rated electromotive force, but at a frequency of 75 cycles per second. Find W_h and W_e each in terms of normal.

(c) The transformer is used at rated frequency, but with primary electromotive force of 1,500 volts. Find W_h and W_e each in terms of normal.

(d) The transformer is used on primary electromotive force of 1,500 volts. Find f for which W_h is normal.

(e) With primary electromotive force of 1,500 volts, what load would give normal W_c ?

Solutions. (a) Increasing the output in the ratio 5 to 6, increases both primary current and secondary current in the same ratio and, therefore, increases I^2R' and I'^2R'' in the ratio of 5^2 to 6^2 . Therefore, the total copper loss becomes $\frac{36}{25} = 1.44$ times the normal copper loss.

(b) Increasing the frequency in the ratio 60 to 75 decreases the flux-density \mathbf{B} in the same ratio, namely, 75 to 60. Hence, the hysteresis loss per cycle is decreased in the ratio $75^{1.6}$ to $60^{1.6}$, and the total hysteresis loss is $\frac{75}{60} \times \frac{60^{1.6}}{75^{1.6}}$ or $\left(\frac{60}{75}\right)^{0.6}$, or 0.87. Therefore, the total hysteresis loss at the increased frequency is 0.87 times the normal hysteresis loss.

From equation (36), the eddy current loss is proportional to $f^2 \mathbf{B}^2$. In the case under consideration, f is increased and \mathbf{B} is decreased in the same ratio, so that the product $f^2 \mathbf{B}^2$ remains unchanged. Hence, the eddy-current loss in a given transformer is independent of the frequency with given primary applied voltage.

(c) Increasing the primary voltage in the ratio 11 to 15 increases the flux-density \mathbf{B} in the same ratio. Therefore, the hysteresis loss is increased in the ratio $\left(\frac{15}{11}\right)^{1.6} = 1.64$; and the eddy current loss is increased in the ratio $\left(\frac{15}{11}\right)^2 = 1.86$. That is, the hysteresis loss becomes 1.64 times its normal value; and the eddy current loss becomes 1.86 times its normal value.

(d) The hysteresis loss is proportional to $f \mathbf{B}^{1.6}$; and \mathbf{B} is proportional to $\frac{E'}{f}$; therefore, the hysteresis loss is proportional to $f \times \left(\frac{E'}{f}\right)^{1.6}$ or to $\frac{E'^{1.6}}{f^{0.6}}$.

This ratio $\frac{E'^{1.6}}{f^{0.6}}$ must have the same value under the normal conditions as under

the new conditions, if the hysteresis loss is to be the same. That is

$$\frac{(1,100)^{1.6}}{(60)^{0.6}} = \frac{(1,500)^{1.6}}{x^{0.6}}$$

or

$$(1,100)^{1.6} \times x^{0.6} = (60)^{0.6} \times (1,500)^{1.6}$$

or taking logarithms of both sides, we have

$(1.6 \times \log 1,100) + (0.6 \times \log x) = (0.6 \times \log 60) + (1.6 \times \log 1,500)$; or, $(0.6 \times \log x) = (0.6 \times \log 60) + (1.6 \times \log 1,500) - (1.6 \times \log 1,100)$; from which we find x equal to 137 cycles per second.

(e) The copper loss W_c has normal value when the primary and secondary currents have normal value. Therefore, when the primary applied voltage is increased in the ratio 11 to 15, the output increases in the same ratio, the current and W_c being normal. Therefore, the output is $\frac{15}{11} \times 5$ kw., or 6.82 kilowatts, to give normal W_c with a primary applied voltage of 1,500 volts.

COMMERCIAL TYPES OF TRANSFORMERS

Transformers may be classified, according to the relative disposition of the iron and copper, into *core-type transformers* and *shell-type transformers*. The distinction between these two types of transformer may be understood by referring to Figs. 237 and 267.




Fig. 237. Core-Type of Transformer Assembled with Case Removed

In the core type, Fig. 237, it will be seen that the iron core is almost entirely surrounded by the copper windings, while in the shell type, Fig. 267, the coils are almost entirely surrounded by the sheet-iron laminations, forming a shell.

There has been much discussion as to the relative merits of

the shell and core types, some manufacturers going so far as to claim exclusive advantages for one or the other. The fact is that no general conclusion can be drawn as to which type is better, for each possesses inherent characteristics which specially adapt it to certain conditions. A brief comparison of these characteristics will aid in determining which type to use for specified conditions of service, size, voltage, and the like.

The core type has relatively a lighter core of smaller sectional area but a greater length of magnetic circuit, while the copper is relatively heavier, containing more turns, although of shorter mean length. The core type is more easily wound as cylindrical formed coils may be used, and the coils are more accessible and expose more surface to radiation. The core type, with its relatively large winding space, is better adapted for high voltages which require many turns and large space for insulation, smaller currents and, therefore, small wires, and higher frequencies with low magnetic flux densities.

The shell type, on the other hand, is particularly suited for transformers of moderate voltage, requiring few turns and little insulation, large currents, and low frequency with corresponding magnetic flux.

The net result is that manufacturers generally adopt the core type for transformers of small capacity and high voltage, and the shell type for large transformers, even up to 150,000 volts.

Substantial advancement in transformer design has been made in the past few years, notably in the combination of the advantages of both the core and the shell types in one transformer, in the use of silicon-steel for the laminations, thus greatly reducing the core loss, in the use of better insulating materials and methods, and in more effective methods of cooling. With these improved materials and methods it is even feasible to build reliable transformers with outputs up to 14,000 kilovolt amperes, and for voltages up to 150,000, or higher.

Core Type. Fig. 237 shows a complete core-type transformer without its case; Fig. 238 shows the complete core built up of thin




Fig. 238. Standard Form of Laminated Transformer Core




Fig. 239. Core with Upper Yoke Removed, Showing One Coil in Position

sheet steel strips, or stampings. The two upright portions of the core upon which the wire coils are placed, as shown in Figs. 237, 239,




Fig. 240. Both Transformer Coils in Position, Showing Laminated Strips Which Form the Upper Yoke of Core

and 240, are called the *limbs* of the core. The short horizontal parts of the core that do not have windings of wire upon them are called *yokes*. These yokes serve to complete the magnetic circuit, and they are made just long enough to give room for the coils, as shown in Fig. 241. Fig. 239 shows the core with its upper connecting yoke removed to permit of the slipping of the coils into position on the core; the left-hand limb of the core is shown wrapped with a thick layer of insulating material in order to prevent electrical contact between the wire of the coil and the iron of the core. Fig. 240 shows the coils in place, and a pile of loose sheet-iron stampings which are used to form the upper connecting yoke.




Fig. 241. Section Through Core-Type of Transformer

Fig. 241 is a sectional view of the completed core and coils; and Fig. 242 is a sectional view of the complete transformer enclosed

in a cast-iron case, which is usually filled with oil. Half of the primary coil and half of the secondary coil also is placed upon each limb of the core, as shown by the sectional view, Fig. 241. The terminals of each half of the primary (fine-wire) coil are connected to binding screws on a porcelain connection board mounted on top of the transformers inside the case, as shown at the right in Fig. 242. The terminals of each half of the secondary (coarse-wire) coil are passed through porcelain bushings to the outside of the case, as shown at the right in Fig. 242. The half coils of the primary may be connected in parallel or in series according




Fig. 242. Section Through Commercial Core-Type of Transformer

to the value of the voltage applied to the primary; and the half coils of the secondary may be connected in parallel or in series according to the desired value of the secondary voltage, as explained on page 244.




Fig. 243. Plan of Transformer Showing Strap Connections for Arranging Primaries in Series or Parallel

Fig. 243 is a top view of the transformer with the cover of its case removed showing the terminals of the secondary coils, and the

porcelain connection-board to which the terminals of the primary coil are connected. The change from series to parallel connection of the halves of the primary coils, is effected by means of the copper connecting straps *S S*.

The style of core-type transformer illustrated in Figs. 237 to 242 is adopted by several manufacturers for transformers of small output. The style of core-type transformer adopted by the General Electric Company for larger outputs up to 350 kilowatts, is illustrated in Figs. 244 to 248, which show a high voltage core-type

transformer designed for 60 cycles. These transformers are submerged in tanks of oil, one of which is shown in Fig. 248, and which are made with a cast-iron base and sides of heavy steel with deep corrugations to facilitate cooling of the tank by radiation. Fig. 246 shows the arrangement of the coils on the core; it also shows the passages between the core and the inside coil, and between the two coils, for the circulation of the oil.




Fig. 244. General Electric Core-Type Transformer Partly Assembled

Oil is a better heat-conducting medium than air; it carries heat from a transformer to the containing case much better than air, so that a transformer in oil will show a much lower temperature. The use of oil, moreover, preserves the insulation, keeping it soft and pliable, and preventing oxidation

by air; consequently, its use is advantageous in producing proper conditions to maintain uniform core loss and a superior insulation. Furthermore, oil is itself a very good insulator having the valuable property common to all liquid insulators, that it is not permanently damaged by a puncture caused by lightning; for example, in this case the resistance of the oil is only momentarily broken down, the oil immediately flowing into the break and sealing the insulation.

Another variety of the core type is that adopted by the Crocker-Wheeler Company in their "remek-type" transformer. The core punchings are shown in Fig. 249. Each lamination consists of a

core and yoke punching, which are punched simultaneously from the whole sheet by a compound die. In assembling the transformer, care is taken to get the core and yoke punchings back into the same




Fig. 245. General Electric Core-Type Transformer with Tank Removed

relative position as before punching, in order to secure the lowest possible magnetic reluctance of the joints, and hence a small magnetizing current. The laminations when assembled are held to-

gether by iron end plates bolted together and the core portions are securely clamped together and to the yokes, as shown in Fig. 250.




Fig. 246. Coils and Core of General Electric Transformer Showing Oil Ducts

The core, as seen, constitutes a double magnetic circuit, the magnetic flux due to the windings on the central core dividing on passing into the yokes, half on each side. The yoke laminations are made wider than one-half the width of the central core, in order to reduce the flux density in them, thereby reducing the core loss and the magnetizing current.

The windings consist of former-wound coils which surround the core as illustrated in Fig. 251. The high voltage winding is placed between the two halves of the low voltage winding in order to reduce magnetic leakage

and thus improve regulation.

Vertical ducts are provided between the windings, and between the core and windings, as may be seen in Fig. 251. This arrangement is to insure a free circulation of the oil in which the transformer is immersed and facilitates dissipation of the heat by radiation and convection.

The assembled transformer core and coils ready to be placed in the oil-filled tank are shown in Fig. 252. The high voltage termi-




Fig. 247. Specimen Coils for General Electric Core-Type Transformer

nals are shown connected to a terminal board in front, and the four secondary terminals, two for each coil, are shown in the rear.

These "remek-type" transformers are wound for a primary voltage of 2,200, secondary voltages of 220 and 110, and are built in sixteen sizes ranging from 0.6 to 50 kilowatts.

Fig. 253 shows a 10-kw. combination core- and shell-type




Fig. 248. General Electric Core-Type Transformer Completely Assembled Showing Deep Corrugations to Facilitate Cooling

transformer removed from its tank. It is called the *distributed core type* (type H form K) by its makers, the General Electric Company, although it resembles the shell rather than the core type.

The primary and the secondary coils are wound on formers of cylindrical shape, and placed on the center limb only. They are separated from each other and from the core by spacing blocks, thus forming ducts and passages for free circulation of the oil with which the containing tank is filled. Fig. 254 shows clearly the disposition of the coils, mica insulation, and oil ducts, with respect to the central limb.

The core, as shown in Fig. 255, contains four magnetic circuits in parallel, each circuit consisting of a separate core similar in general outline to that used in the simple core type. One limb of each magnetic circuit is built up of two different widths of punchings, forming a cross-section such that when the four circuits are assem-




Fig. 249. Core Punchings for Crocker-Wheeler "Remek-Type" Transformer

bled together they interlock to form a common central limb upon which the primary and the secondary coils are placed.

The four remaining legs consist of punchings of equal width. These occupy a position surrounding the coil at equal distances from the center, on the four sides, forming a channel between each leg and coil, thereby presenting large surfaces to the oil and allowing it free access to all parts of the winding.

The punchings of each size of transformer are all of the same length, assembled alternately, and forming two lap joints equally distributed in the four corners of the core, thereby giving a magnetic circuit of very low reluctance.

This type of construction combines the best features of both shell and core types, namely a short mean length of turn in the windings, and a short length of magnetic circuit in the core.




Fig. 250. Assembled Core Showing Method of Clamping




Fig. 251. Method of Assembling Coils Sawing Oil Ducts




Fig. 252. Assembled "Remek" Core and Coils




Fig. 253. General Electric Combination Core and Shell Type Transformer




Fig. 254. Details of Core and Coils Showing Oil Ducts




Fig. 255. Plan of Assembled Core and Coils Showing Four Magnetic Circuits in Parallel




Fig. 256. Westinghouse Combination Shell and Core Type




Fig. 257. Assembled Coils for Westinghouse Transformer

Another example of the combined shell- and core-type of transformer is the distributing transformer (types S and SA) of the West-




Fig. 258. Section through Westinghouse "Type S" Transformer




Fig. 259. Part Section through Westinghouse Transformer




Fig. 260. Pancake Coil for Shell-Type Transformer




Fig. 261. Pancake Coil Wound with Tape

inghouse Electric Company. These transformers are almost identical in form and design with the "type H form K" transformers just described.

Fig. 256 shows the core and coils and terminals of the "type S" transformers removed from the case, and a general view of the case. Fig. 257 shows the appearance of the assembled coils and leads of 10- and 15-kw. transformers, with the ventilating ducts. The figure shows the high voltage winding mounted concentrically between two low voltage windings, which arrangement reduces magnetic leakage and thus improves "regulation."

As illustrated in Fig. 256, separate high and low voltage porcelain terminal blocks are mounted upon extensions of the upper end frame, and are thus kept well apart to prevent mistakes in making electrical connection between the high and low voltage coils.

Fig. 258 is a section through a $\frac{1}{2}$ -kw. "type S" transformer, and shows the distribution of the windings in layers, the high voltage coils being placed between two sections of low voltage coils. Fig. 259 is a section through a 50-kw. transformer and shows the large oil ducts arranged between sections of the high voltage winding. The angle irons used to clamp the laminations together are shown at the top and bottom. These distributing "type S" transformers are built in sixteen sizes from $\frac{1}{2}$ to 50 kilowatts, and for the standard primary voltages of 2,200 and 1,100, and secondary voltages of 220 and 110. Standard frequencies are 25, 40, and 60 cycles.

Shell Type. In shell-type transformers the coils, both primary and secondary, are usually wound in pancake form on formers, as shown in Figs. 260 to 263. The coils in small transformers are wound with round wire, but in the larger sizes flat rectangular copper strip is used with one turn per layer, in many layers, Figs. 260 and 262. The insulation between turns consists of paper, mica, or varnished cambric, or all three together, according to the voltage




Fig. 262. Pancake Coil Showing Use of Insulated Flat Strips




Fig. 263. Method of Binding up Pancake Strip Coils

and other conditions. The thin pancake coils are then treated with an insulating compound and wound with a number of layers of tape according to the voltage for which they are designed, each layer being given several coats of insulating varnish baked on in ovens. The coils are then assembled into groups of two or more sections, Fig. 263, and the groups into complete windings, the primary and the secondary being intermixed or sandwiched in order to





Fig. 264. Partially Assembled Air Blast Shell-Type of Transformer

reduce magnetic leakage. Between the various groups suitable insulating barriers are interposed.

In transformers for high voltages used for transmission of power, the insulation of a considerable length of the conductor nearest the terminal leads is heavily reinforced. This is a very important precaution, as the extra dielectric strength of the insulation of these end turns is a safeguard against break-downs which might otherwise occur due to the excessive voltages from lightning discharges or other surges to which transmission lines are unfortunately subjected.



FIVE 3,000 K. W. BULLOCK WATER-WHEEL TYPE GENERATORS
Bullock Electric Manufacturing Co.



The various groups of windings are encased in a box-like structure which, while serving as an electrical and a mechanical protection, is so arranged that it does not obstruct the air or oil ducts which are provided between the various coil sections. The windings are then set up vertically in the bottom frame and the magnetic circuit is built up piece by piece around them in the form of rectangular sheets of steel, Fig. 264. In building up the core out of the stampings care is taken to break joints in successive layers. The top frame is then put on and tightly clamped to the bottom, thus compressing and holding the core. After the addition of connection board, leads, insulating bushings, and the like, the transformer is ready for its casing or tank.




Fig. 265. Sectional View of Fort Wayne Shell-Type Transformer

Fig. 264 shows a large General Electric air-blast, shell-type transformer at that stage of construction where the core stampings are being built up around the coils, the coils being protected by thick strips of insulating material. In this air-blast transformer, air passages or ducts are provided between the layers of the coils, and at intervals, between the core stampings, as shown in the figure. The air for cooling the transformer is admitted at the base, and passes vertically through the ducts in the coils. Air is also admitted to the air ducts in the core through a damper on one side of the transformer, and escapes through the perforations in the casing on the opposite side.



Fig. 266. Sample Coils for Fort Wayne Transformer

Figs. 265 to 268 give a general view and structural details of a 15-kw. shell-type transformer manufactured by the Fort Wayne Electric Works. The shape of the core stampings is shown in Fig. 265, which is a section through the transformer. The secondary winding, as seen in the figure, is subdivided into four sections, and the primary into two. The order of the sections as arranged in the "window" of the core is: One-fourth total secondary turns, one-half total primary turns, one-fourth secondary turns, one-fourth




Fig. 267. Assembled Core and Coils for Fort Wayne Transformer

secondary turns, one-half primary turns, and one-fourth secondary turns. This intermixing the various sections reduces greatly magnetic leakage, and thus improves regulation.

Fig. 266 shows a group of pancake coils insulated and taped ready to be assembled.

Fig. 267 shows the core and coils assembled. The four leads on the left are from the secondary coils, and the six leads on the right are the four primary terminals to which are added two extra taps.

Fig. 268 is a top view of the transformer with the cover re-

moved and shows how the leads are brought up to the connection board and out of the case. Each of the two primary sections is provided with what is called a ten per cent tap. That is, while the normal voltage for which each primary section is wound is 1,100 volts, by using the ten per cent taps, it is possible to change the ratio of transformation, and obtain ratios of 20 : 1, 19 : 1, 18 : 1, 10 : 1, 9.5 : 1, 9 : 1, 5 : 1, and 4.5 : 1, according to the connections of the primary and the secondary sections, whether in series or in parallel. The advantage of these ten per cent taps is that it permits a transformer to be used near the station where the voltage is high or at the end of a feeder where the voltage may be five or ten per cent lower, by simply changing the electrical connections at the terminal board shown in Fig. 268.




Fig. 268. Top View of Fort Wayne Transformer with Cover Removed Showing Arrangement of Lead Wires

Figs. 269 to 271 show constructive details peculiar to very large shell-type transformers which are usually of the water-cooled type. Fig. 269 represents a General Electric transformer with its containing tank removed to show the method of suspending the core and cooling coils from the cover. The cooling coils are of lap-welded wrought-iron pipe with electrically welded joints. Water is kept circulating through these coils in order that the oil filling the case and surrounding the transformer may be kept cool while the transformer is in operation. The core and the coils are first assembled after which they are tightly clamped and suspended from the cover

by means of heavy bolts, as shown in Fig. 269. The completed transformer filled with oil may be easily lifted and moved about by means of the heavy lifting lugs on the upper side of the cover.

Some of the advantages of this cover suspension construction are: (a) all coil terminals are brought out through the cover and,




Fig. 269. General Electric Shell-Type Water-Cooled Transformer—Tank Removed and Cooling Coils Shown in Section

therefore, are not interfered with when the transformer is removed from its tank. (b) The terminal board at the top is accessible through openings in the cover and changes in electrical connection can be made by simply raising the transformer a few feet out of the tank by a crane, without drawing off any oil. Inspection of all parts is also easily and quickly made. (c) There being but a few bolts to loosen, it is easy to remove the transformer from the tank,

or to lift tank and all by means of the lugs on the cover. (d) With this construction there is no need of lowering crane hooks or chains into the tank, thereby avoiding possible danger to insulators and to coil insulation.

The construction of water-cooled transformers is, in mechanical




Fig. 270. General Electric Water-Cooled Transformer Showing Coils in Position

and electrical design, similar to the oil-cooled transformers, the only difference being in the tank. In the water-cooled type the tank is built up of heavy boiler plate iron riveted to a cast-iron base. All joints on the tank are heavily riveted and thoroughly caulked to make them oil tight.

Three-Phase Transformers. During the past few years the size of transformer units has been steadily increasing in response

to the demand from the power companies engaged in generating and transmitting electrical power on an enormous scale. Long-distance transmission of electrical power is most economically carried out by the three-phase system, which is the standard prac-




Fig. 271. General Electric Water-Cooled Transformer Completely Assembled

tice. These conditions have caused a demand for large three-phase transformers, which under certain conditions are to be preferred to three single-phase transformers of the same aggregate capacity, but no general rule can be given as to the relative value of the two types.

The advantages of the three-phase transformer over a group of three single-phase transformers of the same total capacity are:

- (1) Lower cost.
- (2) Higher efficiency
- (3) Requires less floor space.
- (4) Has less weight.
- (5) Connections and outside wiring very much simplified as only three primary and three secondary leads are usually brought out.
- (6) Lower transportation charges and cost of installation.
- (7) Presents a symmetrical and compact appearance.

The disadvantages of the three-phase type are:

- (1) Greater cost of spare units.
- (2) Greater derangement of service in case of break-down.
- (3) Greater cost of repairs.
- (4) Reduced capacity obtainable in self-cooling units.
- (5) Greater difficulty in bringing out taps for a large number of voltages.

In general single-phase transformers are preferable where only one transformer is installed and where the expense of a spare transformer would not be warranted. In such installations the burnout of one phase of a three-phase unit would cause considerable inconvenience for the reason that the whole transformer would have to be disconnected from the circuit before repairs could be made. If, however, single-phase transformers are used, the damaged transformer can be cut out with a minimum amount of trouble, and the other two transformers can be operated at normal temperature open Δ - (or \mathbf{V} -) connected at 58 per cent of the normal capacity of the group of three transformers, until the third unit can be replaced.

With a three-phase shell-type transformer, if both the primary and the secondary are Δ -connected, trouble in one phase will not prevent the use of the other two phases in open delta. By short-circuiting both primary and secondary of the defective phase and cutting it out of circuit, the magnetic flux in that section is entirely neutralized. This cannot be done, however, with any but Δ -connected transformers. Where a large number of three-phase transformers can be used, it is generally advisable to install three-phase units.

Three-phase transformers are made both of the core and the shell types, according to circumstances. Thus, Fig. 272 shows a three-phase core-type transformer with its case removed, made by the General Electric Company. A three-legged core is used, each leg being wound with the primary and the secondary coils of one

phase. The magnetic circuit, arranged as shown in Fig. 226, is explained on page 47. Since the weight of the core and the coils is greater than in the single-phase transformers, the core-clamps and other mechanical parts are made larger and stronger while two bolts on each side, instead of one, are used to support it from the cover. Three leads only are brought out of the cover on the primary and the secondary sides, all connections being made on the inside of the tank.

The General Electric Company has built three-phase transformers of the shell type up to 10,000 kilowatts capacity, for 100,000 volts primary and 11,000 volts secondary, and a frequency of 60 cycles. They are now building them for an output of 14,000 kilowatts.




Fig. 272. General Electric Three-Phase Core-Type Transformer—Case Removed

Fig. 273 shows a three-phase shell-type of transformer removed from its tank. It is rated at 1,800 kilovolt-amperes, 48,000 volts and 25 cycles. This transformer, which is built by the Westinghouse Company, is designed to be placed in a tank filled with oil which is kept cool by water circulating in a coil of brass tubing surrounding the transformer and below the surface of the coil.

Cooling of Transformers.

Transformers of moderate size have large radiating surface compared with their losses. Such transformers, therefore, can radiate the heat due to core losses and copper losses without excessive rise of temperature.

A transformer which is twice as large as a given transformer in length, in breadth, and in thickness, has eight times as much volume but only four times as much radiating surface as the latter. The large transformer having nearly eight times the losses and four times the radiating surface of the smaller transformer would rise to a much higher temperature than the smaller transformer in

order to radiate the heat due to its losses. Large transformers must, therefore, be provided with special means for cooling. It is much cheaper to provide special cooling devices than to attempt to make the transformer large enough to keep cool by natural radiation.




Fig. 273. Westinghouse Three-Phase Shell-Type Transformer—Tank Removed

Various methods of cooling are adopted in practice, according to which the following classification of transformers may be made:

- Self-cooling dry transformers.
- Self-cooling oil-filled transformers.
- Transformers cooled by forced current of air.
- Transformers oil-filled cooled by forced current of water.

Self-Cooling Dry Transformers. These transformers are usually of small output, and no special means of cooling is provided, the

natural radiation being depended upon for cooling. Some larger ones up to 5- or 10-kilowatt capacity have been made in this way, but they are heavier and more expensive than if oil-cooled.

Self-Cooling, Oil-Filled Transformers. Transformers of this type are very generally employed, the entire core and coils being immersed in oil. Transformers are practically always enclosed in a cast-iron or sheet-steel case, and this is simply filled with a special high-grade mineral oil. No increase in cooling surface is thereby secured, but the natural circulation of the oil tends to equalize the temperature of the various parts, and carries the heat to the case, from which it is radiated. In most self-cooling types, the case is made with external ribs or corrugations to increase its radiating surface. The large volume of oil also absorbs considerable heat, so that the temperature rises more slowly. Hence, for moderate periods of operation, up to 3 or 4 hours—which is ordinarily sufficient in electric lighting—the maximum temperature would not be reached. Another advantage gained by this arrangement is an improvement in insulation. This is due to the high insulating qualities of the oil itself, and to the fact that a disruptive discharge takes place through it much less readily than through the air that it displaces, distances being the same. This arrangement possesses, moreover, the power of self-repairing any break in the insulation. If ordinary materials, such as cloth or mica, become punctured, they lose their insulating properties, and the apparatus cannot be used until the fault is repaired, which ordinarily involves considerable time and expense. On the other hand, if oil is punctured, it tends to close in and repair the break, unless the discharge lasts so long that a charring occurs, which may make a permanent conducting path.

The chief objection to the use of oil is the danger of fire. If a short-circuit occurs inside the transformer, the oil may be thrown out and ignited at the same time; or a fire started in any other way might be made far more disastrous than it would otherwise be owing to the presence of a large quantity of oil. In this way, several power plants have been destroyed by fire with large loss of property. There is no special precaution that will entirely eliminate this risk; but care in locating such transformers, in avoiding overheating, and in protecting the machines by effective lightning arresters, will reduce the hazard.

Oil-cooled transformers can be built for any voltage and to almost any size, although the economical maximum limit in output is reached at about 500 kilowatts.




Fig. 274. Bank of Air-Blast Transformers Showing Arrangement of Air Chamber

Air-Blast Transformers. These transformers are now commonly employed, and have advantages over those of the oil-cooled type, in that the danger of fire is avoided, and the cooling effect can be regulated in accordance with working conditions. They are so constructed that air can circulate through and around the core and coils, the ventilation being forced by a blower driven by a motor. A transformer of 100-kw. capacity requires about 450 cubic feet of air per minute at a pressure of 0.5 ounce per square inch, the power consumed by the blower set being less than one per cent of the full-load output of the transformer. The flow of air is controlled by dampers; and the proper amount of air can be determined from its temperature as it issues from the top; ordinarily this temperature should not be more than 20°C. above the temperature of the room.




Fig. 275. Section of Air-Blast Transformer Showing Circulating Currents

Fig. 274 shows a bank of six large air-blast transformers supported on I beams over an air chamber supplied with air from a fan blower. The air passes in at the bottom of each transformer

case, penetrates through ducts in the core and coils, and passes out at the top of the case, as shown in Fig. 275.

The process of building up the core of a shell-type air-blast transformer is illustrated in Fig. 264. The air-blast type is used for moderate voltages where cooling water is expensive or not available, and is built for voltages up to 33,000 in sizes up to 5,000 kilowatts. The limiting voltage for this type is determined by the excessive thickness of the solid insulation needed and the consequent difficulty in radiating heat from the copper. For voltages above 33,000, the oil-insulated water-cooled type is, therefore, recommended.

Water-Cooled Transformers. Transformers in which water is used for cooling are always immersed in oil. In an oil-insulated water-cooled transformer, all the heat generated in the iron and copper, except a small amount radiated from the surface of the case, is dissipated by means of water flowing through coils of pipe placed under the oil near the surface. As the copper and iron become heated, the heat is transferred to the oil coming into contact with their surfaces. As the oil is heated up, convection currents are produced by the hot oil rising from the transformer and flowing over towards the sides of the case; here it comes into contact with the surface of the cooling coils, giving up its heat to them and then sinks along the sides of the case to the bottom where it is ready to be heated up again and repeat the cycle. This method of water cooling is so effective that very little heat is dissipated from the tank and there is nothing to be gained by corrugations. From this it is seen that the cooling coils form a very important part of the oil-insulated water-cooled transformer and that, if for any reason they should fail to perform their work of carrying away the heat or should develop a leak, the transformer may be seriously damaged or even destroyed.

Water cooling is at present the most effective method for dissipating the heat generated in very large units and wherever the voltages exceed 33,000 volts. It is very convenient for water-power plants, the supply of water being at hand; but where a natural flow is not available, and pumps or city water mains have to be utilized, the expense may be prohibitive.*

*In any of these types of transformers depending upon forced circulation of air or water, it is *vital*ly important to avoid any stoppage of the flow, as this is likely to cause a burn-out of the transformer coils.

Series or Current Transformers. The chief difference between the series (current) and the shunt (voltage) transformer is, as the name implies, in the manner of connecting it in the circuit. The series transformer has its primary coil in series with the line, while the shunt transformer has its primary shunted across the line wires. In the latter the primary voltage is determined by that of the main circuit, and the primary current is determined by the impedance of the transformer, varying according to the secondary load. In the series transformer, on the other hand, the primary current is determined by the current in the main circuit, and the primary voltage is merely the drop across the primary terminals due to the primary impedance. The total impedance of the secondary circuit being normally constant, the change in load is due to a simultaneous change in the primary current and voltage. In the shunt (voltage) transformer the actual ratio of the primary to the secondary current is of minor consequence, whereas a constant ratio of voltages (especially in the so-called potential transformers used in connection with voltmeters and wattmeters) is of the highest importance. In the design of a series transformer, the questions of constant-voltage ratio and of high efficiency receive no attention, whereas the matter of securing a definite ratio of secondary to primary amperes receives the most careful attention.




Fig. 276. Portable Current Transformer Showing Primary Winding Terminals

It was pointed out on page 249 that a transformer intended to give an accurately fixed ratio between primary and secondary currents must be so designed as to have a very small magnetizing current. This is accomplished by using a very low magnetic flux density in the iron core, so as to reduce the watts of core loss to a minimum. The magnetizing current is also reduced by using iron-core plates of high permeability and with no breaks or joints in the magnetic circuit.

The series transformer is mostly employed for insulating an ammeter, a current relay, or series coil of a wattmeter or watt-hour meter from a high voltage circuit, or for reducing the line current to a value suited for these instruments. The secondary coils of such current transformers are usually wound for five amperes.

Figs. 276 and 277 show two commercial types of portable current transformers made by the General Electric Company. Both types have cores built up of closed ring-shaped stampings of thin sheet steel. The primary winding of the transformer shown in Fig. 276 is divided into four coils, both ends of each coil being brought out at one end and connected to suitable terminal blocks. By connecting these coils in series, series-parallel, or in parallel, three different current ratios are obtained, the standard ratings being 200-100-50 amperes primary with 5 amperes secondary. The secondary is wound as one coil, the terminals of which are brought out at the top.




Fig. 277. Portable Current Transformer without Regular Primary Windings

The type shown in Fig. 277 has no regular primary winding, but the core is provided with an opening through which a cable carrying the current to be measured may be passed one or more times to make the primary winding.

The ratio of transformation depends upon the number of times the cable is made to pass through this opening. This form of current transformer is designed to have 1,000 ampere turns at full-load rating. The standard transformer has a 5-ampere secondary winding giving a ratio with one primary turn passing through the center of the core of 100:5, or 200:1. If the cable is passed through the opening twice, the ratio is 500:5, or 100:1, etc. Both types are rated at 40 watts, and may be used on circuits the voltage of which does not exceed 2,500 volts.

The instrument, such as an alternating-current ammeter, to be used with these transformers, is connected directly in series with the secondary coil. If the ratio of transformation is 200:5 and the ammeter indicates 5 amperes, the actual value of the current passing

in the line and through the primary will be 200 amperes. In Fig. 217 the coil A , in series with the secondary coil S^* , may represent the switchboard ammeter.

The question may arise as to why the switchboard ammeter is not connected as a shunt across the terminals of a low-resistance link inserted in the main circuit whose current is to be measured, exactly as in the case of switchboard ammeters for direct currents. There are two reasons why this arrangement would not be permissible:

(a) An alternating current does not divide between two branches of a circuit in inverse proportion to the resistances of the branches, when either branch has inductance. Therefore, the reading of a shunted alternating-current ammeter cannot be multiplied by a constant factor to give the total current in the main circuit.

(b) It is objectionable to have the ammeter in electrical connection with high-voltage mains. The use of the series transformer is, therefore, preferable on the grounds of both accuracy and safety.

Constant-Current Transformers. The constant-current transformer is a transformer specially designed to take a nearly




Fig. 278. Magnetic Circuit in Constant-Current Transformer

constant current at varying angles of lag from constant-voltage mains, and to deliver a constant current from its secondary coil to a receiving circuit of variable resistance. The action of this transformer is as follows: The primary coil P and the secondary coil S of the transformer surround a long, laminated-iron core, as shown in Fig. 278. This core, and the yokes at the top, bottom, and sides, form a double magnetic circuit. The magnetic flux Φ , which at a given instant passes through the primary coil, flows partly through the secondary coil as the useful flux U , and partly leaks across between the primary and secondary coils as the leakage flux L .

The leakage flux L , in flowing across the air spaces from core to

*The electrical connections for a series transformer have been described on page 249.

TABLE VIII
Constant-Current Transformer Data*

PRIMARY VOLTS	NUMBER OF LAMPS	VOLTS PER LAMP	SECONDARY VOLTS	SECONDARY AMPERES
2,200	50	76.6	3,830	6.60
2,200	40	77.6	3,105	6.70
2,200	30	77.2	2,315	6.67
2,200	25	81.4	2,035	6.65
2,200	20	84.2	1,685	6.65
2,200	15	86.0	1,290	6.65


*Test of a 50-light, 6.6-ampere constant-current transformer, frequency 60 cycles per second.

yokes, constitutes an intense magnetic field which pushes up on the secondary coil. The secondary coil is suspended, and partly counter-balanced by a weight, so that the upward push of the leakage flux just suffices to sustain the coil. If the resistance of the secondary receiving circuit is increased, the immediate result is to reduce the secondary current below its normal value, which lessens the upward push of the leakage flux on the secondary coil. The secondary coil then, owing to the unbalanced action of the weight, moves down towards *P*; the leakage flux is lessened in amount and the useful flux *U* is increased in amount. This increase of useful flux increases the induced electromotive force in *S*; and the downward movement of *S* continues until the induced electromotive force in *S* is large enough to produce the normal value of the current through the increased secondary resistance.

Similarly, a decrease of resistance of the secondary receiving circuit causes a momentary increase of secondary current which increases the upward push on the secondary coil. This coil moves upwards until the secondary current is reduced to the normal value.

Table VIII shows the approximate constancy of secondary current in a constant-current transformer supplying current to a varying number of arc lamps connected in series to its secondary coil.

With 50 lamps, the primary current is 14.83 amperes; and with 20 lamps, is 14.78 amperes. In the latter case, the primary current lags 71 degrees behind the primary applied voltage; the power factor corresponding to this angle is 0.326; and the power received from the mains is $2,200 \times 14.78 \times 0.326 = 10,600$ watts, or



ENGINE TYPE ALLIS-CHALMERS ALTERNATOR
Courtesy of *Allis-Chalmers Company, Milwaukee, Wis.*

530 watts per lamp. With 40 lamps, the primary current lags 55 degrees behind the primary applied voltage; the power factor corresponding to this angle of lag is 0.574; and the power received from the mains is $2,200 \times 14.81 \times 0.574$ which is equal to 18,800 watts, or 470 watts per lamp. The efficiency of the transformer with a 50-lamp load was 93.9 per cent, and with a 20-lamp load it was 85.7 per cent. The power factor of the system as a whole varies




Fig. 279. Mechanism of General Electric Two-Coil Constant-Current Transformer

from 72 per cent to 76 per cent at full load, decreasing considerably at light loads.

Fig. 279 is a general view of the mechanism of the two-coil (one primary, and one secondary), constant-current transformer of the General Electric Company; and Fig. 280 shows the transformer in its containing case.

The mechanism of the transformer is surrounded by a corrugated sheet iron casing designed primarily for the protection of the

coils. The casing is enclosed by a cast-iron base and top which are provided with ample openings for the proper ventilation of the transformer.

Within the working limits, the magnetic repulsion between the fixed and moving coils of the system for a given position is proportional to the current flowing in the coils, which makes the



Fig. 280. General Electric Two-Coil Transformer Completely Assembled

transformer capable of being adjusted, therefore, so as to maintain any current, simply by changing the amount of counterweight.

In transformers up to and including 50-lamp capacity having but one movable coil—the secondary, as in Fig. 279—the counterweight is equal to the weight of the coil less the electrical repulsion; and a reduction in the counterweight will produce an increase

in the current. A lever is supported by knife-edge bearings on hardened steel tables which are clamped to the top of the core. To one end of this lever are secured two fixed arcs to which are attached two cables which support the movable secondary coil. At the outer end of the lever an adjustable arc carries a counterweight suspended by a cable.

In transformers designed to supply 75 and 100 lights, having two primary and two secondary coils, the movable secondary coils are balanced one against the other by a system of double-rocker arms supported on knife edges. The weight necessary to balance the repulsion between the primary and the secondary coils is carried on a small auxiliary lever. In this case, a decrease in the counterweight is followed by a decrease in the current.

The arc on the counterweight lever is made adjustable because the repulsion exerted by a given current flowing in the coils is not the same for all positions of the coils, being greater when the primaries and secondaries are close together and less when the primaries are separated. By means of the adjustable arc, the effective radius of the balancing weight is made to change as the coils move through their working range. When the primary and the secondary coils are separated by the maximum distance, the resultant force which tends to attract them to each other should be less than when they are close together.

Regulation. When current flows in the primary and secondary coils, the mutual repelling forces separate the coils until equilibrium is restored. The current corresponding to the position of equilibrium may be adjusted by changes in the counterweights, and the coils will then always take such a position as will maintain that current constant in the secondary coils, regardless of the external resistances to which the coils are connected. With any current less than normal, the repelling force diminishes, and the primary and secondary coils approach each other, thus restoring normal current. As soon as the secondary current exceeds normal, the resultant pull exerted by the counterweight and coils is overcome, and the secondary coil moves away from the primary, again restoring normal current. Transformers of this design can be made to maintain constant current even more accurately than the constant-voltage transformer maintains uniform voltage.

In Fig. 281 on the left is shown the diagram of electrical connections for a constant-current transformer for either 5, 35, or 50 lights, and on the right, the diagram for the 75- or 100-light transformer. The 75- and 100-light transformers are furnished with two primary coils which may be connected in series for 2,200 volts or in parallel for 1,100 volts; for example, connecting *B* to *C* puts the two primary coils in series, and connecting *B* to *D* and *C* to *A* puts them in parallel for 1,100 volts. In these larger transformers there are two secondary coils also, and leads are arranged so that the




Fig. 281. Connections for Constant-Current Transformer for 5, 35, 50, 75, and 100 Lights

lamps can be divided between two circuits by means of multi-circuit connections, as shown in Fig. 281 on the right.

Open-circuiting plug switches are used to disconnect the line from the secondary of the transformer when testing for a ground or an open circuit. These are also used to disconnect one of the circuits of a multi-circuit transformer in order that it may be repaired without interrupting the other circuit. The ammeter jacks, which are provided, are used for the purpose of enabling one ammeter to measure the current in more than one circuit. By

inserting the plug in any ammeter jack, that particular ammeter is connected in series with that circuit.

The primary windings are provided with fuses which are made part of the primary plug switch and are mounted on the back of




Fig. 282. Westinghouse Single-Pole Primary Fuse Block

the panel. They are of the tube expulsion type, depending on the expulsive force exerted by the gases formed by melting of the fuse. This force is sufficient to blow out any arc which tends to form within the narrow tube in which the fuse is located.

Transformer Fuse Blocks. The safety fuse links designed to protect a transformer from burn-out in case of short-circuit, are usually placed in circuit with both primary and secondary coils. The fuse links connected in circuit with the high-voltage coil are usually encased in a porcelain tube which encloses the arc that is formed when the fuse melts; and the expansion of the highly heated vapors in the tube extinguishes the arc by what is called "expulsive" action.

The tubes containing the fuses are usually provided with brass terminals for the fuses, the terminals projecting as blades from one side of the tube. With fuse and terminals complete, the tube is pushed home in a receptacle containing metal spring clips that receive the fuse terminals somewhat after the manner of an ordinary knife-switch.




Fig. 283. Fort Wayne Single-Pole Primary Fuse Block

When the fuse melts or "blows," the tube carrying the fuse and terminals is withdrawn from the receptacle. A new fuse may




Fig. 284. Method of Connecting Wires to
Primary Fuse Block on Poles Before
Current Passes to Transformer

then be put in place without danger to the attendant, after which the tube and fuse may be replaced in the receptacle.

In small transformers for moderate voltages, the fuse receptacles sometimes form part of the containing case; but in large transformers the fuse receptacles are, as a general rule, entirely

separate from the transformer, and are mounted at any convenient point near the transformer, for example, on a cross-arm or on the pole where the transformer is placed. In the case of transformers for use out-of-doors, the fuse receptacles always consist of waterproof cases of cast iron or porcelain, usually the latter.

Fig. 282 shows the type of single-pole primary fuse block furnished by the Westinghouse Electric Company. The block is made of porcelain, finished in black, and is weatherproof. The upper portion of the cut-out contains the stationary contacts which are deeply recessed in the porcelain and are well separated from each other. The contacts are so constructed that the plug is held securely in place by giving it a partial turn after inserting it. When the plug is in position, the fuse is in sight, so that its condition can be easily noted without incurring the danger of opening the primary circuit by pulling out the fuse plug while the fuse is still intact and the transformer is under load.




Fig. 283 shows a single-pole fuse-plug block made by the Fort Wayne Electric Works for protecting primary circuits. The block and plug are all porcelain, finished in black, and serve as both a primary switch and a cut-out. The block is mounted on the





Fig. 285. Sample Mounting for Out-Door Transformers

upper cross-arm of the pole and is shaped so as to be used as an insulator. The wires may be brought directly from the line to the cut-out, and thence to the primary winding of the transformer without other support, as shown in Fig. 284.

The plug and cavity in the fuse block are elliptical in section. The plug, shown at the bottom of the block in Fig. 283, is inserted

concentrically with the cavity and by a quarter turn the contact blade is forced between bronze spring terminal clips, and the major axis of the elliptical section of the plug brought into line with the minor axis of the cavity. The result is that the cavity is divided into two parts separated by the plug which tightly fits the cavity. The fuse lies in a groove in the plug with its ends held under screws on the plug blades. The groove is long enough to prevent arcing, and danger of shock is prevented by the insulated rim of the plug. The plug is firmly held in place by the spring terminal clips.

Mounting of Outdoor Transformers. Fig. 285 shows a transformer in its water-tight containing case, mounted on a pole, with its primary coil connected through a double-pole fuse block to 1,100-volt mains, and its two-coil secondary connected to three-wire mains for supplying incandescent lamps in a near-by building. Two suspension hooks *A*, made of heavy strap iron, are attached to the back of the transformer case by slipping the bolt-heads *B* into the sockets *C*, after which the nuts are screwed tight.

The transformer is hoisted to its position on the building or cross-arm by means of a rope or chain, which is slipped over the two hoisting lugs *D*. When the transformer is hoisted into position, the suspension hooks are slipped over the cross-arm, and screwed fast by means of lag screws. The lead wires from the primary coil are connected to the lower fuse-box leads, and the upper fuse-box leads are connected to the mains. The wires from the secondary coils are led into the building where the secondary fuses are placed. It is now more usual to install two single-pole fuse blocks as illustrated in Fig. 284, than one double-pole block as shown in Fig. 285.

TRANSFORMER TESTS

Heat Test. The simplest method of performing this test is to connect the primary coil of the transformer to mains giving the rated voltage and frequency of the transformer, and to load the secondary with a bank of lamps or a water rheostat, adjusting the resistance so as to get rated full-load current from the transformer. The run should be continued until an approximately constant temperature is reached.

The objection to loading the transformer in the way described

is that it requires taking the full rated power from the transformer, which power, therefore, is usually wasted. If two transformers of the same voltage and rated capacity are available, the test may be made on the two simultaneously by what is known as the *motor-generator* method, as follows:

The two secondaries, Fig. 286, connected in parallel, are excited from a low-voltage circuit *A* at normal voltage and frequency; consequently normal voltage is induced in each primary winding. The two primaries are connected in series, but in such a way as to oppose each other. The resultant voltage between the points *a* and *b* will then be zero, notwithstanding the fact that full voltage exists between the terminals of each transformer secondary. Therefore, if the points *a* and *b* be joined together no current will flow. If, however, instead of being joined, these terminals are connected to the terminals of the circuit *C*, any voltage impressed at *C* will produce a current in the circuit of the primary coils independent of the voltage existing in each of




Fig. 286. Connections for Transformer Heat Test

the primary coils. Since each transformer is in effect short-circuited by the other, it follows that approximately twice the impedance voltage* of one transformer impressed at *C* will cause full-load current to flow through the primaries and secondaries of both. Under these conditions, the transformers will run at full load, while the total energy required for the test amounts to merely the losses in the two. The circuit *A* supplies the excitation current and core losses, the circuit *C* the full-load current and copper losses.

The auxiliary electromotive force impressed at *C* may be derived from the same source as the electromotive force at *A*, by means of a transformer.

*The impedance voltage of a transformer is the electromotive force which must be applied to the primary coil to produce full-load current in both coils when the secondary coil is short-circuited. This voltage is from 2 per cent to 6 per cent of the rated full-load primary voltage. See page 312.

A regulating resistance must be connected in series with it to allow adjustment of the electromotive force at C until the ammeter registers full-load current.

The important temperatures to be observed are those of the coils, core, and room. The temperature of the case and of the oil may be observed as checks. The determination of the temperature of the coil may be made by thermometer or by measurement of resistance. If a transformer has remained in a room of constant temperature many hours, so that the temperature is approximately uniform throughout, thermometer measurement indicates quite accurately the temperature of the windings. If, however, the transformer is radiating heat, as during the heat run, the actual temperature of the copper coils will be much greater than the temperature of surface insulation.

If we know the "cold" resistance, as measured under the first of the above conditions, and the temperature of the coil at the time of measurement, we have a means of finding the "hot" temperature of the coil by measuring its "hot" resistance. The rise in temperature above the temperature at which the "cold" resistance was measured, may be determined from the equation

$$r = (238.1 + i) \left(\frac{R_{i+r}}{R_i} - 1 \right)$$

in which R_i is the "cold" resistance, R_{i+r} is the "hot" resistance, i is the initial temperature, and r is the rise in the temperature expressed in degrees centigrade. The temperature coefficient for commercial copper wire is taken at 0.0042.

If the room temperature differs from 25°C. the observed rise in temperature should be corrected by 0.5 per cent for each degree centigrade. Thus, with a room temperature of 35°C. the observed rise should be decreased by 5 per cent; and with a room temperature of 15°C., the observed rise should be increased by 5 per cent.

Core-Loss and Exciting-Current Test. For this test, the transformer is connected as shown in the diagram, Fig. 287, the primary being left on open circuit. Theoretically the test may be carried out with *either* coil connected to mains of the proper voltage and frequency. In practice, however, it is better, from the standpoint both of convenience and of safety, to connect the *secondary* coil.

The electromotive force is adjusted by means of the variable resistance until the voltmeter indicates rated secondary voltage. The ammeter then indicates the exciting or no-load current; and the wattmeter indicates, very closely, the core loss.

Resistance of Coils. The resistance of a coil of a transformer may be measured by the ordinary drop-of-voltage method. This method consists in passing through the coil a direct current, the value of which is noted by an ammeter, while the drop of voltage across the coil is measured by a voltmeter. Then the resistance is

$R = \frac{E}{I}$. Knowing the resistance of the coils, we can determine the drop in voltage due to resistance, under load. This loss of electro-




Fig. 287. Wiring Diagram for Core Loss and Exciting Current Test

motive force is usually expressed in per cent of the electromotive force supplied to the primary.

Impedance. One of the important constants of a transformer is its *impedance ratio*, that is, the ratio of the voltage consumed by its total internal impedance at full-load current to its rated full-load voltage. The impedance of a transformer is measured by short-circuiting one of its windings, impressing an alternating electromotive force on the other winding and making simultaneous measurements of current and impressed voltage. E and I being thus observed,




Fig. 288. Diagram of Connections for Making Transformer Impedance Test

the impedance is found as $Z = \frac{E}{I}$ ohms. The value thus obtained includes the impedance of both primary and secondary windings.

Impedance may be considered as constant at all loads. It is usually measured at full-load current, and the impressed voltage is then called the *impedance volts*, and when expressed in per cent of the rated voltage of the transformer, it is called the per cent *impedance drop*. It is evident that the "impedance ratio" as defined above is simply the per cent impedance drop divided by 100.

The impedance of a transformer is an important factor in determining the regulation by calculation. To determine the impedance voltage, the transformer is connected as shown in Fig. 288. As the impedance voltage is not very large—varying from 2 per cent to 6 per cent of rated primary voltage in standard transformers—a much more accurately readable deflection of the voltmeter will be obtained if the primary coil is connected to the mains. As will be seen by referring to Fig. 288, the secondary coil is short-circuited. The primary coil is connected in series with an adjustable resistance to the low-voltage mains. The resistance is slowly cut out, until full-load current flows in the coil, as indicated by the ammeter. Then the voltmeter indicates the impedance voltage. This should be expressed in per cent of the normal voltage of the coil. From the equation

$$I = \frac{E}{\sqrt{R^2 + (2\pi fL)^2}}$$

the total impedance, inductance, and reactance can be computed, provided R and the frequency f are known.

Example. In a test on a 7.5-kw. transformer with secondary short-circuited and primary connected to 2,080-volt mains, the impedance voltage was 61.1 volts at full-load current of 3.6 amperes in the primary, at a frequency of 60 cycles. The impedance drop being 61.1, the per cent impedance drop is $\frac{61.1}{2080} = 2.935$ per cent, and the impedance is $Z = \frac{61.1}{3.6} = 16.95$ ohms.

Since impedance $= Z = \sqrt{R^2 + X^2}$, $X = \sqrt{Z^2 - R^2}$ and the total reactive drop expressed in per cent is

$$\% XI = \sqrt{(\% \text{ impedance drop})^2 - (\% RI)^2}$$

If $\% RI = 1.57$ from test, and $\% ZI = 2.935$ as calculated above, then

$$\% XI = \sqrt{2.935^2 - 1.57^2} = 2.48$$

or

$$X = \frac{2.48}{3.6} \times \frac{2080}{100} = 14.3 \text{ ohms}$$

Regulation. The definition of regulation given on page 266 will be repeated here, it is: *the rise of secondary terminal voltage from rated non-inductive load to no load (at constant primary impressed terminal voltage) expressed in per cent of the secondary terminal voltage at rated load.* The regulation of a transformer may be determined directly by exciting the transformer at rated frequency and with a primary voltage such that rated secondary voltage is obtained at full load, using lamps or a water rheostat as load. The increase in secondary terminal voltage from full load to no load is then observed, the primary voltage and frequency being kept constant throughout the test. This increase in secondary voltage divided by the secondary full load voltage is then the regulation expressed in per cent. This method is, however, unsatisfactory, because of the small difference between the full load and no load values, and the liability of error in measuring either of them. Much more reliance can be placed on results calculated from separate measurements of impedance drop and resistance than on actual measurement of regulation.

A number of methods have been proposed for the calculation of transformer regulation, but the following formula will be found simple and practically correct.

$$\text{per cent regulation} = pRI + qXI + \frac{(pXI - qRI)^2}{200} \quad (40)$$

in which RI is total resistance drop in the transformer due to load current expressed in per cent of rated voltage; XI is total reactive drop due to load current similarly expressed; p is power factor of the load on the secondary = $\cos \theta$; for a non-inductive load $p = 1$; and q is reactive factor of the load = $\sin \theta$.

Example. A 7.5-kw., 60-cycle transformer of 10 to 1 ratio with secondary voltage of 208 at full load has the following constants:

Primary resistance, $R_1 = 5.65$ ohms.

Primary $R_1 I_1 = 5.65 \times 3.6 = 20.34$ volts, or $\%R_1 I_1 = \frac{20.34}{2080} \times 100 = 0.978\%$.

Secondary resistance, $R_2 = 0.0334$ ohm.

Secondary $R_2 I_2 = 0.0334 \times 36 = 1.24$ volts, or $\%R_2 I_2 = 0.596\%$.

Total RI (reduced to primary) = $20.34 + 10 \times 1.24 = 32.74$ volts, or 1.57% .

Reactive drop, $XI = 2.48\%$.

(a) *Regulation on non-inductive load.*

Here $\cos \theta = 1 = p$, and $\sin \theta = 0 = q$.

$$\begin{aligned} \% \text{ regulation} &= 1 \times 1.57 + 0 \times 2.48 + \frac{(1 \times 2.48 - 1.57 \times 0)^2}{200} \\ &= 1.57 + 0.031 = 1.60 \end{aligned}$$

(b) Regulation on inductive load.

Assuming the power factor of the load to be $0.80 = p$, gives $q = \sqrt{1 - 0.8^2} = 0.6$

$$\begin{aligned} \% \text{ regulation} &= 0.8 \times 1.57 + 0.6 \times 2.48 + \frac{(0.8 \times 2.48 - 0.6 \times 1.57)^2}{200} \\ &= 1.256 + 1.488 + 0.0054 = 2.75. \end{aligned}$$

The regulation for any other power factor p may be calculated in a similar manner.

Efficiency Calculation. The efficiency of any piece of apparatus at a given load is equal to the output divided by the input. The input is equal to the output plus the losses. The efficiency may then be defined as *the ratio of the output to the output plus the losses*. In nearly every case the efficiency can be determined more accurately by measuring the losses, and then computing the efficiency accord-




Fig. 289. Transformer Connected for Polarity Test




Fig. 290. Wiring Diagram for Transformer Polarity Test

ing to the second definition, than by attempting to measure the total output and input, and then taking their ratio.

Example. A given 5-kw. transformer is rated at 2,000 volts primary, and 200 volts secondary, at a frequency of 60 cycles per second. The coil resistances are found by measurement to be:

Primary coil resistance.....	10.1 ohms
Secondary coil resistance.....	0.067 ohms
At full load, full-load currents are:	
Primary current.....	2.5 amperes
Secondary current.....	25.0 amperes
Core loss, as determined by test.....	70 watts
Copper losses at full-load are:	
Primary loss = $I'^2 R'$ = $10.1 \times (2.5)^2 =$	63 watts
Secondary loss = $I''^2 R'' = 0.067 \times (25)^2 =$	42 watts

Total loss at full-load.....	175 watts
Full-load output.....	5,000 watts
Full-load intake.....	5,175 watts
Full-load efficiency $5,000 \div 5,175 =$	96.6 per cent

At half load:

Total I^2R loss.....	.26 watts
Core loss.....	.70 watts
Total loss.....	.96 watts
Half-load output.....	2,500 watts
Half-load intake.....	2,596 watts
Half-load efficiency, $2,500 \div 2,596 =$	96.3 per cent

The all-day efficiency of a transformer is the ratio of the output of work (watt-hours) during the day to the total input of work (watt-hours). The usual conditions of practice will be met if the calculation is based upon 5 hours at full load, and 19 hours at no load. See page 265.

Output:

5 hours at full load = 5 hours \times 5,000 watts =	25,000 watt-hours
19 hours at zero load =	0 watt-hours
Total output in 24 hours	= 25,000 watt-hours

Input:

5 hours at full load = 5 hrs. \times 5,175 watts =	25,875 watt-hours
19 hours at zero load = 19 hrs. \times 70 watts =	1,330 watt-hours

The zero load intake is but very little more than core loss, since I'^2R' is negligible at zero load.


Total intake in 24 hours	27,205 watt-hours
All-day efficiency $25,000 \div 27,205$	= 91.9 per cent

Polarity Test. Transformers are generally designed so that the instantaneous direction of flow of the current in certain selected leads is the same in all transformers of the same type. For example, the transformer shown in Fig. 289 is designed so that the current at any instant flows into lead *A* and out of lead *C*. Such transformers run properly in parallel when similar primary and secondary leads on different transformers are connected together. The primaries of two transformers *A* and *B* are connected to supply mains, the connections of one primary being made without reference to the connections of the other. It is desired to determine *first*, how the secondaries are to be connected in parallel to supply current to one and the same receiving circuit; and *second*, how the secondaries are to be connected in series to supply current to a receiving circuit. This test is made as follows:

Connect a terminal, say *a*, Fig. 290, of the secondary of one transformer to one terminal *c* of the secondary of the other transformer. Then connect two 110-volt lamps in series (or a voltmeter) to the other two terminals *b* and *d*. If the lamps do not light (or if the voltmeter gives no deflection), then *first*,

the terminals *a* and *c* are the proper ones to connect together to one service main; and the terminals *b* and *d* are to be connected together to the other service main; and *second*, the terminals *a* and *c* are not the proper ones to be connected together, but *b* and *c* are properly connected together in order to connect the two coils in series, the other two terminals *a* and *d* being connected to the service mains.





TURBINE ALTERNATOR. 200 K.W. 300 H.P.
De Laval Steam Turbine Co.

ALTERNATING-CURRENT MACHINERY

PART V

CONVERSION OF ALTERNATING INTO DIRECT CURRENT

In spite of the increasing use of alternating currents, there is always a demand for devices of various kinds for converting the power received from an alternating-current circuit into power in the form of direct current. Thus, many electro-chemical processes, electrolytic refining of silver and copper, the charging of storage batteries, and direct-current motors all require direct current. Electric power, as is well known, can be transmitted long distances most economically by the three-phase alternating-current system employing high voltages. The demand for direct-current power arises when the power is to be utilized at the receiving end of the line.

The conversion from alternating current to direct current is accomplished in practice in the following ways: (a) by the rectifying-commutator; (b) by the aluminum valve rectifier; (c) by the mercury-vapor rectifier; (d) by the rotary (or synchronous) converter; (e) by the motor-generator.

Rectifying Commutator. The rectifying commutator is a commutator driven at a speed synchronous with the alternating current supplied to its brushes and it reverses the connections of the armature windings of an alternator as a whole. The rectifying action consists in reversing alternate (negative) half waves of the current delivered by the alternator so that the current in the receiving circuit is always in one direction. The application of this device to the compounding of alternators is explained on page 111.

The rectifying commutator is limited to the rectifying of comparatively small currents at moderate voltages on account of the prohibitive sparking which occurs at the brushes at high voltages and large outputs.

Copyright 1911, by American School of Correspondence.

Aluminum Valve Rectifier. The aluminum valve rectifier is an electrolytic coil which depends on the property of aluminum electrodes in certain electrolytes to let electric current pass in one direction (when the aluminum electrode is cathode) but not in the other. The simplest arrangement of a single-cell valve rectifier is to connect the secondary of the transformer whose current is to be converted into direct current to the positive plate (iron) of the cell and the negative plate (aluminum) to the positive terminal of the storage battery to be charged. To complete the series circuit the negative terminal of the storage battery is connected to the other end of the transformer secondary. A common glass battery jar, containing an approximately neutral solution of pure ammonium phosphate in which an iron plate (the positive) and an aluminum




Fig. 291. Diagram of Connections for Aluminum Valve Rectifier

plate (the negative) are immersed, constitutes the rectifier. With such a single cell only one-half of the complete alternating-current wave is utilized, the other half of the current wave of reversed sign being suppressed by the aluminum valve action. The reversed current which would tend to flow from the aluminum plate through the electrolyte to the iron plate is stopped because of the formation of a thin insulating film of aluminum oxide over the aluminum plate which resists the passage of current unless the voltage exceeds about 150 volts.

A better plan of connecting a single cell so that both halves of the alternating-current wave will be rectified is given in Fig. 291. The choke coil *C* is an autotransformer, tapped at its middle point by a connection to the direct-current load *B*, such as a storage

battery to be charged. The other terminal of the battery is connected to the iron plate in the cell. The coil *C* offers a high impedance to the alternating current, but very little impedance to the intermittent direct current flowing out from its middle tap, because an equal amount of current comes from each end and flows in opposite directions around the core of the choke coil. Assuming that at a given instant the terminal *A* of the secondary of the supply transformer is positive, the path of the current will be as shown by the arrowheads. Since current cannot enter the solution of the cell by way of an aluminum electrode, the 5 amperes have to pass through one-half of the choke-coil winding and out of the middle tap into the battery *B*, from which it enters the rectifier cell through the iron electrode and returns through the aluminum electrode at the right, back to the other terminal *D* of the transformer secondary. Since the tap point of the autotransformer *C* is at its middle point, the energy delivered to its lower half acting as a primary coil is transferred by transformer action to its upper half, so that the 10-ampere pulsating direct current is furnished by the combined currents of 5 amperes in each of the two halves of the coil *C*. It follows that at any instant there is twice as much current through the direct-current circuit *B* as through the alternating-current circuit, but at half the voltage.

Thus, if both the alternating-current and the direct-current voltages are measured by alternating-current voltmeters, which give effective values, the alternating-current voltage would be, say, 100 volts, and the direct-current voltage would be 50 volts. In practice the direct-current voltage would be less than 50 volts on account of voltage drops and leakage in the cell.

With each reversal of the alternating-current voltage, the direction of the current in the alternating-current circuit, including the coil *C*, is reversed and each aluminum electrode alternates with the other in becoming an active negative terminal and then an inactive positive, but the direction of flow of the direct current through the battery *B* will remain unchanged.

The aluminum valve rectifier is adapted for rectifying relatively small currents (up to about 25 amperes direct current), its capacity being limited by the heating of the cells. The efficiency is low, ranging from 50 to 60 per cent in practice. The power factor is never over 90 per cent, even on full load. The highest effective value of

the alternating-current voltage that can be used with the cell at normal operating temperatures is about 175 volts, which means that about 55 volts will be obtained on the direct-current side.

As electrolytes, ammonium phosphate or sodium phosphate are considered best. The cell should be artificially cooled to work satisfactorily. The voltage may be regulated by means of resistance in either the alternating-current or the direct-current circuits, but a better method is by adjusting the alternating-current voltage by a small autotransformer having a number of taps. The greatest advantage of the aluminum valve rectifier is its cheapness and sim-




Fig. 292. Mercury-Vapor Arc Rectifiers

plicity. On account of its small direct-current output, its poor efficiency, and comparatively high cost of maintenance, it is not as yet of great commercial importance.

Mercury-Vapor Arc Rectifier. The mercury-vapor arc rectifier, like the aluminum valve rectifier, operates by the action of electric valves. The rectifier bulb consists of a closed glass vessel provided with four electrodes; those marked *AA*, Fig. 292, called anodes (or positives) are of graphite, and the other two *B* and *C*, called cathodes, are of mercury. The air is exhausted from the bulb which contains only mercury vapor. This like other metal vapors is an electrical

conductor under some conditions, and the graphite or positive electrodes are immersed in this vapor. A pool of mercury in the bottom of the bulb forms the negative electrode or cathode *B*, and the small electrode *C* is used merely for starting the mercury arc between *A* and *B*.

The rectifying action depends on the properties of mercury in the presence of mercury vapor, as follows: Current can readily pass from either of the solid graphite electrodes to the mercury vapor, but if it is attempted to reverse the direction of the current, a very high apparent resistance is developed at the surface of the mercury electrode which prevents the flow of current from *B* to *A*. The diagram of electrical connections for a mercury rectifier is given in Fig. 293. The alternating-current supply circuit is connected to the two positive electrodes *A* and *A'* of the bulb and also to two reactance coils *F* and *E*. On account of the check-valve action just described, the pulsations of the alternating current pass alternately from *A* and *A'* into the mercury (negative) electrode *B*, from which




Fig. 293. Connections for Mercury-Vapor Arc Rectifier

they are delivered as an uni-directional current for charging the storage battery *J*. When the bulb starts to rectify there is a high resistance at the surface of the mercury which must be broken down before current can pass. This cathode resistance acts like an insulating film over the surface of the mercury, but when a current is once started it will continue to flow, meeting with but small resistance as long as the current is uninterrupted. The briefest interruption, however, permits the cathode resistance to increase enormously, and thus stop the action of the bulb.

In order to break down the cathode resistance, on starting the rectifier, the bulb is tilted or shaken so that the small starting anode *C*, Fig. 293, is brought into contact with the cathode *B* by a mercury bridge. Current then passes between *C* and *B* and the little stream of mercury which bridges the space between the electrodes breaks with a spark when the bulb is returned to its normal vertical position. This spark or initial arc breaks down the cathode resistance by forming mercury vapor which enables the graphite anodes to become active and the rectifying action to start. After the tube is in operation, the circuit through *C* is opened by a switch.

The action of the rectifier may be followed in detail with the aid of Fig. 293. Let us assume an instant when the terminal *H* of the supply transformer is positive, then the path of the current will be shown by the small arrowheads, the electrode *A* will be positive, and the current is free to flow from *A* across the mercury vapor to *B*, the mercury negative electrode (cathode). From *B* the current passes through the storage battery *J*, through the reactance coil *E*, and back to the negative terminal *G* of the transformer. A moment later when the impressed voltage falls below a value sufficient to maintain the arc against the counter-electromotive force of the arc and storage battery, the current would be interrupted at the end of the first half cycle before the current from anode *A'* could be established.

In order to prevent this interruption two reactance (choke) coils *F* and *E* are connected in the circuit, as shown. The inductance of these coils delays the decreasing current from one anode, as *A*, until the voltage of the transformer has passed through zero, reverses, and builds up to such a value as to cause *A'* to start an arc between it and the mercury cathode *B*. The path of the current is now from *G* down to *A'*, across the mercury vapor to *B*, out through *J*, the coil *F*, and back to *H*, which is now the negative terminal. The new path is indicated by the arrows enclosed in circles. A moment later *A* again becomes active, and the path of the current is again indicated by the plain arrowheads as at first. Mercury-vapor rectifiers as made for charging storage batteries, operating arc lamps, small direct-current motors, etc., are furnished in four sizes, suitable for 10, 20, 30, and 40 amperes of direct current, respectively. They are designed for a frequency of 60 cycles, but can be adapted to com-

mercial frequencies from 25 to 140 cycles per second. They are made for the standard secondary alternating voltages of 110 and 220 volts.

The efficiency varies with the direct-current voltage delivered, and ranges from about 75 per cent from one quarter to full load when the direct-current voltage averaged 80 volts, up to over 80 per cent for direct-current voltages averaging 112 volts.




Fig. 294. Front and Back View of Mercury-Vapor Arc Rectifier Equipment

The rectifier tubes differ in size according to their ampere rating and in shape according to the direct-current voltage for which they are designed. The average life of a tube under normal operating conditions is about 600 hours, when a new tube should be substituted.

Fig. 292 shows two different voltage types of the 30-ampere size of tube made by the General Electric Company. The tube on the left is for direct-current voltages from 25 to 45 volts; and the tube on the right is for 90 to 250 volts.

A wide range of variation in the direct-current voltage is easily obtained by manipulating the dial switch mounted on the panel, shown in Figs. 294 and 295.

Fig. 294 shows front and rear views of a complete mercury arc rectifier outfit with switchboard panel, as built by the General Electric Company. Fig. 295 shows the front, rear, and side views of such an outfit with standard dimensions. The outfit consists of a rectifier tube, reactance, regulating compensator, and panel. The panel is completely wired and simply requires connections to be made to the secondaries of the supply transformer and to the direct-current load circuit. The equipment of the panel is clearly shown in Fig. 295.

The double-pole "line switch" to the left in Figs. 294 and 295 connects to the alternating supply circuit. The circuit breaker at the




Fig. 295. Diagrammatic Views of Front, Back, and Side of Rectifier Equipment Showing Details

top of the panel protects the direct-current circuit from excessive current. The "starting switch" is a single-pole double-throw spring switch which is used to start the tube on a resistance mounted on the back of the panel. The "anode switch" is an auxiliary spring switch mechanically operated by the "starting switch" and automatically opens the starting anode circuit as soon as the handle of the "starting switch" is released.

The dial switch is provided with a double set of contact buttons, one set for rough and the other for fine regulation of the direct-current voltage. These contact buttons are connected to taps

brought out from the regulating compensator mounted at the back of the panel.

Another important application of the mercury-vapor rectifier is in connection with street and out-door lighting by series, constant, direct-current arc and incandescent lamps. The arc lamps commonly used for this service are known as "luminous arc" and "flame arc" lamps. The series incandescent lamps for this service have filaments of tungsten, and are made for candle powers ranging from 25 to 80, and for currents of 4 and 6.6 amperes.

This system of series, constant, direct-current lighting involves an alternator delivering alternating current at 2,200 volts to the primary of a constant-current transformer whose secondary is designed to give a constant alternating current of either 4 or 6.6 amperes at a voltage depending upon the number of arc lamps in series to be supplied. A mercury-vapor rectifier is then used to convert the constant alternating current into a constant direct current suitable for use in the arc lamps.

The rectifiers constructed for this service differ from those described above only in certain details. The rectifier tubes are operated in oil-filled tanks, for cooling purposes, and the voltages of the rectified current range from 1,200 volts in the 12-light outfit up to 6,450 volts in the 75-light outfit. Rectifier tubes can be built for voltages up to 13,000.

ROTARY OR SYNCHRONOUS CONVERTER

The rotary or synchronous converter is a machine for converting alternating current into direct current, or *vice versa*. The importance that such machines have assumed in the electrical industry is due to several causes:

(a) It is necessary, for economic reasons, to use alternating current at high voltages in long-distance transmission, as explained on page 4. Therefore, rotary converters are required for changing the alternating current into direct current for use in electric railway motors, which must be supplied with direct current from the trolley wire at points at a distance from the power house.

(b) Rotary converters are needed for charging storage batteries in places where the central station supplies alternating current, and inverted rotaries are necessary for factory driving with

alternating-current motors in cases where direct current only is supplied by central stations.

(c) Direct current is necessary in many of the chemical and electro-metallurgical industries such as the electrolytic reduction of aluminum from its ores, the electrolytic refining of copper, etc. If alternating current is generated and transmitted to these establishments, it must be converted into direct current before it can be utilized.

The rotary converter is chiefly used to convert polyphase alternating currents into direct current on a large scale.

Comparison with Direct-Current Dynamo. In general appearance and construction, the rotary converter resembles the direct-current generator very closely. The chief outward difference is the addition of a number of collector rings concentric with the shaft on one side of the armature, and the commutator is very much larger than in the ordinary direct-current generator. Another point of difference is in the relative dimensions of the magnetic circuit, including yoke and magnet cores, which are smaller than would be usual or desirable in ordinary direct-current generators.

Under the usual condition of running, the armature is driven, as in a simple synchronous motor, by alternating current supplied to the collector rings from an external source. While so revolving direct current can be taken from brushes bearing upon the commutator.

The current in the armature of a rotary converter may be thought of as the difference between the inflowing alternating currents and the outflowing direct current. The average value of the current in a given armature conductor is, therefore, smaller in value than in the corresponding direct-current generator, and the heating effect I^2R is correspondingly less. Furthermore, the magnetizing action of the inflowing alternating current upon the armature is almost completely neutralized by the magnetizing action of the outflowing direct current. Therefore, a larger number of smaller conductors may be wound upon a given armature core if the armature is to be used for a rotary converter, than would be permissible if the armature were to be used for a direct-current generator. That is, the allowable power output of a machine of given size is not limited to so small a value if the machine is to be used as

TABLE IX

Power Ratings of Rotary Converters in Kilowatts

Continuous- Current Dynamo 100	Single- Phase Converter 85	Three- Phase Converter 132	Four- Ring Converter 162	Six- Phase Converter 192

a polyphase rotary converter, as it would be if the machine were to be used as a direct-current generator.

Table IX gives the power ratings which a machine that would be rated at 100 kw. if used as a direct-current generator has, when it is used as a single-phase, three-phase, two-phase (four-ring), and six-phase converter, respectively.

To Make a Direct-Current Dynamo into a Rotary Converter.

Consider an ordinary bipolar* direct-current dynamo. Imagine two opposite commutator bars of the machine to be marked *a* and *b*, respectively, Fig. 296. Let the field magnet of the machine be excited, and the armature be driven at a speed of n revolutions per second in a counter-clockwise direction, as shown by the arrow. At a given instant the marked bars will be midway between the direct-current brushes, as shown in the figure. Let us call the position of the armature at this instant the position *A*, Fig. 297, and let us consider the way in which the electromotive force between the given pair of commutator bars *a* and *b* changes as the armature rotates.




Fig. 296. Commutator and Brush Diagram for D. C. Dynamo as a Rotary Converter

(1) While the armature is making the first quarter of a revolution from the *A* position, the bars will move until bar *a* touches the + brush and bar *b* touches the - brush; and the electromotive force between the bars will grow from zero to the full value E of the direct electromotive force between the brushes.

*The following discussion applies to multipolar machines also, but the statements are much simpler when limited to the bipolar machine.

(2) While the armature is making the second quarter of a revolution from the A position, the bars will move until they are again midway between the direct-current brushes; and the electromotive force between the bars will drop from the value E to zero.

(3) While the armature is making the third quarter of a revolution from the A position, the bars will move until bar a touches the $-$ brush, and bar b touches the $+$ brush; and the electromotive force between the bars, which must now be considered as negative, will grow from zero to the value E .

(4) While the armature is making the fourth quarter of a revolution from the A position, the bars will move until they are again midway between the direct-current brushes; and the electromotive force between the bars, which is still to be considered as negative, will drop from the value E to zero.




Fig. 297. E.M.F. Curve for One Revolution of D. C. Dynamo

These successive changes of electromotive force, between the given pair $a b$ of commutator bars, which occur during one complete revolution of the armature, are shown graphically in Fig. 297.

It is at once evident that the electromotive force between the bars a and b is an alternating electromotive force, and that this alternating electromotive force passes through a cycle of values during each revolution of the armature, so that *its frequency is equal to the revolutions per second of the armature* in the case of a bipolar machine.

Furthermore, it is clear that the alternating electromotive force between a given pair of commutator bars $a b$ on a direct-current dynamo may be utilized for the production of alternating current; or the direct-current dynamo may be made into an alternator by providing a pair of insulated metal collecting rings connected permanently to the bars a and b , respectively, and which are kept in

continuous connection with an outside circuit by means of an auxiliary pair of brushes, that is, brushes entirely separate and distinct from the direct-current brushes before mentioned.

A direct-current dynamo made into an alternator in this manner but with its direct-current brushes and commutator kept intact, and provided with two collecting rings only, is called a *single-phase rotary converter*. When the machine is provided, as explained below, with three collecting rings, four collecting rings, or six collecting rings, it is called a *polyphase rotary converter*.

Three-Ring Converter. Three equidistant commutator bars *a*, *b*, and *c*, Fig. 298, of a direct-current dynamo are connected to three collector rings. It is shown later in this discussion that the electromotive force between bars *a* and *b* is, in phase, 120 degrees ahead of the electromotive force between bars *b* and *c*, and 240 degrees ahead of the electromotive force between bars *c* and *a*. Three electromotive forces related in this way are called *three-phase electromotive forces*; and a direct-current dynamo provided with three slip-rings as specified, is called a *three-phase, or three-ring, rotary converter*.

Four-Ring Converter. Four equidistant commutator bars *a*, *b*, *a'*, *b'*, Fig. 299, of a direct-current dynamo are connected to four collecting rings. Then the electromotive force between the rings *a* and *a'* is at its zero value when the electromotive force between rings *b* and *b'* is at its greatest value, or *vice versa*. Two electromotive forces related in this way are called *two-phase electromotive forces*; and a direct-current dynamo with four collecting rings, as specified, is called a *two-phase, or more accurately, a four-ring rotary converter*.




Fig. 298. Brush and Commutator Diagram for Three-Ring Converter




Fig. 299. Brush and Commutator Diagram for Four-Ring Converter

Six-Ring Converter. Six equidistant commutator bars a, b, c, a', b', c' , Fig. 300, of a direct-current dynamo, are connected to six slip-rings. Such a machine is called a *six-phase* or *six-ring rotary converter*. The electromotive force between the rings a and a' is, in phase, 120 degrees ahead of the electromotive force between rings b and b' , and 240 degrees ahead of the electromotive force between rings c and c' . Three electromotive forces so related are called *three-phase electromotive forces*; and a six-ring rotary converter may, under certain conditions, be supplied with three-phase alternating currents.

Multipolar Rotary Converters. The discussion already given on converters refers, for the sake of simplicity, to a bipolar machine. In case of a multipolar d. c. dynamo, having p field poles, the connections of the n rings of an n -ring converter are as follows:

Ring 1 is connected to the $\frac{p}{2}$ equidistant commutator bars which, for a given position of the armature, are squarely opposite the centers of, say, the north poles of the field magnet. Let d be the distance between the commutator bars to which ring 1 is connected. Ring 2 is connected to the $\frac{p}{2}$ equidistant commutator bars which are $\frac{1}{n}$ of d ahead of the bars connected to ring 1; ring 3 is connected to the $\frac{p}{2}$ equidistant commutator bars which are $\frac{2}{n}$ of d ahead of the bars connected to ring 1; and so on.





Fig. 300. Brush and Commutator Diagram for Six-Ring Converter

For example, a 6-pole direct-current dynamo with 72 commutator bars, to be made into a three-ring converter, would have ring 1 connected to commutator bars 1, 25, and 49; ring 2 connected to commutator bars 9, 33, and 57; and ring 3 connected to commutator bars 17, 41, and 65.

E. M. F. Relations for Rotary Converter. Let E be the value of the steady electromotive force between the direct-current brushes of a rotary converter; and let E_2, E_3, E_4, E_6 , be the *effective values*



WESTINGHOUSE TWO-PHASE GENERATORS, DIRECT-CONNECTED.
Metropolitan Electric Supply Co., Ltd., London, England.



of the alternating electromotive force between *adjacent* collecting rings of a two-ring, three-ring, four-ring, and six-ring rotary converter, respectively. It is desired to find the relationship between these various electromotive forces.

Relationship between E and E₂. The maximum value of the alternating electromotive force between the collecting rings of a two-ring converter occurs at the instant when the commutator bars to which the collecting rings are connected are in contact with the direct-current brushes, and this maximum value is, of course, equal to E. Therefore, the effective value E₂ of the alternating electromotive force between the slip-rings of a two-ring converter is equal to $\frac{E}{\sqrt{2}}$. That is

$$E_2 = \frac{E}{\sqrt{2}} \tag{41}$$

Relationship between E₂ and E₃. The discussion of the relationship between E₂ and E₃ will be carried out for a very special case, namely, where the armature has 18 conductors; and this special discussion will lead to a very simple geometrical construction which will easily give the relationship between E₂, E₃, E₄, and E₆, and will also show the phase relations of the various electromotive forces of a three-ring, of a four-ring, or of a six-ring converter.




Fig. 301. Diagram of a D. C. Ring-Wound Armature

Fig. 301 represents a direct-current ring-wound armature having 18 conductors, each conductor representing a turn of wire. Consider the conductor a. This conductor has an alternating electromotive force induced in it as the armature rotates. Let this alternating electromotive force (effective value) be represented by the short line a in Fig. 302.

Consider the next following conductor b. The alternating electromotive force induced in this conductor has the same value as that

induced in conductor *a*, but is *behind it in phase* by the angle $\frac{360^\circ}{18}$
 $= 20^\circ$, where 18 is the total number of armature conductors. Let




Fig. 302. E.M.F. Diagram for Fig. 301

the electromotive force induced in conductor *b* be represented by the short line *b* in Fig. 302.

Similarly, the short lines *c*, *d*, *e*, *f*, *g*, etc., in Fig. 302, represent the alternating electromotive forces (effective values) induced in the conductors *c*, *d*, *e*, *f*, *g*, etc.

Consider first the two-ring converter. Suppose that its slip-ring 1 is connected to the commutator bar which is between conductors *r* and *a*, as shown in Fig. 301; then its other slip-ring will be connected to the bar which is between conductors *i* and *j*, and the alternating electromotive force E_2 between these two slip-rings will be the vector sum of the electromotive forces *a*, *b*, *c*, *d*, *e*, *f*, *g*, *h*, and *i* (Fig. 302), as shown in Fig. 303. That is, E_2 (effective value) is represented by the diameter of the polygon (circle) in Fig. 303.

Consider now the three-ring converter. Suppose its three rings are connected as shown by the numbers 1, 2, and 3 in Fig. 301. Then the electromotive force E'_3 , between rings 1 and 2 is the vector sum of the electromotive forces *a*, *b*, *c*, *d*, *e*, and *f*, as shown in Fig. 303; the electromotive force E''_3 , between rings 2 and 3, is the vector sum of the electromotive forces *g*, *h*, *i*, *j*, *k*, and *l*, as shown in Fig. 303 and




Fig. 303. E.M.F. Relations in Two- and Three-Ring Converter

the electromotive force E'''_3 , between rings 3 and 1, is the vector sum of the electromotive forces *m*, *n*, *o*, *p*, *q*, and *r*, as shown in Fig. 303.

Therefore, the effective value of the electromotive force E_2 between the two rings of a two-ring converter, being represented by the diameter of a circle, the effective value of the electromotive force E_3 , between any two rings of a three-ring converter is represented by a 120-degree chord of the same circle. Therefore

$$E_3 = \frac{\sqrt{3}}{2} \times E_2$$

or, using the value of E_2 from equation (41), we have

$$E_3 = \frac{\sqrt{3}}{2} \times \frac{E}{\sqrt{2}} = 0.612 E \quad (42)$$

It is to be noted that in order to make a direct-current machine into a three-, four-, or six-ring converter, the number of armature conductors must be divisible by the number of rings. Therefore, the armature shown in Fig. 301 is not suitable for a four-ring converter, although it is suitable for a three-ring converter.

The foregoing discussion shows that if the effective value of E_2 is represented by the diameter of a circle, then the effective value of E_3 is represented by a 120-degree chord, the effective value of E_4




Fig. 304. E.M.F. Relations in a Four-Ring Converter




Fig. 305. E.M.F. Relations in a Six-Ring Converter

is represented by a 90-degree chord, and the effective value of E_6 is represented by a 60-degree chord of the same circle. This is shown in Figs. 303, 304, and 305.

From Fig. 304, we have

$$E_4 = \frac{E_2}{\sqrt{2}}$$

or, substituting the value of E_2 from equation (41), we have

$$E_4 = \frac{1}{\sqrt{2}} \times \frac{E}{\sqrt{2}} = \frac{E}{2} \quad (43)$$

From Fig. 305 we have

$$E_6 = \frac{1}{2} E_2$$

or, substituting the value of E_2 from equation (41), we have

$$E_6 = \frac{1}{2} \times \frac{E}{1.2} = 0.354E \quad (44)$$

Summary of E. M. F. Relations for the Rotary Converter. Let E be the electromotive force between the direct-current brushes of a rotary converter; then,

$$\left. \begin{aligned} E_2 &= 0.707 E \\ E_3 &= 0.612 E \\ E_4 &= 0.500 E \\ E_6 &= 0.354 E \end{aligned} \right\} \quad (45)$$

in which E_2 , E_3 , E_4 , and E_6 , are the effective values of the alternating electromotive force between adjacent collecting rings on a two-ring, three-ring, four-ring, and six-ring converter, respectively, and E is the steady value of the electromotive force between the direct-current brushes in each case.

Examples. If a rotary converter is to deliver direct current at 500 volts:

(a) It must be supplied with single-phase alternating current at 353.5 volts effective if it is a two-ring converter.

(b) It must be supplied with three-phase currents at 306 volts effective between each pair of the three supply mains, if the converter is a three-ring converter.

(c) It must be supplied with two-phase currents over four-wire supply mains with 250 volts effective between mains connected to adjacent collector rings, or 353.5 volts effective between mains connected to opposite collector rings, if the converter is a four-ring converter.

(d) It must be supplied with six-phase currents over six-wire supply mains, with 177 volts effective between the mains connected to adjacent collector rings; or with 306 volts effective between the mains connected to rings 1 and 3; or with 353.5 volts effective between the mains connected to opposite collector rings.

Modification of Theoretical Voltage Ratios in Actual Machines.

The theoretical ratios of alternating to direct-current voltage are not always found to hold good in practice. This is owing to a variety of causes, chief among which are: the deviation of the generator voltage from a sine wave; the voltage drop in the armature wind-

TABLE X
Voltage Ratios of Rotary Converters

PERCENTAGE POLE ARC	50 Per Cent	67 Per Cent	74 Per Cent	80 Per Cent	
Three-phase {	550-volt	67	63	62	61.5
	250-volt	67.5	63.5	62.5	62
	125-volt	68	63.8	63	62.5
Two-phase {	550-volt	78	73.5	72.5	72
	250-volt	79	74	73	72.5
	125-volt	79.5	74.5	73.5	73

ings; the position of the direct-current brushes on the commutator; and the degree of field excitation.

As the direct-current voltage at the commutator brushes, neglecting the resistance drop IR in the converter, is equal to the maximum instantaneous voltage between opposite collector rings, a flat-top wave gives a higher ratio, *i. e.*, lower direct-current voltage, and a peaked wave a lower ratio, *i. e.*, higher direct-current voltage, for the same impressed alternating-current voltage. Moreover, the shape of the electromotive force wave impressed by the generator upon the converter, is modified by the form of the counter-electromotive force wave of the converter. Hence, a short pole arc of the converter, producing a peaked wave of counter-electromotive force, tends to lower the direct-current voltage, and a long pole arc tends to raise the direct-current voltage, for the same impressed alternating voltage.

A displacement of the brushes from the neutral point decreases the direct-current voltage for a given alternating-current voltage, the variation in extreme cases amounting to several per cent.

Over-excitation of the field magnet may increase the direct-current voltage one or two per cent; while with under-excitation, *i. e.*, with lagging current in the armature, the direct-current voltage may be decreased one or two per cent for a given alternating-current voltage.

Under average conditions of full-load operation, the standard types of converters have ratios *alternating-current voltage* \div *direct-current voltage*, approximately as given in Table X.

In the normal operation of the rotary converter, namely, when furnishing direct current, the drop in the armature reduces the direct-current voltage. When run as an inverted converter, *i. e.*,

when delivering alternating current, direct current being fed to the brushes, the drop is on the alternating-current side; consequently the voltage ratio of a converter is lower when it is run inverted.

For preliminary calculations where the data of operation is not known, the following voltage ratios may be used with most standard converters:

	No load	Full load
For single-phase	71.5	73
For two-phase	71.5	73
For three-phase	61	62.5
For six-phase (measured on diameter)	71.5	73
For six-phase (measured on alternate rings)	61	62.5

In operating rotary converters, it is customary to make allowance for the departure of the actual voltage ratio from the normal ratio. The amount of the allowance to be made cannot always be predetermined; but any ordinary departure from the theoretical voltage may be easily compensated for by using transformers provided with taps on the secondary windings which will permit a voltage change of about 5 per cent.

Current Relations for Rotary Converter. The rotary converter, as ordinarily used to convert alternating current to direct current, behaves as a synchronous motor so far as its intake of alternating current or currents is concerned. In the case of the synchronous motor with a given belt load, the intake of alternating current varies with the degree of field excitation, the intake of current being a minimum for a certain field excitation, and the power factor nearly unity (see page 226). In the case of the rotary converter also, the intake of alternating current or currents is a minimum, and its power factor is unity for a certain field excitation, the direct-current output of power being given. Under these conditions there is a definite relation between the direct-current I delivered by the converter, and the *effective* value of the alternating current flowing in at each collecting ring. In fact

$$\left. \begin{aligned} I_2 &= 1.414 I \\ I_3 &= 0.943 I \\ I_4 &= 0.707 I \\ I_6 &= 0.471 I \end{aligned} \right\} \quad (46)$$

in which I_2 , I_3 , I_4 , and I_6 are the effective values of the alternating current entering at each collector ring of a two-ring, three-ring, four-ring, or six-ring converter, respectively; and I is the direct current delivered by the converter. These equations (46) are based on the assumption that the converter has unity power factor as above pointed out, and that the intake of power is equal to the output of power, *i. e.*, the losses of power in the machine are ignored.

Derivation of the Equations for I_2 and I_3 . The method of deriving equations (46) will be sufficiently indicated by deriving the first two, namely, the equations for I_2 and I_3 .

The direct-current output of power from the converter is EI , E being the electromotive force between the direct-current brushes, and I being the direct current delivered. The intake of power is $E_2I_2 \times$ power factor; but since the power factor is supposed to be unity, the intake of power is simply E_2I_2 . Therefore, ignoring losses of power, we have

$$E_2I_2 = EI$$

But $E_2 = 0.707 E$, by the first of equations (45), so that $E_2I_2 = 0.707E \times I_2 = EI$. Hence

$$0.707 I_2 = I$$

or, in final form, the equation for I_2 is

$$I_2 = 1.414 I$$

The direct-current output of power is EI , and the intake of power is $\sqrt{3} E_3I_3$, the power factor being unity; that is, the power delivered by three-phase supply mains is equal to $\sqrt{3}$ times the voltage between mains times the current in each main, as explained on page 128. Therefore, ignoring power losses in the machine, we have

$$\sqrt{3} E_3I_3 = EI$$

But $E_3 = 0.612 E$, according to the second of equations (45), so that $\sqrt{3} E_3I_3 = \sqrt{3} \times 0.612 \times EI_3 = EI$. Hence

$$\sqrt{3} \times 0.612 I_3 = I$$

or, in final form, the equation for I_3 is

$$I_3 = 0.943 I$$

Example. A rotary converter delivers 500 amperes of direct current, the field excitation being adjusted so that the intake of alternating current may be a minimum.

(a) If this converter is a two-ring converter, it must be supplied with 707 amperes of alternating current from single-phase mains.

(b) If this converter is a three-ring converter, it must be supplied with three-phase currents from three-wire mains, with 471.5 amperes effective in each main.

(c) If this converter is a four-ring converter, it must be supplied with two-phase currents from four-wire supply mains, with 353.5 amperes effective in each main.

(d) If this converter is a six-ring converter, it must be supplied with six-phase currents from six-wire mains, with 235.5 amperes effective in each main.

ROTARY CONVERTERS IN PRACTICE

Uses of the Rotary Converter. The uses of the rotary converter are as follows:

(a) *Direct-Current Generator or Motor.* The rotary converter may be used as a direct-current generator or motor, in which cases the collector rings are not used, but the machine must be provided with a pulley.

(b) *Alternating-Current Generator or Synchronous Motor.* The machine may be driven by belt and used to deliver alternating currents from its collector rings as an ordinary alternator; or the machine may be supplied through its collector rings with alternating currents, and may be driven as an ordinary synchronous motor delivering mechanical power to drive machinery. In either case the direct current for exciting the field magnet may be taken from the commutator of the machine, or from a separate direct-current dynamo (exciter).

(c) *Double-Current Generator.* The rotary converter may be driven by belt, and used to deliver both direct current and alternating current from commutator and collector rings, respectively. When so used, the machine is called a *double-current generator*.

(d) *Regular Rotary Converter.* The machine may be driven as a synchronous motor taking alternating current from supply mains, and delivering, not mechanical power, but electrical power in the form of direct current from its commutator. When so used, the machine is called a *rotary converter*. This is the most frequent use of the machine. The rotary converter does not require a pulley. Under these conditions, the machine exhibits all of the peculiarities of the synchronous motor. Thus, with under-excited field magnet, the rotary converter takes an unduly large amount of alternating

current from the supply mains at a low power factor. As the field excitation is increased, the intake of alternating current decreases (for given output of direct-current power), and the power factor increases. For a certain degree of field excitation the power factor is nearly unity, and the alternating current or currents delivered to the machine are in phase with the alternating electromotive forces between the supply mains. When the field magnet is over-excited, the alternating currents supplied to the converter are ahead of the alternating electromotive forces in phase, and the power factor is less than unity.

(e) *Inverted Rotary Converter.* The machine may be driven as a direct-current motor taking current from direct-current supply mains through its commutator, and delivering, not mechanical power, but electrical power in the form of alternating currents from its collector rings. When so used, the machine is called an *inverted rotary converter*; it does not require a pulley.

Starting Rotary Converters. There are three methods in common use for starting rotary converters, namely, (a) from the alternating-current side, as an induction motor; (b) from the direct-current side, as a shunt motor; or (c) by means of a special direct-connected starting motor, usually of the squirrel-cage induction type.

(a) *As an Induction Motor.* The first method is one of the most common and has been fully discussed on page 209. It consists in supplying polyphase currents at a suitable voltage to the collector rings. The resulting torque developed by the armature will bring the converter up to synchronous speed in from one to two minutes. The proper value of impressed voltage for starting is usually obtained from taps on the main transformers. This method of starting has the advantage of making synchronizing unnecessary, but on the other hand it requires a large starting current which, if the converter is relatively large as compared with the alternator supplying it, causes an excessive drop of voltage throughout the circuit.

A difficulty sometimes met in this method of starting is, that a particular direct-current brush or set of brushes may be positive or negative according to the direction of the last pulse of alternating current just before the machine jumps into synchronism. Therefore, when several rotary converters are to supply direct current to common bus bars, special care must be taken to see that the polarity

of a given machine is correct before it is connected to the bus bars. If the machine happens to come up to the speed with the wrong polarity, the field "break-up" switch, described on page 220, must be thrown from one position to the other, thus reversing the field. Self-starting converters are also generally equipped with a switch for disconnecting the shunt across the series coils from the series field winding, during starting, so as to prevent the circulation of a large induced alternating current in both the shunt and the series field winding. The induced current would not only cause excessive heating, but would also hinder starting by its braking effect.

(b) *As a Shunt Motor.* When a direct-current supply is available, the converter may be started as a direct-current shunt motor, by supplying direct current to the commutator side of the machine, the alternating-current main switch being open. This method is convenient and is used in many installations. In some cases the direct current is obtained from another converter already in operation, or from a small storage battery which may be at hand. Sometimes a small motor-generator set, consisting of an induction motor coupled to a direct-current generator, is installed to supply current for the starting of one or more converters in a station.

In the direct-current method of starting, the fields should be fully excited by closing the field switch first, and there should be a resistance in series with the armature when the motor switch is closed. Failure to excite the field may cause the converter to increase its speed to a dangerous extent, just as in the case of a direct-current shunt motor with excessively weak field, for in starting the converter from the direct-current side, it is not running as a synchronous motor but as a simple shunt direct-current motor. If the converter is compound wound, the series field circuit must be opened, otherwise the current flowing through it will magnetize the field poles in opposition to the shunt field windings (differential compounding) and may even prevent the machine from starting.

The operation of starting is as follows:

- (1) See that the alternating-current main switch is open.
- (2) Close the field switch.
- (3) Leave the starting resistance in circuit with the armature, and then close the direct-current main switch.
- (4) When normal speed is reached, cut out the starting rheostat,

and vary the field strength until the synchronizing device shows that the converter is in synchronism with the generator.

(5) Close the main alternating-current switch when the synchronizing device shows that the rotary converter is in step with the alternating-current supply.

If the converter is furnished with a shunt winding only, adjust the field to give minimum alternating-current input.

If the converter has a series winding also, the shunt field should be adjusted to give at no load the direct-current no-load voltage at which it is rated.

When a rotary converter is started as a direct-current motor,




Fig. 306. Westinghouse Rotary Converter Equipped with Separate Starting Motor on Same Shaft

it is easy to bring the machine into operation with a particular direct-current brush or set of brushes *positive*.

(c) *By Separate Motor.* The third method of starting rotary converters, by means of a separate-starting motor, is often used. In such cases the starting motor is usually supported on the converter either on one end of the base plate or by the pillow block. The rotor is mounted on the armature shaft of the converter just outside of the bearing, as shown in Fig. 306. The starting motor is usually of the induction type with squirrel-cage rotor, and is

furnished with a number of poles which is two less than the number of poles on the converter. This enables the motor to bring the converter up to and above the synchronous speed, and speed regulating devices are arranged for synchronizing the converter with the alternating-current supply mains.

This method of starting has the great advantage of requiring a relatively small starting current, and is used especially when because of limited capacity of generators or transmission system it is essential to keep the starting current as low as possible.

The disadvantages of this method are: that it requires time and skilled attendants to synchronize properly, and that the auxiliary motor adds to the cost and requires additional space.

A modification of the last method is sometimes employed in which the converter is started from rest by means of a separate starting motor and then thrown directly on to the alternating-current bussés in series with a suitable reactance which limits the instantaneous rush of current to a safe value. This method combines the advantages of separate motor starting and self-starting from the alternating-current side, in that it obviates the necessity of synchronizing and insures the rotary coming in with the right polarity; on the other hand, it requires somewhat more time than the self-starting method and a heavier line current than with the induction starting motor alone. An example of this method is shown in Fig. 306, a 300-kilowatt three-phase rotary converter manufactured by the Westinghouse Company. It has 10 poles and when supplied with alternating three-phase, 60-cycle currents, at 367 volts per phase, delivers a direct current of 500 amperes at 600 volts from the commutator. This converter is built for electric railway substation service, and is provided with an induction motor for separate starting. At the right-hand end of the shaft may be seen the mechanical oscillator described below.

Oscillators for Rotary Converters. The armature of a belted dynamo or motor is always caused by the belt to shift slowly to and fro endwise in its bearings, thus entirely obviating the uneven wearing away of the commutator in grooves where the brushes rub. The rotary converter, however, not being mechanically driven tends to run without end-play, and some special end-play device, or oscillator, is necessary. An effective device much used is an electro-

magnet mounted opposite to the end of the rotary-converter shaft. This electromagnet is excited about ten times per minute, and at each time gives an endwise pull on the shaft, causing the desired endwise movement of the latter. A mechanical end-play device regularly used by the Westinghouse Company consists of a steel plate with a grooved ball race and ball backed by a spring, and mounted at one end of the shaft. As the grooved plate is not quite parallel to the end of the shaft, when the converter is prop-




Fig. 307. General Electric 300-Kilowatt Three-phase Rotary Converter

erly installed with the armature slightly inclined towards the oscillator, the hardened steel ball is caught at the lowest point between the race and the end of the shaft. The ball is carried upward as the armature revolves and the spring is compressed. The reaction of the spring now forces the shaft away and the ball falls back to its normal position.

Characteristic Types of Rotary Converters. Fig. 307 shows a 300-kilowatt, three-phase (three-ring) rotary converter built by the General Electric Company. It has a six-pole field magnet and six sets of direct-current brushes, each set having eight single brushes.

Its rated speed is 500 revolutions per minute, which, with a six-pole field, gives a frequency of 25 cycles per second. The three collector rings are mounted on the armature shaft on the end opposite to the commutator. It can be seen from the figure that the commutator is larger in comparison with the size of the machine than is usual in an ordinary direct-current generator. Each collector ring has three brushes bearing upon it in order to permit of the delivery to the machine of the very large alternating currents from the supply




Fig. 308. General Electric Three-Phase Rotary Converter for Electric Light Service

mains. The use of three brushes on each collector ring is preferable to the use of one broad brush, inasmuch as it is desirable to make the rings narrow to save space. This machine is rated at 550 volts between its direct-current brushes, so that the full-load direct-current output is 300,000 watts divided by 550 volts, or 546 amperes. Therefore, on the assumption of unity power factor and 100 per cent efficiency, as explained on page 336, the alternating current entering at each collector ring is $546 \text{ amperes} \times 0.943 = 515 \text{ amperes effective}$; and the effective voltage between collector rings is $550 \text{ volts} \times 0.612^* = 336 \text{ volts}$. The alternating-current power supplied to the machine is

$$\sqrt{3} \times 336 \text{ volts} \times 515 \text{ amperes} = 300,000 \text{ watts}$$

*See Equation (42), page 333.

Fig. 308 shows a three-phase rotary converter manufactured by the General Electric Company for electric lighting service at 250 volts. The characteristic features which distinguish the rotary converter from the direct-current generator are here especially prominent, namely, the large commutator and great brush contact area, the comparatively large collector rings, and the relatively small magnetic system, including yoke and field-magnet cores.

Hunting of Rotary Converter. A rotary converter (regular), being a synchronous motor in relation to its alternating-current supply, has a tendency to hunt, as explained on page 223.

A rotary converter, however, having no pulley and not being mechanically connected to machinery, is much more sensitive in responding to the pulsations of an engine or to other causes of hunting than is a synchronous motor delivering mechanical power.

The hunting oscillations of a synchronous motor are always due to external disturbances, that is, to disturbances originating outside of the alternating-current generator, the line, and the synchronous motor.

A sudden change of load on the synchronous motor, for example, is followed by a series of oscillations. Whether or not the oscillations due to a certain change of load give rise to trouble, depends largely upon the resistance and the reactance of the transmission line, and upon the frequency. The greater the resistance and the reactance of the transmission line, the greater the trouble from hunting; and at high frequencies the trouble from hunting is much greater than at low frequencies. Thus a 25-cycle rotary converter gives no serious trouble from hunting if the line resistance and reactance are not excessively high, whereas a 60-cycle rotary converter is more likely to give trouble unless special provision is made to diminish hunting, as explained below.

A periodic variation in the speed of the engine driving the alternator from which a rotary is supplied with alternating current, produces very troublesome hunting when this variation of speed is in rhythm with the hunting oscillations. This class of hunting is obviated by increasing the fly-wheel capacity of the engine, or by changing the resistance or the reactance of the transmission lines. The latter method changes the rhythm of the hunting oscillations and thereby does away with the coincidence of rhythm, which is the chief cause of excessive hunting oscillations due to engine pulsations.

The hunting oscillations, once started, usually reach their maximum under given conditions in a few minutes of time, so that serious trouble due to hunting, such as the dropping out of step of the rotary, or excessive sparking at the commutator, usually occurs soon after the hunting begins.

Hunting which is approximately the same at all loads, from no-load to over-load, is more troublesome when the field of the rotary converter is over-excited so as to take leading currents, than when the excitation is such as to give either unity power factor or lagging currents.

Hunting is also greater when several rotaries are supplied from an alternating-current generator, than when a single rotary converter is supplied, unless there are short lengths of alternating-current mains between them, or unless the converters supply direct current in parallel to the same direct-current mains.

Dampers. Hunting, whether due to engine pulsations or to momentary outside disturbance, such as sudden change of load or momentary short-circuit, is greatly reduced by the use of massive





Fig. 309. Diagram Showing Copper Dampers in Place in Field Poles

copper bridges or frames extending partly over the pole faces, as shown in Fig. 199. A more effective arrangement is shown in Figs. 171 and 309. A number of holes or channels are provided in each pole tip. In these holes or channels heavy copper conductors *A* and *B* are placed, and these conductors are short-circuited by being connected at the ends by the bars *C C*. These copper frames or "dampers" diminish hunting oscillations because, when a machine is hunting, the magnetic flux from pole-face to armature core is shifted forwards and backwards over the pole-face, and this shifting flux induces electromotive forces in the copper frames, which produce currents tending to oppose the shifting of the flux, and thereby oppose the hunting oscillations.

A rotary converter having solid cast-steel pole pieces has little or no tendency to hunt. The action of the solid poles is the same as the action of the massive copper conductors shown in Fig. 309.



VIEW OF POWER PLANT OF THE SOUTHWESTERN STATES PORTLAND CEMENT CO., SHOWING TWO 750-Kw. GENERATORS DIRECTLY COUPLED TO TANDEM COMPOUND GAS ENGINES
Courtesy of Allis-Chalmers Company, Milwaukee, Wis.

The use of solid poles, however, leads to excessive eddy-current losses; hence solid poles are not considered desirable.

Inverted Rotaries. When a rotary converter is used to convert a direct current into an alternating current, taking direct current in at the commutator and delivering alternating current at the collector rings, it is called an *inverted rotary converter*. While the rotary converter is generally used to convert alternating current into direct current, it sometimes happens that inverted converters are desirable. For example, in a low-tension, direct-current system, a district remote from the central station may be supplied with current by converting direct current to alternating current at the station (by means of inverted rotaries); then, by step-up transformers, raising the voltage to a high value, and transmitting it as high-tension alternating current; and finally, at the distant point, reconverting it (using step-down transformers) to direct current. Again, in a station containing direct-current generators for short-distance supply, and alternators for long-distance supply, the converter may be used as the connecting link to shift the load from the direct to the alternating generators, or conversely. The machine which is used for shifting the load in this way is caused to operate as a regular rotary or as an inverted rotary according to the demand for direct current or alternating current.

The behavior of an inverted rotary converter is different in many respects from the performance of the same machine when used as a regular rotary converter. When converting from alternating current to direct current, the speed of the converter is rigidly fixed by the frequency of the alternating current supplied to it, and cannot be varied by alternating its field excitation. Varying the field excitation would merely change the phase difference between the alternating electromotive force and current supplied to the machine, and hence the power factor, as in the case of the synchronous motor. When converting from direct current to alternating current, however, the speed of the converter, as in a direct-current motor, will be proportional to the applied direct-current voltage, and will also depend upon the field excitation. The effect of weakening the field is to increase the speed, and the effect of strengthening the field is to decrease the speed. It is evident, therefore, that there should be little or no series field winding provided on an inverted rotary con-

verter, as it will change in speed under load and deliver alternating currents at a variable frequency. If the field becomes greatly weakened, an inverted rotary converter may reach a dangerously high speed before the attendant has time to prevent it, and the armature of the machine may be torn to pieces by the excessively large centrifugal forces.

Changing the field excitation of an inverted rotary converter will not change the voltage of the alternating current, because the ratio of transformation in a given converter is fixed; changing the field strength merely causes a change in the speed of the rotary.

The voltage of the alternating current may be changed by changing the voltage of the applied direct current, or it may be varied by using alternating-current potential regulators, page 448.

Speed-Limiting Devices. An inverted rotary being an alternating-current generator, its field strength depends upon the intensity and the phase relation of the alternating current supplied by its armature; thus a lagging current in the armature reduces the field strength, and hence increases the speed and the frequency; whereas, a leading current increases the field strength, and thus decreases the speed and the frequency. Again, if the alternating-current side of an inverted rotary converter delivers large lagging currents to inductive receiving circuits, such as induction motors, the demagnetizing action of the lagging armature currents on the field may result in a dangerously high speed. In operating inverted rotary converters, therefore, especially when they are liable to be overloaded on the alternating-current side, as in the starting of synchronous or induction motors supplied from the inverted rotary, great care should be taken to see that the field excitation is always great enough to prevent excessive speeds. When used for the above purpose, special speed-limiting devices should be used.

A method used by the Westinghouse Company to prevent this tendency of the inverted rotary converter to race, is as follows:

The converter is separately excited by a small direct-current generator mechanically connected to, and driven by, it. The speed of the exciter will, therefore, change with every change in the speed of the inverted rotary. The magnetic circuit (magnet cores, yoke, etc.) and magnet coils of the exciter are so designed that its armature can generate normal voltage when the machine is being worked at a point considerably below the "knee" of the saturation curve. Any increase in the speed of the exciter will, therefore, cause a great

increase in its voltage. If then the speed of the inverted rotary converter increases, the voltage of the exciter immediately increases and strengthens the field of the converter, thus checking its tendency to race.

The same result is attained by the General Electric Company, but in a different manner, as follows:

A kind of centrifugal governor is attached to the shaft of the inverted rotary and revolves with it. If the speed of the rotary converter increases above a certain value, the governor acts, thus closing an electric circuit which automatically throws off the power supplied to the rotary.

Control of Direct-Current Voltage. The relations between the alternating-current voltages supplied to a rotary converter and the direct-current voltage of the machine, as explained on page 331, and as expressed in equations (45), apply to the case in which the field excitation of the rotary converter is such that the alternating currents delivered to the machine are in phase with the applied alternating-current voltages; that is, these relations apply to the case in which the power factor of the machine is unity. The direct-current voltage of a rotary converter may be slightly greater or less than the ideal value given in equations (45), but the fact remains that the ratio of the alternating-current voltage to the direct-current voltage of a given converter is nearly constant. The fixed ratio of these voltages is a serious handicap in electric railway and similar work where it is desirable to have the station voltage increase as the demand for current increases, in order that the voltage at a distant point of the line shall be kept up in spite of the increase in line drop. In order, therefore, to increase the voltage of the direct-current output of the rotary converter it is necessary to increase also the alternating-current voltage supplied to its collector rings. This increase of voltage may be secured by the following methods:

- (a) Variable ratio step-down transformers
- (b) Variable ratio low-voltage autotransformers.
- (c) Voltage regulators (see page 448)
- (d) Synchronous regulators or boosters
- (e) Series field winding properly proportioned in connection with series inductive reactance (compounding)

Methods (a), (b), (c), and (d) are non-automatic, and are used where the load is fairly constant over considerable periods. Method (e) is entirely automatic within a range of 10 to 15 per cent and is frequently used where the load is rapidly fluctuating, as in electric

railway service. With the necessary auxiliary apparatus, methods (c) and (d) can be made to operate automatically.

In using method (a) the transformers for rotary converter service are designed for the normal secondary voltage which will give the required direct-current voltage. They are provided with taps on both primary and secondary windings which allow compensation to be made for line drop or for any small variation from the desired standard voltage. These taps, however, cannot be used for controlling the voltage while the apparatus is in service. Method (d) requires a synchronous booster which is merely an auxiliary alternating-current generator, with the same number of poles as the converter, and whose armature is mounted on the shaft of the converter. The armature winding of this generator is connected in series between the armature and the collector rings of the converter. The field




Fig. 310. Rotor of Westinghouse Six-Phase Rotary Converter with Synchronous Regulator

magnets of the booster are separately excited so that its armature voltage may be varied from zero to a maximum. Thus, since the armature windings of both the converter and the booster are in series, the alternating-current voltage supplied to the collector rings may be varied at will, and the voltage on the direct-current side changed accordingly.

If necessary the excitation and the polarity of the regulator may be reversed, so that the voltage derived from the regulator may be subtracted from the normal value of the impressed alternating-current voltage instead of added to it, and a corresponding reduction of the direct-current voltage obtained. The regulator may be arranged for either automatic or manual control.

With a synchronous regulator having 15 per cent of the rotary converter capacity, the direct-current voltage can be varied 30 per

cent at will; or, if desired, a constant voltage can be maintained. Moreover, the regulator field can be so controlled that when operating in parallel with other rotary converters, or storage batteries, the converter will take its proper share of the total load.

Fig. 310 shows the rotor of a 770-kw., six-phase rotary converter provided with a synchronous regulator or booster, made by the Westinghouse Electric Company. Passing from left to right in the figure, there are: the commutator of the converter, the armature of the converter, the armature of the synchronous regulator, the six collector




Fig. 311. Westinghouse Three-Phase Converter with Synchronous Regulator

rings, and on the extreme right the squirrel-cage rotor of the auxiliary starting motor.

Fig. 311 is a view of a Westinghouse three-phase 1,000-kw. converter with a synchronous regulator. The regulator frame, with its field poles and windings, is supported by brackets attached to the converter frame. The converter itself is the same as other standard converters, the main field windings being free from all regulating devices.

Method (e) for voltage control depends on the action of the series field winding in connection with series reactance. As already

shown on page 226, the field excitation of a synchronous motor may be varied through quite a range above or below that corresponding to unity power factor, the machine taking leading currents when its field is over-excited, and lagging currents when its field is under-excited. This is especially the case when the synchronous motor has considerable armature inductance, and when the transmission line also has considerable inductance. This remark applies to the rotary converter also; and, when the transmission line has considerable reactance, the alternating-current voltages between the collector rings of a rotary converter and the direct-current voltage between its direct-current brushes vary with the field excitation of the converter.

Where there is both inductance and resistance drop in the feeders and a considerable variation in the alternating voltage supply, the converter, if provided with series field winding, can be made to regulate automatically for constant direct-current voltage within reasonable limits, as explained below.

As the ratio of the alternating current to the direct-current voltage of a converter is nearly constant, the impressed alternating voltage must be varied in order to vary the direct-current voltage. This can be done by taking advantage of the fact that an alternating current passing over an inductive circuit will decrease in voltage if lagging in phase behind its electromotive force, and will increase in voltage if leading. Just as in the case of a synchronous motor, a certain field excitation in any converter will give a minimum armature current. If the excitation be decreased, the armature current will be increased but will be lagging. By providing, therefore, sufficient reactance in the alternating-current circuit connecting a converter with its source of power, the alternating-current voltage at the converter terminals may be varied by means of the field excitation of the converter, and without altering the generator voltage.

When it is desired to control the direct-current voltage of a rotary converter independently of the voltage of the alternating-current generator that supplies the alternating currents, the transmission line is frequently given an artificial reactance by connecting inductance (reactance) coils in series with the alternating-current supply mains. Thus, the alternating currents delivered to the converter are caused to flow through these reactance coils. When,

therefore, a rotary converter has a compound field winding (series and shunt), as described below, the use of reactance coils in the supply mains is necessary if the transmission lines do not of themselves have sufficient reactance.

Field Excitation. Various methods are employed for exciting the field magnet of rotary converters, as follows:

(a) *By Armature Reaction.* When an alternating-current generator delivers leading current to a receiving circuit, the magnetizing action of the armature currents tends to strengthen the field magnet poles, as explained on page 109. If an alternating-current generator were always used to deliver leading currents, it would be possible to depend upon the magnetizing action of the armature currents entirely for exciting the field magnet, without using any direct current whatever in the field windings; in fact, the field windings could be dispensed with altogether.

When a synchronous motor, or rotary converter, takes lagging currents from alternating-current supply mains, the magnetizing action of these currents in the motor armature is to strengthen the field magnetism of the motor, or rotary converter. This action alone may be utilized for exciting the field magnet of a synchronous motor, or rotary converter, and rotary converters have been designed and commercially operated with this mode of field excitation.

(b) *Self-Excitation by Direct-Current Taken from the Commutator of the Machine.* The usual method of exciting the field of a rotary converter is by means of direct current taken from the commutator of the machine itself. There are three schemes for carrying out this method of field excitation, exactly as in the case of ordinary direct-current generators, as follows:

(1) *Series excitation.* This scheme, in which the entire direct-current output flows through the field winding (coarse wire), gives a field excitation which is zero when the direct-current output is zero, and which rises to full-rated excitation when full-load output of direct current is reached. This scheme of field excitation is not suitable for rotary converters, inasmuch as a rotary converter should have an approximately constant-field excitation, or a field excitation which changes through a comparatively narrow range only.

(2) *Shunt excitation.* In this scheme the field winding is made of comparatively fine wire. Its resistance, therefore, is comparatively high, and it is connected directly between the direct-current brushes with an adjustable field rheostat in its circuit, exactly as in the ordinary shunt-wound direct-

current dynamo. This scheme gives an approximately constant field excitation, and it is much used in rotary converters. The variation of field excitation for the purpose of controlling the power factor of the converter is accomplished by means of the adjustable field rheostat.

(3) *Compound excitation.* The combination of series and shunt excitation is frequently used in rotary converters so as to provide for slightly increasing field excitation (by means of the series winding) with increasing direct-current output. This scheme of field excitation is, however, more limited when applied to a rotary converter than when applied to an ordinary direct-current dynamo, for the reason that too great an increase of field excitation in a rotary converter (as in the case of a synchronous motor) causes the converter to fall out of synchronism and stop, or "break down," as it is termed.

Compound-wound rotary converters are used to advantage for supplying current which is constantly fluctuating (and where the generators supplying the converters do not greatly exceed the latter in kilowatt capacity) as in railway service, and in cases where it is necessary to maintain constant or increasing voltage with increasing load. More or less prominence can be given to shunt or series windings as may be required.

The regulation is made automatic by a series field winding on the converter, but the inductance of the transmission lines and generator must frequently be increased by introducing reactive coils.

The amount of raising ("boosting") or lowering of the voltage is proportional to the reactance in circuit, for a given series field. Considering, however, that the maximum output of the converter and its stability are affected by too much reactance, the introduction of reactance should not be carried too far.

In compound-wound converters the shunt excitation is generally adjusted to give a lagging current of from 20 per cent to 30 per cent of full-load current at no load by under-excitation, and the series field is adjusted to give a slightly leading current at full load. This arrangement lowers the impressed voltage at the converter at no load and raises it at full load enough (with constant voltage at the generator) to compensate for all the losses of voltage in the system, thus making possible the delivery of a constant direct-current voltage at all loads.

It has been found in practice that the compound winding distinctly diminishes the stability of running when the tendency to hunt is present to any extent. The series winding should be cut out

when starting up from the direct-current side. This is conveniently accomplished by a double-throw switch which in one position connects the junction of the series winding and the negative brushes to the starting rheostat, and in the other position connects this junction with the equalizing bar.

(c) *Separate Excitation.* The use of a small auxiliary direct-current dynamo to supply direct current for exciting the field of a rotary converter has been mentioned on page 348, where it was pointed out that this method of field excitation is especially suited to inverted rotaries.

Rotary Converter with Edison Three-Wire System. The Edison three-wire system must ordinarily be supplied with current from two direct-current generators connected in series between the outside mains, and with the neutral main connected to the junction of the two machines.

To operate a three-wire system from a single direct-current generator would give rise to great differences of voltage on the two sides of the system when the number of lamps on one side differs greatly from the number of lamps on the other side; in fact, it would not be allowable to turn off a lamp on one side without turning off a lamp on the other side at the same time. To avoid this difficulty some arrangement which is equivalent to the use of two generators is necessary.

A rotary converter may be used to deliver direct current to an Edison three-wire system giving every advantage ordinarily obtained by the use of two direct-current generators connected in series. For such service the third wire must be connected to the neutral point of the transformer group in such a manner that the current in the neutral will flow equally in both directions through the transformer windings and, therefore, will not change the effective magnetic flux in the core of the transformer. When three-phase distribution is used the direct current neutral is brought out from the common junction point of the inter-connected Y secondaries. With two-phase distribution the direct current neutral can be connected to the middle point of the secondary coils of the transformer.

The connections of a three-phase rotary converter for supplying direct current to an Edison three-wire system are shown in

Fig. 312. The three primaries *A*, *B*, and *C* of the step-down transformers for supplying alternating currents to the rotary converter




Fig. 312. Connections for a Three-Phase Rotary Converter on Edison Three-Wire System

are either Y - or Δ -connected to the high voltage supply mains. The three secondaries *a*, *b*, and *c* are Y -connected to the collector rings *r'*, *r''*, *r'''*, of the rotary converter. The two outside direct-current mains 1 and 3 are connected to the direct-current brushes of the converter as shown,

and the middle main (neutral main) 2 is connected to the common junction *N*, or neutral point, of the Y -connected secondaries *a*, *b*, and *c*. With these connections, the voltage between mains 1 and 2 is a steady direct-current voltage, as is also the voltage between mains 2 and 3, and each of these voltages is equal to half the voltage between mains 1 and 3. When the number of lamps connected between mains 1 and 2 is different from the number connected between mains 2 and 3, or *vice versa*, the neutral main must carry a direct current equal to the difference of the direct currents in the mains 1 and 3. This direct current in the neutral main 2 is actually supplied through the secondary coils *a*, *b*, and *c* from the collector rings. The rotary converter may also be




Fig. 313. Connections for D. C. Generator on Edison Three-Wire System with Two-Phase Rotary Converter Connected as a Balancer

used to take the place of two machines, a generator and a motor, used in combination to form a "balancer" for keeping the voltages on the two sides of an Edison three-wire system the same.

Fig. 313 shows an ordinary direct-current generator *G*, sup-

plying current to the outside mains 1 and 3, of an Edison three-wire system, and a two-phase rotary converter *R*, connected as a "balancer" to supply the necessary direct current to the middle main 2. The armature only of the rotary converter is shown in the figure, its direct-current brushes being connected to the outside mains 1 and 3. One pair of opposite collector rings of the converter *R* is connected to an inductance coil *a a*, wound on an iron core, and the other pair is connected to an inductance coil *b b*. The middle points of these two inductance coils are connected together and to the middle or neutral main 2 of the three-wire system.

Six-Phase Converter. The large rating of a six-phase converter as shown in Table X, together with other advantages enumerated below, make this machine the standard converter for large outputs. The advantages of the six-phase converter are as follows:

(a) The high rating, namely, 1.92 times the rating of the same machine as a direct-current generator, or 1.45 times the rating of the same machine as a three-phase converter, means that the machine may be smaller and, therefore, cheaper for a given output. The high rating of the six-phase converter is due to the fact that its armature winding is tapped at six points (for a two-pole machine), and that alternating currents enter the armature winding at six points, so that the length and the resistance of the paths from collector rings to commutator are less, and the heating of the armature windings is less than it is in a three-phase converter, for example, for the same direct-current output.

(b) The six-phase converter runs more stably than a converter having a smaller number of collector rings, and has less tendency to hunt.

(c) The magnetizing actions of the alternating and direct currents in the armature are more nearly balanced in the six-phase converter than in a converter having a fewer number of collector rings, and commutation is freer from sparking and flashing.

In spite of the above advantages, the greater complication of the transformer and collector connections outweighs them in the smaller sizes. Six-phase converters, therefore, are rarely built in units of less than 500 kilovolt amperes. Above this output the six-phase is usually preferable to the three-phase machine.

Transformer Connections for Rotary Converters. Figs. 314 to 321 show the connections which are commonly employed between transformers and rotary converters. The circular spiral winding at the bottom of each figure represents the armature winding of a bipolar converter, the collector rings being omitted to avoid confusing the diagram. Figs. 314, 316, 318, and 320 show the two-phase

and three-phase connections, while figures 315, 317, 319, and 321 are for six-phase connection.




Fig. 314. Transformer Connections for Two-Phase Rotary Converter




Fig. 315. Transformer Connections for Six-Phase Rotary Converter

Each pair of figures, 314 and 315, 316 and 317, 318 and 319, 320 and 321 are closely related. Thus in Figs. 314 and 315, the two terminals of each transformer secondary coil are joined to the armature winding of the converter at points 180 degrees apart. Such connection is called the *diametrical connection* and it is possible when the rotary has an *even* number of rings. In any diametrical connection of the secondaries of the step-down transformers (one trans-




Fig. 316. Transformer Δ Connections for Three-Phase Rotary Converter





Fig. 317. Transformer Double Δ Connections for Six-Phase Rotary Converter


former for a two-ring converter, two transformers for a four-ring converter, and three transformers for a six-ring converter), the voltage

in each secondary coil is the same in value, no matter how many rings the converter may have.



Three-Phase Y Connection

Fig. 318. Transformer Y Connections for Three-Phase Rotary Converter




Six-Phase Double Y Connection

Fig. 319. Transformer Double Y Connections for Six-Phase Rotary Converter

The diametrical connection of the transformer secondaries to the converter rings is simpler than the connections shown in Figs. 317, 319, and 321, inasmuch as the diametrical connection requires only one secondary coil on each of the step-down transformers and, therefore, but two secondary leads are brought out from each transformer; whereas the connections shown in Figs. 317, 319, and 321 require two secondaries on each transformer and, therefore, four secondary leads from each transformer. The switching arrangements for the diametrical connection are, therefore, simpler than they are for the connections shown in Figs. 317, 319, and 321.

Fig. 316 shows three step-down transformers receiving three-phase currents and delivering three-phase currents to a rotary converter, the secondaries being connected to the collector rings. Fig. 318 shows the same arrangement except that the secondaries are Y-connected to the collector rings. Fig. 320 shows a Scott* trans-




Three-Phase T Connection

Fig. 320. Transformer T Connections for Three-Phase Rotary Converter

*The principle of phase transformation is explained in detail on page 257.

former receiving currents from two-phase supply mains and delivering three-phase currents to a three-ring converter. This Scott transformer arrangement is often called the **T** connection, and it may be adapted with slight modification to three-phase supply, that is, to transform three-phase alternating currents into two-phase alternating currents.

For three-phase rotary converters, the transformers should preferably be connected in Δ , as this permits the system to be operated with only two transformers, in case the third has to be cut out of the circuit temporarily for repairs.



Six-Phase Double T-Connection
Fig. 321. Transformer Double T Connections for Six-Phase Rotary Converter

The **T** connection as shown in Figs. 320 and 321 requires only two transformers, and it can be used to change from either two-phase or three-phase to three-phase, as shown in Fig. 320, or from two-phase or three-phase to six-phase, as shown in Fig. 321. The **Y** or **T** arrangement of transformers is particularly advantageous where a rotary is to be used to supply direct current to an Edison three-wire system. Of course, two converters can be used, one on

each branch of the three-wire system, and this is the preferable method where the branches are liable to be greatly unbalanced. With the **Y** or **T** connection of transformers a single converter can be connected across the outside wires of the three-wire system, the neutral wire can then be joined to the neutral point of the **Y** connection, or to a tap, in one of the transformer windings, which tap corresponds to the neutral point of the **Y** connection.

TESTING ROTARY CONVERTERS

Standard Tests. For a rotary converter, the *saturation* and *core loss* curves are obtained in the same manner as in the case of an alternating-current generator, with the exception that the direct-current voltage is also recorded. The *phase characteristic* is determined and the *pulsation test* is made in the same manner as for a synchronous motor, except that the direct-current voltage should be

recorded. The machine, of course, is run as a synchronous motor, being supplied with alternating current through its collecting rings. The pulsation test should be made with the converter self-excited.

Heat Run. To make a heat run on a rotary converter it may be run either as a synchronous motor taking alternating currents through its collector rings, or as a direct-current motor supplied with direct current through its brushes and commutator. If driven as a synchronous alternating-current motor, the full load output is taken from the commutator end of its armature, or *vice versa*, and is delivered to a water rheostat or other receiver. During the run the following readings should be recorded every half hour:

Volts D.C.	Volts A. C.	Amperes D. C.	Amperes A. C.	Amperes Field	Volts Field	Speed	Room Temp.
---------------	----------------	------------------	------------------	------------------	----------------	-------	---------------

When the rotary converter has reached a constant temperature, after running continuously a number of hours under rated full-load conditions, the machine may be shut down, and thermometers quickly applied to measure the temperature of the following parts:

- | | |
|----------------------------|--------------------|
| Armature laminations | Field spools |
| Armature ventilating ducts | Pole tip, leading |
| Armature coils front end | Pole tip, trailing |
| Armature coils back end | Frame |
| Armature binding wires | Bearings |
| Commutator | Room |
| Collector rings | |

The condition of constant temperature is indicated when the voltage applied to the terminals of the field winding in order to keep the current in the field winding constant, no longer increases. In other words, the resistance of the field winding increases for a time due to increasing temperature of the winding, and it takes an increasing voltage at the field terminals to maintain the field current constant. But when the temperature of the field windings becomes constant, the voltage required at the field terminals no longer increases.

Motor-Generator Method. If two similar rotary converters are at hand, the heat test may be made by the "motor-generator" method,

in a manner somewhat similar to the method described under transformers. This method applied to rotary converters involves running one machine as an inverted rotary taking power through its brushes and commutator from direct-current mains. The second machine is made to run as a regular rotary converter, taking its power from the collector rings (that is, alternating-current side) of machine No. 1. Machine No. 2 then delivers its power in the form of direct current from its commutator back to the direct-current supply mains, or to the commutator of machine No. 1. Machines Nos. 1 and 2 are now said to be, "tied together in multiple on both the direct-current




Fig. 322. Wiring Diagram for Motor-Generator Method of Testing Rotary Converters

and the alternating-current sides." If the machines are similar in every respect, no appreciable current will flow between the two under these circumstances. Each will run from the direct-current side, the two together taking only enough power from the direct-current mains to supply the no-load losses in both machines. If, however, an auxiliary electromotive force is applied in the circuit between the machines on the alternating-current side, it will immediately cause current to flow between the machines precisely as in the case of the transformer test above referred to.

Fig. 322 is a diagram of the electrical connections for this method of running. R_1 and R_2 are the two three-phase rotaries. They are shown connected together electrically on the alternating-current

side (that is, the collector rings of R_1 are connected to the corresponding collector rings of R_2) through an induction regulator R . This regulator supplies to the circuit of each phase the auxiliary electromotive force necessary to cause the current to flow between the two machines. The electromotive forces supplied by the regulator are adjustable. When the machines are first thrown together the regulator is in such a position that its electromotive forces are zero.

On the direct-current side (commutator ends) both machines are shown electrically connected to the direct-current supply mains. The method of procedure in starting the two machines is as follows:

First, R_1 is started as a direct-current motor from the direct-current side (commutator). Its field current is adjusted until it runs at the right speed when the normal voltage is applied to its armature terminals; R_1 is at this time entirely disconnected from R^2 . Next R_2 is started in the same manner. Then R_1 and R_2 are synchronized and connected together, as shown in the diagram, by closing switches S_1 , S_2 , and S_3 on the alternating-current side.*

The most convenient way to synchronize the machines for testing is to connect up a series of incandescent lamps across each of the switches S_1 , S_2 , and S_3 . The number of incandescent lamps in each series should be such that they can stand twice the normal alternating voltage of each machine.

The field current of R_2 is varied until it is almost in synchronism with R_1 , as shown by the slow pulsations of the synchronizing lamps. When the lamps are dark, there is zero voltage across the terminals of the switches, and then they can be safely closed. If the lamps connected across the switches do not all go out at the same instant, the machines cannot be synchronized. In this case the direction of rotation of one of the machines must be reversed, or two of the leads on the alternating-current side of one of the machines must be interchanged.

Up to this time the two machines have been running independently of each other. Each has taken sufficient current from the mains to supply the losses occurring in it while running unloaded. When the two machines are connected together on the

*The apparatus for determining when the two machines are in synchronism is not shown in the figure.

alternating-current side by closing the switches S_1 , S_2 , and S_3 , they run in synchronism. If the regulator R is in its zero position, no appreciable current will flow between the two machines. As the voltage of R is increased, however, a current will circulate between the two machines. If the voltage of R is in such a direction that V_2 is greater than V_1 , then R_2 will run as a regular rotary converter, and R_1 as an inverted rotary. The power will pass from R_1 to R_2 on the alternating-current side, and from R_2 to R_1 on the direct-current side. R_1 will run as an inverted rotary, driving R_2 on the alternating-current side, and R_2 will run as an ordinary rotary converter driving R_1 on the direct-current side.

By sufficiently increasing the voltage of R we can cause full-load or even over-load conditions to obtain. The direct-current mains deliver merely the power to supply the losses in the entire system. Ammeter A indicates the current supplied to overcome the losses in the system. Under these circumstances, R_1 will have a load slightly greater than R_2 . Ammeter A_1 should give a reading equal to the sum of the readings of the two ammeters A and A_2 .

The chief advantage of this method is that full-load conditions are obtained without actually supplying full-load current from the direct-current supply mains. The mains supply simply the power losses in both machines. Another great advantage is the ease with which the load can be controlled. By this method, moreover, two machines can be tested more easily than a single machine by the ordinary method. If it is desired to test one machine only, the load may be put on in the same way by connecting it up with a second machine. It is not necessary in this case that the second machine be of the same size as the first. It is only necessary that it be of the same voltage and frequency, and that it can carry without excessive heating the full-load current of the machine to be tested. The current, during the run, is adjusted to the normal full-load value of the machine to be tested.

MOTOR-GENERATORS

The last method of obtaining direct current from alternating-current circuits is by a motor-generator, which consists of an alternating-current motor driving one or more direct-current generators.

The motor may be of the induction or of the synchronous type. In either case the motor is usually mounted on the same base with, and mechanically coupled to, the generator. The smaller sets up to about 150 kilowatts are usually driven by induction motors for 25, 40, or 60 cycles, and are customarily used for charging storage batteries or for furnishing the exciting current for the fields of alternators or synchronous motors. The larger sets, from 200 kilowatts upwards, are used for the supply of lighting, railway, or power systems, and are usually driven by synchronous motors, which have the advantage of permitting the control of the power factor of the circuit by varying the field excitation, but have the disadvantage of requiring a direct-current field excitation. Synchronous motors have an advantage over induction motors in that large sizes may be wound for 11,000 or 13,200 volts, whereas induction motors of the same size are limited to 2,080 or 6,000 volts.

Comparison with the Rotary Converter. A motor-generator employing a synchronous motor does not seem to possess any essential advantages over the rotary converter, except in some cases where independent control of the direct-current voltage is desired. The use of the synchronous motor does not remove the objections to the rotary converter which are based on the fact that it is a synchronous machine.

A motor-generator employing an induction motor has the advantage of using induction instead of synchronous apparatus, thereby securing many of the advantages summarized later in the comparison between synchronous and induction motors, page 401.

Circuits which are supplied by alternating-current generators the speed of which has rapid and periodic fluctuations, or in which for any other reason the conditions are such as to cause "hunting" in synchronous machines, may, however, satisfactorily supply an induction motor driving a generator. The various characteristics of the induction motor under emergency conditions, such as a sudden overload, momentary interruption, or lowering of the voltage of the supply circuit, may cause little or no inconvenience if the induction motor is used, whereas it might cause serious interruption to a rotary converter or a synchronous motor. The induction motor driving a generator is also to be preferred where the size of the units is quite small and the attendance is unskilled. It is also preferable for single-

phase work. The armature for the induction motor should in general be of the squirrel-cage type as the required starting torque does not exceed 20 per cent of full-load torque, and the required starting torque can be obtained with about full-load current.

The rotary converter, like the synchronous motor, is not suitable for general distribution in small units. It has the advantage over the motor-generator in point of cost, there being but one machine instead of two; in point of efficiency, there being the loss in one machine instead of two; and in its effect upon the voltage of the transmission system as a whole, as it may be compounded to overcome the drop which would otherwise occur in generator and transmission circuit.

On the other hand, the electromotive force of the direct current delivered by the converter has a more or less fixed relation to the electromotive force of the alternating currents supplied; whereas the electromotive force of a motor-driven generator is independent of the electromotive force of the supply circuit, and it may be adjusted or compounded as desired. In practice, however, it is found that the voltage delivered by a rotary converter can be satisfactorily adjusted and controlled by regulating devices or by compounding, so that usually the close relation between the electromotive forces at the two ends of the converter is not disadvantageous, provided the electromotive force of the supply circuit is reasonably constant. This statement applies to those cases where a practically constant direct-current voltage is desired. There are, of course, special cases, in which the voltage is to be adjusted over a wide range, or where, for other reasons, the motor-generator is to be preferred. In many cases the motor may be operated without requiring step-down transformers, whereas they would be necessary with rotary converters.

Uses of Motor-Generators. Motor-generator sets are often used in central stations in connection with arc-lighting service. In these cases alternating-current motors are used for driving arc-lighting generators, as in the large plant of the Buffalo General Electric Company. They are also used in some places for supplying three-wire direct-current lighting circuits from alternating-current mains.

Motor-generators are often used in central stations for fur-

nishing direct current to the field-magnet windings of alternators, the direct-current generator part of the set acting as the exciter for one or more large alternators. The alternating current supplied to the (synchronous or induction) motor end of the motor-generator set is taken from the main station bus bars, and may or may not be stepped-down by means of reducing transformers.

Examples of this use of motor-generator sets are to be found in the immense power stations of the Interborough Rapid Transit Company, and the New York Edison Company, of New York City, and in many other places.

Another use for motor-generators is as frequency changers (or converters). In such cases they are used for transforming an




Fig. 323. General Electric Motor-Generator Set with D. C. Exciter

alternating current of one frequency to another alternating current of higher or lower frequency, usually the former. The current may be transformed from three-phase to two-phase, or *vice versa*, at the same time. Thus it might be required to supply a two-phase, 60-cycle lighting system from a 25-cycle, three-phase transmission system, with or without change of voltage.

Types. A motor-generator set built by the General Electric Company is shown in Fig. 323. It consists of a combination of three distinct machines, all mechanically coupled to the same shaft, viz, a three-phase synchronous motor of the revolving-field type; a three-phase alternator also of the revolving-field type; and a direct-

current generator acting as an exciter for the fields of both the alternator and the synchronous motor.

Summary of Data for Fig. 323

	Synchronous Motor	Alternator	Exciter
No. of poles.....	8	12	10
Rated output (kw.)....	275	250	10
Speed.....	570	570	570
Frequency.....	38	57	
Volts.....			60

This particular motor-generator set is designed to be used as a frequency-changer to change from 38 to 57 cycles per second.




Fig. 324. General Electric Motor-Generator Set—Induction Motor Driving Compound-Wound D. C. Generator

The three-phase alternating currents having a frequency of 38 cycles per second are led into the stationary armature terminals of the synchronous motor (shown next to the pulley in Fig. 323). The motor having eight field poles, its synchronous speed is 570 r. p. m.; and since both the alternator and the exciter are coupled to the same shaft, all the machines run at 570 r. p. m.

The alternator having 12 field poles, the frequency of its induced electromotive forces is 57 cycles per second. Hence, the

three-phase alternating electromotive forces induced in the stationary armature of the alternator have a frequency 50 per cent higher





Fig. 325. Two Sets of Brush Arc Light Dynamoes Direct Connected to Induction Motors

than those of the alternating currents which are supplied to the driving synchronous motor.

Fig. 324 is a view of a motor-generator set built by the General Electric Company. It consists of a compound-wound direct-current generator driven by an induction motor, both machines being mounted on the same bed-plate and having a common shaft.

Fig. 325 shows two motor-generator sets, each consisting of two Brush arc-light dynamos directly coupled to an induction motor. In some of the stations of the Brooklyn Edison Company Brush arc-light dynamos are driven in pairs by being directly coupled to three-phase, 25-cycle synchronous motors. The constancy of the speed of synchronous motors makes them especially well suited for driving electric generators.





S.K.C. INDUCTION MOTOR, WITH ARMATURE OR SECONDARY REMOVED,
Showing Field or Primary Winding and Bearings in the End Frames.

ALTERNATING-CURRENT MACHINERY

PART VI

INDUCTION MOTOR

Constructive Elements. It has already been pointed out that the successful use of alternating current for power purposes depends largely upon the use of the *induction motor* supplied with polyphase currents. This machine consists of a primary member and a secondary member, each with a winding of bars or wire. The primary




Fig. 326. Diagram of Squirrel-Cage Type of Rotor




Fig. 327. Diagram Showing Slots in Stator of Induction Motor

member is usually stationary, and is often called the *stator*. The secondary member is usually the rotating member, and is often called the *rotor*. Fig. 326 shows a rotor of the *squirrel-cage* type. It consists of a drum *A* built up of thin circular sheet-iron disks. Near the periphery of this drum are a number of holes parallel to the axis of the drum. In these holes heavy copper rods *b* are placed, and the projecting ends of these rods are screwed and soldered to massive copper rings *r*, one at each end of the drum.

The stator is a laminated iron ring *FF*, Fig. 327, closely surrounding the rotor. This ring is slotted on its inner face, as shown; windings are arranged in these slots, and these windings receive

Copyright, 1911, by American School of Correspondence.

current from polyphase supply mains. These polyphase currents produce in the stator iron a rotating state of magnetism, the action




Fig. 328. Squirrel-Cage Rotor Mounted in Ordinary Four-Pole Field




Fig. 329. Diagram of Four-Pole Two-Phase Induction Motor

of which on the rotor is the same as the action of an ordinary field magnet mechanically revolved. Thus Fig. 328 shows a squirrel-cage rotor *A* surrounded by an ordinary field magnet revolving in the direction of the arrows. This motion of the field magnet induces currents in the short-circuited copper rods of the rotor; the field magnet exerts a dragging force on these currents, and causes the rotor to revolve. No electrical connections of any kind are made to the rotor.

No electrical connections of any kind are made to the rotor.

Stator Windings and Their Action. The stator windings are arranged in the slots *s*, Fig. 327, in a manner exactly similar to the arrangement of the windings of the two-phase or three-phase alternator armature according as the motor is to be supplied with two-phase or three-phase currents.

Two-Phase. Fig. 329 shows an end view of a four-pole two-phase induction motor. In




Fig. 330. Diagram of One-Half the Stator Conductors of Fig. 329

this figure, the outline only of the rotor (or secondary) is shown. The stator conductors are represented in section by the small circles, the slots being omitted for the sake of clearness, and the end con-

nections of half the stator conductors are shown in Fig. 330. In this figure the straight radial lines represent the conductors which lie in the slots of the stator, and the curved lines represent the end connections. The stator conductors are arranged in two distinct




Fig. 331. Magnetic Action of Conductors Carrying Currents between Iron Poles




Fig. 332. Magnetic Action of Conductors Carrying Currents between Iron Poles

circuits. One of these circuits includes all of the conductors marked *A*, and this circuit receives current from one phase of a two-phase system. The other circuit includes all of the conductors marked *B* and this circuit receives current from the other phase of the two-phase system. The terminals of the *B* circuit are shown at *tt'*, Fig. 330. The conductors which constitute one circuit are so connected that the current flows in *opposite directions* in adjacent groups of conductors as indicated by the arrows in Fig. 330.

The action of a band of conductors between the two masses of iron is shown in Figs. 331 and 332. The small circles represent the conductors in section; conductors carrying down-flowing currents




Fig. 333. Instantaneous Effect of Alternating Current for a Given Position of Rotor




Fig. 334. Magnetic Effect of Alternating Current $\frac{1}{2}$ of a Cycle Later than in Fig. 333

are marked with crosses and those carrying up-flowing currents with dots. The action of the currents in these bands of conductors is to

produce magnetic flux along the dotted lines in the direction of the arrows.

The lines A' and B' in the clock diagrams of Figs. 333, 334, and 335 are supposed to rotate, and their projections on the fixed line ef represent the instantaneous values of the alternating currents in the A and B conductors, respectively. These conductors are represented in section by the small circles.




Fig. 335. Magnetic Effect of Alternating Current $\frac{1}{4}$ of a Cycle Later Than in Fig. 333

These conductors are represented in section by the small circles. These small circles are marked with crosses when they carry down-flowing currents, with dots when they carry up-flowing currents, and they are left blank when they carry no current.

Fig. 333 shows the state of affairs when the current in conductors A is a maximum and the current in conductors B is zero, and the dotted lines indicate the paths of the magnetic flux. This flux enters the rotor from the stator at the points marked N and leaves the rotor at the points marked S .

Fig. 334 shows the state of affairs, one-eighth of a cycle later, when the current in the B conductors has increased and the current in the A conductors has decreased to the same value, so that equal currents flow in the A and in the B conductors. The points N and S have moved over one-sixteenth of the circumference of the stator ring, from the positions they occupied in Fig. 333.




Fig. 336. Complete Connections for Four Poles of One Circuit of Three-Phase Induction Motor

Fig. 335 shows the state of affairs, after another eighth of a cycle, when the current in the B conductors has reached its maximum value, and the current in the A conductors has dropped to zero. The points N and S have moved again over one-sixteenth

to zero. The points N and S have moved again over one-sixteenth

of the circumference of the stator ring. This motion of the points N and S is continuous, and these points make one complete revolution (in a four-pole motor) during two complete revolutions of the vectors A' and B' , that is, while the alternating currents supplied to the stator windings are passing through two cycles. In general:

$$n = \frac{2f}{p} \quad (47)$$

in which n is the revolutions per second of the stator-magnetism, p is the number of poles, N and S , and f is the frequency of the alternating currents supplied to the stator windings.

Three-Phase. When an induction motor is driven by three-phase currents, the stator conductors are arranged in three distinct circuits A , B , and C , which are either Δ -connected or Y -connected to the supply mains. Fig. 336 shows the complete connections, for four poles, of the A circuit with its terminals tt' . The B and C circuits are similarly connected.

In general, the q -phase stator winding for p poles has pq equidistant bands of conductors. The first, $(q+1)$ th, $(2q+1)$ th, etc., bands are connected in one circuit, so that currents flow oppositely in adjacent bands, and this circuit takes current from one phase of the q -phase system. The second, $(q+2)$ th, $(2q+2)$ th, etc., bands are similarly connected in another circuit and take current from the second phase of the q -phase system. The third, $(q+3)$ th, $(2q+3)$ th, etc., bands are similarly connected in another circuit and take current from the third phase of the q -phase system; and so on.

ACTION OF INDUCTION MOTOR

Many important details of the action of the induction motor are most easily explained by looking upon the induction motor as a rotor influenced by an ordinary field magnet, mechanically revolved. The complete theory of the action of the induction motor is, however, similar to the theory of the alternating-current transformer.

Torque and Speed. Let n be the number of revolutions per second of the field, and n' the revolutions per second of the rotor. When $n=n'$, the rotor and field revolve at the same speed, so that their *relative* motion is zero; no electromotive force is then induced in the rotor conductors and no current flows and, therefore, the revolving field exerts no torque upon the rotor. As the speed of the

rotor decreases, the difference of the speeds of rotor and field ($n-n'$), increases and, therefore, the electromotive force induced in the rotor conductors, the currents in the conductors, and the torque with which the field drags the rotor, all increase. If the whole of the field flux were to pass into the rotor and out again in spite of the demagnetizing action of the current in the rotor conductors, then the torque would increase in strict proportion to $(n-n')$. As a matter of fact, because of the demagnetizing action of the rotor currents, a larger and larger portion of the field flux passes through the space between the stator and rotor conductors as the speed of the rotor decreases, and this magnetic leakage causes the torque to increase more and more slowly as $(n-n')$ increases. The torque usually reaches a maximum value, and then decreases with further increase of $(n-n')$.

Fig. 337 shows the typical relation between torque and speed of an induction motor. Ordinates of the curve represent torque, and abscissas measured from O represent rotor speeds. The rotor is said to run above synchronism when it is driven so that n' is




Fig. 337. Graphical Relation of Torque and Speed of Induction Motor


greater than n . The rotor never actually reaches synchronous speed, but approaches it very nearly when the induction motor is running unloaded. In order to cause the rotor to run above synchronism, that is, to make n' greater

than n , or in order to cause the rotor to run backwards, that is, in a direction opposite to that of the revolving magnetism in the stator iron, the rotor must be driven mechanically from an outside source of power.

Starting Resistance in the Rotor Windings. The speed of the rotor for which the maximum torque occurs, depends upon the resistance of the rotor windings, and it is advantageous under certain conditions of operation to provide at starting such resistance in these windings as to at once produce the maximum torque, this resistance being cut out as the motor approaches full speed.

Efficiency and Speed. For the sake of simplicity, let us assume that the only opposition to motion of the revolving field magnet

Made by **Curtis Steam Turbine**
General Electric Company



CURTIS TURBINE DRIVING ALTERNATING-CURRENT GENERATOR.
General Electric Company.

is the reaction of the torque which it exerts on the rotor. Let this torque be represented by T . Then the power expended in driving the field magnet is $2\pi nT$, and the mechanical power delivered to the rotor is $2\pi n'T$, and this power $2\pi n'T$ is available at the pulley of the motor, except for slight losses due to friction in the bearings and to air friction. Therefore, ignoring friction losses, $2\pi nT$ is the input of power in driving the revolving field, and $2\pi n'T$ is the output of power, so that the efficiency of the induction motor is $\frac{n'}{n}$.

This expression for efficiency ignores all the losses of power in the revolving field magnet* and the friction and windage losses in the rotor, and shows that the efficiency of an induction motor is zero when the rotor stands still, that it increases as the rotor speeds up, and approaches 100 per cent, *ignoring field losses and friction*, as the rotor speed approaches the speed of the revolving field. The ratio $\frac{n'}{n}$ ranges from 0.85 to 0.95 or more, in commercial induction motors under full load, but the actual full load efficiencies of induction motors range from 75 per cent, or even less for small motors, to about 95 per cent for very large motors.

Ratio of Mechanical to Electrical Energy in Rotor. The total power delivered to the rotor is equal to $2\pi nT$ where n and T have the meanings above specified. That is, all of the power used to drive the field magnet (ignoring losses in the field) is delivered to the rotor. Now, the mechanical power delivered to the rotor is equal to $2\pi n'T$, as already explained; therefore, the difference $2\pi nT - 2\pi n'T$ † is electrical power used to force the rotor currents through the rotor windings.

Therefore, when the field speed is n and the rotor speed is n' , the total power delivered to the rotor, the mechanical power developed in turning the rotor, and the electrical power developed in the rotor windings are to each other as, n , n' , and $(n - n')$, respectively.

*In the actual induction motor, it ignores the loss of power due to the heating of the stator windings by the supplied alternating currents, and the loss of power due to core losses in the stator iron.

†When torque is expressed as pounds weight on a lever arm of one foot in length the torque is said to be expressed in pound-feet, and power in watts is equal to $\frac{2\pi nT \times 746}{550} = 8.52nT$ watts, where n is the speed in revolutions per second.

Ratio of Rotor Voltages to Stator Voltages. When the rotor is wound with the same number of conductors as the stator, then when the rotor is standing still, the rotating stator magnetism induces in the rotor windings electromotive forces of the same value and of the same frequency as the electromotive forces induced in the stator windings by this rotating stator magnetism (neglecting magnetic leakage). Moreover, the electromotive forces induced in the stator windings are very nearly equal and opposite to the voltages applied to the stator windings. When the difference of the speeds of the rotor and the stator magnetism is $(n-n')$, the electromotive forces induced in the rotor windings are the fractional part, $\left[\frac{n-n'}{n} \right]$, of the voltages applied to the stator windings, and the frequency of the electromotive forces induced in the rotor windings is the fractional part, $\left[\frac{n-n'}{n} \right]$, of the frequency of the voltages applied to the stator windings.

Example. Let a certain three-phase induction motor having a stator wound for 6 poles, and taking three-phase alternating currents at a frequency of 60 cycles and a voltage of 220 between any two of the three supply mains, have a rotor furnished with the same number of conductors as the stator. Further, let the no-load speed of the rotor be 1194 r.p.m., and its full-load speed be 1,143 r. p. m. Assuming that the magnetic leakage is negligible, it is required to find:

- (a) The synchronous speed.
- (b) The electromotive forces (three-phase) induced in the rotor windings at no-load and at full-load.
- (c) The frequency of the electromotive forces induced in the rotor windings at no-load and at full-load.

Solution: (a) The synchronous speed of the rotating magnetism in the stator is, according to equation (47),

$$n = \frac{60}{\frac{6}{2}} = 20 \text{ revolutions per second, or } 1,200 \text{ r.p.m.}$$

- (b) The electromotive forces (three-phase) induced in the rotor windings at no-load are

$$\frac{(n-n')}{n} \times \text{voltage applied to stator}$$

or

$$\left(\frac{1200 - 1194}{1200} \right) \times 220 = 1.10 \text{ volts}$$

The voltages induced in the rotor windings at full-load are

$$\left(\frac{1200 - 1143}{1200} \right) \times 220 = 10.45 \text{ volts}$$

It is interesting to note that if the slip of the rotor at no load were zero, or in other words, if n' were equal to n there would be zero electromotive forces induced in the rotor windings at no-load.

(c) The frequency of the electromotive forces induced in the rotor windings at no-load is

$$\frac{(n - n')}{n} \times \text{frequency of stator voltage}$$

or

$$\left(\frac{1200 - 1194}{1200} \right) \times 60 = 0.3 \text{ cycles per second}$$

The frequency of the electromotive forces induced in the rotor windings at full-load is

$$\left(\frac{1200 - 1143}{1200} \right) \times 60 = 2.85 \text{ cycles per second}$$

When the rotor is at rest, the frequency of the electromotive forces induced in the rotor windings is the same as the frequency of the stator voltage, namely, 60 cycles per second.

Efficiency and Rotor Resistance. For a given difference $(n - n')$ between field speed and rotor speed, a definite electromotive force is induced in the rotor conductors, and the less the rotor resistance, the greater the current produced by this electromotive force, and the greater the torque. Therefore, a given induction motor will develop its full load torque for a small




Fig. 338. Iron Stator Frame for Westinghouse Induction Motor

value $(n - n')$ or for a large value of $\frac{n'}{n}$ (efficiency) if its rotor resistance is small. High efficiency depends, therefore, upon low rotor resistance.

The necessity of high rotor resistance to give large torque at starting has nothing to do with the necessity of making the rotor

resistance small in order to secure full load torque at as nearly synchronous speed as possible. These two conflicting conditions may be realized in one motor by an arrangement whereby a resistance which is in circuit with the rotor conductors at starting, may be short-circuited when the motor nearly reaches its rated speed.

Structural Details of a Typical Induction Motor. Figs. 338 to 341 show the structural details of a typical induction motor manufactured by the Westinghouse Electric and Manufacturing Company. It has a stationary primary member (often called the stator or field) and a rotating secondary member (often called the rotor or armature).



Fig. 339. Primary Member of Westinghouse Induction Motor Completely Wound

The primary member is mounted in a hollow cylindrical frame of cast iron shown in Fig. 338. This frame forms a base for the machine, and also supports the two end-brackets which carry the self-oiling bearings. Inside the frame are several lugs that support the stator core laminations far enough from the frame to leave space between the frame and the core for ventilation. The iron core of the primary member consists of a ring built up of sheet-steel stampings slotted on the inside to receive the primary conductors as shown in Fig. 339. The laminations are assembled, clamped, and keyed between stiff end rings inside the lugs on the frame. Steel keys in one or more of the lugs prevent circular movement of the laminations. Fig. 339 shows the primary member completely wound.

The primary conductors are usually grouped in former-wound coils of wire which are thoroughly taped and insulated before being slipped into place in the slots in the stator core. In larger motors

The primary member is mounted in a hollow cylindrical frame of cast iron shown in Fig. 338. This frame forms a base for the machine, and also supports the two end-brackets which carry the self-oiling bearings. Inside the frame are several lugs that support the stator core laminations far enough from the frame to leave space between the frame and the core for ventilation. The iron core of the primary member consists of a ring built up of sheet-

copper strap bent into the proper form is used instead of wire for forming the coils.

The terminals of the primary winding are brought out, usually at one side of the motor, and are clamped in insulated cleats or bushings. The leads which supply alternating currents to the motor are attached to these terminals through suitable connectors.




Fig. 340. Iron Rotor Core for Westinghouse Induction Motor

The iron core of the secondary member (rotor), shown in Fig. 340, is also built up of ring-shaped stampings of sheet-steel assembled, clamped, and keyed between stiff end plates on the arms of the rotor spider. The spider is pressed on the shaft and keyed. Ventilating plates on the rotor cores of the larger motors act like the blades of a fan and force strong currents of air between the rotor end rings and the core and through all the openings in and around the stator windings and core, thus keeping all parts cool. The secondary conductors consist of rectangular copper bars placed in nearly closed slots, around the periphery of the core. These bars project beyond the laminated core, and they are screwed and soldered at each end to massive rings of copper, thus forming a short-circuited secondary winding, as shown in Fig. 340. This type of secondary member is called a *squirrel-cage* rotor. The complete motor is shown in Fig. 341.




Fig. 341. Westinghouse Induction Motor Completely Assembled

Types of Rotors for Constant and Variable Speed. There are three types of secondary members used in commercial induction motors, according to the conditions of service to be met. The start-

ing and running conditions determine which type to adopt in any given case. These types are shown in Figs. 342, 343, and 344.




Fig. 342. Squirrel-Cage Type of Rotor

Fig. 342 is a squirrel-cage rotor. Fig. 343 is a rotor wound with insulated wire, forming what is called a *definite**, or *polar*, winding. The terminals of this winding are connected to a starting resistance mounted inside of the rotor. A switch is arranged to short-circuit this starting resistance, and is operated while the motor is running by means of a rod which lies inside of the hollow shaft of




Fig. 343. Rotor with Definite or Polar Winding with Starting Resistance Inside Core

the rotor. This rod terminates in a small handle or knob at the end of the rotor shaft as shown in Fig. 343. Fig. 354 shows a complete three-phase induction motor with the knob and rod for operating the internal starting resistance.

*This winding is identical with the stator winding as described on page 374.

Fig. 344 is a rotor with a winding similar to the winding of Fig. 343, but instead of connecting the terminals of the rotor winding to an internal starting resistance, these terminals are brought out to collector rings on the end of the shaft as shown in Fig. 344. The circuits of the rotor windings are completed through adjustable external resistances which are connected to the rotor windings by means of brushes rubbing on the collector rings. These adjustable external resistances are regulated by a cylindrical switch or controller similar in general to the ordinary electric street-car controller. Fig. 345 shows a Westinghouse controller for induction motors used for cranes, hoists and similar apparatus.

The cylinder has a set of contacts for making, breaking, and reversing the primary circuit, and another set of contacts for control-




Fig. 344. Rotor with Polar Winding and Collector Rings

ling the speed of the motor by varying the resistance in the secondary circuits. The two sets of contacts on two drums are mounted on the same shaft and all operations are performed by moving one controller handle. The number of speed steps in each direction of rotation may be 6, 9, 12, or 15, according to the capacity of the controller.

An induction motor provided with a squirrel-cage rotor takes excessive current from the alternating-current supply mains at starting. The squirrel-cage rotor requires from three to four times full-load current to produce at starting a torque equal to the torque developed when running at full-load. Hence, when the motor has to start under a heavy load, or where the taking of excessive currents from the supply mains will interfere with other apparatus supplied

from the same mains by causing excessive drop of voltage, the squirrel-cage type of rotor is objectionable, especially in large size motors. On the other hand, the extreme simplicity of the squirrel-cage rotor and its ability to carry enormous currents without injury, largely compensate for the above mentioned disadvantages. Its speed is practically constant, varying only a few per cent from full load to no load. The operating characteristics of the squirrel-cage type of induction motor are such as adapt them to a wide variety of purposes and make them especially suitable for continuous constant-speed service.

An induction motor provided with a rotor like that shown in Fig. 343, with an internal starting resistance, takes at starting only about one and one-half full-load rated current from the supply mains, giving a starting torque of about one and one-half full-load torque. Such an induction motor, therefore, is used only where a starting torque not greatly in excess of full-load torque is required. The advantage of this type of rotor is that it does not take excessive currents at starting, and it will start, therefore, without producing excessive drop of electromotive force in the alternating-current system from which the motor receives its power. The starting resistance in motors up to about 50 horse-power consists of cast-iron grids enclosed in a triangular frame which is bolted to the end plates holding the rotor laminations together. The whole of this resistance is in series with the secondary winding at starting.




Fig. 345. Westinghouse Controller for Induction Motors

As the motor increases in speed, the resistance is short-circuited by sliding spring metal brushes along the inside surface of the grids. The brushes are supported by a metal sleeve sliding on the shaft which is operated by a rod passing through the end of the shaft.

An induction motor having a rotor provided with collector

rings is generally used for cranes, hoists, elevators, and other work where variable speed is required. The starting resistance used in the type of rotor shown in Fig. 343 is designed to carry the rotor current for a short time only, that is, during starting; if kept continuously in circuit for the purpose of speed control, this starting resistance would become excessively hot. For speed control, therefore, an external resistance must be used.

The range of speed control possible in the case of an induction motor provided with a rotor having collector rings connected to external adjustable resistances is about the same as the range of speed control obtainable with a shunt-wound direct-current motor having a regulating rheostat in its armature circuit.

Behavior at Starting and in Operation. When an induction motor is running without load, its speed is nearly equal to the speed of the rotating magnetic field, namely, synchronous speed. Under these conditions the stator takes only sufficient current to force the magnetic flux through the reluctance of the magnetic circuit, and to supply the I^2R losses of the stator windings, the core loss, and the friction and windage loss of the rotor.

When the motor is loaded, its speed decreases in nearly direct proportion to the load, from nearly synchronous speed at no-load to about 98 per cent of synchronous speed in the case of large motors, and to about 92 per cent of synchronous speed in small motors at full-load. Therefore, the induction motor is practically a constant-speed motor. The decrease in speed expressed as a percentage of synchronous speed is called the *slip* of the motor. The slip of large motors is thus about 2 per cent at full-load, and that of small motors is about 8 per cent at full-load.

When an induction motor is overloaded, it takes excessive current from the supply mains, and its torque increases up to a certain value of the slip (a definite value for a given motor). When loaded up to this point the machine is unstable, and the least additional loading causes the machine to "break down" or stop.

This maximum output which a given motor can deliver is usually about one and one-half to two and one-half times as great as its rated full-load output. This maximum output is proportional to the square of the electromotive force of the alternating currents supplied to the motor. Thus a certain induction motor rated at 220

volts has a *maximum* power output of 1.8 times its *rated* output. The same motor supplied with currents at 200 volts would have a maximum output of $\left(\frac{200}{220}\right)^2 \times 1.8 = 1.49$ of its rated output.

When an induction motor is operated at slightly less than its rated frequency but with full-rated voltage, the speed of the motor will be decreased in proportion to the frequency, but its power output will not be greatly affected. The efficiency of the motor, and its rise of temperature under full-load, will be approximately




Fig. 346. Three-Phase Starting Compensator Complete




Fig. 347. Three-Phase Starting Compensator with Cover Removed

unchanged, and the maximum power output will be slightly increased.

An induction motor having a squirrel-cage rotor will develop sufficient torque to start satisfactorily with from 40 per cent to 80 per cent of the rated voltage applied to the primary member. Therefore, the current required at starting may be greatly reduced by supplying the primary member, at starting, with current through a step-down transformer which is designed to reduce the supply voltage to 40, 50, 60, or 80 per cent of the rated voltage of the motor, and to multiply the delivered current in the same ratio. This

step-down transformer is usually an autotransformer. An autotransformer, with its special switching device for changing the motor connections quickly from the low-starting voltage to the full-running voltage, is called an *autostarter*, or a *compensator*. The autostarter may be located at any convenient point, either near the motor or at a distance from it.

Figs. 346 and 347 are general views of a three-phase hand-operated starting compensator of the wall type, as manufactured by the General Electric Company. The compensator consists of three core-type autotransformers, a cable clamp, and a special switch assembled in a metal case with external handle and release lever. In the wall-suspension type the switch is located at the bottom, as seen in Fig. 347, and is enclosed by an oil-filled tank. Fig.




Fig. 348. Electrical Connections for Three-Phase Starting Compensator

348 is a diagram of the electrical connections. The three coils of the three-phase winding are connected in Y , the line to the three free ends of the coil, and the starting connections of the motor to the taps. For motors from 5 to 18 horse-power, these compensators are provided with taps for starting the motor at 50, 65, and 80 per cent of the line voltage, any one of which may be selected after trial for permanent connection to the switch, for starting according to the requirements of any individual case.

The shaft of the switch, as seen in Fig. 347, extends through the sides of the compensator case, and is operated by a lever at the right, being held in the running position by a lever at the left. The switch, provided with heavy wiping contacts, is immersed in oil

and is intended to be used as a line switch as well as for starting the motor. The lever has three positions: "off", "starting", and "running".

To start the motor, the switch is thrown to the "starting position", and is left there until the motor reaches nearly full speed and then the switch is quickly thrown over to the "running position". The time required for bringing an induction motor from rest up to rated speed is about one minute, the time in any given case depending upon the value of the starting voltage used, and the amount of load on the motor at starting. In the "off position" both compensator and motor windings are disconnected from the line. In the




Fig. 349. Diagram of Electrical Connections for a Two-Phase Compensator for Starting Two-Phase Induction Motors

"starting position", Fig. 348, the switch connects the line to the terminals, and the motor to the taps, of the compensator winding, without circuit breakers or fuses in circuit. In the "running position" the compensator winding is cut out and the motor is connected to the line through suitable fuses or overload relays mounted directly above the compensator. For instance, Fig. 347 shows three "cartridge" fuses, one in each of the three line wires. To prevent the attendant from carelessly throwing the motor directly on the line at starting, an automatic latch is provided, so arranged that the lever at the "off position" can be thrown only into the "starting position"

(backward), and can be thrown into the "running position" (forward) only by a quick throw of the lever.

The "no-voltage release", shown in Fig. 348, is an electromagnet whose laminated plunger holds a tripping lever which engages with the lever mounted on the switch shaft. If for any reason the supply voltage is cut off from the motor, the no-voltage release acts promptly to release the tripping lever which in turn, through the action of a strong spring, throws the operating lever to its "off position", where it remains until the supply voltage is again restored, and the motor is to be started.

Fig. 349 shows a diagram of connections for a two-phase compensator for starting two-phase induction motors. In this case the line is connected to the ends of each coil, and the starting connections of the motor to one of these ends and the taps. The arrangement and wiring is essentially similar to the three-phase compensator.

For starting constant-speed polyphase motors above 5 horsepower, a starting compensator is generally used, but below 5 horsepower it is customary to connect polyphase motors directly to the supply mains.

The direction of rotation of a two-phase motor is reversed by reversing the connections of one of the phases, that is, by reversing the connections of the two wires belonging to one-phase supplying current to the stator windings of the motor.

The direction of rotation of a three-phase (three-wire) motor is reversed by interchanging the connections of any two of the three wires used to lead the three-phase currents to the stator windings of the motor.

Typical Induction Motor Installations. The application of induction motors to the driving of machine tools has been rapidly




Fig. 350. Snyder Drill Press
Driven by Induction Motor

growing in favor. Among the advantages of electric driving over mechanical driving through shafting and belting are: increased shop production, economy of power, ease of control, better and more convenient arrangement of machines, and saving of floor space. Fig. 350 is a view of a Snyder 21-inch drill press driven by a constant-speed two horse-power induction motor. Fig. 351 shows a 24-inch Chandler planer driven by a $7\frac{1}{2}$ horse-power induction motor running at 1,200 revolutions per minute. The individual motor drive as




Fig. 351. Chandler Planer Driven by Induction Motor

applied to planers has many advantages, among them being the use of independent motors, one for planing and one for raising or lowering the cross-head.

A typical application of constant-speed induction motors to the driving of spindles in a textile mill is illustrated in Fig. 352. A large number of Crocker-Wheeler 5-h.p. motors are directly coupled to the shafts which drive the spindles above, thus eliminating all overhead shafting, hangers, and belts.

An application of variable-speed induction motors having phase-wound rotors with slip rings is given in Fig. 353, which shows several Westinghouse 500-h.p. "type HF" induction motors operating Worthington centrifugal pumps in a municipal pumping plant.




Fig. 352. Constant Speed Induction Motors Used for Driving Spindles in a Textile Mill




Fig. 353. Westinghouse 500-H. P. Induction Motors Operating Centrifugal Pumps in a Municipal Pumping Plant

The laminations of both the stator and the rotor of large induction motors are provided with ventilating ducts through which air is driven by centrifugal action. Fig. 353 shows a number of holes in the cast-iron casing through which the air flows after passing through the ventilating ducts between the laminations of the rotor and the stator.

Fig. 354 shows an induction motor driving a triplex pump. This induction motor has a starting resistance inside of the rotor,






Fig. 354. Induction Motor Driving Triplex Pump

and the switch rod and knob are shown projecting from the rotor shaft at the left.

Fig. 355 illustrates a very common method of installing induction motors when used for driving line shafting in shops or factories. The motor is shown bolted in an inverted position to the ceiling by means of lag screws, and is furnished with two pulleys, each belted to a different line shaft.

Since induction motors require no adjustment and practically no attention, they may be installed where direct-current motors are





INSTALLATION OF CONSTANT-CURRENT TRANSFORMERS.
General Electric Co.

not suitable, with the consequent advantage of saving valuable floor space.

Single-Phase Induction Motor. When an induction motor (two-phase or three-phase) is once started, and is running at full speed, all the phases but one may be disconnected from the primary member and the machine will continue to operate and to carry approximately 70 per cent as much load with the same slip and temperature rise as when all the phases are connected to the supply mains.

An induction motor, however, will not start when one phase only of its primary member is connected to single-phase supply




Fig. 355. Induction Motor Suspended from the Ceiling, Driving Shafting by a Belt

mains. Therefore, when it is to be operated from single-phase mains, special provision for starting must be made. An induction motor designed to operate from single-phase mains and provided with special arrangements for starting, is called a *single-phase* induction motor.

Three methods of starting single-phase induction motors are in general use, as follows: (a) by hand; (b) by phase splitting; (c) by repulsive action of field on armature obtained by temporary connections during starting.

(a) *Hand Starting.* Very small induction motors may be

started by giving a vigorous pull on the belt which connects the motor to the machinery which it drives.

(b) *Split-Phase Starting.* When an alternating current divides between two branches of a circuit, there is a phase difference between the currents in the two branches, if the ratio of resistance to reactance is different in the two branches. This is especially true if one branch contains a condenser. A two-phase motor will start when the cur-




Fig. 356. Stator of Single-Phase Induction Motor—
Holtzer-Cabot Company

rents in the two stator circuits are less than 90 degrees apart in phase, although the starting torque grows less and less as the phase difference of the two currents decreases. The dephasing of the two parts of a single alternating current in two dissimilar branches of a given circuit is called *phase-splitting*, and a single-phase induction motor may be arranged to start as a two-phase motor, by splitting a single-phase current and using the two parts of the split current exactly as one would use two genuine two-phase currents.

Fig. 356 shows the stator of a 2-h.p. single-phase induction motor of the Holtzer-Cabot Electric Company. One set of stator

coils, the "working coils", consist of many turns of coarse wire occupying three-fourths of all the stator slots, and the other set of stator coils, the "starting coils", consist of fewer turns of fine wire occupying one-fourth of all the slots.

At starting, both sets of coils are connected to the single-phase supply mains, and the difference in the resistance and the reactance in the two sets of coils splits the single-phase current supplied, sufficiently to give a slight starting torque. This type of split-phase induction motor cannot start with any considerable load, hence the load, if it is difficult to start, should be thrown on to the motor




Fig. 357. Wagner Single-Phase Induction Motor

by means of a friction clutch after the motor is running at full speed. The rotor used in the Holtzer-Cabot motor is of the squirrel-cage type.

A single-phase motor will run in either direction equally well, depending only upon the direction in which it is started. Therefore, the hand-started motor may be started in either direction. The direction of starting of the split-phase motor may be reversed by reversing the connections of the starting winding.

(c) *Repulsion Motor Starting.* If an ordinary direct-current dynamo were provided with a laminated field magnet, and if its field magnet were excited by an alternating current, currents would

be induced in the armature windings by the alternating field, provided the brushes of the direct-current machine were set at an angle of about 45° (for a two-pole machine) from their proper position for collecting a direct current. These currents induced in the armature would be acted upon by the alternating field so as to produce a torque which would cause the armature to rotate. A self-starting, single-phase, alternating-current motor constructed on this principle is called a *repulsion motor*. It is not entirely satisfactory in operation, but the repulsion-motor principle furnishes the




Fig. 358. Part Section of Wagner Single-Phase Induction Motor

best means for making a self-starting single-phase induction motor, that is, a motor which is arranged so that it can act as a repulsion motor while starting, and which by changing certain inside connections can be altered into an induction motor when it reaches full speed.

Fig. 357 is a general view of a single-phase induction motor arranged to start as a repulsion motor, and built by the Wagner Electric Manufacturing Company. The motor shown has a four-pole stator winding, the iron stator core being made very much like the core of an ordinary induction motor, namely, in the form of a laminated ring closely surrounding the armature, and slotted on its inner face.

The armature is of the ordinary direct-current drum type provided with a disk commutator with radial commutator bars. Four (for a four-pole machine) short-circuited brushes are pressed against the face of the disk-shaped commutator, as shown in Fig. 357. At starting, the stator winding is connected to the single-phase supply mains, and the machine starts as a repulsion motor. Inside of the armature are two governor weights V , Fig. 358, which are thrown outwards by the centrifugal force when the machine reaches full speed, thus pushing the solid copper ring K into contact with the inner ends of the commutator bars L , and thus completely short-circuiting the armature winding. At the same time barrel I , which is pushed endwise by the governor weights and which carries the short-circuiting copper ring K , pushes the brush holder or rocker arm endwise, and lifts the brushes off the commutator.

In starting the Wagner single-phase motor, the supply voltage is usually reduced to a fractional part of the full running voltage. This is accomplished by the use of a small step-down transformer, usually an autotransformer, in much the same way as has been explained in connection with the autostarter or starting compensator for two-phase and three-phase induction motors.

Induction Generator. An induction motor runs as a motor at a speed less than the speed of the rotating magnetism in the stator iron (synchronous speed). When the motor load is decreased, its speed approaches synchronous speed, and the intake of power from the alternating-current mains falls off more and more. If the rotor is driven by an external source of mechanical power, it may be speeded up to synchronism, in which case the intake of power becomes zero, except for core loss in the stator iron. If now the rotor is speeded *above* synchronism by the external source of power, the stator windings deliver power to the alternating-current mains, *provided the alternating-current generator remains connected to the mains to fix the frequency*. When an induction motor is so used, it is called an *induction generator*. The use of the induction motor as an induction generator is not of much commercial importance.

Frequency Changer. An induction motor provided with a rotor having a definite winding with terminals brought out to collect rings, see Fig. 344, may be used as a so-called *frequency changer*. When the rotor stands still, the rotating stator magnetism induces electro-

motive forces at full frequency, that is, of the same frequency as the alternating currents supplied to the stator. If the rotor runs at one-fourth speed, let us say, the relative speed of the rotor and the stator magnetism is three-fourths of the speed of the latter, and hence electromotive forces of three-fourths full frequency are induced in the rotor windings. If the rotor is run backwards at, let us say, one-half of the speed of the stator magnetism, then the relative speed of the rotor and the stator magnetism is one and one-half times the speed of the stator magnetism, and electromotive forces of one and one-half times full frequency are induced in the rotor windings.

Example. A certain induction motor runs at one-third synchronous speed ($n' = \frac{1}{3}n$, page 377), then, ignoring stator losses, all of the power delivered to the stator is transmitted to the rotor, and of this total power one-third appears as mechanical power driving the rotor, and two-thirds appears as electrical power developed in the rotor windings. This electrical power, ignoring the resistance loss in the rotor windings, is delivered to the rotor collecting rings.

Furthermore, if the rotor has the same number of conductors as the stator, then the electromotive forces between collector rings are two-thirds as great as the voltages applied to the stator windings, and their frequency is two-thirds as great.

If the rotor of an induction motor is driven backwards by an external source of power at one-half synchronous speed ($n' = -\frac{1}{2}n$), then all of the electrical power delivered to the stator together with the mechanical power used for driving the rotor, appears as electrical power in the rotor windings, and the rotor voltages are one and one-half times as great in value, and one and one-half times as great in frequency as the voltages applied to the stator.

The stator current in an induction motor, or a frequency changer, is sufficient at no-load to magnetize the stator. This stator current is called the no-load current of the machine. When current is taken from the rotor, an equal (and opposite) additional current is taken from the supply mains by the stator windings, *exactly as in the case of the transformer.*

The above statements are based on the assumption that the rotor windings are exactly like the stator windings, both as to the number of conductors, and as to the grouping of the conductors into separate circuits or phases. If the rotor has half as many conductors as the stator, the rotor voltages are halved and the rotor currents are doubled, other things being equal.

In alternating-current plants, designed primarily for the transmission of power, and hence using a low frequency (*e. g.*, 25 to 40 cycles per second), there is sometimes a need for a limited amount

of current of a higher frequency. To meet such conditions, a frequency suitable for lighting purposes, 60 cycles or more, may be cheaply and easily obtained by means of the frequency-changer. This is essentially an induction motor as explained above, the rotor of which is driven mechanically by an auxiliary synchronous motor in a direction, usually opposite to its natural rotation. The current of lower frequency is fed to the stator windings and the current of higher frequency is taken out of the rotor windings by means of collector rings. The frequency of the motor current will depend on the speed at which the rotor is driven. Thus, if the rotor is driven at its rated speed but in a direction opposite to its natural rotation, the frequency of the current delivered by it to the collector rings will be twice the normal, or if run at half the normal speed in its natural direction, the frequency will be one-half the normal. To change a current with a frequency of 40 cycles into one of 60, the motor would be run at one-half speed in an opposite direction, while to obtain 60 cycles from a 25-cycle current, the rotor would run nearly one and one-half times the rated speed in an opposite direction.

The total power delivered to a frequency changer is partly electrical power delivered directly from the low frequency supply mains to the stator of the frequency changer, and partly mechanical power delivered by belt to the rotor of the frequency changer from the auxiliary driving motor. The power output of the frequency changer is wholly electrical and in the form of increased-frequency alternating currents from the rotor.

The electrical power delivered to the stator of the frequency changer is

$$P_e = \frac{f P}{f'}$$

and the mechanical power delivered by belt to the rotor of the frequency changer is

$$P_m = \frac{(f' - f) P}{f'}$$

where P is the total power delivered to the machine, being a little greater than the total power delivered by the machine at the increased frequency; f is the low frequency of the alternating currents supplied to the stator of the machine; and f' is the higher frequency

of the alternating currents delivered by the rotor of the machine.

Therefore, the rotor of the frequency changer must be designed for the total output of power at the higher frequency, and the stator of the frequency changer must be designed for the intake of the amount of power P_e , which is supplied to it electrically.

For example, a frequency changer rated at 100 kw. to change a 40-cycle current to one having a frequency of 60 cycles per second would be made up as follows: An auxiliary *driving synchronous motor* rated at 33.3 kw. designed to take current from 40-cycle mains at a speed of, say 600 r. p. m.; it would, therefore, have eight poles. Its *armature* would be direct connected to the *rotor* of the frequency-changer which would be rated at 100 kw. The *stator* of the frequency-changer would be rated at 66.7 kw. and would be supplied with current having a frequency of 40 cycles per second. If wound for four poles, the synchronous speed (as an induction motor) of the rotor of the frequency-changer would be normally 1,200 r. p. m. But by driving the rotor (by the auxiliary synchronous motor) at a speed of 600 r. p. m. in a direction opposite to its natural rotation, the frequency of the rotor currents would be that due to an equivalent speed of $1,200 + 600 = 1,800$ r. p. m.; corresponding thus to a frequency of 60 cycles per second.

For the sake of a simple illustration, the ratings as given above are based on the assumption of a 100 per cent efficiency, which, of course, on account of the unavoidable power losses, is never realized in practice.

It is evident that the frequency-changer can at the same time be designed to change the electromotive force by using a suitable number of turns in the stator and rotor windings. It can also be used to change the number of phases of the system by providing a rotor wound for a number of phases different from that of the stator. For instance, it may be designed to convert from three-phase, 6,000 volts, and 25 cycles, to two-phase, 2,500 volts, and 62.5 cycles. On account of this flexibility the frequency changer is sometimes called a "general alternating-current transformer." A number of these frequency changers are in present use, but on account of excessive magnetic leakage, they are not as satisfactory in operation as motor-generators. One of the large manufacturing companies is now recommending as a frequency changer a motor-generator consist-

ing of a polyphase induction motor of one frequency driving mechanically an alternator designed for the frequency desired.

COMPARISON OF SYNCHRONOUS MOTOR AND INDUCTION MOTOR

To summarize the characteristic behavior in service of synchronous and induction motors, and to simplify the comparison between them, the following tabular statement in parallel columns, prepared by C. F. Scott, is given.

The induction motor chosen for comparison with the synchronous motor is of the so-called "squirrel-cage" type, started by applying a low electromotive force to the primary winding. The description following will, of course, require modification in some particulars, if the secondary is furnished with adjustable resistance, but these modifications are of minor importance and do not affect the general comparison.

SYNCHRONOUS MOTOR

INDUCTION MOTOR

Auxiliary Apparatus Required

1. A starting motor; or, if self-starting, some form of resistance or transformer for reducing the voltage.
2. An exciter, driven by the motor or otherwise, with circuits to switchboard and motor.
3. Rheostats for exciter and motor.
4. Instruments for indicating when field current is properly adjusted.
5. Main switch and exciter switches.
6. A friction clutch is required in many cases.

1. A two-way main switch with autotransformers giving a low e.m.f. for starting. This may be at any distance from the motor.
2. No exciter is required.
3. No field rheostats are required.
4. No instruments are required.
5. No exciter switches are required.
6. No friction clutch is required, as the motor starts its load

Construction

1. Armature winding.
2. Field winding with many turns. Liable to accident from "field discharge" if exciting current is suddenly broken; or from high e.m.f. by induction from the armature if the field circuit is open.
3. Collector rings and brushes.

1. Primary winding.
2. Secondary, short-circuited.
3. No moving contacts on "squirrel cage" secondary.

Starting—Normal

1. Motor is brought up to speed without load; if starting motor is used, the main motor must be brought to proper speed and "synchronized"; if self-starting, the starting devices must be cut out of circuit at the proper time.

2. Exciter is made ready for delivering proper current and the motor field must be excited, adjustments being made by rheostats until instruments give proper indication.

3. Load is thrown on by friction clutch or other means.

1. Throw switch to starting and then to running position.

2. There is no exciter. (The motor is magnetized by lagging current from the generator.)

3. The motor starts its own load.

Starting—Abnormal

1. If the several operations in starting be performed improperly or in wrong order, injury may result. If a starting motor is used, the synchronizing may be attempted at an improper speed or phase; if the motor is self-starting and it is connected to the circuit without the starting devices, a large current will flow which may induce a high e.m.f. in the field circuit; if the field circuit be open, a high e.m.f. may be induced in it at other times also.

2. If a load having inertia be applied by closing the friction clutch too quickly the motor may be overloaded and stopped.

3. If motor stops owing to failure of current supply, it is not self-starting when the current returns. An attendant is always required for starting.

1. The only possible error is in starting with the switch in the running or full voltage position, which simply causes the motor to exert a greater torque and consume a greater current than is necessary.

2. The motor starts its own load and requires no friction clutch.

3. The motor will stop if the current is cut off at the power house and then start again when the current is supplied to the circuit.

Starting and Maximum Running Torque

1. The starting torque of the self-starting motor is very small and an excessive current is required for developing it. The motor starts as an induction motor, but inefficiently, as the design which is best for synchronous running is not good for starting.

1. The starting torque is adjustable and may be several times full load torque.

2. The maximum torque is several times the full load torque, and occurs at synchronous speed; below this speed the torque is very small; any condition which momentarily lowers the speed causes the motor to stop.

2. The maximum torque is usually greater than that of the synchronous motor, but it occurs at a reduced speed and there is a large torque at lower speeds.

Speed

1. The motor has a single definite speed; at other speeds its torque is very small, and the current is very large.

1. The motor may be designed for a practically constant speed, with large torque at lower speeds; or for several definite speeds by changing the number of poles; or for variable speed, for cranes, elevators, hoists, and the like.

Current

1. If there is useful starting torque, the current required for producing it is very great.

1. The starting current may be made proportional to the torque, and is $1\frac{1}{2}$ to $2\frac{1}{2}$ times that required for the same torque at high speed.

2. The running current depends upon the wave form. If the wave form of the motor and of the circuit differ, a corrective current will follow, which cannot be eliminated by adjustment of field excitation.

2. The running current is practically independent of the difference in wave form, as it has no wave form of its own.

3. The running current depends upon uniformity of alternations of the current, *i.e.*, upon the uniformity of the speed of the generator and other synchronous motors. The motors attempt to follow the generator speed exactly. If the latter pulsates, the motors pulsate also; they vibrate about a mean position, "hunting" or "pumping." One motor pumping incites others. The current is increased even though the conditions may still be operative.

3. The current is practically independent of fluctuations in generator speed, as there is a slip between the synchronous and the actual speed of the motor.

4. The running current depends upon the relation between the field current (which is adjusted by the attendant) and the e.m.f. of the circuit. The main current may be made leading or lagging or theoretically it may be neither. The e.m.f. of the circuit is an element which is under the partial control of the attendants at every motor, as well as at the generator station.

4. The current is not subject to any adjustments which the motor attendant can make, nor is the e.m.f. of the circuit in any way under his control.

Power Factor

1. As the power factor is the relation between actual current and energy current, it is dependent upon wave form, hunting, and field current. Under favorable conditions, the motor may have a high power factor; under many actual conditions it may not; under some conditions the highest attainable power factor is less than that of the induction motor.

2. The current may be lagging or leading, depending upon the motor field strength.

1. The power factor varies with load, but is definite and is practically independent of wave form and hunting.

2. The current to the motor is always a lagging current.

Reaction Upon Generator and Circuit

1. The motor impresses its own wave form on the circuit.

2. A motor may augment the fluctuations in generator speed by the oscillation of its own armature. One motor may increase the disturbance in the circuit so as to interfere with other motors not otherwise seriously affected.

3. As the current may be either lagging or leading, the drop in e.m.f. in the generator, and between generator and motor may be either more or less than that which could be caused by a non-inductive load or by an induction motor.

4. If a short-circuit occurs in the transmission system, the motor acts as a generator, which thereby greatly increases the current and the intensity of the short-circuit.

5. If the circuit is opened, either by a switch, a circuit breaker, a fuse, or the breaking of the line, the motor speed falls, its e.m.f. is no longer in phase with that of the circuit; the two are thereby added, thus doubling the normal e.m.f. and bringing increased strains on the insulation and the opening devices.

1. The motor has no wave form to impress upon the circuit; its tendency is to smooth out irregularities in a wave not a sine.

2. The motor has a damping action upon fluctuations in frequency; in some cases a synchronous motor which hunts may run smoothly when an induction motor is connected to the same circuit.

3. The drop in e.m.f. is always greater than would be caused by non-inductive load.

4. The motor does not generate current when there is a short-circuit.

5. The motor does not generate e.m.f. when it is disconnected from the circuit.

Causes which May Accidentally Stop a Motor

1. Momentary lowering of e.m.f. caused by short-circuit on the line, or by accident to another motor, or by error in synchronizing a generator, or by the "switching over" of the motor from one circuit to another, is apt to cause the motor, particularly if carrying load, to fall from synchronism and stop.

2. A heavy load, even momentary, may exceed the limiting torque and cause the motor to drop from synchronism, even though the load be removed immediately. The connection between generator and motor is rigid.

3. If the generator speed suddenly increases, a motor carrying a load having inertia may be unable to increase its speed quickly without exceeding the limiting torque, which will cause the motor to stop.

1. Momentary lowering of e.m.f. causes momentary decrease in speed.

2. An excessive load receives the stored energy of the motor and of the load itself as the motor speed falls; when the excess load is removed the motor speed increases again. The connection between generator and motor is elastic.

3. The motor readily follows changes in generator speed.

Summary

1. The motor is an *active* element in the system; it acts as a generator in impressing its own wave form, its e.m.f. and its fluctuations upon the circuit. These fluctuations may be caused by an intermittent load.

2. The motor is a sensitive element in the system. Its successful operation is dependent upon a proper relation between the design of the motor itself and of other machines in the system. Its successful operation also depends upon the proper adjustment and freedom from speed fluctuation in generators and other motors. It is liable to momentary variations from normal conditions, such as a sudden over-load and sudden increase of generator speed or a momentary fall in e.m.f.

3. The motor requires skill and care on the part of the attendant for starting, for readjusting and for keeping the various brushes and auxiliary apparatus in condition.

1. The motor is a *passive* element in the system. Each motor attends to its own work and does not try to run the system.

2. The motor is not sensitive to differences in the design of other apparatus operating on the same system.

3. No experience and electrical skill are required of the attendant and there is little or nothing to get out of order either through carelessness or design.

4. The power factor is under the control of the operator and the current may be made leading or lagging. Instruments are necessary in order that proper adjustments may be made by the attendant.

5. The motor and its operation are complex and involve many possibilities of accident.

4. The motor has a definite power factor, depending upon the load; the out-of-phase current does not vary greatly at different loads. The changing load, therefore, has comparatively little effect upon the drop in voltage and in regular service there is little liability that the motor will disturb the e.m.f. of the circuit.

5. The motor and its operation are simple and reliable.

The synchronous motor is obviously not suitable for general distribution of power, owing particularly to its lack of starting torque, the skill required in attendance, and the liability of the motor to stop if the conditions become abnormal. These objectionable features, however, are of much less importance when motors are installed in substations or are of sufficiently large size to justify an attendant.

The characteristic of the synchronous motor which may be particularly advantageous is the fact that the power factor of the current can be varied and that the current may be made leading.

INDUCTION MOTOR TESTS

Heat Test. The heat test on induction motors is usually carried out by connecting the terminals of the stator windings to mains of the proper voltage and frequency, and taking rated full-load mechanical power from the rotor until a constant temperature has been reached. Then the motor is shut down, and the temperatures of the following parts are taken:

- Armature laminations
- Armature conductors
- Field conductors
- Field laminations
- Frame
- Bearings
- Room

If the motor is small, the mechanical power output may be absorbed by a brake. For large power motors, however, a brake becomes troublesome. In any case, the most convenient way to

measure the power is to belt to the motor a direct-current separately-excited generator, whose losses can be easily determined, and measure the output of this generator. The output of the motor is equal to the output of the generator plus the losses in the generator. The losses in the generator are: the I^2R loss in the armature, brush and bearing friction, and windage loss, and the core loss due to hysteresis and eddy currents.

The field being separately excited, the field loss need not be considered. The field current must, however, be kept constant.

During the heat run, the following observations are regularly recorded:

MOTOR			GENERATOR			
Volts	Amperes	Speed	Volts	Amperes Armature	Amperes Field	Speed

The I^2R loss in the generator armature can be calculated from the current flowing, and the resistance of the armature.

To determine the stray-power losses (equal to all the losses except I^2R) proceed as follows:

Disconnect the motor from the alternating-current mains, and run the combination of motor and generator from the direct-current end, at the same speed as that recorded during the run, the direct-current machine being now used as a motor. Its field is excited to the same value that it had during the run. The speed is adjusted to the right value by varying the voltage supplied to the direct-current machine used as a motor. When the speed is correct, record the amperes and volts taken by the direct-current machine. Next the belt is thrown off, and the voltage supplied to the armature terminals of the direct-current motor is adjusted until proper speed is attained, the field current remaining as before, and the input of power is again recorded.

Let W_1 = the watts input to the direct-current motor with the belt off; W_2 = watts at same speed to drive both machines with belt on; C = core loss of direct-current machine; F = friction of direct-current machine without belt; F_1 = friction of induction motor without belt; f = increase of bearing friction of direct-current machine due to belt tension; and f_1 = increase of friction of bearings of induction motor due to belt tension. Then

$$W_1 = C + F \tag{i}$$

and

$$W_2 = C + F + F_1 + f_1 + \tag{ii}$$

Subtracting

(i) from (ii) we get

$$W_2 - W_1 = F_1 + f_1 + f$$

or

$$W_2 - W_1 - F_1 = f + f_1$$

Now, since the two machines are of about the same size, we may assume that the increase in friction of each, due to belt tension, is the same, so that

$$f = f_1 = \frac{W_2 - W_1 - F_1}{2}$$

But F_1 , the friction of the induction motor, can be determined as described under core-loss test. Hence, we have the following expression for the stray-power loss of the generator:

$$\text{stray-power loss} = W_1 + \frac{W_1 - W_2 - F_1}{2}$$


$$\text{total output of motor} = \text{stray-power loss} + EI + I^2R$$

This expression gives an exact method of determining the output of any kind of motor, by using a direct-current generator as a load. If F_1 is unknown, we may neglect the increase of bearing friction due to belt tension, giving results sufficiently accurate for a heat run.

Breakdown Test. The breakdown test, as in the case of a synchronous motor, is to determine the maximum output of the motor, that is, the load which will cause the motor to "break down" and stop. To make this test the load on the motor is increased, until the motor breaks down, the maximum output being noted. It is essential that the alternating currents be supplied to the motor at normal voltage. As the torque and, therefore, the maximum output, varies as the square of the voltage, the results obtained by this test will not be accurate unless the voltages applied to the stator windings are kept constantly at normal value. If for any reason it is impossible to load the motor to the breakdown point, the voltage may be reduced, and the maximum load at normal voltage may be calculated from the value obtained at the reduced voltage by multiplying the observed maximum load by $\left(\frac{\text{normal voltage}}{\text{reduced voltage}}\right)^2$.

If, for example, an induction motor rated at 50 horse-power gives a maximum output of 25 horse-power at one-half its rated voltage, its maximum output at normal voltage would be approximately 100 horse-power.

The most convenient way to load the motor in the above test is to belt it to a direct-current generator, as previously explained. To determine the output of the induction motor, from observations on the direct-current generator, proceed in the same manner as described under heat run.



POWER STATION OF INDIANA UNION TRACTION COMPANY
At Anderson, Indiana

In commercial work it is not customary to run this test to the breakdown point. The usual method is to find out if the motor will stand 50 per cent overload without breaking down. When, however, it is desired to obtain a full set of data on a machine, the test is carried to the breakdown point.

Starting Torque Test. The stationary or starting torque developed by a motor determines the amount of load under which it will start. To perform this test a brake is clamped to the pulley as shown in Fig. 359. A is the center of the pulley; B is the point of suspension of the brake arm from the spring dynamometer S ; C is a reference pointer, carried on a standard, on a horizontal line through the center of the pulley. The spring S will measure the




Fig. 359. Prony Brake Arrangement for Testing Starting Torque

tangential force exerted by the motor at a radius AB when B has moved down to the point C , and the spring dynamometer S is suspended vertically.

The reading of S will be affected by the friction in the motor bearings. The following procedure will eliminate this error: Fasten to the brake arm a weight W , sufficient to overcome the friction of the bearings, so that the arm, if left unsupported, will always be carried downward by its weight. By slowly raising and lowering the brake arm by means of the cord which supports the spring dynamometer S (no current passing through the motor), we get two different readings of S when B passes the point C . While the arm is being raised the friction in the bearings acts in the *same* direction

as the weight W . Second, as B passes C , while the arm is being lowered, the friction of the bearing acts *against* the direction of the pull due to W .

Let W =pull, exerted by the weight of the brake and arm weight; F =friction of the bearings; a =scale reading when arm is being raised; and b =scale reading when arm is being lowered. Then

$$W + F = a$$

and

$$W - F = b$$

or

$$W = \frac{a + b}{2}$$

Let T be the force exerted by allowing the current to act on the motor, this force being in the same direction as W . Then, with current flowing in the motor, let c =scale reading while arm is being raised; and d =scale reading while arm is being lowered. Then

$$T + W + F = c$$

and

$$T + W - F = d$$

or

$$T + W = \frac{c + d}{2}$$

But from above we have

$$W = \frac{a + b}{2}$$

substituting this value of W , we have

$$T = \frac{c + d}{2} - \frac{a + b}{2}$$

By this method both the weight of the brake arm and the friction of rest in the bearings are eliminated.

To carry out this test, this set of observations is repeated for as many values of the current in the motor as desired. The current should range at least from one-half to twice the normal full-load current. To obtain the desired current, the voltage across the motor terminals must be adjusted.

Core Loss Test. The core loss of an induction motor cannot

be measured by the method used in the case of a synchronous motor or alternating-current generator, namely, by driving it by a direct-current motor and observing the motor input for various voltages generated, since an induction machine will not generate electromotive force unless it is connected to the mains. If it is connected to the mains, the mains may supply power to it, and hence the power supplied by the direct-current motor is not the total power delivered to the machine.

The core loss is measured in the same manner as in the case of a transformer, namely, by connecting it to the alternating-current




Fig. 360. Curve Showing Watts Input to a 1-H. P. Motor at Different Voltages

mains at normal voltage and frequency, and measuring the watts input at no-load. There is this difference, however, between the case of the transformer and that of an induction motor, that, whereas in the former the power input is practically all needed to supply the core loss, in the latter, a part of the power input goes to supply the friction and windage losses of the motor, and the appreciable I^2R loss in the stator windings.

When an induction motor is run at no-load, the speed remains practically constant as the voltage is reduced, until the motor "breaks down" and stops. The power input to the motor (at no-load) at any voltage consists of the core loss at that voltage plus the friction

and windage loss plus the I^2R losses in the stator and rotor windings. But the friction and windage loss is nearly constant at constant speed, therefore the watts input to the motor at various voltages consists in part of the constant friction and windage loss, and in part of the variable core loss. Such a series of observations on a 1-h. p., 550-volt, 3-phase motor is shown plotted in Fig. 360. The voltage can be reduced to the point at which the motor breaks down; beyond this we cannot go. As the ordinates on this curve are equal to the sum of a constant and a variable part, and since at zero voltage the variable part becomes zero, it follows that if we prolong the curve as shown in the dotted portion until it crosses the axis of watts, that is for zero volts, the value intercepted on the axis of watts may be considered, without much error, to be the constant part of the watts, namely, the friction and windage loss. Thus in Fig. 360, 26 watts represents the power lost due to friction and windage in the case of the induction motor above mentioned. The sum of the core loss, friction losses, and I^2R loss at normal voltage, viz, 550 volts, is found from the curve to be 109 watts. For each observed value of the volts and the watts, the current per phase to the stator windings must be recorded. Then, the resistance of the stator windings having been measured, the I^2R loss corresponding to any given voltage can be calculated. To obtain the core loss corresponding to any voltage, we must, therefore, subtract the constant friction losses plus the I^2R loss in the stator windings from the total observed input to the motor (when running unloaded).

For example, in the case of the 1-h. p. induction motor under consideration, the current input per phase at no-load was measured and found to be 0.655 amperes, when the voltage between supply mains was 550 volts. The resistance per phase was also measured and found to be 15.5 ohms. The total I^2R loss at no-load was, therefore, $3 \times \overline{0.655^2} \times 15.5 = 20$ watts.

Therefore, at normal voltage

$$\text{core loss} = 109 - 26 - 20 = 63 \text{ watts}$$

Impedance Test. This test is carried out in the same manner as the core-loss test. The motor is connected to the alternating-current supply mains and the amperes flowing, the watts input, and the volts at the terminals of the motor are measured, the watts,

of course, being measured by wattmeters. In this test, however, the motor is not allowed to run free, but its armature is blocked to prevent it from turning. Instead of supplying normal voltage to the motor, the voltage supplied is cut down to only five or ten per cent of the normal value and is then raised carefully until the ammeters show about one-third to one-half of the full-load current. The motor must be supplied with current at normal frequency. The following observations should be recorded:

- Amperes in each line
- Volts for each phase
- Total watts

The observations are repeated with increasing value of the voltages, until the current has reached from one and one-half to over twice the full-load value.

Fig. 361 shows curves of observations taken in this way for the 1-h. p., 550-volt, three-phase motor referred to above. This motor takes one ampere of current per phase at full-load with normal voltage of 550 volts. The two curves are plotted with current and volts, and with watts and volts as ordinates and abscissas, respectively. The former curve is the straight line.




Fig. 361. Curve for Impedance Test of Induction Motor

Since for full-load current with the armature standing still, the voltage applied to the terminals of the motor is very low, the number of watts supplied to overcome core loss is very low. In fact, practically all the watts supplied are used up in heating the conductors of the stator and rotor. The watts input, therefore, for normal rated full-load current but with rotor blocked, may be taken as a measure of the total I^2R losses (primary and secondary) of the entire machine at full-load. For the motor for which the curves are shown, the I^2R losses at full-load current are equal to 100 watts.

Efficiency Test. As in the case of the machines previously

considered, the efficiency of an induction motor, at a given load is equal to the output, divided by the output plus the losses, at that load. All the losses can be determined from the core-loss test and the impedance test; the core loss and friction and windage losses being determined from the former, and the copper losses from the latter. For the three-phase, 1-h. p. motor above mentioned, the losses at full load are as follows:

Friction and windage loss	=	26 watts
Core loss	=	63 watts
Copper loss (I^2R)	=	100 watts
Total losses	=	189 watts

therefore,

$$\text{efficiency at 1-h. p. output} = \frac{746}{746 + 189} = 79.8\%$$

The efficiency of large machines is generally calculated in this way. For smaller machines it is more usual to determine the efficiency by actually measuring input and output. The reason for this is that the actual losses occurring in the motor when it is loaded, are different from the values as calculated from results of tests at no-load. The differences between these calculated and actual losses are comparatively large in a small machine.

To test the efficiency by measuring the total input and output, the most convenient method is to belt the motor to a direct-current generator, measuring the output of the generator, and the input to the motor. The output of the motor is, of course, equal to the output of the generator plus the generator losses. The losses of the generator may be calculated as described under the heat test.

The output and input of the motor are measured for various loads successively from a very small load to perhaps 50 per cent overload, so that a curve may be constructed showing the relations between efficiency and load. The losses of the generator must be determined at each speed occurring in the series of observations, because the generator losses vary with the speed.

Slip Test. The slip at a given load on the motor is the ratio

$$\frac{n - n'}{n}$$

where n is the synchronous speed of the motor, and n' is the speed

under the given load. Slip is usually expressed in per cent, in which case

$$\text{per cent slip} = \frac{n - n'}{n} \times 100$$

The synchronous speed in revolutions per second is equal to $\frac{2f}{p}$, where f is the frequency of the alternating currents supplied to the stator, and p is the number of "poles" of stator magnetism, NS , NS in Figs. 333, 334, and 335. The slip is independent of the number of phases.

The speed of the motor at zero-load is very nearly equal to the synchronous speed, and where f and p are not known, the zero-load speed may be used for n without great error.

The determination of the slip of an induction motor at full-load with full-rated voltage applied to the stator windings, is an important test. This slip may be determined by observing, by means of a speed counter or tachometer, the speed n' of the motor under full load and with full rated voltage. If p and f are known, the slip may be calculated as explained above.

Various methods have been proposed for measuring the slip of an induction motor directly. A simple piece of apparatus for this purpose consists of a black disk with p white radial lines or sectors painted upon it, where p is the number of poles of the motor. This disk is attached to the motor pulley. If, when the motor is running, the disk is illuminated by an alternating-current arc lamp supplied with current from the same mains as the motor, the white lines on the disk would appear stationary if the motor were running in synchronism. If the motor were below synchronism, the disk would appear to rotate with a speed equal to the difference between the synchronous and the actual speed. Thus the slip can be measured directly by counting the apparent revolutions per minute of the disk. For example, the synchronous speed of the 1-h. p. motor considered above, is 1,200 r. p. m. In applying the above test the disk made 70 apparent revolutions per minute when the motor was running at full load and, therefore, the slip at full-load was

$$\frac{70}{1,200}, \text{ or } 5.83\%$$

Performance Curves of an Induction Motor. Fig. 362 shows the performance curves of a 175-h.p., three-phase, twelve-pole induction motor having a synchronous speed of 600 r. p. m., when supplied with three-phase currents at 550 volts and 60 cycles per second. The abscissas of all the curves are *horse-power output*. The dropping of all the curves in the region between 340 and 360 horse-power shows that the maximum power which the machine can develop is about 350 horse-power. There are three scales of ordinates, namely, *amperes input*, *per cent*, and *pounds torque*.

The ordinates of the curve marked "synchronism" are measured on the per cent scale, and they represent the speeds in per cent of the synchronous speed at the various loads.

The ordinates of the curve marked "amperes input" give the amperes input per phase at the various loads.




Fig. 362. Performance Curves of a 175-H. P. Three-Phase Induction Motor

The ordinates of the curve marked "torque" are measured on the pounds torque scale, and they represent the torque developed by the motor at various loads, these torques being expressed in pounds of force acting at one foot radius, that is, in pound-feet.

The ordinates of the curves marked "efficiency", "apparent efficiency", and "power factor", are measured on the per cent scale, and they represent these quantities at various loads. The efficiency is, of course, the ratio, $\frac{\text{output}}{\text{input}}$. The power factor is the factor by which the product of volts times amperes must be multiplied to give the true input of power per phase.

The product volts times amperes is called the *apparent power* delivered by an alternating-current generator, and the *apparent efficiency* of an induction motor is the ratio, $\frac{\text{apparent power input}}{\text{output}}$.

The apparent efficiency is thus equal to the true efficiency multiplied by the power factor.

The relation between the three factors, efficiency, power factor, and apparent efficiency, will be made clear by the following equations, each based on definition:

$$\begin{aligned} \text{efficiency} &= \frac{\text{useful output}}{\text{actual input}} \\ \text{power factor} &= \frac{\text{actual input}}{\text{apparent input}} \\ \text{apparent efficiency} &= \frac{\text{useful output}}{\text{apparent input}} \end{aligned}$$

From the above three equations, it is evident that

$$\text{apparent efficiency} = \text{efficiency} \times \text{power factor}$$

When the output of a motor under a given load is measured mechanically by observing the useful torque developed at the armature shaft, and the speed of the armature, we have

$$\begin{aligned} \text{useful output} &= \frac{2\pi n' T}{33,000} \text{ horse-power} \\ &= 0.142 n' T \text{ watts} \end{aligned}$$

where n' is the speed of the armature in revolutions per minute; and T is the *useful* torque in pound-feet, developed by the armature.

The actual input to a three-phase alternating-current motor of the induction type may be expressed as follows:

$$\text{actual input} = \sqrt{3} EIP \text{ watts}$$

where E is the electromotive force (effective value) applied between any two of the stator terminals; I is the current (effective value) in any one of the leads supplying the stator windings; and P is the power factor of the motor.

The apparent input to a three-phase induction motor may be expressed as follows:

$$\text{apparent input} = \sqrt{3} EI \text{ watts}$$

From the above equations we may easily write the expressions for the efficiency, power factor, and apparent efficiency, as follows:

$$\begin{aligned} \text{efficiency} &= \frac{0.142 n' T}{\sqrt{3} EIP} \\ \text{power factor} = P &= \frac{\sqrt{3} EIP}{\sqrt{3} EI} \\ \text{apparent efficiency} &= \frac{0.142 n' T}{\sqrt{3} EI} \end{aligned}$$

Example. A certain 12-pole induction motor whose performance curves are given in Fig. 362, is rated as follows:

- Number of phases, 3
- Output rated at full load, 175 horse-power
- Voltage supplied (between mains) 550 volts
- Speed, at full load, 585 r.p.m.
- Frequency, cycles per second, 60

A brake test on the motor when running at full load gave the following data (see curves in Fig. 362).

Useful torque on rotor shaft, pound-feet	1,560
Speed, in revolutions per minute	585
Amperes input per phase	170
Power factor, in per cent	88

It is required to calculate the following quantities in order to check the accuracy of the curves plotted in Fig. 362.

- (a) The synchronous speed in r.p.m.
- (b) The slip at full load in per cent.
- (c) The useful output in watts and in horse-power
- (d) The actual input in watts
- (e) The efficiency
- (f) The apparent input in watts
- (g) The apparent efficiency

Solution.

- (a) The synchronous speed, according to equation (47) is

$$\frac{2f}{p} = \frac{2 \times 60}{12} = 10 \text{ revolutions per second}$$

or

$$10 \times 60 = 600 \text{ r.p.m.}$$

- (b) The slip as referred to on page 415, is

$$\left(\frac{n - n'}{n} \right) 100 = \left(\frac{600 - 585}{600} \right) 100 = 2.5 \text{ per cent}$$

TABLE XI
Capacities of Standard Transformers

H. P. CAPACITY MOTOR	THREE-PHASE		TWO-PHASE 2 TRANSFORMERS
	2 TRANSFORMERS	3 TRANSFORMERS	
1	.6 kw.	.5 kw.	.6 kw.
2	1.5 kw.	1.0 kw.	1.0 kw.
3	2.0 kw.	1.5 kw.	1.5 kw.
5	3.0 kw.	2.0 kw.	2.0 kw.
7½	4.0 kw.	2.5 kw.	4.0 kw.
10	5.0 kw.	3.5 kw.	5.0 kw.
15	7.5 kw.	5.0 kw.	7.5 kw.
20	10.0 kw.	7.5 kw.	10.0 kw.
30	15.0 kw.	10.0 kw.	15.0 kw.
50	25.0 kw.	15.0 kw.	25.0 kw.
75		25.0 kw.	35.0 kw.
100		30.0 kw.	45.0 kw.

(c) The useful output from the above equations is $0.142 n' T$ watts. Substituting the given values of n' and T , we have

$$0.142 \times 585 \times 1560 = 129,600 \text{ watts}$$

or

$$\frac{129,600}{746} = 173 \text{ horse-power}$$

(d) The actual input in watts is $\sqrt{3} EIP$, whence substituting the given values of E , I , and P gives

$$\begin{aligned} \text{actual output} &= 1.732 \times 550 \times 170 \times 0.88 \\ &= 142,500 \text{ watts} \end{aligned}$$

(e) The efficiency (real) is

$$\frac{\text{useful output}}{\text{actual input}} = \frac{129,600}{142,500} = 90.9 \text{ per cent}$$

(f) The apparent input in watts is $\sqrt{3} EI$, or

$$1.732 \times 550 \times 170 = 162,000 \text{ watts}$$

(g) The apparent efficiency is

$$\frac{\text{useful output}}{\text{apparent input}} = \frac{129,600}{162,000} = 80 \text{ per cent}$$

A comparison of the above results with the corresponding values obtained from the curves in Fig. 362, shows on the whole a very satisfactory agreement.

The power factors of standard commercial induction motors of American manufacture vary at full load from 0.75 to 0.92, de-

pending upon the size and the frequency of the motor. The efficiencies range from 0.80 to 0.95. The apparent efficiencies in motors above 5 h. p. output will be found, as a rule, not less than 0.75. This means that the transformers supplying current to induction motors of average sizes, must have an aggregate capacity of about one kilowatt for every horse-power of rated output of the motors.

Table XI gives approximate capacities of standard transformers that should be used with two-phase and three-phase induction motors.

SWITCHBOARD AND STATION APPLIANCES

The switchboard is a supporting frame upon which are mounted most of the measuring instruments and safety and controlling devices used in a generating or receiving station.




Fig. 363. Diagram Showing Switchboard Control for Large Rheostats

Lightning arresters are usually mounted on the wall of the station building at the points where the lines enter the building.

Large apparatus such as rheostats, oil-switches, circuit breakers, and voltage regulators are frequently installed at a distance from the switchboard, and are controlled from the switchboard by systems of levers, by compressed air, or by electrical relays which are in turn controlled by contact switches on the switchboard. Thus Fig. 363 shows a large rheostat mounted underneath the floor upon which the switchboard stands.

The rheostat is operated by means of sprocket-wheels and chain which are moved by a hand-wheel on the switchboard.

SWITCHBOARDS

Alternating-current switchboards differ from direct-current switchboards as follows:

(a) On account of the many special devices such as frequency meters, switchboard transformers, power-factor indicators, and synchronizing devices, which are used in alternating-current work, and are not used in direct-current work.

(b) Because of complications associated with the use of an auxiliary direct-current generator for exciting the field magnets of alternators.

(c) Because of the frequent use of extremely high voltages, as high as 100,000 volts or more, in alternating-current systems.

Switchboards are now usually built up of standard panels uniform in size, the style varying with the service required. Large switchboards for handling many generators or many feeder circuits, are built up by placing a number of these standard panels side by side. This method of building large switchboards has the following advantages:

(1) It reduces the necessity of special work to a minimum, and permits the use of standard apparatus, thus reducing cost.

(2) It provides for interchangeability of panels, thus making rearrangement of feeder, generator, and exciter panels easy and convenient.

(3) The use of standard panels uniformly equipped with standard apparatus makes it easy and cheap to renew damaged parts.

(4) It enables extensions to be made easily and systematically.

In some large stations as many as ten or more generator panels and fifteen or more feeder panels are erected side by side. The panels of a switchboard are usually erected and wired completely at the factory, and all the instruments are attached. After thorough inspection and testing, they are shipped to their destination, the instruments being detached, and shipped separately.

Switchboards are usually constructed of a skeleton frame of angle iron, to which panels of marble or slate are fastened by bolts and nuts. The various instruments are




Fig. 364. Standard Switchboard for Single-Phase Generator and Two Feeder Circuits

attached to the marble or slate panels. In many cases the apparatus itself is located behind the board, the hand-wheel or operating lever only, being placed on the front of the board.

Slate, when entirely free from metallic veins, is a fair insulator, but the frequent occurrence of such veins, and the tendency of slate to absorb moisture from the air, render it unreliable, especially for switchboards on which high-voltage apparatus is to be installed.




Fig. 365. Front Elevation and Connections for Board Shown in Fig. 364

Marble is the standard material for switchboard panels, and it only is used for high-voltage panels.

Typical Single-Phase Switchboard. Fig. 364 shows a front view of a standard switchboard for one single-phase generator and two feeder circuits. The front elevation of this board and the complete diagram of electrical connections are shown in Fig. 365. These switchboards are manufactured by the Fort Wayne Electric Works, for electric lighting plants of moderate size.

The standard voltages for this type of panel are 1,150 and 2,300 volts, at frequencies of from 25 to 140 cycles per second.

The kilowatt capacity or rating of switchboard panels depends on the current carrying capacity of its equipment. Thus, the rating of these panels ranges from 15 to 300 kilowatts at 2,300 volts and from $7\frac{1}{2}$ to 150 kilowatts at 1,150 volts.

The ammeter and voltmeter used on these boards, indeed nearly all switchboard ammeters and voltmeters, are of the electromagnetic type, that is, they consist of a coil of wire actuating a movable piece of soft iron to which the pointer is attached. The electromagnetic type is described on page 67.

The essential features of the electrostatic ground detector are also described on page 67.




Fig. 366. Details of Switchboard Fuse Holder




Fig. 367. Front and Side Views and Complete Diagram of Connections for Standard Panel for Two or More Single-Phase Alternators in Parallel

The two double-pole quick air-break generator switches with marble barriers are shown in Fig. 364. They are used for connect-

ing the generator terminals to either or both of the feeder circuits at the top of the panel, as may be seen in the diagram of connections shown in Fig. 365. When either switch is opened, the arc which is produced is prevented by the marble barrier from flashing across from blade to blade of the switch, and thus short-circuiting the generator.

Instead of these air-break switches, panels may be equipped with non-automatic oil switches, mounted at the back of the board. The type of switch illustrated in Fig. 364, and which breaks the circuit in air is suitable only for moderate voltages up to perhaps 2,300 volts, on account of the danger of arcing.

One of the fuse holders, shown at *A* in Fig. 365, is illustrated in Fig. 366. The body of the fuse holder consists of an insulated metallic chamber, into which is screwed a fiber tube. That portion of the fuse located in the lower chamber has a smaller cross-section than the portion in the upper tube, which insures that the fuse will melt inside the chamber. When the fuse melts and breaks, the arc is extinguished by the explosive action which accompanies the sudden heating of the air enclosed in the fuse chamber. New fuses can be easily inserted in the holder by removing the screw plug shown at the bottom of the bulb. The holder is connected by means of blades fastened to each end which fit into clips mounted at the top of the panel, as shown in Figs. 364 and 365. The potential transformer has its secondary connected through a high resistance to the voltmeter. If the ratio of transformation of the potential transformer is 20 to 1, and the voltmeter reads 110 volts, the voltage between the generator terminals is $20 \times 110 = 2,200$ volts.

Typical Switchboard for Operating Two or More Single-Phase Alternators in Parallel. Fig. 367 shows front and side elevations and a complete diagram of electrical connections of one of the General Electric Company's standard panels for one of several single-phase generators to be operated in parallel. The equipment of this panel is as follows:

- 1 double-pole generator switch, mounted on the back of the board, and operated by a lever on the front of the board.
- 2 expulsion fuse blocks complete.
- 1 generator ammeter.
- 1 field ammeter.
- 1 voltmeter and one potential transformer.
- 1 field switch.



Seven 5000 H. P. Westinghouse Generator at Niagara
Falls Power Co.

1 synchronizing device, complete.

Tripod and front plate for "generator rheostat" (in the field circuit of the generator) with shaft and hand-wheel.

Tripod and front plate for "exciter rheostat" (in the field circuit of the exciter.)

All necessary framework and connections.

The location of apparatus for this panel, as designated by letter, is as follows:

R = rheostat in the field circuit of the generator, "generator rheostat."

a = ammeter in the field circuit of the generator "field ammeter."

V = voltmeter between the generator terminals (through potential transformer).

A = ammeter for the main alternating current.

L = synchronizing lamp.

S = "generator switch" in the main circuit.

r = rheostat in the exciter field circuit, "exciter rheostat."

This apparatus is essentially the same as the apparatus already described on page 424 with the exception of the ground detector, the field switch with discharge resistance, and the synchronizing device. One ground detector is sufficient for a number of machines operated in parallel, and it is usually mounted on a bracket attached to one of the generator panels. The field switch is arranged to short-circuit the field winding of the alternator at, or just before, the instant of disconnecting the exciter from the field windings. This allows the current in the field winding to die away slowly. The opening of a field switch which is not provided with a resistance produces an excessively high electromotive force between the field terminals, which is likely to cause puncture of the insulation of the field windings.

The synchronizing device consists of the synchronizing bus bars connecting the various generator panels; the synchronizing lamps; a small transformer (the same one being used for the voltmeter) for stepping down the voltage to a suitable value for the synchronizing lamps; and connection plugs for connecting the secondary of the potential transformer through the synchronizing lamps to the synchronizing busses. Two types of connecting plugs are used, one of which reverses the connections made by the other. The complete connections of the synchronizing device for two single-phase machines is shown in Fig. 368.

Polyphase Switchboard. In case of polyphase machines, one phase only is connected to the synchronizing device, which is, there-

fore, the same for single-phase and for polyphase alternators. The operation of alternators in parallel is very common in modern central stations.*

The voltmeters and synchronizing device are always connected back of the main generator switch, that is, between the generator and the switch, for the reason that the voltage of the machine must be synchronized *before* the main switch is closed.

The connections of the two types of synchronizer plugs are shown in Fig. 368. Neither plug is used when one alternator only is operated. When another machine is to be put into operation,




Fig. 368. Complete Connections for Synchronizing Device for Two Single-Phase Machines

either type of plug is used to connect the synchronizer busses to any one of the machines already running, and the other type of plug is used for connecting the machine which is being synchronized to the synchronizer busses. Thus the synchronizer busses are *oppositely* connected to the two machines, and the synchronizing lamps are *bright* when the conditions are proper for closing the main switch. This is the common practice of the General Electric Company.

When more than two generators are operated in parallel, and one direct-current generator is used as an exciter for supplying current to the field windings of all the alternators, a separate switch-

*A detailed explanation of how two or more alternators are synchronized in order to run in parallel is given in the Appendix, Part VI, page 462.

board panel called the *exciter panel*, is usually installed. Upon this panel the exciter field rheostat and controlling devices are mounted. In this case exciter bus bars are led from the exciter panel to all the main generator panels.

Typical Switchboard Panel for Two-Phase Alternator Operated in Parallel with Other Two-Phase Machines. Fig. 369 shows front and side elevations, and complete wiring diagram (back view), of one of the General Electric Company's switchboard panels for a two-phase alternator which is to be operated in parallel with other two-phase machines.




Fig. 369. Front and Side View and Complete Wiring Diagram of Switchboard Panel for Two-Phase Alternator Operated in Parallel with Other Two-Phase Machines

The potential transformer which supplies reduced voltage to the voltmeter and to the synchronizer busses has its primary connected across *one phase* of the generator, and the synchronizing device is exactly the same as for the single-phase machines.

The equipment of this two-phase generator panel differs from that of the single-phase panel shown in Fig. 367, in the following particulars:

(a) The main generator switch is a four-pole switch for connecting the four leads from the generator to the four lines which pass out from the top of the board through four fuses.

(b) Two alternating-current ammeters are used, one for each phase

The "generator rheostat" is in the field circuit of the two-phase generator, and the "exciter rheostat" is in the field circuit of the exciter, exactly as in Fig. 367.

The equipment of apparatus for this panel is as follows:

R = rheostat in the field circuit of the generator, "generator rheostat".

a = ammeter in the field circuit of the generator, "field ammeter".

V = voltmeter between the terminals of one phase of the generator (through the potential transformer).

A_1 and A_2 = ammeters, one for each phase of the generator.

L = synchronizing lamp.

r = rheostat in the field circuit of the exciter, "exciter rheostat".

f, f, f, f = fuses.

The four small circles above and below the words "synchronizing busses" are the points of the four-pole main switch.




Fig. 370. Complete Wiring Diagram for Two Two-Phase Generators Running in Parallel

Fig. 370 shows the complete connections of two two-phase generators for parallel running.

Typical Switchboard Panel for Three-Phase Generator Operated in Parallel with Other Three-Phase Machines. Fig. 371 shows front and side elevations, and complete wiring diagram (back view) of one of the General Electric Company's switchboard panels for a three-phase alternator, which is to be operated in parallel with other three-phase machines. The potential transformer which supplies reduced voltage to the voltmeter and to the synchronizing busses

has its primary connected across one phase of the generator, and the synchronizing device is exactly the same as for single-phase machines.

The equipment of this three-phase panel differs from that of the single-phase and two-phase panels shown in Figs. 367 and 369 in that (a) the main generator switch is a three-pole switch for connecting the three generator leads to the three lines which pass out from the top of the board through three fuses; and (b) three alternating-current ammeters are used, one for each phase.

Fig. 371 also shows the following points, which however, are not characteristic of a three-phase panel, but might be used on a two-phase panel.




Fig. 371. Front and Side View and Complete Wiring Diagram for a Three-Phase Generator Operated in Parallel with Other Three-Phase Machines

(a) The two phases not connected to the potential transformer proper, are stepped-down to a reduced voltage by the use of one additional potential transformer T, Fig. 371.

As explained on page 260, two transformers suffice for stepping-down three phases to two phases. Both potential transformers have their secondaries connected to a "voltmeter plug switch", by means of which the voltmeter may be connected so as to indicate, at the will of the operator, the voltage of any one of the three phases.

(b) The lines which pass out at the top of the panel in Fig. 371 are shown connected to the three main bus bars or rods.

(c) No exciter is shown in Fig. 371, and no exciter field rheostat, but the panel is arranged so that one large exciter may be used for all the generators. For this purpose exciter busses (two of them), connect the one large exciter to all the generator panels.

(d) The generator field rheostat is geared to the hand wheel by means of sprocket wheels and chain on the back of the switchboard.

The equipment of apparatus for this panel is as follows:

- R = "generator field rheostat".
 a = ammeter (direct-current) in the field of the generator.
 V = voltmeter between the terminals of one phase of the generator (through potential transformer).
 p = voltmeter plug switch.
 A_1, A_2, A_3 = ammeters for alternating currents, one in each phase of the generator.
 L = synchronizing lamp.
 S = main generator switch.
 f, f, f = fuses.
 T = additional potential transformer.

Feeder Panels. In large generating stations, the bus bars, to which the various generators are connected in parallel, lead from the generator panels to the feeder panels.

The feeders are the separate and distinct circuits which receive current from the bus bars and transmit it outside the station to points more or less remote. Each pair of feeders (or set of three or four in polyphase distribution), as it comes into the station, is protected by lightning arresters. From the lightning arresters the feeders are brought to the feeder panels through fuse blocks, and through ammeters, and connected to bus bars by means of suitable switches.

When there are but few feeder circuits, the feeder switches are mounted on the generator panel as shown in Fig. 364.

Ground detectors are used primarily for detecting grounds on feeder circuits, and where many feeders are connected

to the bus bars, the ground detectors are mounted on the feeder panels. When there are but few feeder circuits the ground detector may be connected to the bus bars, in which case the ground detector may be mounted on a generator panel or on a feeder panel, if feeder panels are used.

It is frequently desirable to control the voltage supplied to a feeder circuit independently of the voltage between the bus bars.




Fig. 372. Front Elevation of Typical Three-Phase Feeder Panel

For this purpose voltage or potential regulators are used, and these voltage regulators are either mounted upon the feeder panels or are controlled by levers or hand wheels which are mounted on the feeder panels.




Fig. 373. Front View of Standard High Voltage Switchboard for Central Stations, etc.

When the energy (watt-hours) delivered to a feeder circuit is to be measured, the integrating watt-hour meter is mounted on the feeder panel.




Fig. 374. Rear View of Switchboard Shown in Fig. 373

Circuit breakers, when used, are usually mounted upon the feeder panels and arranged to open the feeder switch when the current delivered to the feeder becomes excessive.




Fig. 375. Diagram of High Voltage Switchboard Showing System of Levers for Operating Switches by "Remote Control"

Fig. 372 shows a front elevation of a typical three-phase feeder panel manufactured by the Crocker-Wheeler Company. The equipment of this panel includes the following apparatus:

3 alternating-current ammeters, one for each line of the three-line feeder.

Necessary current transformers.

1 three-pole, single-throw, non-automatic oil switch, mounted back of the panel and operated by a lever on the front of the panel.

3 expulsion fuse blocks.

High-Voltage Panels. In alternating-current generating stations for long-distance transmission, the alternating currents are generated at a medium or low voltage, and are then stepped-up to 10,000 or to 100,000 volts or more for transmission. In such stations, the low-voltage switches and controlling devices, including exciter switches and rheostats, are mounted on panels separate from the high-voltage switches and devices. Such stations have, therefore, low-voltage panels and high-voltage panels. The high-voltage panels differ from the low-voltage panels in having very much greater distances between the high-voltage parts, in order to avoid the danger of short-circuit by sparking across through the air, and in having special forms of remote control switches.

Figs. 373 to 375 give views of a standard switchboard designed for central stations and industrial plants for voltages from 2,200 to 13,000. They are given here to illustrate especially the so-called "remote control" method of operating switches.

SPECIAL SWITCHBOARD APPARATUS

Lincoln Synchronizer. When incandescent lamps are used as synchronism indicators in the starting of a synchronous motor, or in the paralleling of alternators, the pulsations of brightness indicate only the *difference* in frequency of the two machines, and it is in general impossible to tell from the behavior of the lamps which of the machines is running at the greater frequency.

The Lincoln synchronizer is a device for indicating positively the difference in the frequency of two alternators which are being adjusted into synchronism, and also for indicating positively the phase difference of the two machines at each instant.

The Lincoln synchronizer is a very small machine of which the iron parts are exactly like the field magnet and armature core

of a very small two-pole direct-current motor, except that both field magnet and armature core are laminated. The field magnet




Fig. 376. Lincoln Synchroscope

is excited with alternating current by connecting the field winding to the terminals of *A*, of the alternators *A* and *B*, which are being synchronized. The armature of the synchronizer is wound with two coils *c* and *d* at right angles to each other. Each of these coils is independently connected through collecting rings to the terminals of alternator *B*. Coil *c* has connected in series with it a non-inductive resistance, and coil *d* has connected in series with it a large inductance. The armature of the small

machine has attached to it a pointer which moves over a divided circle. When machines *A* and *B* have exactly the same frequency, this pointer is stationary and its reading on the circle indicates the phase difference between the two machines. When machine *A* is




Fig. 377. Wiring Diagram for a Synchroscope for Single-Phase or One Phase of Poly-phase Circuit

running at a slightly greater frequency than *B*, the pointer rotates in a certain direction indicating at each instant the changing phase-difference between *A* and *B*. When machine *A* is running at a

slightly lower frequency than *B*, the pointer rotates in the opposite direction, indicating at each instant the changing phase-difference between *A* and *B*. The speed of the pointer in revolutions per second is in each case equal to the difference in frequency of machines *A* and *B*, in cycles per second.

Fig. 376 is a view of the exterior of a Lincoln synchroscope, "type A," as made by the Westinghouse Electric Company. It has a 9-inch dial and is intended to be mounted on the switchboard. Its coils are wound for 100 volts so that a voltage transformer is necessary for connecting it to the bus bars, and one voltage transformer for each machine to be synchronized.

Fig. 377 is a diagram of connections for the "type A" synchroscope for single-phase or one phase of polyphase circuits for voltages of 500 and over.

CIRCUIT-INTERRUPTING DEVICES

Devices whose sole function is the opening of an electric circuit may be classified into: fuses, switches, and circuit breakers. In the design of any circuit-interrupting device four general requirements are involved:

(a) To provide means for carrying the rated current of the device without excessive drop of voltage or heating, and also such overloads as will occur in practice.

(b) To insulate all live parts for the maximum voltage.

(c) To provide mechanical means for opening the circuit.

(d) To prevent or make harmless any arc that may form.

Circuit-interrupting devices may be automatic or non-automatic. In general, fuses are always automatic, switches always non-automatic, and circuit breakers either one or the other. In general, circuit breakers are so arranged that a spring or gravity tends to open them, and they are held closed by latches or toggle mechanisms. It is this feature which makes the difference between a switch and a non-automatic circuit breaker.

Fuses. A fuse is the simplest and cheapest circuit-breaking device. It consists of a wire or link of fusible metal (usually of lead alloyed with zinc and tin) connected electrically in series with the circuit to be protected. When more than the predetermined current passes through it, the heat generated in it due to its resistance is sufficient to melt it, and the fuse is said to "blow", thus opening the circuit. The open or exposed type of wire- or link-fuse is rarely used

on account of its tendency to scatter molten metal and increase the fire hazard. Moreover, open link fuses cannot be accurately rated on account of the exposure and variable length of the fusible strip. It was to overcome these objections that the enclosed type of fuse was developed. The latter type of fuse* consists of a fusible wire or link enclosed within a fiber tube fitted with a fireproof material to exclude the air and suppress the arc formed when the fuse embedded in this material melts and opens the circuit. Suitable terminals are provided so that the fuse may be mounted in a fuse block. Enclosed fuses have been standardized into classes according to the voltage and ampere capacity, and are rated so that they will carry ten per cent overload indefinitely, and will open at twenty-five per cent overload.

A very important difference between the fuse and the circuit breaker is the matter of time element. Thus the over-load circuit breaker depends for its operation on the value of the current only, whereas the blowing of a fuse depends not only on the current but also on the time it flows. That is, the breaker will open immediately at any load in excess of that for which it is set, and will not operate at any smaller current, no matter how long it may continue. Standard fuses, on the other hand, will in time operate at an overload of only 25 per cent, and will open in a proportionately shorter time with greater over loads. Certain conditions, therefore, require the use of fuses, while others are better met by breakers, or by a combination of the two.

Air-Break Switches. Special styles of switches are required in many cases in alternating-current work on account of the excessively high voltages, especially when the switch has to handle large currents at high voltage.

Mention has been made on page 421 of the use of a marble slab between the blades and contact points of a double-pole switch to prevent the arcs, formed when the switch is opened, from flashing across and short-circuiting the points of the switch which are connected to the generator terminals. Such a switch with marble barrier is shown in Fig. 364.

Arcing is reduced to a minimum in every case by opening the switch very quickly, and all of the special alternating-current switches

*The expulsion type of fuse, much used for medium voltages in alternating-current systems, is described on page 305, in connection with transformer fuse blocks.

described below, are arranged to open with a snap, even though the controlling lever is moved slowly.

Fig. 378 shows a common form of knife switch specially constructed to give a quick break. The switch blade is in two parts *a* and *b*, to one of which, *a*, is attached the operating handle. The two parts *a* and *b* of the blade are connected by strong helical springs




Fig. 378. "Quick Break" Knife Switches

s s, one on each side of the blade. When the handle is pulled forward to open the switch, blade *a* leaves clip *c*, while the springs are put in tension more and more until the switch blade *b* is pulled from the clip *c*, with a snap, thus causing a sudden breaking of the circuit. Fig. 378 shows two single-pole quick-break switches. The one on the left, designed for 600 amperes, is provided with two massive tubular terminals *tt*, into which the terminals of the main circuit are inserted and soldered. The switch on the right, designed to carry 3,600 amperes, is furnished with massive studs *dd*, which project through holes drilled in the switchboard to the back of the board.

Connection to these studs is made by clamping the terminals of the main circuit to them by means of the threaded nuts *n n*. On account of the large current to be carried, extra large contact surfaces are provided between switch blades and clips, as seen in the figure.

Damage to switch-blades and clips, due to arcing, is reduced to a minimum by providing carbon blocks which make a connection in parallel with the switch connection proper. When the switch is opened, the metal connection is broken first, and the carbon connections afterwards, so that the arcing always takes place between the carbon blocks.




Fig. 379. Half Section of Over-Load Type of Circuit Breaker—Closed

Circuit Breakers. In Fig. 379 there is shown in elevation and half section a plain overload type of circuit breaker for either direct- or alternating-current circuits up to 600 volts. Fig. 380 is a general view of the same single pole breaker as manufactured by the Roller-Smith Company. Fig. 379 shows the breaker closed and Fig. 380, open. Referring to Fig. 379, *A* is a rectangular magnet core journaled on the cylindrical shaft shown, and supported by it between two non-magnetic supporting frames, only one of which, *B*, is shown in the sectional view. To *A* is secured one of the terminals of the main

coil *C*, which is made up of a number of hard-rolled copper strips; and also the arm *D*. The other terminal of the laminated winding is secured to the lower stud *P*. Current entering through the stud *P* passes through the main windings *C* into the arm *D*, through the contact plate *E* into the stationary copper brush *F*, and finally out through the upper stud *Q*. When the current through the breaker exceeds the predetermined value for which it is adjusted, the attraction exerted by the core *A* on the ends *K* of the pivoted armature causes it to rise with increasing speed until the finger *M*, a part of the armature, strikes *R*. The roller *H* is thus forced downward past the roller *G*, thus permitting the strong outward pressure of the brush *F* and that of the coil *C* to throw the arm outward and thus break the circuit, first between the brush fingers and the contact plate *E*, and finally between the carbons *S* and *F*. It will be noted that the carbon block *F* is mounted on a spring support and thus maintains its contact with *S* after the main contacts between the copper brush *F* and plate *E* have been broken. This action effectually prevents arcing and pitting of the main contacts which would soon wear out the breaker.




Fig. 380. General View of Roller-Smith Single-Pole Breaker—Open

To reset the breaker, the handle which the act of opening has raised, is pulled down, thus forcing the roller *H* up past the roller *G*, which compresses the brush *F* and the coil *C*, by forcing the arm back into its initial position.

These breakers are also made with under-load, no-voltage, and shunt-trip attachments, and may be operated from any distant point if desired.

The same methods are available for suppressing the arc between the break points of a switch as for suppressing the arc which tends to maintain itself between the terminals of a fuse link when

the link fuses. Thus some of the older switches were designed to break the circuit between the end of a movable copper rod and a stationary copper socket, both of which are surrounded by a porcelain tube, thus utilizing the expulsion principle for suppressing the arc.

The most effective method, however, for suppressing the arc* on a high-voltage switch is to design the switch so as to open quickly under oil, and for very high voltages to provide for several simultaneous breaks in series.




Fig. 381. General Electric Oil Break Switch Mounted on Panel




Fig. 382. General Electric Oil Break Switch —Rear View—Switch Open

Oil-Break Switches. Air-break switches are not now considered reliable or safe for alternating-current circuits above about 600 volts, hence the adoption of oil-break switches for practically all alternating-current circuits of 440 volts and over is today almost universal.

Figs. 381 and 382 are views of a typical General Electric oil-break switch, mounted on a panel. The six insulators which support

*A multiple-break switch which makes two or more breaks (in series) in a circuit simultaneously, is used to lessen the trouble from arcing. Some of the special switches described subsequently are double-break switches.

the stationary contacts and studs each consist of a single piece of porcelain, and can be easily detached from the frame when necessary. The contact fingers are flared, are of copper, and are fastened to the studs by heavy springs which insure good contact with the moving blades. The oil tanks are of sheet metal lined with maple, and are designed to be easily removable for inspection of switch contacts and oil.

These oil switches are designed with operating mechanism mounted directly on switchboard panel and the oil switch proper mounted:




Fig. 383. Westinghouse Three-Pole Oil Circuit Breaker—"Remote Control"

- (a) directly on panel;
- (b) on pipe framework directly back of panel;
- (c) on pipe framework remote from panel; or
- (d) on flat surfaces or in cells remote from panel.

These switches are made single-throw with one, two, three, or four poles; and for voltages of 2,500 up to 15,000, and with current capacities ranging from 1,000 to 300 amperes, respectively.

Any of these oil switches may have operating mechanisms which are either non-automatic, or automatic with one, two, or three overload-coil attachments. Fig. 381 shows front view of the switch closed, and Fig. 382 back view of the switch open.

Great improvement has been made in recent years in the design of large circuit breakers for protecting alternating-current circuits up to 110,000 volts and over. Fig. 383 shows a Westinghouse three-pole oil circuit-breaker for 44,000-volt circuits. Its capacity is 300 amperes. It is hand-operated and illustrates what is called "remote-control". This type of breaker may also be electrically operated




Fig. 384. "Type GA" Westinghouse Oil Circuit Breaker Removed from Tank Showing Open and Closed Positions

by means of suitable solenoids or coils energized by direct current under the control of the operator. They may also be made automatic in action by the addition of suitable relay attachments.

Fig. 384 shows a single-pole of the "type GA" Westinghouse oil circuit breaker removed from its tank, in both the open and closed positions. The upper or fixed contacts are firmly secured to the lower end of the leads, which are clamped by iron collars, which in

turn are bolted to the tank cover through which the leads pass. This upper contact consists of a circular piece of brass of greater area than the moving contact, which insures the entire surface of the latter bearing upon the stationary contact, the object being to eliminate the necessity of accurately centering the contacts one upon the other.

The lower or movable contacts are carried by a heavy metallic cross bar and consist of pieces of cylindrical brass rod backed by compression springs of sufficient strength to insure good contact and which also render the contacts self-aligning. Copper braid shunts are used to carry the current around the springs in order to prevent any deterioration by the passage of current through them.

It will thus be seen that the contact is of the simple "butt" type between two circular plane surfaces. The high voltage necessitates the unusually long, widely separated, and specially insulated "condenser" type of terminals shown in Fig. 384.

The general type of oil switch illustrated in Fig. 383 is today the standard for high-voltage circuits carrying large alternating currents, and is used extensively in many of the most recent high-voltage generating stations.

Fig. 385 is a general view of a General Electric three-pole oil switch, or rather three single-pole switches operated by an electric motor, which is controlled from the switchboard. Each single-pole switch in Fig. 385 is mounted in a separate brick compartment. The oil is contained in long metal cylinders in order to reduce the amount of oil to a minimum. The long brass connecting rods pass through holes in the porcelain bushings in the tops of the cylinders and the ends of these rods carry conical lugs which fit into spring sockets. These spring sockets are connected to rods which pass




Fig. 385. General Electric Three-Pole Oil Switch Operated by Electric Motor

out through porcelain bushings in the bottoms of the cylinders, and these lower rods are connected together in each compartment, thus making a double-break single-pole switch. The metal cylinders in




Fig. 386. Stillwell Single-Phase Voltage Regulator Complete

Fig. 385 are entirely insulated from the switch points proper.

Feeder or Voltage Regulators. When several feeder circuits are supplied from the same bus bars, and when it is desired to control the voltage on each feeder circuit independently of the others, feeder regulators are required.

Single-phase feeder regulators are autotransformers with their primary coils connected across (that is, as a shunt to) the bus bars, and their secondaries connected in series with the feeder circuit. They are of three types, as follows:

(a) A type in which the secondary coil has many leads brought out to points on a dial switch, so that the number of active turns on the secondary coil may be changed at will, thus permitting the adjustment of the feeder voltage to any desired value.

(b) A type in which the primary and secondary coils are wound at right-angles to each other on the inner face of a laminated iron ring very much like the stator ring of an induction motor. The magnetic flux, due to the primary coil, is made to pass *in whole or in part* through the secondary coil by turning a laminated core as explained below.




Fig. 387. Dial of Stillwell Single-Phase Voltage Regulator

(c) Polyphase feeder-regulators usually consist of several single-phase regulators, one for each phase. The advantage of this arrangement is that the voltage of each phase may be controlled separately. A combined poly-phase feeder regulator is, however, sometimes used.

(a) *Stillwell Regulator.* Fig. 386 is a general view of a Stillwell single-phase voltage regulator with its dial switch complete. The dial switch alone is shown in

Fig. 387. The complete internal connections are shown in Fig. 388. The primary coil of the regulator is permanently connected across the bus bars (or generator terminals). One feeder wire passes out directly from the generator and the other passes through few, or many, turns of the secondary coil of the regulator, and thence to the line. The reversing switch A_1 serves to connect the feeder f to one or the other terminal of the secondary coil, and the arm of the dial switch connects the line wire to any one of the taps which are brought out from the secondary coil. For one position of the reversing switch, the induced voltage in the secondary turns, which are connected in series with the feeder circuit, is added to the generator voltage, thus raising the feeder voltage. For the other position of the reversing switch, the induced voltage in the secondary turns, which are in series with the feeder circuit, is subtracted from the generator voltage, thus reducing the feeder voltage.




Fig. 388. Complete Internal Connections for Stillwell Voltage Regulator

When the arm of the dial switch touches two adjacent contact points (and it must be arranged to always touch one point before it leaves the other), the intervening turn (or turns) of the secondary coil of the regulator is short-circuited. To overcome this difficulty, the arm is made double, that is, two arms A and B move together side by side as shown in Fig. 389. These arms are shown connected




Fig. 389. Diagram of Special Form of Dial Switch for Stillwell Regulator

to two contact points, say 15 and 16. C represents a special form of choke coil consisting of two windings on one iron core. These two windings are arranged so that equal currents flowing out from A and B circulate around the core in opposite directions, so that the

core is not magnetized, and the windings of C have no choking action. When, however, the two fingers A and B touch adjacent points of the dial switch, the turns of wire S on the regulator secondary tend to send a very large current out on A , say, and back on B . These oppositely flowing currents circulate around the core of C in the same direction. These currents, therefore, magnetize the core, and the windings have in consequence a very considerable choking action, the effect being to choke down oppositely flowing currents in the fingers A and B , and to allow currents in the same direction to flow freely through it.




Fig. 390. Diagram of Magnetic Voltage Regulator

(b) *Magnetic Voltage Regulator.* The type of voltage regulator mentioned under (b) is sometimes called the magnetic voltage regulator. A laminated iron ring $R R R R$, Fig. 390, has four large deep slots on its inner face in which the primary coil $P P$ and the secondary coil $S S$ are placed. A laminated core $C C$ mounted on a spindle is arranged to be turned into any desired position by means of a hand wheel. In the position indicated by full lines, the core carries the magnetic flux due to the primary coil in one direction through the secondary coil, and in the position indicated by dotted lines, the core carries the magnetic flux due to the primary coil in the other direction through the secondary coil. Therefore, when the core is moved slowly from position 1 to position 2, in the direction indicated by the arrows, the voltage induced by the secondary coil changes gradually from a full positive value to an equal negative value in its relation to the primary voltage. That is, when the core is in position 1, the induced voltage in the




Fig. 391. Magnetic Voltage Regulator in Case with Cover Removed

secondary coil has its greatest value of say, 100 volts which, if the coils are properly connected, is added to the bus-bar voltage E , giving a feeder voltage of $E+100$. When the core is midway between the two positions 1 and 2, the induced voltage in the secondary coil is zero, and the feeder voltage is then equal to the bus-bar voltage E . When the core is in position 2, the induced voltage in the secondary coil is




Fig. 392. General Electric Six-Phase Induction Regulator Complete in Case

again at a maximum of say, 100 volts, but in such a direction as to oppose the bus-bar voltage, so that the feeder voltage is $E-100$ volts.

Fig. 391 is a view of a magnetic voltage regulator with the covering of its containing case removed. The two coils, primary and secondary, at right angles to each other, are clearly shown with their leads passing out to the connection board which occupies the compartment on the back of the case in the figure. The hand wheel

for turning the iron core is also shown. A valuable feature of this type of regulator is that it produces a continuous variation of voltage, whereas the Stillwell regulator produces a step-by-step variation.

(c) *Induction Regulator.* The combination polyphase induction regulator is called the *induction regulator* from its similarity to the induction motor. The action of the induction regulator stated in simplest terms is as follows: A regular induction motor stator has its polyphase windings connected across the polyphase bus bars. This produces a rotating magnetism in the stator iron as explained on page 372. This rotating magnetism rotates in synchronism with the generator or generators which are supplying current to the bus bars. Inside of this induction motor stator (or primary) is placed a polyphase armature which does not revolve, but it is mounted




Fig. 393. Laminated Core of the Stationary Member of an Induction Regulator

on a spindle so that it may be turned through an angle of 60° or 90° by means of a hand wheel and worm gear. The rotating stator magnetism induces polyphase electromotive forces in the windings of this polyphase armature; these polyphase electromotive forces are in synchronism with the electromotive forces between the bus bars, and the two (or more) windings of the polyphase armature are connected in series with the two (or more) feeder circuits (constituting of course one set of polyphase feeders) which are to be regulated. The electromotive forces in the stationary armature windings may be in phase with the bus-bar electromotive forces, in which case the regulator raises the voltage by the greatest amount of which it is

capable. By turning the stationary armature by means of the hand wheel and worm gear, the phase difference between the bus-bar voltages and the voltages induced in the stationary armature windings may be gradually changed from coincidence of phase to opposition of phase, during which time the boosting effect of the regulator will gradually drop to zero, become negative, and reach its greatest negative value when opposition of phase is reached. Thus, if the electromotive force induced in each armature winding of the regulator is 100 volts, and if the bus-bar voltage is 1,000 (each phase), then the voltage between the feeders can be varied from 900 volts to 1,100 volts by means of the regulator.

Fig. 392 is a general view of a six-phase induction regulator in its containing case, manufactured by the General Electric Company. This particular machine has the primary windings on the movable member, whereas the armature windings are on the stationary member. It is used for controlling the alternating-current voltages applied to the collector rings of a six-phase rotary converter. The figure shows a small direct-current motor mounted on the regulator case for turning the movable member of the regulator, this motor being controlled by the hand wheel shown in the figure.



Fig. 394. Movable Core of the Primary Member of an Induction Regulator

Fig. 393 shows the laminated iron core of the stationary member of an induction regulator, the stampings of which are clamped in a cast-iron shell. Fig. 394 shows the movable core.

Ratings of Voltage Regulators. It was shown, page, 253 that the total amount of power delivered to service mains at a slightly increased voltage produced by an autotransformer is very much greater than the power actually transformed from the primary to the secondary of the transformer. In fact, the power actually transformed is equal to the increase (or decrease) of voltage multiplied by the total current delivered, and the rating of the autotransformer (which determines its size) is based upon the power transformed.

For example, a voltage regulator is to be used for raising the voltage of 2,000-volt bus bars to a maximum of 2,100 volts, and the





Fig. 395. Diagram of Connections for Voltmeter Compensator

maximum current to be handled is 100 amperes. In this case the transformer rating of the regulator is 100 amperes at 100 volts (or 10 kilowatts), whereas the total power to be delivered to the feeders is, at its maximum, 2,100 volts \times 100 amperes or 210 kilowatts.

Since a voltage regulator transforms only a small fraction of the power delivered to the feeders which it controls, the losses of power in the regulator are very small indeed. Thus the 10-kilowatt regulator might have a total loss of 300 watts, which is 3 per cent of the power actually transformed by the regulator, and only one-seventh of one per cent of the total power delivered to the feeders.

Voltmeter Compensator. The voltmeter compensator is a device by means of which the voltmeter on the switchboard in a station is made to indicate the voltage between the transmission lines at some remote feeding center or receiving station. The essential principles of this instrument are made clear from Fig. 395. An alternating-current generator *G* delivers alternating current at voltage E_0 be-



Figs. 396 and 397. Vector Diagrams Showing E.M.F. Relations in the Line and in the Compensator

tween its terminals. This current is transmitted over a line of which the resistance is R (including r) and the reactance is X (including

x), and the voltage at the receiver is E . The line loss of electro-motive force is XI due to reactance, and IR due to resistance, as




Fig. 398. Wiring Diagram for Voltmeter Compensator as Used in Practice in High Voltage Circuits

explained on page 58. The relation between E_0 , E , IR , and XI is shown in Fig. 396. T , Fig. 395, is a transformer which supplies to the voltmeter V a voltage exactly in phase with E_0 , and, say, one-




Fig. 399. Diagram of Circuits and Apparatus in Connection with Westinghouse Compensated Voltmeter

tenth as great. Let x be a reactance one-tenth as great as X , and r a resistance one-tenth as great as R . Then the voltage between

the points *a* and *b* consists of two parts, rI and xI , which are in phase with, and one-tenth as great as, IR and XI , respectively. Therefore rI and xI subtracted from one-tenth E_0 give a voltage which is exactly equal to, and in phase with, one-tenth E , as shown in Fig. 397, so that the voltmeter being acted upon by (one-tenth $E - rI - xI$) gives a reading which multiplied by 10 is equal to E .

In practice, it is not desirable to connect the voltmeter wires to the high-voltage mains, and the essential features of the arrangement shown in Fig. 395 are realized by introducing r and x in series with the secondary of a current transformer T' , as shown in Fig. 398. More or less of the resistance r and of the reactance x may be included in the voltmeter circuit by means of two dial switches of which the arms are represented by dd , Fig. 398. The object of these dial switches is to enable a given compensator to be adjusted to any given transmission line.

Fig. 399 shows all of the apparatus used in connection with the Westinghouse compensated voltmeter; the lines ll are shown at the left, T is the step-down potential transformer, T' is the series transformer, dd is the case containing the resistance r and the reactance x , and upon which the dial switches are mounted, V is the voltmeter, and VR is the resistance in series with the voltmeter.

LIGHTNING ARRESTERS

Effects of Lightning. When a lightning stroke occurs in the neighborhood of a transmission line, a sudden rush of electric current takes place over the line due to one or more of the following causes:

- (a) Electric charge accumulated on the line is suddenly released and tends to flow to earth.
- (b) The magnetic action of the lightning discharge induces a sudden rush of current in the line.
- (c) When the lightning discharge actually strikes the line, an enormous rush of current takes place over the line and to earth.

When the sudden rush of current which accompanies a lightning discharge encounters a portion of the circuit which has considerable inductance, very great electromotive forces are created, in the same way that enormous mechanical forces are created when a moving body strikes a heavy obstacle, and the insulation of the circuit, be it air or solid insulation, is likely to be broken down, or

punctured, giving a short path to the earth for the rush of current. Thus, a sudden rush of current coming into a station over a transmission line, encounters the highly inductive windings of wire of a transformer, dynamo, or other apparatus. The electrical inertia (inductance) of the windings dams up the rush of current, as it were, and the current rush is almost sure to break through the insulation at the very entrance to the winding, passing from the copper wire over to any metal which is connected more or less thoroughly to earth, resulting in the coils or apparatus being burned out or badly damaged.

A lightning arrester is a device for shielding a transformer, dynamo, or other piece of apparatus from the rushes of current which come into a station on an overhead line during a thunderstorm and from disturbances due to the static unbalancing of the electrical circuits.

The lightning arrester consists of:

(a) An inductance coil, or choke coil as it is called, for damming up more or less completely the rush of current before it reaches the dynamo or other apparatus.

(b) A weak place, specially arranged in the insulation of the line, that is, a spark gap, just in front of the choke coil through which the dammed up rush of current may break, and flow harmlessly to earth.

(c) A conducting path to earth as straight and direct as possible, and a good earth connection. Turns and bends in the conducting wire connected to earth are to be avoided, inasmuch as they introduce inductance which tends to check the quick flow of current to earth.

(d) A device for extinguishing the electric arc which may be maintained across the spark gap by the regular line current itself, after the rush of current from the lightning discharge has passed and gone.

The choke coil of a lightning arrester must be very highly insulated. Two types of choke coil are commonly used. Fig. 400 shows a cylindrical choke coil mounted on a marble base, and consisting of three layers of large and very highly insulated wire. The




Fig. 400. Choke Coil Mounted on Marble Base

terminals of the coil are at its two ends. Fig. 401 shows a choke coil consisting of an insulated copper strip wound like a roll of tape.




Fig. 401. Choke Coil made of Insulated Copper Strip

One terminal of this choke coil is on the outer edge and the other is at the center. The figure shows the method of supporting the coil on a special insulator carried on a bracket. Iron cores do not add to the damping action of a choke coil in the case of the excessively quick rushes of current which accompany lightning discharges, for the reason that the iron does not have time to become magnetized. Therefore, lightning arrester choke coils are always made without iron cores.

Multi-Gap Non-Arcing Arrester. The spark gap of alternating-current lightning arresters is usually made between blocks of metal containing zinc or cadmium. A. J. Wurtz made the discovery that it takes a very high voltage to maintain an alternating-current arc between metal electrodes which contain zinc or cadmium. The behavior of these alloys is somewhat analogous to that of the mercury-vapor rectifier described




Fig. 402. Westinghouse Multi-Gap Lightning Arrester

on page 321 in that reversal of the current flow which makes the mercury an anode requires a greatly increased voltage. If this is not supplied the flow could not be maintained. Thus an alternating electromotive force of a frequency of 60 cycles per second, and 500 volts (effective value), cannot maintain an arc across a $\frac{3}{4}$ -inch air gap between massive blocks of brass. This non-arcing property of certain alloys is made use of in the multi-gap arrester of the Westinghouse Electric Company, shown in Fig. 402. It consists of seven

independent knurled brass cylinders supported by two overhanging

porcelain blocks forming a unit which is mounted in a weatherproof cast-iron case. The two end cylinders are connected, respectively, to the two line wires and the center cylinder is connected to ground. This arrester may also be used single pole, one for each side of a two-wire circuit. Connections for single-phase and for three-phase circuits are given in Fig. 403. For two-phase circuits each phase is to be connected as in the single-phase diagram.

This type of arrester is suited for use within a radius of three miles from the source of power on systems of 200-kw. capacity or less, and up to 400 kilowatts when connected more than three miles away from the power source.




Fig. 403. Lightning Arrester Connections for Single-Phase and Three-Phase Circuits

This type of arrester is not recommended for protecting circuits liable to low power factors, nor for 25-cycle circuits, for experience has shown that under these conditions the arcing cannot be suppressed.

Multi-Path Arrester. The multi-path arrester of the Westinghouse Company is single pole and adapted to either alternating- or direct-current circuits of any voltage up to 1,000. It can be mounted upon a pole. It consists of a spark gap in series with a high resistance block of carborundum. This block offers a very high resistance under normal conditions and moderate voltages, but its resistance to a static discharge is very low, and it readily conducts a lightning

discharge to ground. After the discharge has passed, it resumes its normal high resistance, thus preventing the line voltage from maintaining an arc. Fig. 404 is a view of the arrester in the lower half of its iron casing, the upper half being shown removed.

Electrolytic-Cell Lightning Arrester. This type of arrester, which has proved highly effective, is widely used. A single cell consists of two aluminum plates and an electrolyte, such as ammonium phosphate, which form a condenser that will stand about 340 volts alternating before breaking down. Up to this critical value of the voltage, which varies somewhat with the electrolyte used, a very small current passes through the cell, but as soon as the critical voltage




Fig. 404. Westinghouse Multi-Path Lightning Arrester
—Upper Half of Case Removed

is exceeded, the current increases very rapidly with even a slight increase in the voltage. As soon, however, as the voltage drops below the critical value, the resistance of the cell increases greatly.

In applying this interesting property of the aluminum cell to the lightning arrester, a large number of cells are made up in series and mounted in standard size units to be connected in series, the number of units chosen depending upon the voltage of the lines to be protected, allowing on the average about 300 volts per cell.

Fig. 405 shows a cross-section of an aluminum cell lightning arrester as made by the General Electric Company. It consists of

a series of concentric inverted cones of aluminum placed one above the other with a vertical spacing of about 0.3 inch. The electrolyte is poured into the cones and partly fills the space between adjacent ones. The pile of cones with the electrolyte between them is then immersed in a tank of oil, which helps to insulate cones from each other except for the electrolyte, and also prevents evaporation of the solution. A cylinder of insulating fiber concentric with the stack of cones is placed between the latter and the steel tank. This arrangement assists the free circulation of the oil and increases the insulation between tank and aluminum cones.

A stack of cones is used for each phase, and up to 7,250 volts all the stacks are placed in a single tank. Where the line voltage exceeds 7,250, each stack of cones is placed in a separate tank. The connection of the stacks to the line wires through spark gaps and to the ground is different, depending upon whether the circuits have their neutral point purposely grounded or not, and upon the line voltage.

The top cone of each stack is not directly connected between a line wire and the ground, because at normal line voltage some current would flow continuously through the aluminum cells, which would heat them and evaporate the electrolyte. To prevent this flow of current, the aluminum stacks are in practice connected to the line wires through spark gaps adjusted for a sparking voltage just above that of the normal line voltage. Under normal conditions no current passes from the line wires through the aluminum cells, but a lightning discharge with its accompanying high voltage easily jumps the spark gap and passes through the aluminum cells to ground. As soon, however, as the discharge is over, the resistance of the spark gap in series with the aluminum plates is too large to permit the line voltage to maintain an arc.

Fig. 406 is a view showing a typical installation of an aluminum lightning arrester for a 6,600-volt, three-phase, non-grounded neutral




Fig. 405. Cross-Section of Aluminum Cell Lightning Arrester

circuit. As shown the three stacks of cones, one for each phase, are installed in one tank which is placed on a rack insulated from the ground. Two of the stacks are connected directly to two of the




Fig. 406. Typical Installation for Aluminum Lightning Arrester on Three-Phase Non-Grounded Neutral Circuit

three line wires, each through a "horn-gap"; the third is connected to the remaining line wire through a "transfer device" or rotating switch, and a horn gap. The fourth stack is connected to the ground through the transfer device, which may be explained as follows:

When the stacks of aluminum cones have been disconnected from the line wires for a certain length of time, the insulating film

on the cones deteriorates, and experience has shown that in order to keep the aluminum cells in good working order, they must be connected to the line wires and charged at certain definite intervals. In some cases this type of arrestor must be charged daily, and in others weekly. The charging process consists simply of short-circuiting the spark gaps between the stacks and the line wires for a few moments. The transfer device provides a means of interchanging the ground stack with one of the line stacks during the charging operation so that the insulating films of all the cells may be reformed to an equal extent. For arresters up to 27,000 volts, the device is mounted with three insulators on the pipe frame work and is operated by a hand-wheel, as shown in Fig. 406.

Combination of a Condenser with a Choke Coil. The choking action of a coil of wire is due to its electrical inertia or inductance,




Fig. 407. Combination of Condenser and Choke Coil as Lightning Arrester

and the shielding of the apparatus behind a choke coil from severe electrical strains is precisely analogous to the following mechanical arrangement:

A wall is shielded from the severe strains due to a hammer blow by allowing the hammer to strike against a very heavy ball of iron which rests against the wall. The completeness with which this heavy iron ball shields the wall depends upon the interposing of an elastic substance between the ball and the wall. The ball alone cannot shield the wall unless the wall itself is slightly elastic.

In the same way the completeness with which a choke coil shields the dynamo and other apparatus depends upon the presence of some electro-elasticity*, or capacity in the circuit behind the choke coil. In some cases the circuit behind the choke coil has suf-

*See page 111.

ficient capacity for this purpose; it is always best, however, to connect a condenser behind the choke coil as shown in Fig. 407.

The choke coil and condenser are immersed in an oil tank when installed. From Fig. 407 it is seen that three wires *b b b* connect to choke coil and condenser. This combination of choke coil and condenser is called a *static interrupter* by the Westinghouse Company.

INSTRUCTIONS FOR INSTALLING LIGHTNING ARRESTERS

Location. As regards the location of lightning arresters, electric plants may be divided into two groups:

(a) Plants in which the individual pieces of apparatus such as transformers, motors, arc lights, etc., are many in number and widely scattered. In these cases lightning arresters should be located for the purpose of protecting the whole line. They should be located at a number of points, more numerous on the parts of the line particularly exposed, and fewer in number on the parts that are naturally protected, especially those parts shielded by tall buildings or numerous trees. No definite statement can be made as to the number of arresters needed per mile, as the requirements of different cases vary widely. Under average conditions no point of the circuit should be more than 1,000 feet from an arrester. It is not usual to find distributed apparatus on circuits of over 2,500 volts, but when such cases occur, a lightning arrester should be placed as near as possible to each piece of apparatus.

(b) Plants in which the apparatus is located at a few definite points in the system, as in a high-voltage transmission line. In such cases the arresters should in general be located to protect especially those points where apparatus is situated, that is, should be placed with the object of protecting the apparatus rather than the line as a whole.

The lightning arrester should always be so connected that in passing from the line to the apparatus the arrester is reached first, the choke coil second, and the condenser, if one is used, third.

Insulation. A lightning arrester is naturally exposed to severe voltage strains and, therefore, all active parts must be well insulated. On arresters for low voltages it is not a difficult matter to secure proper insulation, as the construction of the arrester itself affords protection. On high-voltage arresters, however, proper insulation is a more difficult matter. All arresters are marble or porcelain mounted, the marble or porcelain serving as an insulating support for the arrester. On circuits exceeding 6,000 volts, to obtain further insulation, the marble or porcelain bases should be mounted on wooden supports, well dried and shellaced. For 12,000 volts and above, the bases or panels should receive additional insulation in the form of porcelain or glass insulators used as supports.

Two high-voltage arresters attached to different line wires should not be placed side by side without either a barrier or a considerable space between them.

Grounds. Too much importance cannot be attached to the making of proper ground connections which should be as short and straight as pos-

sible. A poor ground connection will render ineffective every effort made with choke coils and lightning arresters to divert static electricity into the earth. It is important, therefore, to not only construct a good ground connection, but to maintain it so.

A good ground connection for a bank of station arresters may be made as recommended by the Westinghouse Company in the following manner: *First*, dig a hole 4 feet square as near the arrester as possible until permanently damp earth has been reached; *second*, cover the bottom of this hole with crushed charcoal (about pea size); *third*, over this lay 10 square feet of tinned copper plate; *fourth*, solder the ground wire, preferably No. 0 copper, securely across the entire surface of the ground plate; *fifth*, cover the ground plate with crushed charcoal; and *sixth*, fill the hole with earth, using running water to settle.

The above method of making a ground connection is simple, and has been found to give excellent results, and yet, if not made in proper soil, it will prove of little value. Where a mountain stream is conveniently near it is not uncommon to throw the ground plate into the bed of the stream. This, however, makes a poor ground connection, owing to the high resistance of the pure water and the rocky bottom of the stream. Clay, even when wet, rock, sand, gravel, dry earth, and pure water are not suitable materials in which to bury the ground plate of a bank of lightning arresters. Rich soil is the best. It is, therefore, advisable, before installing a bank of choke coils and lightning arresters, to select the best possible site for the lightning arrester installation with reference to a good ground connection. This may often be at some little distance from the station, in which case it is, of course, necessary to construct a lightning-arrester house. Where permanent dampness cannot be reached it is recommended that water be supplied to the ground through a pipe from some convenient source.

Where possible, a direct connection to an underground pipe system, especially of a town or city water main, furnishes an excellent ground on account of the great surface of pipe in contact with the earth and the numerous alternative paths for the discharge. In a water-power plant the ground should always include a connection to the pipe line or penstock and to the case or frame of the apparatus to be protected. An effective and easily made ground may be effected by using a large, old iron casting, like an old car wheel, fitted with a riveted copper strap and buried in damp earth. A few pounds of common salt thrown around any ground terminal before covering helps to maintain dampness.

Inspection. As the effectiveness of every arrester is of great importance, they should be inspected from time to time and the resistances and earth connection tested for open circuit.

APPENDIX

PARALLEL OPERATING OF ALTERNATORS

Necessary Conditions. In the parallel or multiple operation of alternators, it is necessary that they be similar in three respects in order to insure their working together properly when connected in parallel,* viz, frequency, phase, and voltage.

(a) *Frequency.* Two generators are of the same frequency when the numbers of alternations or reversals of their electromotive forces in a given time are equal. This requirement is fulfilled when the product of the number of poles by the revolutions per minute is the same for each machine. The frequency of a generator, being dependent upon its speed, may be controlled by the regulation of the speed of its prime mover.

(b) *Phase.* Two generators are in phase when the positions of their armatures with respect to their field poles are the same, *i. e.*, when similar armature coils are opposite positive field poles at the same instants. When this condition exists the electromotive forces of the machines are both positive at the same time, and their maximum values occur at the same instant; the electromotive forces are said to be coincident in phase.

(c) *Voltage.* Two generators are of the same voltage when the pressure measured across the armature terminals is the same for each machine. The voltage for a given speed being dependent upon the field strength may be controlled by means of the rheostat in the field circuit.

Determination of Relative Frequency and Phase Coincidence. If two similar generators are running at exactly the same speed their difference in phase remains constant. This condition, however, does not exist in practice unless the armatures are rigidly connected, as the inevitable fluctuation in engine and water-wheel speeds and in belt slippage causes the position of the armatures with reference to their field poles to be continually changing, and consequently the difference between the phases to be likewise changing. As generators should not be thrown in parallel excepting when their frequencies are practically the same, and at the time their phases

*Furthermore, two alternators, to operate satisfactorily in parallel, must have electromotive force waves of the same shape.

are in exact coincidence, or nearly so, it is essential to have an accurate means of determining when these conditions exist.

The principle of the most common method of determining when generators are of the same frequency and are coincident in phase, is illustrated in Fig. 408. *A* and *B* represent two single-phase generators, the leads of which are connected at the switch *C*, through two series of incandescent lamps *D* and *E*. It is evident that as the relative positions of the phases of the electromotive forces change from that of exact coincidence to that of exact opposition, the flow of current through the lamps varies from a minimum when the machines oppose each other in forcing current through the lamps as shown by the arrows in Fig. 408, to a maximum when the machines help each other in forcing current through the lamps.* If the electromotive forces of the two machines are exactly equal and in phase, the current through the lamps will be zero, and as the difference in phase increases, the lamps will light up and will increase in brilliancy until the maximum is reached; when the phases are in exact opposition. From this condition they will decrease in brilliancy until completely dark, indicating that the machines are again in phase. The rate of pulsations of the lamps depends upon the difference in frequency, *i. e.*, upon the difference in the speeds of the machines, and by adjustment of the governors of the engine or water-wheel, or the tension of the belt, the rate can generally be reduced to as low as one pulsation in ten seconds, which affords ample time for throwing the switch connecting the generators in parallel.




Fig. 408. Wiring Diagram Showing Method of Determining Coincidence in Phase and Frequency of Two Generators

Synchronizer. When the phases of two generators coincide, the machines are said to be “in phase,” “in step,” or “in synchronism”. The apparatus used for determining when generators are in phase is called a *synchronizer*. In Fig. 408 the lamps constitute the synchronizer. While a series of lamps, alone, may be used for syn-

*When the two machines oppose each other in forcing current through the lamps they would help each other, or be in phase with each other, in producing current in the receiving circuit to which the machines are to be connected in parallel.

chronizing machines of very low voltage, it is not safe or practical to use this method for machines of high voltage. The most common arrangement for synchronizing alternators, in general, is illustrated in the diagram, Fig. 409. *A* and *B* represent two single-phase generators with switches in the main leads. There are two transformers, the primaries of which are connected across the main leads of *A* and *B*, respectively, the secondaries being connected in series through the lamps *E*. Now, if the transformers are connected similarly in the two circuits, as shown in the diagram, then when the generators *A* and *B* are in phase, the electromotive forces in the secondaries will be in phase and no current will flow through the lamps, but when the generators are out of phase, the electromotive forces in the secondary circuits will be out of phase also, and current will flow through the lamps. The amount of this current and the resultant brilliancy of the lamps depends on the difference in phase. If the connections of either the primary or the




Fig. 409. Wiring Diagram Showing Method of Determining Phase Relation by Synchronizer

secondary of either transformer be now reversed from those shown in Fig. 409, the indications of the lamps will be reversed; that is, when the generators are in phase the lamps will burn at maximum brilliancy, and *vice versa*. It is the common practice of the Westinghouse Company to arrange the transformer connections so that the lamps shall be dark when the generators are in phase.

In order to determine whether the synchronizer lamps will be bright or dark for a given connection of transformers when the generators are coincident in phase, remove the main fuses or raise collector brushes from one machine, and throw in the main switches with the other generator at full voltage. Since both primaries are now connected through the switches to one machine, the lamps will be in the same condition as when the main or paralleling switches

are open and both generators are coincident in phase. If the lamps burn brightly and it is desired that they be dark for an indication of phase coincidence, the connections of one of the primaries or of one of the secondaries of the transformers should be reversed.

The lamps which are used with the synchronizer should be adapted for the highest voltage which they will receive. Thus, if they are placed upon the secondaries of two 100-volt transformers, there should be two 100-volt lamps or four 50-volt lamps in series. If two 200-volt machines have the lamps applied directly without transformers it will be necessary to use four 100-volt lamps, or their equivalent.

Rate of Pulsation and Size of Pulley. The difference in speed between two machines may be determined by the rate of pulsation of the synchronizing lamps. It is sometimes convenient to know this difference in speed, especially when two generators are belt-driven from the same shaft. If the speeds are not equal, it may be necessary to turn off one of the pulleys in order to make them equal. One pulsation of the lamps, *i. e.*, the interval between two consecutive occurrences of maximum brilliancy, indicates a gain of one cycle or two alternations of one machine over the other. Thus, if there is one pulsation of brightness per minute, and the number of alterations is 7,200 per minute, then one machine gives 7,202 alternations, while the other gives 7,200. If the number of pulsations of brightness is 36 per minute, then one machine gives 7,272 alternations, while the other gives 7,200 alternations, and the first machine is, therefore, running 1 per cent faster than the second machine. In order to determine which machine is running the faster, the load may be thrown upon one machine, or its belt may be slackened so as to decrease its speed. If this be done to the machine which attempts to run too fast, the pulsations will become less rapid; while if it be done to the machine which is running slower, the pulsations will become more rapid. If one machine is running 1 per cent faster than the other, it will be necessary to reduce the diameter of the pulley of the other (slower) machine by 1 per cent.

The thickness of the belt, the tightness of the belt, the slippage (dependent upon the kind of belt, the condition of the surfaces of the pulley and belt, and the load) are all factors which affect the speed and must all be kept in mind.

Directions for Connecting One Alternator in Parallel with Another Alternator.

(1) *Frequency.* The speed of the new machine which is to be connected in parallel must be made such as to give the same frequency as the one already running. If the latter is carrying a load, it may be necessary to reduce the speed of the unloaded machine below that at which it tends to run with no load, by adjusting the engine valve, or the water wheel gate or nozzle, or the belt slip-page, in order to secure the proper speed.

The adjustment of the engine should preferably not be by throttling, as the governor is liable to "hunt" when the throttle is opened. It is desirable to be able to adjust the governor for changing the speed while the engine is running.

(2) *Voltage.* The field excitation of the new machine should be adjusted so that its voltage is the same as that on the bus bars, the measurement being made by a voltmeter.

(3) *Phase Coincidence.* Synchronizer lamps indicate by their slow rate of pulsation that the machines are of practically equal frequency. When the synchronizer lamps indicate the proper phase relation, *i. e.*, phase coincidence (preferably when the lamps are dark), all is ready for closing the switch.

(4) *Main Switch.* Close the main switch a little too soon (when the machines are approaching the proper position) rather than too late (when they are receding from it). If the switch is operated by compressed air or for any other reason does not close the instant the handle is operated, due allowance must be made for the interval.

(5) *Equalizing Switch.* If the generators are composite wound, close the equalizer switch.

(6) *Adjustment of Load.* Adjustment may now be made by means of the governor or otherwise so that each machine receives its proper share of load.

(7) *Adjustment of Field Currents.* The field currents of the several generators should be properly adjusted to eliminate cross currents between the armatures and maintain the proper voltage on the bus bars.

Directions for Cutting Out An Alternator Which is Running in Parallel with One or More Alternators.

(1) Preferably cut down the driving power until it is just

about sufficient to run the generator at zero load. This will automatically reduce the load on the generator.

(2) Adjust the resistance in the field winding of the machine which is to be cut out until its armature current is a minimum.

(3) Open the main switch, then the equalizer switch.

It is usually sufficient, however, to simply disconnect a machine from the bus bars, thereby throwing all the load suddenly on the remaining machines, without having made any special adjustments of the load or the field current. The objection to this method is that it may cause serious hunting of the remaining machines.

The field circuit of the generator to be disconnected from the bus bars must not be opened before the main switch has been opened; for if the field were opened first, a heavy current would flow between the armatures.

REVIEW QUESTIONS



REVIEW QUESTIONS

ON THE SUBJECT OF

ALTERNATING CURRENT MACHINERY.

PART I.

1. Explain the term "apparent watts."
2. What is the inductivity of a dielectric, and how is it determined?
3. Explain, with diagram, the method of adding two synchronous harmonic electromotive forces or currents.
4. Draw a curve of alternating current, electromotive force, and power in case the current lags nearly 90° behind the electromotive force.
5. Explain inductance.
6. For a given per cent of line loss in the transmission of a certain amount of power, what is the effect of making the voltage four times as great—(a) on the current? (b) on the resistance of line? (c) on the diameter of wire? (d) on the weight of wire? (e) on the cost of line?
7. If an alternator has 12 poles and is to give a frequency of 25, what must be its speed?
8. What is an exciter? Explain its function.
9. Define alternator alternating electromotive force, and alternating current.
10. What determines the difference between the generator electromotive force and the receiver electromotive force, (a) when the receiving circuit is non-reactive? (b) when the receiving circuit is highly reactive? (c) when the receiving circuit has large capacity reactance?

ALTERNATING CURRENT MACHINERY

11. Give conventional representation of a resistance, an inductance, and a capacity.
12. If a harmonic current has an effective value of 200 amperes, what is its maximum value?
13. What is a harmonic electromotive force?
14. What is meant (*a*) by the effective or virtual value of an alternating current or electromotive force? (*b*) by the average value? (*c*) What is the relation of each to the maximum value?
15. If an alternator has 8 poles and runs at a speed of 900 r.p.m., what is its frequency?
16. What is a cycle? an alternation?
17. In an alternator, explain why the electromotive forces generated by adjacent armature coils do not oppose each other.
18. What is meant by capacity?
19. Does an alternating-current ammeter or voltmeter read effective or maximum values?
20. What is the inductance of a coil of wire wound on a wooden spool if its length is 40 centimeters, its mean radius $3\frac{1}{2}$ centimeters, and it consists of 200 turns?
21. Draw a sine curve, giving lines used in its construction.
22. What is the form factor of a circuit, and what is the least possible value it can have?
23. State the power law for alternating currents.
24. Define reactance and impedance.
25. When is a revolving-armature type of alternator generally adopted?
26. What are collecting rings, and how do they differ from the commutator of a direct-current machine?
27. State Ohm's Law for alternating currents.
28. What is the power factor of an alternating-current circuit?
29. Give formula for capacity of a condenser.
30. State Joule's Law for alternating currents.
31. Explain synchronism and phase difference.
32. When are two electromotive forces in quadrature? in opposition?
33. Discuss the advantages and disadvantages of alternating currents.



REVIEW QUESTIONS

ON THE SUBJECT OF

ALTERNATING CURRENT MACHINERY.

PART II.

1. Is the three-ammeter method used in practice?
2. What is the necessity of a starting coil in the Thomson recording wattmeter?
3. In the two accompanying meter dials, give the reading in watt-hours and calculate the customer's bill.



4. Give the simplest method of determining the inductance of an armature, with the proper formula.
5. An alternator gives 1,000 volts between its collector rings at full load current and field excitation; when the armature current is decreased to zero, it gives 1,050 volts. What is the regulation?
6. What discovery made possible the use of polyphase currents for power purposes, through the medium of the induction motor?
7. How is the E.M.F. measured in the break-down test? Describe the apparatus used.
8. Supposing the power of a single-phase alternating-current circuit as measured by a wattmeter is 450 watts. and the

ALTERNATING CURRENT MACHINERY

power factor is .82 while the voltage is 1,000, what current is taken from the mains ?

9. Explain the effect of armature reaction upon the magnetic flux in case the armature current is in phase with the electromotive force, in case it lags behind the electromotive force, and in case it leads the electromotive force.

10. What methods are used in the field excitation of alternators ?

11. In what way did the single-phase system fail to fulfill all the requirements for general purposes ?

12. For an alternating current of a given frequency and wave shape how should a plunger type voltmeter be calibrated ?

13. How is the speed of the Thomson recording wattmeter made proportional to the driving torque ?

14. Give the fundamental equation of the alternator and explain the meaning of the symbols.

15. What do you understand by the regulation of an alternator ?

16. Why is the three-voltmeter method not used in practice ?

17. Using the price chart in Fig. 84, determine what will be charged for 86,500 watt-hours at 10 cents per thousand.

18. Which has the greater inductance; an armature with concentrated winding, or an armature with a distributed winding ? Why ?

19. What is meant by the synchronous reactance of an armature ?

20. How does the inductance of an armature alternator vary with its linear dimensions ?

21. Explain the Thomson inclined coil meter.

22. In the three-phase star-connected alternator, what is the relation between the electromotive force across the terminals of any given winding and the electromotive force between the mains ?

23. Describe the two methods of constructing field coils for revolving field machines used by the General Electric Co.

24. What do you understand by the two-phase four-wire system ?

REVIEW QUESTIONS

ON THE SUBJECT OF

ALTERNATING CURRENT MACHINERY.

PART III.

1. Explain why the armature windings are utilized to only $\frac{1}{2}$ the extent in the inductor alternator that they are in the ordinary alternator.
2. Mention the different causes of losses in alternating-current machines.
3. What is meant by synchronous impedance and what relation does the synchronous impedance curve show?
4. Explain what is meant by a fly-wheel alternator and give an example of the same.
5. Explain clearly the inductor alternator, and how it differs from the regular type of alternator.
6. Mention briefly the different methods of starting a synchronous motor, both single-phase and polyphase.
7. Theoretically what relation exists in the transformer between the primary and secondary electromotive force and the number of turns of each coil? Express this as a formula.
8. Explain the principles of operation of the synchronous motor.
9. Describe the type of generating unit used in the Manhattan power station.
10. What are the standard frequencies used with S. K. C. alternating current generators?
11. What do you understand to be meant by the term *windage*?
12. Outline briefly the method of performing the heat test on a generator.

REVIEW QUESTIONS

ON THE SUBJECT OF

ALTERNATING CURRENT MACHINERY.

PART IV.

1. In the mesh connection of transformers, if one coil is cut out, what per cent of the total power capacity remains ?
2. If in a given transformer the voltage is increased 50%, how will this affect the eddy current and hysteresis loss ?
3. What considerations prevent the action of the actual transformer from agreeing exactly with that of the ideal transformer ?
4. When current is generated as two-phase, what is the object of changing it to three-phase when it is stepped up for long-distance transmission ?
5. What can you say of the regulation of constant-current transformers as compared with that of constant-potential transformers ?
6. What do you understand by a three-ring rotary converter ?
7. Describe with sketch the method of testing for proper connection of secondaries to be connected in parallel to supply current to a given receiving circuit.
8. If the electromotive force between any two rings of a three-ring rotary converter is 500, what will be the direct-current voltage ?
9. Without referring in any way to the book, show sketches of proper and improper connections of transformers, both in parallel and in series.
10. If the output of a 3 K.W. transformer is increased to 5 K.W., how does this affect the core loss ?

REVIEW QUESTIONS

ON THE SUBJECT OF

ALTERNATING CURRENT MACHINERY.

PART V.

1. When a rotary converter is self-started as an alternating-current motor, what precaution must be taken in regard to the polarity before connecting several rotaries to common bus-bars?
2. Why should there be very little, if any, series field winding provided on a machine to be run as an inverted rotary converter?
3. What factors enter into modifying the theoretical voltage ratios in actual rotary converters?
4. Is hunting more troublesome when the field of a motor is over-excited, or when it is under-excited?
5. Show sketch of method of supplying direct current to the Edison three-wire system with only a single machine.
6. In making a heat run on a rotary converter, what data should be taken and recorded?
7. Mention the different methods of starting a single-phase induction motor.
8. What effect does the load upon a rotary converter have upon the amount of pulsation or hunting?
9. In the case of a two-ring converter if the effective value of the alternating current flowing in at each collector ring is 150, what will be the direct current delivered by the converter?
10. What do you understand by an inverted rotary converter?
11. Name the principal tests that should be made upon rotary converters?

REVIEW QUESTIONS


ON THE SUBJECT OF

ALTERNATING CURRENT MACHINERY.

PART VI.

1. With a synchronous motor it is possible under certain circumstances to cause the current to lead the E.M.F. Is this possible with the induction motor?
2. Describe the most convenient method of obtaining the output of an induction motor in testing it for efficiency?
3. Give an expression for the apparent input in watts for the induction motor.
4. What precautions must be taken when operating compound alternators in parallel?
5. What do you understand to be meant by feeder panels?
6. If the voltage is 220 and the current 150. what is the apparent input in the case of a three-phase induction motor?
7. If the power factor of the above motor is .85 what is the actual input in watts?
8. Why cannot the core-loss test be performed on an induction motor by the method used in the case of a synchronous motor?
9. Describe the method of performing the slip test on an induction motor.
10. What are the disadvantages of slate as an insulator?
11. How are voltage regulators rated?
12. Describe the double-pole quick-break generator switch, manufactured by the Ft. Wayne Co., and explain the use of the marble barrier.
13. Explain the method of cutting out an alternator which is running in parallel with others.

INDEX



INDEX

*The page numbers of this volume will be found at the bottom of the pages;
the numbers at the top refer only to the section.*

	Page		Page
A		Alternating electromotive forces and currents	
A. c. circuit, fundamental equation of	42	d. c. and a. c. calculations	20
Air-brake switches	454	d. c. and a. c. problems, comparison of	17
All-day efficiency	279	capacity	40
Alternating currents, advantages and disadvantages of	14	condenser, capacity of	41
a. c. machines, miscellaneous	16	condenser as compensator for lagging current	57
a. c. machines, simple, construction of	16	circuits in parallel	61
high e. m. f.'s, transformation of	15	circuits in series	60
Alternating-current machinery	11, 485	electrical resonance	51
appendix	480	electromotive force, average and effective values of	24
alternating into direct current, conversion of	333	electromotive force losses in alternator	69
alternating electromotive force and currents	11	electromotive force losses in transmission lines	66
alternators	109	electromotive force, variations of	13
armature windings	147	graphical representations of	22
commercial types of machines	157	harmonic electromotive forces and currents	26
induction motor	389	inductance	37
measurement of power	140	maximum and effective values, relation between	34
measuring instruments	70	power, instantaneous and average	25
motor-generators	380	simple alternator	11
rotary converter	341	speed and frequency, relations between	13
switchboard and station appliances	438	Alternating into direct current, conversion of	333
synchronous motors	228	aluminum valve rectifier	334
transformer	247	mercury-vapor arc rectifier	336
Alternating electromotive forces and currents	11	motor-generators	380
a. c. circuit, fundamental equations of	42	rectifying commutator	333
alternating currents, advantages and disadvantages	14	rotary or synchronous converter	341
alternating e. m. f.'s and currents	22		

Note.—For page numbers see foot of pages

	Page		Page
Alternator testing	200	Armature windings	
alternating-current testing in		classification	
general	200	according to disposition of	
armature resistance	210	coils	151
characteristic curves	205	according to form of con-	
saturation	205	ductor	153
synchronous impedance	208	according to progression of	
core loss and friction test	221	winding	151
efficiency, calculation of	226	according to shape of core	147
• heat test	217	single-phase	154
insulation testing	200	three-phase	155
break-down	203	two-phase	155
dielectric strength	201	Autotransformer	265
resistance	201		
regulation	212	B	
American Institute rules	215	Bar winding	154
curve	214	C	
Alternators	109	Circuit breakers	456
armature inductance	118	Circuit-interrupting devices	453
armature reaction	116	air-break switches	454
armature windings	147	circuit-breakers	456
commercial types	157	feeder or voltage regulators	462
economy factors	191	fuses	453
electromotive force lost in arma-		lightning arresters	470
ture drop	119	oil-break switches	458
field excitation	121	voltmeter compensator	468
fundamental equation of	109	Commercial types of machines	
measurement of power	140	revolving-armature alternators	159
parallel operating of	480	revolving field alternators	166
polyphase alternators	130	Compensated wattmeter	89
single-phase system	130	Condensers, capacity of	41
three-phase system	133	Constant-current transformer	313
two-phase system	130	Cooling of transformers	306
regulation of	120	self-cooling dry transformers	307
Aluminum valve rectifier	334	self-cooling, oil-filled transformers	308
American Institute rules	196	water-cooled transformers	310
limiting temperature rise	197	Core-loss and exciting-current test	324
overload capacities	199	Core type transformer	285
rating	196	Current relations for rotary converter	352
Appendix	480	Curtis turbo-alternator	187
Armature drop, e. m. f. lost in	119	Customer's bills, calculations of	105
Armature inductance	118	D	
Armature reaction	116	Dielectric, inductivity of	41
Armature windings	147	Direct- and alternating-current prob-	
classification	147	lems, comparison of	
according to construction of		alternating current	18
core	148	direct current	17

Note.—For page numbers see foot of pages.

INDEX

3

	Page		Page
Direct-current voltage, control of	365	Field excitation	121
E		Field excitation and power factor	238
Economy factors in alternators	191	Field excitation of rotary converter	369
alternator testing	200	Form factor	25
conditions affecting cost	191	Fort Wayne single-phase alternator	159
frequency	192	Four-ring rotary converter	345
regulation	192	Frequency changer	415
speed	191	Fuse blocks transformer	319
voltage	191	Fuses	453
efficiency	193	G	
power losses	193	General Electric rotary converter	359
rating and overload capacities	195	General Electric three-phase alter- nator	164
Efficiency of alternator	193	H	
influence of power factor upon output	195	Harmonic electromotive forces and currents	26
practical and ultimate limits of output	194	addition of	31
Efficiency calculation	328	algebraic representation	29
Electrical resonance	51	clock diagram representation	27
multiplication of current by	56	graphical representation	28
multiplication of e. m. f. by	54	phase difference	29
Electrodynamometer	82	subtraction of	34
used as an ammeter	83	synchronism	29
used as a voltmeter	84	Heat run	377
Electrolytic-cell lightning arrester	474	Heat test	322
Electromagnetic ammeters and volt- meters	77	Hot-wire ammeter and voltmeter	70
Roller-Smith repulsion ammeter	80	Hunting action	235
Thomson inclined-coil meter	80	Hunting of rotary converter	361
Electromotive force, average and effective values of	24	I	
Electromotive force relations for ro- tary converter	352	Impedance	325
Electromotive force, variations of		Indicating instruments	70
cycle	13	electrodynamometers	82
frequency	13	electromagnetic ammeters and voltmeters	77
period	13	electrostatic voltmeter	74
Electrostatic ground detector	77	hot-wire ammeter and voltmeter	70
Electrostatic voltmeter	74	induction instruments	85
F		wattmeter	87
Feeder panels	448	Inductance	37
Feeder or voltage regulators	462	formulas for	39
induction	466	series and parallel	40
magnetic	464	Induction generator	415
ratings of	467	Induction instruments	85
Stillwell	462	Induction motor	389

Notes.—For page numbers see foot of pages.

	Page		Page
Induction motor		Integrating instruments	
action of	393	induction watt-hour meter	95
behavior at starting and in operation	403	sparks gauge	105
efficiency and rotor-resistance	397	Thomson watt-hour meter	92
efficiency and speed	394	watt-hour meter dials	103
mechanical to electrical energy in rotor, ratio of	395	Inverted rotaries	363
rotor for constant and variable speed	398	Iron losses	276
rotor voltages to stator voltages, ratio of	396		
rotor windings, starting resistance in	394	J	
torque and speed	393	Joule's law	17
typical induction motor, structural details of	398	K	
constructive elements	389	Kirchoff's laws	17
frequency changer	415		
induction generator	415	L	
installations	407	Lightning arresters	470
single-phase	411	condenser with choke coil, combination of	477
hand starting	411	electrolytic-cell	474
repulsion motor starting	413	installing, instructions for	478
split-phase starting	412	ground	478
stator windings and their actions	390	inspection	479
tests	424	insulation	478
break-down	426	location	478
core loss	428	lightning, effects of	470
efficiency	431	multi-gap, non-arcing	472
heat	424	multi-path	473
impedance	430	Lincoln synchronizer	451
performance curves of	434		
slip	432	M	
starting torque	427	Measuring instruments	70
Induction watt-hour meter	95	indicating	70
meter friction, compensation for	101	integrating	92
moving element	99	recording	70
polyphase	103	Mercury-vapor arc rectifier	336
power factor adjustment	99	Motor-generators	380
single-phase	96	comparison of with rotary converter	381
Inductivity of dielectric	41	types	383
Integrating instruments		uses of	382
customer's bill, calculations of	105	Motor testing	241
		break-down test	243
		phase characteristic	241
		pulsation test	242
		self-starting test	243
		Multi-gap, non-arcing lightning arrester	472
		rester	472
		Multi-path lightning arrester	473

Note.—For page numbers see foot of pages.

INDEX

5

	Page		Page
Multipolar rotary converter	346	R	
O			
Ohm's law	17	Rating and overload capacities	195
Oil-break switches	458	American Institute rules	196
Oscillators for rotary converters	358	limiting temperature rise	197
Outdoor transformers, mounting of	322	overload capacities	199
P			
Parallel operating of operators	480	rating	196
connecting one alternator in		Rating of transformers	281
parallel with another	484	Rectifying commutator	333
equalizing switch	484	Regulation	327
field currents, adjustment		Regulation of alternator	120
of	484	Resistance of coils	324
frequency	484	Revolving-armature alternators	159
load, adjustment of	484	field structure for Westinghouse	
main switch	484	180-kw.	164
phase coincidence	484	Fort Wayne single-phase	159
voltage	484	General Electric three-phase	164
cutting out alternator	484	Westinghouse armature with	
necessary conditions	480	distributed winding	163
frequency	480	Westinghouse uni-coil armature	162
phase	480	Revolving-field alternators	166
voltage	480	construction	166
relative frequency and phase co-		armature	167
incidence	480	armature coil	169
pulsation and size of pulley	483	bed plate and bearing	
synchronizer	481	pedestals	168
Phase difference	29	excitation	175
Phase transformation	271	field coils	175
Polarity test	329	frame	166
Portable torsion wattmeter	90	rotating field	171
Power, expression for	36	supporting ring	170
Power, measurement of	140	terminals	171
balanced systems	141	steam turbine-driver	181
three-wire three-phase	143	water-wheel driver	177
three-wire two-phase	141	Roller-Smith repulsion ammeter	80
unbalanced systems	143	Rotary converters in practice	354
four-wire two-phase	143	characteristic types of	359
six-wire three-phase	144	direct-current voltage, control of	365
three-wire three-phase	145	with Edison three-wire system	371
three-wire two-phase	144	field excitation	369
Power factor, influence of upon out-		hunting of	361
put	195	inverted	363
Power law	17	oscillators for	358
Power losses	193	six-phase	373
		starting of	355
		transformer connections for	373
		uses of	354
		Rotary or synchronous converter	341

Note.—For page numbers see foot of pages.

	Page		Page
Rotary or synchronous converter		Synchronous motors	
comparison with direct-current		starting motor	232
dynamo	342	exciter	232
current relations for	352	polyphase	232
direct-current dynamo into a		polyphase type, self-start-	
rotary converter	343	ing of	233
e. m. f. relations for	346	separate starting	233
four-ring	345	single-phase circuit	232
multipolar	346	torque and power output	237
in practice	354	use as a condenser	239
six-ring	346	Switchboard apparatus	451
testing of	376	circuit-interrupting devices	453
heat run	377	lightning arresters	470
standard	376	Lincoln synchronizer	451
three-ring	345	Switchboards	438
		feeder panels	448
S		high-voltage panels	451
Saturation curve	205	polyphase	443
Scott transformer	273	typical single-phase	440
Series or current transformer	311		
Shell type transformer	297	T	
Simple alternator	11	Tables	
Single-phase alternator	130	capacities of standard trans-	
Single-phase windings	154	formers	437
Six-phase rotary converter	373	constant-current transformer	
Six-ring rotary converter	346	data	314
Spark gauge	105	Δ - and Y-connection data in	
Speed and frequency, relations be-		mains	139
tween	13	Δ - and Y-connection data in re-	
Speed-limiting devices	364	ceiving circuits	140
Steam turbine-driven alternators	181	inductivities of dielectrics	41
advantages	182	power ratings of rotary conver-	
Curtis turbo-alternator	187	ters in kilowatts	343
rotor	185	size and cost of copper wire—	
stator	183	two-wire system	15
Strap winding	154	sparkling distances for various	
Synchronism	29	voltages	204
Synchronous impedance curve	208	transformer efficiencies, losses,	
Synchronous motor and induction		etc.	277
motor, comparison of	419	turbine speeds for alternators	182
Synchronous motors	228	voltage ratios of rotary con-	
advantages	230	verters	351
compared with d. c. motors	231	Thomson inclined coil meter	80
disadvantages	231	Thomson watt-hour meter	92
field excitation and power factor	238	Three-phase alternator	133
hunting action	235	Δ -connected armatures	137
motor testing	241	current relations	137

Note.—For page numbers see foot of pages.

INDEX

7

	Page		Page
Three-phase alternator		Transformer	
Δ -connected armatures		physical action	248
electromotive force relations	137	current relations	249
receiving circuits	138	electromotive force relations	248
dissimilar circuits (unbalanced system)	138	with load	248
similar circuits (bal. system)	138	without load	248
Y-connected armatures	136	polyphase systems	268
current relations	137	with compound magnetic circuits	271
electromotive force relations	136	phase transformation	271
Three-phase transformers	303	three-phase	269
Three-phase windings	155	two-phase	269
Three-ring rotary converter	345	practical considerations	276
Torque and power output	237	efficiency	277
Transformer	247	rating of	281
automatic action of	250	regulation	280
coil resistances and magnetic leakage	254	transformer losses	276
commercial types of	284	regulation	255
constant current	313	with highly inductive load	255
fuse blocks	319	with non-inductive load	255
cooling of	306	tests	322
core	285	core-loss and exciting-current	324
series or current	311	efficiency calculation	328
shell	297	heat	322
three-phase	303	impedance	325
connections	256	polarity	329
auto-transformer	265	regulation	327
auto step-down transformation	267	resistance of coils	324
auto step-up transformation	266	Transformer connections for rotary converters	373
current relations	267	Two-phase alternator	130
parallel-constant-voltage transformers	256	Two-phase windings	155
banking of	261	V	
Edison three-wire system-single-phase	260	Voltmeter compensator	468
multi-coil type	257	W	
series-current transformers	263	Water-wheel-driven alternators	177
description	247	Watt-hour meter dials	103
ideal action graphically represented	253	Wattmeter	87
ideal and practical	250	Westinghouse armature with distributed winding	163
maximum core flux	251	Westinghouse uni-coil armature	162
		Wire winding	153

Note.—For page numbers see foot of pages.

