



T ELEVISION SERVICE TIPS

IMPORTANT INFORMATION FOR YOUR SERVICE DEPARTMENT

PREPARED AND DISTRIBUTED BY RCA SALES CORPORATION, PRODUCT PERFORMANCE
600 N. SHERMAN DRIVE, INDIANAPOLIS, 1, INDIANA

VOLUME XV


ISSUE 2

JULY 10, 1964

KRK 114 SCHEMATIC DIAGRAM CORRECTION

SERVICE DATA - Chassis KCS 148
1964 No. T5

The heater wiring diagram and tube lineup for the KRK 114 schematic diagram on Page 5 of Service Data 1964 No. T5 should be corrected as reproduced below:



SERVICE DATA - Chassis KCS 151
1964 No. T8

Change the tube type of the KRK 114 RF amplifier, shown on page 5, to read 3GK5.